




ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJH 8746T Regn: 27/08/2008  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Wish CC 181744.  
 Colour: Black A/C Insured / Std / NI / NA  
 Sp. Reading: 166428 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 CrNo: JTDER12W 20300.8 650

Gen. Cond: Good (Fair) Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or RIVERA

Front Rear  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 22/2/19 D.O.I. 26/2/19  
 Survey held at STK Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 front LH, RH side

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : \_\_\_\_\_ Action / Instruction  
 MV - 31,880  
 PV - 15,746  
 NV - 15,254

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:  
 Transportation

4) Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

) \$ + RT: \$  
 ) Photos  
 ) Other  
 )

Report Format: DAR

Lump Sum / L.B. (\$)



**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 26/2/2019 12:33:14 PM  
Attachments:  tmp2428.tif  2nd PRS (STK) Template.pdf

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref : SMA 1748K  
Our Ref : SJH 8746T/STK/jp/ps  
Date : 25 February 2019

Fax : 6538 3708  
Tel : 3152 0984  
Email : accident@kscgp.com

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

**DATE OF ACCIDENT: 22 FEBRUARY 2019**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email on even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/No. | Name of Surveyor    |
|-------|---------------------|
| 1     | Ho Joo Loong, Danny |
| 2     | Lee Kok Weng        |
| 3     | Seah Kwang Boon     |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : STK Auto (S) Pte Ltd  
Block 8 Kaki Bukit Avenue 4  
#03-21 Premier @ Kaki Bukit  
Singapore 415875

Contact Person/Tel : Jingjing / Tel: 6386 0669 or Guohua / Tel: 9123 7949

Yours faithfully,

*PS*

MYT21024780 / Yew Tee Automobile Tech Pte Ltd - Kallang  
 ENTRY DATE & TIME: 22/02/2019 13:01  
 SUBMITTED BY: Tan Lai Ming

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 22/02/2019 13:01  
 Date Of Accident 22/02/2019 07:15  
 Exact Location Of Accident PASIR RIS DR 1  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SJH8746T

Insured/Policyholder

Name Of Registered Owner ZHANG WEI

NRIC No

Email Address NOEMAIL

Mobile Phone No

Alternative Phone No

Vehicle Particulars

Manufacturer TOYOTA

Model WISH

Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRER USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5104524115

Cover Note Number

Driver

Name of Driver ZHANG WEI

NRIC No

Date Of Birth 25/01/1979

Occupation OUTDOOR

Date Of Driving Pass 28/10/2016

Driving Experience 2 YEARS AND 3 MONTHS

Gender MALE

Mobile Number

Fax Number

Contact Number

E-Mail Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) Involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : PASSENGER

GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SMA1748K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver PHUA SEOW TONG

NRIC/Passport Number S1537602C

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                          |
| Owner ID Type:                                                                                                                                                                                                          | Singapore NRIC           |
| Owner ID:                                                                                                                                                                                                               | 3869B                    |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                          |
| Vehicle No.:                                                                                                                                                                                                            | SJH8746T                 |
| Vehicle to be Exported:                                                                                                                                                                                                 | Yes                      |
| Intended Deregistration Date:                                                                                                                                                                                           | 26 Feb 2019              |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                   |
| Vehicle Model:                                                                                                                                                                                                          | WISH 1.8 AUTO            |
| Primary Colour:                                                                                                                                                                                                         | Blue                     |
| Manufacturing Year:                                                                                                                                                                                                     | 2008                     |
| Engine No.:                                                                                                                                                                                                             | 1ZZ3131395               |
| Chassis No.:                                                                                                                                                                                                            | JTDER12W203000650        |
| Maximum Power Output:                                                                                                                                                                                                   | 97.0 kW (130 bhp)        |
| Open Market Value:                                                                                                                                                                                                      | \$18,803.00              |
| Original Registration Date:                                                                                                                                                                                             | 27 Aug 2008              |
| First Registration Date:                                                                                                                                                                                                | 27 Aug 2008              |
| Transfer Count:                                                                                                                                                                                                         | 3                        |
| Actual ARF Paid:                                                                                                                                                                                                        | \$18,803.00              |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                          |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                        |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                   |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                          |
| COE Expiry Date:                                                                                                                                                                                                        | 26 Aug 2023              |
| COE Category:                                                                                                                                                                                                           | B - Car (1601cc & above) |
| COE Period(Years):                                                                                                                                                                                                      | 5                        |
| PQP Paid:                                                                                                                                                                                                               | \$17,496.00              |
| COE Rebate Amount:                                                                                                                                                                                                      | \$15,746.00              |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$15,746.00</b>       |
| <b>Message</b>                                                                                                                                                                                                          |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 26 Feb 2019

OK

# SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!

POST AN AD NOW!

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Beautiful Nissan Pulsar 1.2 Turbo Free Of Accident.



Very New Direct One Owner, 6  
Airbags, Tinted, Sports Rims,  
Original Sports Kit,  
Direct Owner - SunAd

**PRIME MOTOR & LEASING**  
[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]  
With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category

« Back ( 1 2 3 ) Next »

Sort by Date Posted

20 results/page

55 vehicles

Toyota Wish

Advanced Search

| Make                                                                                                                                                                                                         | Model                                                  | Price           | Depreciation       | Reg Date           | Eng Cap         | Mileage           | Veh Type   | Status          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|-----------------|--------------------|--------------------|-----------------|-------------------|------------|-----------------|
| Search Selection                                                                                                                                                                                             | Toyota Wish                                            | Any             | Any                | > 10 year(s) old   | Any             | Any               | Any        | Availabl        |
|                                                                                                                              | <b>Toyota Wish 1.8A Sunroof (COE till 01/2027)</b>     | <b>\$50,800</b> | <b>\$6,410 /yr</b> | <b>30-Jan-2007</b> | <b>1,794 cc</b> | <b>172,664 km</b> | <b>MPV</b> | <b>Availabl</b> |
| Rare Wish 1.8A With Sunroof/Rear Air-Con Of Low \$6,400 Depreciation Yet Price Negotiable! Road Tax Till Jan 20! Low Mileage Clocked Of 14500km Annually. Superb Condition. 100% Accident Free. Call Now!    |                                                        |                 |                    |                    |                 |                   |            |                 |
| Lake View Credit Pte Ltd                                                                                                                                                                                     |                                                        |                 |                    |                    |                 |                   |            |                 |
| Posted: 23-Feb-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota                                                                                      |                                                        |                 |                    |                    |                 |                   |            |                 |
|                                                                                                                            | <b>Toyota Wish 1.8A (COE till 01/2024)</b>             | <b>\$32,800</b> | <b>\$6,720 /yr</b> | <b>14-Jan-2009</b> | <b>1,794 cc</b> | <b>-</b>          | <b>MPV</b> | <b>Availabl</b> |
| 2.38%P.A Lowest Interest At \$638 Monthly For Honda Stream, \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox, Add Ons Available                                                   |                                                        |                 |                    |                    |                 |                   |            |                 |
| GV Credit Pte Ltd                                                                                                                                                                                            |                                                        |                 |                    |                    |                 |                   |            |                 |
| Posted: 23-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota                                                                                      |                                                        |                 |                    |                    |                 |                   |            |                 |
|                                                                                                                            | <b>Toyota Wish 1.8A X (COE till 12/2023)</b>           | <b>\$34,800</b> | <b>\$7,180 /yr</b> | <b>31-Dec-2008</b> | <b>1,794 cc</b> | <b>-</b>          | <b>MPV</b> | <b>Availabl</b> |
| Inclusive Insurance And 1st Month Installment) Low Monthly Installment At \$786 x 54 Months! New 5 Years COE. 120 Point Check By Our In House Workshop. High Trade In/High Flex Loan Available. Please Ca... |                                                        |                 |                    |                    |                 |                   |            |                 |
| Viking Motor Pte Ltd                                                                                                                                                                                         |                                                        |                 |                    |                    |                 |                   |            |                 |
| Posted: 23-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota                                                                                      |                                                        |                 |                    |                    |                 |                   |            |                 |
|                                                                                                                            | <b>Toyota Wish 1.8A Aero Tourer (COE till 07/2023)</b> | <b>\$31,500</b> | <b>\$7,120 /yr</b> | <b>31-Jul-2008</b> | <b>1,794 cc</b> | <b>136,000 km</b> | <b>MPV</b> | <b>Availabl</b> |
| Great MPV Choice Of Toyota Wish 1.8A With New 5 Years COE! Low Mileage Clocked Of 17500km Annually. No Other Repairs Needed. New Tyres, 100% Accident-Free. Trade In Welcome!                                |                                                        |                 |                    |                    |                 |                   |            |                 |
| Posted: 22-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota                                                                                      |                                                        |                 |                    |                    |                 |                   |            |                 |

GET YOUR  
COE  
RENEWAL  
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Compare

**Toyota Wish 1.8A (New 10-yr COE)**

**\$51,888****\$5,180 /yr****25-Feb-2009****1,794 cc****-****MPV****Availabl**

1 Owner Only! Best Condition In Town! Do Not Miss This Deal! Everything Still In Stock Condition! Tip Top Condition! Trade In Welcome! Call For Availability And Test Drive Appointment Before Its Gone!...

Posted: 22-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (COE till 12/2028)**
**\$58,800****\$5,970 /yr****30-Dec-2008****1,794 cc****-****MPV****Availabl**

Beautiful Smoke Free Interior And Well Maintained, Tip Top Condition, Low Mileage Done.

**DIRECT OWN**

Posted: 21-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (New 10-yr COE)**
**\$49,800****\$4,980 /yr****13-Jan-2009****1,794 cc****-****MPV****Availabl**

Interest From 3.18%, Bank Loan And In House Loan Available. Lowest Monthly Installment \$800. Vehicle Checked By In House Workshop. Trade In Welcome.

Posted: 21-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (New 5-yr COE)**
**\$35,800****\$7,160 /yr****23-Feb-2009****1,794 cc****111,000 km****MPV****Availabl**

100% In House Loan Available! Highest Offer For All Trade In! Selling Cheap! Well Kept And Maintained By Previous Owner. Most Popular 7 Seaters MPV, Low Depreciation, Excellent Condition For COE Car! ...

Posted: 21-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (COE till 11/2023)**
**\$31,777****\$6,710 /yr****21-Nov-2008****1,794 cc****-****MPV****Availabl**

Make Your Wish Come True! New COE! Up To 100% Financing. Regularly Serviced. New Paint/Road Tax. Good Condition, Test Drive You Will Know! Most Affordable, Practical And Fuel Efficient MPV For Your Fa...

Posted: 21-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (COE till 02/2024)**
**\$36,800****\$7,420 /yr****11-Feb-2009****1,794 cc****152,500 km****MPV****Availabl**

\$3,000 Drive Away! (Inclusive Insurance And 1st Month Installment) Low Monthly Installment At \$847 x 54 Months! New 5 Years COE! 120 Point Check By Our In House Workshop. High Trade In/High Flexible L...

Viking Motor Pte Ltd

Posted: 21-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Sell to direct buyers at the price you want!**

Make the choice to sell only if the price meets your expectations. Contact our agents to find out how to list on consignment.

Find out more!


**Toyota Wish 1.8A (COE till 03/2021)**
**\$18,800****\$9,210 /yr****13-Mar-2006****1,794 cc****-****MPV****Availabl**

Engine, Gearbox And Undercarriage Are All In Good Running Condition, No Repair Is Needed. Current Registration Numbers Will Be Used For New Car, So A New Registration Numbers Will Be Issued To This Ve...

**DIRECT OWN**

Posted: 20-Feb-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (COE till 02/2024)**
**\$34,800****\$7,030 /yr****09-Feb-2009****1,794 cc****108,231 km****MPV****Availabl**

One Owner "One Year In House Warranty", \$50,800 For 10 Years COE, STA Or VICOM Evaluation Are Welcome, New Paintwork Done, Accident-Free, Wear And Tear Replaced, Finance Or In House Loan Available, Ne...

Posted: 20-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota


**Toyota Wish 1.8A (New 5-yr COE)**
**\$36,800****\$7,360 /yr****18-Feb-2009****1,794 cc****-****MPV****Availabl**

Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Arrange Call To Our Sales For Appointment!

Posted: 20-Feb-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A Aero Tourer (New 5-yr COE)**
**\$33,800****\$6,760 /yr****26-Feb-2009****1,794 cc****111,530 km****MPV****Availabl**

Monthly Of \$768, Genuine Low Mileage Done! Accident Free! High Loan Available! Too Good To Scrap! Best Unit Ever, Very Well Kept And Maintained By Pre-Owner! Warranty Will Be Provided, Call For Viewin...

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 22/02/2019 13:01 |
| Date Of Accident           | 22/02/2019 07:15 |
| Exact Location Of Accident | PASIR RIS DR 1   |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJH8746T             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | ZHANG WEI            |
| NRIC No                     | S7963869B            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-85752888 |
| Alternative Phone No        | OFFICE-85752888      |

### Vehicle Particulars

|                                                                              |                   |
|------------------------------------------------------------------------------|-------------------|
| Manufacturer                                                                 | TOYOTA            |
| Model                                                                        | WISH              |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE HIRER USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                |
| If No, Please state action to be taken                                       | THIRD PARTY       |
| Vehicle Category                                                             | PRIVATE HIRE      |

### Insurance Company

|                           |                                        |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5104524115                             |
| Cover Note Number         |                                        |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | ZHANG WEI            |
| NRIC No              | S7963869B            |
| Date Of Birth        | 25/01/1979           |
| Occupation           | OUTDOOR              |
| Date Of Driving Pass | 28/10/2016           |
| Driving Experience   | 2 YEARS AND 3 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-85752888 |
| Fax Number           |                      |
| Contact Number       | OFFICE-85752888      |
| Email Address        | NOEMAIL              |

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and/or, necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any inquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me) which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages; and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively, the "Purposes").
- (b) all insurers(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared, disclosed:
  - (i) to all insurers and/or any other third party that assist in evaluating, investigating, controlling or managing claims, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Person's Signature  
Name  
NRIC/IN No.:

indusog (CON)

(1) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary (12) Missing  
(13) Torn (14) Unconfirmed (15) Not Working

## MOTOR CAR (LH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (✓)  
(4) Not Consistent (N/C)

Aug 2005

Vehicle No:

SJH 8746T

Left Portion

| IAC  | INC    | Item                              | CON | AC | Qty |
|------|--------|-----------------------------------|-----|----|-----|
| 255  | 995326 | Frt LH Door                       |     | R  |     |
| 256  | 995140 | Frt LH Door Protector             |     |    |     |
| 257  | 995104 | Frt LH Door Hinge                 |     |    |     |
| 258  | 995142 | Frt LH Door Wing Mirror           | OR  | ✓  |     |
| 259  | 995102 | Frt LH Door Garnish               |     |    |     |
| 260  | 991593 | Frt LH Door Glass Outer Moulding  |     |    |     |
| 261  | 991588 | Frt LH Door Glass Inner Moulding  |     |    |     |
| 262  | 995103 | Frt LH Door Glass                 |     |    |     |
| 263  | 991595 | Frt LH Door Glass Regulator       |     |    |     |
| 264  | 991596 | Frt LH Door Glass Regulator Motor |     |    |     |
| 265  | 991662 | Frt LH Door Rubber                |     |    |     |
| 266  | 991636 | Frt LH Door Outer Handle          |     |    |     |
| 267  | 991607 | Frt LH Door Inner Handle          |     |    |     |
| 268  | 991625 | Frt LH Door Lock w/Key            |     |    |     |
| 269  | 991624 | Frt LH Door Lock                  |     |    |     |
| 270  | 991562 | Frt LH Door Central Lock          |     |    |     |
| 271  | 991675 | Frt LH Door Switch                |     |    |     |
| 272  | 991617 | Frt LH Door Inner Trim Board      |     |    |     |
| 273  | 991568 | Frt LH Door Checker               |     |    |     |
| 274  | 991575 | Frt LH Door Felt                  |     |    |     |
| 275  | 991688 | Frt LH Door Wire Harness          |     |    |     |
| 276  | 991683 | Frt LH Door Window Glass Pillar   |     |    |     |
| 277  | 991640 | Frt LH Door Outer Pillar          |     |    |     |
| 278  | 991613 | Frt LH Door Inner Pillar          |     |    |     |
| 279  | 991646 | Frt LH Door Pillar Inner Garnish  |     |    |     |
| 280  | 990554 | Centre Pillar LH                  |     |    |     |
| 281  | 990542 | Centre Inner Pillar LH            |     |    |     |
| 282  | 990517 | Centre Pillar Upper Garnish LH    |     |    |     |
| 283  | 990564 | Centre Pillar Lower Garnish LH    |     |    |     |
| 284  | 991670 | Frt LH Door Step Garnish          |     |    |     |
| 285  | 994052 | Rocker Panel LH                   |     |    |     |
| 286  | 994049 | Rocker Panel Inner Panel LH       |     |    |     |
| 287  | 994046 | Rocker Panel Garnish LH           |     |    |     |
| 288  | 994055 | Rocker Panel Outer Side Skirt LH  |     |    |     |
| 1004 | 991300 | Frt Bumper                        | SCR | R  |     |
| 1006 | 991325 | Frt Bumper Bracket                | OR  | ✓  |     |
| 1007 | 991462 | Frt Bumper Side Retainer          |     |    |     |
| 1008 | 991433 | Frt Bumper Reinforcement          |     |    |     |
| 1010 | 991468 | Frt Bumper Sponge                 |     |    |     |
| 1011 | 991427 | Frt Bumper Protector              |     |    |     |
| 1014 | 991301 | Frt Bumper Moulding               |     |    |     |
| 1015 | 991407 | Frt Bumper Lower Spoiler          | OR  | ✓  |     |
| 1029 | 995153 | Frt LH Headlamp Assy              |     |    |     |
| 1031 | 995088 | Frt LH Side Lamp                  |     |    |     |
| 1096 | 995070 | Frt LH Fender                     | DD  | R  |     |
| 1098 | 995147 | Frt LH Fender Lamp                |     |    |     |
| 1099 | 995148 | Frt LH Fender Protector           |     |    |     |
|      |        | FR LH Wheel Rim                   | CUT |    |     |
|      |        | " " " Tyre                        |     |    |     |

| NAC  | INC    | Item                                | CON | AC | Qty |
|------|--------|-------------------------------------|-----|----|-----|
| 1289 | 995156 | Rear LH Door                        |     |    |     |
| 1290 | 993282 | Rear LH Door Protector              |     |    |     |
| 1291 | 995194 | Rear LH Door Hinge                  |     |    |     |
| 1292 | 993228 | Rear LH Door Garnish                |     |    |     |
| 1293 | 993278 | Rear LH Door Glass Outer Moulding   |     |    |     |
| 1294 | 993231 | Rear LH Door Glass Inner Moulding   |     |    |     |
| 1295 | 995190 | Rear LH Door Glass                  |     |    |     |
| 1296 | 993238 | Rear LH Door Glass Regulator        |     |    |     |
| 1297 | 995192 | Rear LH Door Glass Regulator Motor  |     |    |     |
| 1298 | 993294 | Rear LH Door Rubber                 |     |    |     |
| 1299 | 993275 | Rear LH Door Outer Handle           |     |    |     |
| 1300 | 993250 | Rear LH Door Inner Handle           |     |    |     |
| 1301 | 993261 | Rear LH Door Lock                   |     |    |     |
| 1302 | 993256 | Rear LH Door Inner Trim Board       |     |    |     |
| 1303 | 993218 | Rear LH Door Checker                |     |    |     |
| 1304 | 993230 | Rear LH Door Glass Channel          |     |    |     |
| 1305 | 993242 | Rear LH Door Glass Triangle Garnish |     |    |     |
| 1306 | 993285 | Rear LH Door 1/4 Glass              |     |    |     |
| 1307 | 993288 | Rear LH Door 1/4 Glass Rubber       |     |    |     |
| 1308 | 993287 | Rear LH Door 1/4 Glass Pillar       |     |    |     |
| 1309 | 993305 | Rear LH Door Step Garnish           |     |    |     |
| 1310 | 993309 | Rear LH Door Switch                 |     |    |     |
| 1311 | 994070 | Roof Top Panel                      |     |    |     |
| 1312 | 994098 | Roof Top Moulding                   |     |    |     |
| 1313 | 994085 | Roof Top Air-bag                    |     |    |     |
| 1314 | 994084 | Roof Top Air-bag Sensor             |     |    |     |
| 1315 | 994083 | Roof Top Air-bag Control Unit       |     |    |     |
| 1141 | 992958 | Rear Bumper                         |     |    |     |
| 1147 | 992976 | Rear Bumper Bracket                 |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer           |     |    |     |
| 1149 | 993045 | Rear Bumper Reinforcement           |     |    |     |
| 1151 | 993077 | Rear Bumper Sponge                  |     |    |     |
| 1153 | 993040 | Rear Bumper Protector               |     |    |     |
| 1155 | 993026 | Rear Bumper Moulding                |     |    |     |
| 1157 | 993023 | Rear Bumper Lower Spoiler           |     |    |     |
| 1163 | 993851 | Rear LH Taillamp                    |     |    |     |
| 1218 | 993436 | Rear LH Fender                      |     |    |     |
| 1219 | 993449 | Rear LH Fender Protector            |     |    |     |
| 1136 | 990247 | Sticker                             |     |    |     |

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                          | Adj Submitted                              | Ins Auth'd | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|--------------------------------------------------|--------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 26 Feb 2019<br><a href="#">Edit Reg</a> |               | 26 Feb 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                          | Reference                                                                                                                                    | Claim Details          | Documents                                                                            | <a href="#">Show All</a>          |         |             |              |            |       |
|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|------------------------|--------------------------------------------------------------------------------------|-----------------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                |                                                                                                                                              |                        | <b>[Created by adjuster]</b>                                                         |                                   |         |             |              |            |       |
| Insured:                                                                                                      | <b>PHUA SEOW TONG</b> , ID: S1537602C                                                                                                        |                        |                                                                                      |                                   |         |             |              |            |       |
| Main Claimant:                                                                                                | <b>ZHANG WEI</b> , ID: -                                                                                                                     |                        |                                                                                      |                                   |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                             | <b>SJH8746T</b>                                                                                                                              | Date of Loss:          | 22/02/2019 07:00 - :59<br><b>[125 Months and 26 Days From LTA Reg Date (Man Yr)]</b> |                                   |         |             |              |            |       |
| Claim Type:                                                                                                   | <b>TP / 3563885241SG</b>                                                                                                                     | Policy/Cover Note No.: | 1800069352 (Comprehensive)                                                           |                                   |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                   | <b>SMA1748K</b>                                                                                                                              | Policy No. (Claimant): |                                                                                      |                                   |         |             |              |            |       |
|                                                                                                               |                                                                                                                                              | Excess:                |                                                                                      |                                   |         |             |              |            |       |
| Repairer:                                                                                                     | <b>Stk Auto (s) Pte Ltd (HQ)</b> 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:                                                         |                        |                                                                                      |                                   |         |             |              |            |       |
| Handling Insurer:                                                                                             | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ]<br>Norsiah.MdNoor@aig.com |                        |                                                                                      |                                   |         |             |              |            |       |
| Adjuster:                                                                                                     | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 07/03/2019]</b>       |                        |                                                                                      |                                   |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>                                                                               |                                                                                                                                              |                        | <a href="#">View All</a>                                                             | <a href="#">Compose Case Mail</a> |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (27/02/2019): <b>Request To Upload TP GIA Report</b></li> </ul> |                                                                                                                                              |                        |                                                                                      |                                   |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>                                                                                   |                                                                                                                                              |                        | <a href="#">View All</a>                                                             | <a href="#">Search Tasks</a>      |         |             |              |            |       |
|                                                                                                               |                                                                                                                                              |                        | <a href="#">Create New Task</a>                                                      | <a href="#">Complete</a>          |         |             |              |            |       |
| Due Date                                                                                                      | Priority                                                                                                                                     | Type                   | Task Group                                                                           | Subject                           | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                   |                                                                                                                                              |                        |                                                                                      |                                   |         |             |              |            |       |



## Claim Documents

**\*SJH8746T (3563885241SG)**  
**[SMA1748K]**  
**TP**  
**ZHANG WEI**  
**Feb 22 2019 7:00AM**  
**[PHUA SEOW TONG]**  
**Stk Auto (s) Pte Ltd**

| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a> |                 |                                   | <a href="#">View</a> <a href="#">View in Browser</a>                                           |                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| Photos/Images                                                                                                                                               |                 |                                   | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                                                                                                                                                          | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 2                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 4                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 5                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 6                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 7                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 8                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 9                                                                                                                                                           | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 10                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 11                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 12                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 13                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 14                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 15                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 16                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 17                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 18                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 19                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 20                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 21                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 22                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 23                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 24                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 25                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 26                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 27                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 28                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 29                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 30                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 33                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 34                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 35                                                                                                                                                          | 27/02/19 08:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page ▼                                                                                   | ✓     |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 36            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 37            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 38            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 39            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 40            | 27/02/19 08:48  | Odometer Reading                  |  Load JPG   | ✓     |
| 41            | 27/02/19 08:48  | Chassis Number                    |  Load JPG   | ✓     |
| 42            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 43            | 27/02/19 08:48  | General View                      |  Load JPG   | ✓     |
| 44            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 45            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 46            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 47            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 48            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 49            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 50            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 51            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 52            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 53            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 54            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG   | ✓     |
| 55            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG  | ✓     |
| 56            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 57            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 58            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 59            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 60            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 61            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 62            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 63            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 64            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 65            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 66            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 67            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 68            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 69            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 70            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 71            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 72            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 73            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 74            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 75            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 76            | 20/03/19 17:20  | Photographs of Damaged Parts      |  Load JPG | ✓     |
| 77            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 78            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 79            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 80            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 81            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 82            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |
| 83            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | ✓     |

| Photos/Images |                 |                                   | 3 per page ▾                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 84            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 85            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 86            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 87            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 88            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 89            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 90            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 91            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 92            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 93            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 94            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 95            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 96            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 97            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 98            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 99            | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 100           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 101           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 102           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG  | <input checked="" type="checkbox"/> |
| 103           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 104           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 105           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 106           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 107           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 108           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 109           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 110           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 111           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 112           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 113           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 114           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 115           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 116           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 117           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 118           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 119           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 120           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 121           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 122           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 123           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 124           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 125           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 126           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 127           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 128           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 129           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 130           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 131           | 20/03/19 17:21  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                           | 3 per page ▾ | ✓               |
|---------------|-----------------|-------------------------------------------|--------------|-----------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |              | Thumbnail Print |
| 132           | 20/03/19 17:21  | Photo After Spray                         | 1 Load JPG   | ✓               |
| 133           | 20/03/19 17:21  | Photo After Spray                         | 1 Load JPG   | ✓               |
| 134           | 20/03/19 17:21  | Photo After Spray                         | 1 Load JPG   | ✓               |
| 135           | 20/03/19 17:21  | Photo After Spray                         | 1 Load JPG   | ✓               |
| Documentation |                 |                                           | 1 per page ▾ | ✓               |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) |              | Thumbnail Print |
| 1             | 27/02/19 09:16  | OI GIA REPORT                             | 1 Load PDF   |                 |

## Documents Checklist

| DOCUMENTS CHECKLIST                          |  |  | Reset | Save | Print |
|----------------------------------------------|--|--|-------|------|-------|
| There are no document checklists configured. |  |  |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003618/ECD3S2

Date: 22/03/2019

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 1800069352   |
| Claimant Vehicle No : | SJH8746T                             | Insured Vehicle No : | SMA1748K     |
| Date of Loss:         | 22/02/2019                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 3563885241SG |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJH8746T                     | Engine No:  | 1ZZ3131395        |
| Make & Model:               | TOYOTA WISH, 1.8 (A)         | Chassis No: | JTDER12W203000650 |
| Reg. Date:                  | 27/08/2008 (Man. Year: 2008) | Odometer:   | 166428 km         |
| Colour:                     | Black                        |             |                   |
| Engine Capacity:            | 1794 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

## CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 205/55R16   | Rear Tyre Size:  | 205/55R16   |
| Front Left Side:  | RIVERA 7 mm | Rear Left Side:  | RIVERA 7 mm |
| Front Right Side: | RIVERA 7 mm | Rear Right Side: | RIVERA 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

|                             |            |               |                                                                            |
|-----------------------------|------------|---------------|----------------------------------------------------------------------------|
| Date of Assignment:         | 26/02/2019 |               |                                                                            |
| Date Inspected:             | 26/02/2019 | Inspected At: | Stk Auto (s) Pte Ltd (HQ)<br>8 kaki bukit ave4, #03-21<br>Singapore 415875 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                            |

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                  | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|-----------|------------|--------|
| 1   | 1   |          | *FRT LH DOOR                 | Repair    | 0.00 F     | *- F   |
| 2   | 1   |          | *FRT LH DOOR WING MIRROR     | Broken    | 0.00 F     | *- F   |
| 3   | 1   |          | *FRT BUMPER                  | Repair    | 0.00 F     | *- F   |
| 4   | 1   |          | *FRT BUMPER BRACKET          | Broken    | 0.00 F     | *- F   |
| 5   | 1   |          | *FRT BUMPER LOWER SPOILER    | Broken    | 0.00 F     | *- F   |
| 6   | 1   |          | *FRT LH FENDER               | Repair    | 0.00 F     | *- F   |
| 7   | 1   |          | *FRT LH WHEEL RIM            | Cut       | 0.00 F     | *- F   |
| 8   | 1   |          | *FRT LH WHEEL TYRE<br>(80%)  | *Check    | 0.00 F     | *- F   |
| 9   | 1   |          | *FRT LH SHOCK ABSORBER       | *Check    | 0.00 F     | *- F   |
| 10  | 1   |          | *FRT LH KNUCKLE ARM          | *Check    | 0.00 F     | *- F   |
| 11  | 1   |          | *FRT LH KNUCKLE ARM BEARING  | *Check    | 0.00 F     | *- F   |
| 12  | 1   |          | *FRT LH LOWER ARM            | *Check    | 0.00 F     | *- F   |
| 13  | 1   |          | *AXLE BEAM                   | *Check    | 0.00 F     | *- F   |
| 14  | 1   |          | *FRT RH SHOCK ABSORBER       | *Check    | 0.00 F     | *- F   |
| 15  | 1   |          | *FRT RH KNUCKLE ARM          | *Check    | 0.00 F     | *- F   |
| 16  | 1   |          | *FRT RH KNUCKLE ARM BEARING  | *Check    | 0.00 F     | *- F   |
| 17  | 1   |          | *FRT RH LOWER ARM            | *Check    | 0.00 F     | *- F   |
| 18  | 1   |          | *FRT RH WHEEL RIM            | Cut       | 0.00 F     | *- F   |
| 19  | 1   |          | *FRT RH WHEEL TYRE<br>(80%)  | *Check    | 0.00 F     | *- F   |
| 20  | 1   |          | *REAR RH SHOCK ABSORBER      | *Check    | 0.00 F     | *- F   |
| 21  | 1   |          | *REAR RH KNUCKLE ARM         | *Check    | 0.00 F     | *- F   |
| 22  | 1   |          | *REAR RH KNUCKLE ARM BEARING | *Check    | 0.00 F     | *- F   |
| 23  | 1   |          | *REAR RH WHEEL RIM           | Cut       | 0.00 F     | *- F   |
| 24  | 1   |          | *REAR RH TYRE<br>(80%)       | *Check    | 0.00 F     | *- F   |

F=Franchise part.

|                          |             |             |
|--------------------------|-------------|-------------|
| <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |
|--------------------------|-------------|-------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

< END OF ESTIMATES >