

ASS. REC. BY:

REF:

CS3/AIG19003620/Bcd3^{SP}

Object of Instruction

SALE/RENT

Mr Lim

ASSIGNMENT (Office)

From (Person):

ehin lee Ying

of

AIG

Date/Time: 26/2/19 @ 12:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 2316J

Insured:

SDR 1772G

at Workshop m/s

Keng Seng Auto

Tel:

9125 4835 / 6337 7533

of

Blk 9004 Tampines St. 93 #01-94

Policy No:

1800011949

Claim No:

1351381060SG

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 16/2/19

5/3/2019 After lunch.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:44pm 26/2/19

Person Contacted:

jane

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SME 2316J-X
	SDR 1772G-X
	Dismantle: 6/3/2019.

REF:

A16

ASSIGNMENT

From

Date: 26/2/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SME 2346 J.

at Workshop n/s

Keng Seng

of Blk 9004 Tampines St. 93 #01-94

Insured:

63377533

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After lunch.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days: Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SME 2346 J

Yr Regn: 24/3/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI ELANTRA

CC: 1591C

Colour: BLUE

AC Insured / Std / NI / NA

Sp. Reading: 4348

T/Radio: Insured / Std / NI / NA

Eng/No: G4FGJU142986

C/No: KMHD841CAJU644978

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R5

R: 195/65R5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 16/2/19

D.O.I. 26/2/19

Survey held at KENG SENG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3,000/2 - 4,000/2

MY 78,800/2

FY 44,807/2

NY 33,193/2

TGM Lin
26/3/19

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ Site Insp. (\$)

1) 5-PS 24

☐ Interview (\$)

2) Phone

☐ Tech. Inv. (\$)

3) Other

☐ Weekend (\$)

Report Format: DAR.

Lump Sum / I.B.I. (\$)

TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/2/2019 12:03:17 PM

Attachments:  1st PRS 20190222185501.pdf  Template 2nd PRS (reject).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref : 1351381060SG003

Our Ref : **SME 2346J/SK/jn/mt**

Date : 25 February 2019

Fax : **6538 3708**

Tel : **3152 0986**

Email : **accident@ksecp.com**

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL ONLY

DATE OF ACCIDENT: 16 FEBRUARY 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 25 February 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	Lee Kok Weng	Lee Automobile Appraisal Services
2.	Patrick Ng Kong Beng	Carlink Consultancy
3.	Ang Guea Kiang	CA Appraisal
4.	Philip Foo	Precision Appraisal Services
5.	Ong Ah Keng, Kent	KTO Automobile Assessors
6.	Ong Poh Meng	Aeon Auto Consultants LLP
7.	Chang Fuh Keong, Dave	Sincere Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Keng Soon Auto Pte Ltd
Khek Joo Motor Workshop
Block 9004 Tampines Street 93
#01-94
Singapore 528838
Contact Person/Tel : Jane / 6337 7533

Yours faithfully,

MT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/02/2019 10:39
Date Of Accident 16/02/2019 11:50
Exact Location Of Accident QUEENSWAY SHOPPING CENTRE CARPARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME2346J
Insured/Policyholder
Name Of Registered Owner KENG SOON AUTO PTE LTD
Co Reg No 197701612E
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No

Vehicle Particulars

Manufacturer HYUNDAI
Model ELANTRA AD 1.6 GLS AT (AMS)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY
Fleet Policy YES
Policy Number D-18090222MFZH/144 (TP)
Cover Note Number

Driver

Name of Driver CURLEY DAVID
Passport No/FIN
Date Of Birth
Occupation
Date Of Driving Pass
Driving Experience
Gender MALE
Mobile Number
Fax Number
Contact Number
Email Address NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle Involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDR1772G
 Vehicle Make/Model/Colour MERCEDES BENZ GLA180
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAY BOON TAT
 NRIC/Passport Number S2557847C
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 22 FEB 2019

IDAC KAKI BUKIT(VAC)
Reporting Centre
Name: Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was half turned into the parking lot, Suddenly
SDR 1772G hit my Left rear Bumper.

DECLARATION

I/We declare foregoing particulars are true in every respect.


Policyholder Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:
22 FEB 2019

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Singapore 415933
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1812E
Vehicle Details	
Vehicle No.:	SME2346J
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4FGJU148986
Chassis No.:	KMHD841CMJU644978
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,641.00
Original Registration Date:	24 Sep 2018
First Registration Date:	24 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$11,641.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2028
PARF Rebate Amount:	\$8,730.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$36,077.00
Total Rebate Amount:	\$44,807.00

The information contained herein is correct as at 26 Mar 2019

OK

Dep 7,500/yr
625/mth

MV 78,000/2
PV 44,807/2
NV 33,123/2

luc
26/3/19

#Elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$76,800** **\$7,590 /yr** 13-Jul-2018 1,591 cc 9,500 km Sedan Available

Lowest Depreciation! Buy This Low Mileage Unit With A Peace Of Mind With Full Agent Warranty. The Perfect Fuel Efficient Model. High Loans Up To 80% With Lowest Interest Rates From 2.18%. Trade In Wel...

CONSIGNMENT

Posted: 01-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$80,800** **\$8,080 /yr** 18-Jun-2018 1,591 cc - Sedan Available

1 Owner, Low Mileage Done, Like New Interior, Agent Maintained.

DIRECT OWNER

Posted: 06-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$69,000** **\$6,980 /yr** 11-Apr-2018 1,591 cc - Sedan Available

Keyless Entry And Push/Start, Servicing Fully Maintained And Well Taken Care By Komoco Motors Since Day One, Accident-Free 5 Years Engine Unlimited Mileage With 5 Years Warranty Included Major Part Se...

350 VR Cars

Posted: 17-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Free Valuation by sgCarMart Quotz

Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.

Find out more!



Hyundai Elantra 1.6A GLS - N.A 11-Apr-2018 1,591 cc - Sedan SOLD

AA Trust Certified 01 Owner Vehicle! One Of The Sought After Sedan Car That Boast A Spacious Cabin Space And Generous Boot Space! Powered By CVVT Engine, The Elantra Will Response In The Way That Sati...

AA Trust Automotive

Posted: 10-Jan-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$68,800** **\$6,980 /yr** 31-Mar-2018 1,591 cc 36,000 km Sedan Available

Buy At The Best Depreciation! Still Under Agent Warranty. Well Maintained. The Perfect Family Car With Fuel Efficiency. Loan Available With Lowest Interest Rates From 2.18%, Trade In Welcome. Call Now...

CONSIGNMENT

Posted: 25-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$69,800** **\$7,220 /yr** 14-Mar-2018 1,591 cc 9,963 km Sedan Available

Superb Condition. Low Mileage. Like New. Agent Warranty And Maintained. Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And Trade In Are Available. Package With Unrivalled Warranty Comple...

Classic Credit Pte Ltd

Posted: 26-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$72,800** **\$7,540 /yr** 13-Feb-2018 1,591 cc 12,500 km Sedan Available

Superb Condition. Low Mileage. Like New. Agent Warranty And Maintained. 1 Lady Owner, Car Plate Not Included.

DIRECT OWNER

Posted: 21-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS - N.A 12-Feb-2018 1,591 cc - Sedan SOLD

1 Owner, Superb Condition. Like New. Agent Warranty And Maintained. Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled War...

TTS Eurocars

Posted: 11-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS **\$68,800** **\$7,220 /yr** 16-Jan-2018 1,591 cc 18,356 km Sedan Available

Accredited Company! Enjoy Exclusive 1.98% Interest Rate! Accident-Free, Low Mileage Done, Fully Maintained/Warranty By Agent, Well Maintained By 1 Only Meticulous Owner. High OMV And COEI Low Maintena...

Fu Ylap Motor Trading

Posted: 10-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS - N.A 16-Jan-2018 1,591 cc - Sedan SOLD

Nice Bidded Number (7887), Up To 90% In-House Loan And Balloon Scheme Available, No Gimmicks! 1 Owner, Keyless Entry/Start, Android Auto/Apple CarPlay, Bluetooth, Reverse Camera, Rear Aircon, White In...

Posted: 01-Jan-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

Compare

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	ACQ	Q
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: 5ME 2346J

NAC	INC	Item	CON	ACQ	Q
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	23 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEE MAY LIN, ID: S2599510D		
Main Claimant:	-		
Vehicle Reg. No.:	SME2346J	Date of Loss:	16/02/2019 00:00 - :59 [4 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1351381060SG	Policy/Cover Note No.:	1800011949 (Comprehensive)
Vehicle Reg. No. (Insured):	SDR1772G	Policy No. (Claimant):	
		Excess:	
Repairer:	Keng Seng Co (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-307, 569535 Ang Mo Kio - Tel: 64810336		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 07/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (27/02/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

***SME2346J (1351381060SG)**
[SDR1772G]
TP

Feb 16 2019 12:00AM
[LEE MAY LIN]
Keng Seng Co

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser ▾	
Photos/Images										3 per page ▾			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	02/04/19 09:46	General View									Load JPG		
2	02/04/19 09:46	General View									Load JPG		
3	02/04/19 09:46	General View									Load JPG		
4	02/04/19 09:46	General View									Load JPG		
5	02/04/19 09:46	General View									Load JPG		
6	02/04/19 09:46	General View									Load JPG		
7	02/04/19 09:46	General View									Load JPG		
8	02/04/19 09:46	General View									Load JPG		
9	02/04/19 09:46	General View									Load JPG		
10	02/04/19 09:47	General View									Load JPG		
11	02/04/19 09:47	General View									Load JPG		
12	02/04/19 09:47	General View									Load JPG		
13	02/04/19 09:47	General View									Load JPG		
14	02/04/19 09:47	General View									Load JPG		
15	02/04/19 09:47	General View									Load JPG		
16	02/04/19 09:47	General View									Load JPG		
17	02/04/19 09:47	General View									Load JPG		
18	02/04/19 09:47	General View									Load JPG		
19	02/04/19 09:47	General View									Load JPG		
20	02/04/19 09:47	General View									Load JPG		
21	02/04/19 09:47	General View									Load JPG		
22	02/04/19 09:47	General View									Load JPG		
23	02/04/19 09:47	General View									Load JPG		
24	02/04/19 09:47	General View									Load JPG		
25	02/04/19 09:47	General View									Load JPG		
26	02/04/19 09:47	General View									Load JPG		
27	02/04/19 09:47	General View									Load JPG		
28	02/04/19 09:47	General View									Load JPG		
29	02/04/19 09:47	General View									Load JPG		
30	02/04/19 09:47	General View									Load JPG		
31	02/04/19 09:47	General View									Load JPG		
32	02/04/19 09:47	General View									Load JPG		
33	02/04/19 09:47	General View									Load JPG		
34	02/04/19 09:47	General View									Load JPG		
35	02/04/19 09:47	General View									Load JPG		

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/04/19 09:47	General View	Load JPG	✓
37	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
38	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
39	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
40	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
41	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
42	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
43	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
44	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
45	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
46	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
47	02/04/19 09:47	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/02/19 09:05	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003620/BCD3S2
Date: 03/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800011949
Claimant Vehicle No : SME2346J Insured Vehicle No : SDR1772G
Date of Loss: 16/02/2019 Nature of Claim: TP Claim No: 1351381060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME2346J**
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGJU148986
Reg. Date: 24/09/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU644978
Colour: Blue Odometer: 4348 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Nexen 7 mm Rear Left Side: Nexen 7 mm
Front Right Side: Nexen 7 mm Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/02/2019
Date Inspected: 26/02/2019 Inspected At: BLK 9004 TAMPINES ST 93 #01-94
Estimated Period of Repair: 4.0 days Repairer: Keng Seng Co

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1		*REAR BUMPER BEAM	Dented	0.00 F	*- F
6	1		*REAR BUMPER REFLECTOR LH	Cracked	0.00 F	*- F
7	2		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >