

REF:

AIG

ASSIGNMENT

From:

Date: 26/2/19

Veh No: SME 2346 J Yr Regn: 24/9/2018

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SME 2346 J.

Make: HYUNDAI ELANTRA C.C. 1591C

at Workshop m/s

Colour: BLUE A/C: Insured / Std / NI / NA

of Blk 9004 Tampines St 93 #01-94

Sp. Reading: 4348 T/Radio: Insured / Std / NI / NA

Insured:

63377533

Eng/No: G4FGJU148986

Policy No.:

C/No: KMHD841CMJU644978

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or


After lunch.

Tyre Size: F: 195/65R15

(Policy Condition)

R: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

7

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

7

mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

16/2/19

D.O.I.

26/2/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

KENG SENG

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 3,000/2 - 4,000/2

MV 78,000/2

PV 44,807/2

NY 33,193/2

TGM Lin
26/3/19

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair: 4

1)

☐

Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee:

☐

Site Insp (\$)

S + RS. SI

Interview (\$)

Photos

Tech. Invs (\$)

Others

Weekend (\$)

Report Format: DAR.

Lump Sum / I.B.I: (\$)

TOTAL