

ASS. REC. BY:

REF:

CJ3/AIG1900362/Ecd/Bev

Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

26/2/19 @ 1:03pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 9305M

Insured:

SMH 2281 X

at Workshop m/s

Verve Motorworks

Tel:

91444476

of

25 lanki Bkt Rd 4 # 0332

Policy No:

1800151499

Claim No:

796285887486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/2/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:47pm @ 26/2/19

Person Contacted:

Kenneth

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate Insp: 1 lanki Bkt Ave 6 # 02-38

SJT 9305M - X

SMH 2281 X - X

After repair: 4/3/2019

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJT 9305M Yt Regn: 10/11/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer

CC: 1.5

Colour: Red

A/C Insured / Std / NI / NA

Sp. Reading: 210376

T/Radio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: JMYSRCK 2A 94 004553

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 17/2/19

D.O.I. 26/2/19

Survey held at H.S Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

MV - 15,900
PV - 12251
NV - 4749

RECEIVED 21 MAR 2019

Date/Time, File Pass to?

: Prol. Report

4)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 190

Transportation

) \$ + R. CI

) Photos

) Other

)

TOTAL

190
to
190

Report Format: DAR.

Lump Sum / I.B.I. (\$) _____

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/2/2019 1:03:39 PM
Attachments:  tmp18E7.tif

Hi LKK,

Kindly assist to survey after 1.30pm today, vehicle in Autobay, #02-38.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Nur Ardiilah Ramli [mailto:ardiilah@aplp.com.sg]
Sent: Tuesday, February 26, 2019 9:53 AM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Kaur, Baljit; Azlan, Syazairdina; Mithoosingh, Aashweenjeetkaur; Charles Hoon; Armelia Binte Abdul Wahab; Jean
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMH2281X AND SJT9305M ON 17/02/2019

Dear Yinrul,

Our client's vehicle can be inspected at:

Verve Motorworkz
25 Kaki Bukit Road 4
#03-32 Synergy@KB
Singapore 417800

Contact Person: Kenneth (91444476)

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Please note our new office address as of 1st March 2019.

**50 Chin Swee Road,
#07-01 Thong Chai Building, Singapore 169874**

Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899

Ardiilah
Secretary to Mr Charles Hoon

A P Law Practice
50 Chin Swee Road #07-01 Thong Chai Building, Singapore 169874
T: 6955 8899 F: 6900 9899 E: ardiilah@apl.com.sg
Singapore UEN No.: 53380739E

=====
This email transmission is confidential and intended only for the addresses(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.
=====

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7047Z
Vehicle Details	
Vehicle No.:	SJT9305M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	4A910124844
Chassis No.:	JMYSRCY2A9U004553
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,142.00
Original Registration Date:	10 Nov 2009
First Registration Date:	10 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$18,142.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Nov 2019
PARF Rebate Amount:	\$9,071.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,747.00
COE Rebate Amount:	\$1,180.00
Total Rebate Amount:	\$10,251.00

The information contained herein is correct as at 26 Feb 2019

OK

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

sgCARMART CONNECT
BRIDGING BUYERS & SELLERS

Mitsubishi Lancer Price Range Depreciation 2009 Vehicle Type

Advanced Search

Home » Used Cars » Direct Owners » Mitsubishi Lancer EX 1.5A GLS

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Engine Oil

FREE ENGINE OIL SERVICE PACKAGE WORTH \$98

Participating Brands:
YOKOHAMA ROADSTONE

Republic

Terms and conditions apply.

Mitsubishi Lancer EX 1.5A GLS

Overview Financial Insurance Accessories Similar Research Photos Map


DIRECT OWNER

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$15,800	?
Depreciation	\$10,110 /yr <small>View models with similar depreciation</small>	?
Reg Date	28-Oct-2009 <small>(8mths 1day COE left)</small>	
Manufactured	2009	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,499 cc	
Road Tax	\$684 /yr	?
Power	80.0 kW (107 bhp) <small>View specs of the Mitsubishi Lancer EX (2008-2017)</small>	?
Curb Weight	1,313 kg	?
Features	Powerful And Fuel Efficient 1.5L DOHC MIVEC Engine, Smooth 4 Speed Auto Trans, Dual SRS Airbags, Climatic Aircon, Auto Headlights, Keyless Entry/Start	
Accessories	Leather Seats, Upgraded Sports Rims, Factory Fitted Audio With Steering Controls, Solar Film, Fog Lights, Reverse Sensors.	
Description	Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper. All Wear And Tear Parts Are Newly Replaced. View And Test Drive To Believe. Call Or Message To Arrange For Viewing.	
COE	\$18,899	?
OMV	\$18,142	?
ARF	\$18,142	?
Dereg Value	\$10,329 as of today (change)	?
No. of Owners	4	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist Add to Compare Add a Note



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Seller Information

Contact Person(s) Qayyum / Harry
Contact No. 94231074 / 97322324
Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer

GET HELP WITH PAPERWORK

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments**

Compare

MSME19023287 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME 19/02/2019 15:35
 SUBMITTED BY: Chia Pei Ying

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 19/02/2019 15:43

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2019 15:36
Date Of Accident	17/02/2019 23:20
Exact Location Of Accident	MALAYSIA CUSTOM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT9305M
Insured/Policyholder	
Name Of Registered Owner	JARON RANZ
NRIC No	S7917047Z
Email Address	JARONRANZ92@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91595951
Alternative Phone No	OFFICE+91595951
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER EX
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MA003108
Cover Note Number	
Driver	
Name of Driver	FU KEE MIN
NRIC No	G7106820Q
Date Of Birth	17/02/1977
Occupation	INDOOR
Date Of Driving Pass	15/11/2018
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92 190132
Fax Number	
Contact Number	
Email Address	NOEMAIL

Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

VEHICLE B
PRIVATE CAR
TAN JUN WEI
S8710595D


Sketch Plan #2 Pg. 1

Circumstances of the Accident
 MUST STATIONARY IN MY LANE AT THE MALDENIA CUSTOM, SUDDENLY VEH 'B' SML7281X
 ENCRDGED INTO MY LANE AND COLLIDED ONTO MY RIGHT HAND REAR PORTION.

Declaration

We declare the foregoing particulars are true in every respect


 Policyholder's Signature / Date & Time


 Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Handwritten notes and stamps in a box:
 07/02/19
 12:05:00
 12:05:00

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

(1) Replace (✓) (2) Repair (S) (3) Check (C)
 (4) Not Consistent (NC)

FORM 2003

Right Portion

Vehicle No:

SJT 9395 M

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	SCR	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1013	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door		R	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1371	994070	Roof Top Panel			
1372	994098	Roof Top Moulding			
1373	994085	Roof Top Air-bag			
1374	994084	Roof Top Air-bag Sensor			
1375	994083	Roof Top Air-bag Control Unit			
1111	992958	Rear Bumper	SCR	R	
1117	992976	Rear Bumper Bracket			
1143	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	SCR	R	
1229	993450	Rear RH Fender Protector			
1166	990247	Sticker			

No of Items:

Assessor:

RH Runny door garnish R
 Rear RH Rim CUT ✓
 Rear RH Absorb ?
 Rear RH lower arm ?
 Rear RH Knuckle arm ?
 Rear RH knuckle arm bearing ?

Rear RH fender

[Signature]
 20/3/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TANG HUI LING , ID: S8775098A		
Main Claimant:	JARON RANZ , ID: S7917047Z		
Vehicle Reg. No.:	SJT9305M	Date of Loss:	17/02/2019 23:00 - :59 [111 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7962858874SG	Policy/Cover Note No.:	1800151499 (Comprehensive)
Vehicle Reg. No. (Insured):	SMH2281X	Policy No. (Claimant):	
		Excess:	
Repairer:	Verve Motorworkz Pte. Ltd (HQ) 25 Kaki Bukit Road 4, #03-32/39 Synergy@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 07/03/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (27/02/2019): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT9305M (7962858874SG)
[SMH2281X]
TP
JARON RANZ
Feb 17 2019 11:00PM
[TANG HUI LING]
Verve Motorworkz Pte. Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
2	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
3	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
4	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
5	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
6	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
7	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
8	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
9	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
10	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
11	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
12	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
13	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
14	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
15	27/02/19 09:06	General View	<input checked="" type="checkbox"/>
16	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
17	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
18	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
19	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
20	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
21	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
22	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
23	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
24	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
25	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
26	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
27	27/02/19 09:07	General View	<input checked="" type="checkbox"/>
28	27/02/19 09:07	Odometer Reading	<input checked="" type="checkbox"/>
29	27/02/19 09:07	Chassis Number	<input checked="" type="checkbox"/>
30	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
31	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
32	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
33	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
34	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
35	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
36	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>
37	20/03/19 18:21	Photo After Spray	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	20/03/19 18:21	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/02/19 12:53	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003621/ECD3E2
Date: 22/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800151499
Claimant Vehicle No : SJT9305M	Insured Vehicle No :	SMH2281X
Date of Loss: 17/02/2019	Nature of Claim:	TP
		Claim No: 7962858874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9305M		
Make & Model:	MITSUBISHI LANCER EX, 1.5 (A)	Engine No:	4A910124844
Reg. Date:	10/11/2009 (Man. Year: 2009)	Chassis No:	JMYSRCY2A9U004553
Colour:	Red	Odometer:	210376 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/02/2019	
Date Inspected:	26/02/2019	Inspected At:
		Verve Motorworkz Pte. Ltd (HQ) 25 Kaki Bukit Road 4, #03-32/39 Synergy@KB Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*REAR RH DOOR	Repair	0.00 F	*- F
3	1		*REAR BUMPER	Repair	0.00 F	*- F
4	1		*REAR RH FENDER	Repair	0.00 F	*- F
5	1		*RH RUNNLY BOARD GARNISH	Repair	0.00 F	*- F
6	1		*REAR RH RIM	Cut	0.00 F	*- F
7	1		*REAR RH ABSORBER	* Check	0.00 F	*- F
8	1		*REAR RH LOWER ARM	* Check	0.00 F	*- F
9	1		*REAR RH KNUCKLE ARM	* Check	0.00 F	*- F
10	1		*REAR RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
11	1		*REAR RH FENDER	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >