

ASS. REC. BY

REF CS/FCI 19003627/KISD307 Special Instruction

Sub Veyor

CWS

RASU

ASSIGNMENT (Office)

From (Person)

Karen Tan

of

FCI

Date/Time

5:13pm @ 25/2/19

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

8MF 411SR

Insured:

SHC 3206T

at Workshop m/s

Tan chong Motpr

Tel:

67038914

of

913 Bkt timah Rd

Policy No:

Claim No:

D19001224MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/2/19

CA / REV / REP. / REV 24 HRS

(OS)

12/3/2019.

H.O.D. Endorsement:

Date/Time:

11:00am @ 26/2/19

Person Contacted:

Vehicle IN/OUT

(OUT)

Date/Time

Action/Instruction (✓) Estimate

call back 27/2/19

8MF 411SR-X

SHC 3206T-CS/FCI 16003112/Uqbd1

DoA. 17/2/16

14/03/19

@ 16:07 p.m. revised PA to Karen Tan via email.

Psm

FCI

9047F

12/3/2019

SMF 4115R 2018 NOV

Vehicle Type: ☒ Car / ☐ Motorcycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: NISSAN SYLPHY 1.6 CVT 1598

Colour: BROWN A/P: Insured / Std / Nil / NA

Sp. Reading: 6165 U/Cade: Insured / Std / Nil / NA

Eng/No: MNTBBAB1720033400

Gen. Cond: Good ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Normal / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Normal / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ R/B / ☐ STD A/Rim or

Tyre Size: F: 155/60R16  
R:

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front	Rear
R/Bal: 6 mm	R/Bal: 6 mm
L/Bal: 6 mm	L/Bal: 6 mm
D.O.A: 18/02/19	D.O.A: 12/03/19

Survey held at: TAN CHONG

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Roof/Top or  
FR O/S

The U/C / Chassis frame / Body Structure affected due to collision

1. Damaged Area: 01 P/W/S / 11 P/S / 10 P/S / EVA / HV / MV

Vehicle No: SMF4115R

At Work: Report: Tan Chong  
at 913 Bukit Timah Rd

In used

Policy No:

Claim No:

Sum Insured

(Client's Record)

Make of Veh:

12/3/2019 After 10am.  
(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / P/P: Consistent? Yes or No

Est. Repair: 3 days Res: Yes or No

Est. Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN/OUT

Date / Time: Action / Instruction

18/04/19 Confirmed P/P \$ 689.92 @ 3 days with Resu 1  
( \$ 1,086.92 Red- 61% )

RECEIVED 1 8 APR 2019

18/04/19  
Type: ☐ Preli. Report  
☒ Final Report

Date/Time: File Return to:

Report Format

Lump Sum / U/C: 689.92 P/P

Days Of Repair: 3  
Resurvey No. of Trip:

Add Fee: ☐ Site Insp. ☐ ☐ Interpage ☐ ☐ Loan fee ☐ ☐ Workshop ☐

Survey Fee:  
Transportation  
F. 100  
F. 50  
F. 16  
F. 166

100
50
16
166

**MOTOR SURVEY ASSIGNMENT**

Date	19-02-2019	Our Ref No. D19001224MFSH
Accident Date	18-02-2019	Claim Type. Third Party
Insured Vehicle	SHC3206T	Third Party Vehicle. SMF4115R
Survey Location	913 BUKIT TIMAH ROAD	
Contact Person.	LAWRENCE TEO	
Contact No.	64694091/ 0	Fax No. 64697472
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	TAN CHONG MOTOR SALES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 18 April 2019 10:25 AM  
**To:** 'Norsipah'  
**Cc:** Admin A; Asher Sng (LKKAuto); Mei Kwan (LKKAuto); SUR; Rasul (LKKAuto)  
**Subject:** RE: COR Final SMF4115R doa 18.02.2019

Dear Norsipah,

Confirmed final fig \$689.92 @ 3 day of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Norsipah [mailto:norsipah@tanchong.com]  
**Sent:** Monday, 15 April 2019 9:55 AM  
**To:** Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Subject:** COR Final SMF4115R doa 18.02.2019

Hi

Attach for your finalization.

Thank you.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589623

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 14 March 2019 4:07 PM  
**To:** 'Karen Tan'; 'CWS Motor Claims'  
**Cc:** assignments; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19001224MFSH/1  
**Attachments:** SMF 4115R - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SMF 4115R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 26 February 2019 4:58 PM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19001224MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Monday, 25 February 2019 5:13 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001224MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001224MFSH

Date: 14 March 2019

Our Ref: CS/FCI19003627/R1sd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SMF 4115R .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/03/2019 at the premises of M/s Tan Chong Motor Sales Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,776.84</u> .
Revised Estimate Amount	: S\$ <u>689.92</u> .
"Check" Items Amount	: S\$ <u>25.36</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the front o/s portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 3 Days

Yours faithfully,  
Mohammed Rasul  
Automotive Assessor

S/C  
DS

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 13:17
Date Of Accident	18/02/2019 07:55
Exact Location Of Accident	ASIA SQ DRIVE WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMF4115R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM XIANG YU (LIN XIANGYU)
NRIC No	S7519047F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97424312
Alternative Phone No	OFFICE-97424312

<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	SYLPHY-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800133518
Cover Note Number	

<b>Driver</b>	
Name of Driver	LEW TZE CHONG (LIU ZHIZHONG)
NRIC No	S7228990J
Date Of Birth	20/08/1972
Occupation	INDOOR
Date Of Driving Pass	30/08/1990
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98556174
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	11 TAMPINES ST 86 #14-31
Postcode	528588
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	COVERED DRIVEWAY
Road Surface	COVERED DRIVEWAY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM XIANG YU (LIN XIANGYU) GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3206T <i>(First Capital)</i>
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	NG KOK HENG
NRIC/Passport Number	S1003003Z
Contact Number	83551533
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

Vehicle No: SMF 4115R

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My Vehicle No (A): SMF4115R

Accident Location: <u>Asia Sq Drive Way</u>			
Accident Date: <u>18 Feb 2019</u>		Time: <u>07:56</u> am/pm	
- Brief Details Of Accident -			
<p>On 18 Feb 2019 @ 07:56am I was driving along the Drive Way of Asia Sq. As I was driving straight I notice a Taxi entering the drive way. When I notice the driver have no intention of stopping at the stop line I apply E-brake while the vehicle (SHL3206T) continue to drive forward and hit my Right Front of vehicle.</p> <p>I have car cam and photos. And the driver particulars as follow</p> <p>SHL3206T</p> <p>Ng Kok Heng</p> <p>S1003003Z</p> <p>Phone: 83551533</p>			
- Other Vehicle Involve Details -			
(B)	Veh No: <u>SHL3206T</u>	Hp: <u>83551533</u>	Pax: <u>Driver Name: Ng Kok Heng</u>
(C)	Veh No:	Hp:	Pax: <u>Driver Name:</u>

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

18 Feb 2019

To Whom It May Concern

Dear Sir/Madam,

**Re: Authorization Letter for Auto Insurance Claim**

I hereby authorize Mr. Lew Tze Chong of NRIC No:S7228990J to handle my Auto Insurance Claim under Vehicle No: SMF4115R.

Kindly liaise with him on all claim-related matters relating to the above.

Thank you.

Yours sincerely,



LIM XIANG YU

S7519047F

4811618



NRIC No. S7519047F



Date of issue  
07-12-2012

11 TAMPINES STREET 86 #14-31  
SINGAPORE 528588


NRIC No: S7519047F Date: 24/11/2016

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)



	EFFECTIVE DATE
Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =<2500kg	26 Nov 1998

NP 428A

Licence No: S7519047F



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7519047F



Name  
LIM XIANG YU  
(LIN XIANGYU)  
林香玉

Race  
CHINESE


Date of birth Sex  
03-07-1975 F

Country of birth  
SINGAPORE

S7519047F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7519047F




Name  
LIM XIANG YU  
(LIN XIANGYU)

Birth Date: 03 Jul 1975

Issue Date: 07 Sep 2013

00222 1544C



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Form Number **S7228990J**

**LEW TZE CHONG**  
(LIU ZHIZHONG)

Birth Date: **20 Aug 1972**  
Expiry Date: **14 Jul 2003**

1000654303J

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. **S7228990J**

Name: **LEW TZE CHONG**  
(LIU ZHIZHONG)  
**柳志忠**

Race: **CHINESE**  
Date of Birth: **20-08-1972** Sex: **M**  
Country of Birth: **SINGAPORE**

37228990J

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:**

Class 2B Motorcycles not exceeding 200 cc  
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

25 Apr 1994  
30 Aug 1990

NP 428A

Licence No: **S7228990J**

2218090

NRIC No. **S7228990J**

Blood Group: **A+** Date of issue: **11-07-1994**

**11 TAMPINES STREET 86 #14-31**  
**SINGAPORE 528588**  
NRIC No: **S7228990J** Date: **24/11/2016**





# CERTIFICATE OF INSURANCE

## NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Xiang Yu (Lin xiangyu)  
Period of Insurance : 09 Nov 2018 To 08 Nov 2019  
Engine No. : HR16933995C  
Chassis No. : MNTBBAB17Z0033400

Vehicle No. : SMF4115R  
Policy No. : 1800133518  
Endorsement No. :  
Issued Date : 23 Nov 2018

### ABOUT THE COVER

Make/Model : NISSAN SYLPHY 1.6 PREMIUM  
Engine Capacity/Tonnage : 1,598.00 CC Sum Insured : Market Value First Year of Registration : 2018  
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes  
Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Xiang Yu (Lin xiangyu) - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No.1, Sixth Lok Yang Road Singapore 628099 62622212
2. Autolotion Industrial Add: 19 Ubi Road 4 Singapore 408623 64909666
3. TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 67038511 67038512 67038513
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 589623 64694091 64694092 64694093
5. Tan Chong Motor Sales Add: 17 Lorong 8 Toa Payoh Singapore 319254 63570753 63570754

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500610527

TAN CHONG CREDIT PTE LTD - LTB  
911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE  
SINGAPORE 589622 ANSP-MOTOR  
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSCNF



TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

17 Jan  
22/02/19.

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0109/2019  
DATE : 22-FEB-2019

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848  
FAX :  
ATTN:MOTOR CLAIM DEPT

### DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

OWNER'S NAME : MDM LIM XIANG YU (LIN XIANGYU)  
ADDRESS : 11 TAMPINES STREET 86  
#14-31  
S(528588)  
TELEPHONE NO : 98556174

100%

LKIC

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-SHC3206T  
VEHICLE NO : SMF4115R  
MODEL CODE : BDTARCZB17EWA----K19  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019  
ENGINE NO : HR16933995C  
CHASSIS NO : MNTBBAB17Z0033400  
MILEAGE : 1 KM  
DATE IN : 22/02/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 18/02/2019

LOU / Lawrence

12/03/19

Lawrence  
9-00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF4115R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	ZZ/001	REPAIR AND RENEW FRONT BUMPER	<del>700.00</del>	390
3	ZZ/002	S/PAINT FRONT BUMPER	<del>400.00</del>	250
TOTAL LABOUR CHARGES			1148.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF4115R

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	GROMMET BUMPER \$1.30-EA X 02 <i>Neu</i>	01281-01431	2.40	<i>✓</i>
2	SUNDRIES <i>X</i>	NPN		100.00 <i>X 19</i>
3	BRKT FR BUMPER RH <i>?</i>	62224-3SN5A	5.80	<i>? X su</i>
4	FINISHER FRT BUMPER RH FOG LAMP <i>? 7.80</i>	62256-3SN5A	25.90	<i>? X su</i>
5	RH FOG LAMP <i>X</i>	26150-8995A-VL0		75.00 <i>X su</i>
6	FASCIA FR BUMPER <i>repair</i>	62022-3SN5H	533.20	<i>Repair</i>
SUB TOTAL			567.30	0.00 175.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			113.46	0.00 0.00
GRAND TOTAL			453.84	0.00 175.00
OVERALL TOTAL			628.84	

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF4115R

TOTAL LABOUR CHARGES	1148.00
TOTAL SPARE PARTS CHARGES	628.84
GRAND TOTAL	1776.84 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	12/09/19 @ 1210
AUTHORIZED DATE	:	3 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Ready after repair

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0109/2019  
DATE : 22-FEB-2019

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848  
FAX :  
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MDM LIM XIANG YU (LIN XIANGYU)  
ADDRESS : 11 TAMPINES STREET 86  
#14-31  
S(528588)  
TELEPHONE NO : 98556174

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-SHC3206T  
VEHICLE NO : SMF4115R  
MODEL CODE : BDTARCZB17EWA----K19  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019  
ENGINE NO : HR16933995C  
CHASSIS NO : MNTBBAB1720033400  
MILEAGE : 6165 KM  
DATE IN : 22/02/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 18/02/2019

RASU

A

LICK

D/S

LOW \$50 x 51

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMP4115R

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2 ZZ/001	REPAIR AND RENEW FRONT BUMPER	700.00	390.00
3 ZZ/002	S/PAINT FRONT BUMPER	400.00	250.00
TOTAL LABOUR CHARGES		1148.00	688.00

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF4115R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 GROMMET BUMPER \$1.30 EA X 02	01281-01431	2.40			OK
2 SUNDRIES	NPN			100.00	X
3 BRKT FR BUMPER RH	62224-3SN5A	5.80			X
4 FINISHER FRT BUMPER RH FOG LAMP	62256-3SN5A	25.90			X
5 RH FOG LAMP	26150-8995A-VL0			75.00	X
6 FASCIA FR BUMPER	62022-3SN5H	533.20			X
SUB TOTAL		2.40	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		0.48	0.00	0.00	
GRAND TOTAL		1.92	0.00	0.00	
OVERALL TOTAL		1.92			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMF4115R

---

NETT ITEM	2.40
LESS 20.00%)	-0.48
NETT AMOUNT	1.92

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00

TOTAL LABOUR CHARGES	688.00
TOTAL SPARE PARTS CHARGES	1.92

TOTAL CHARGES	689.92
ADD 7 % GST	48.29

GRAND TOTAL	738.21
-------------	--------

---





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003627/R1sd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-04-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 3206T	Veh. Inspected	SMF 4115R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001224MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	25/02/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN SYLPHY 1.6 CVT	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MNTBBAB17Z0033400	Colour	BROWN	
Odometer	6165	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	18/02/2019	Inspection Date	12/03/2019	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913 BUKIT TIMAH ROAD SINGAPORE 589623			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 4115R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	GROMMET BUMPER (N)	NECESSARY	2.40	2.40
1	BRKT FR BUMPER RH (N)	SERVICEABLE	5.80	-
1	FINISHER FRT BUMPER RH FOG LAMP (N)	SERVICEABLE	25.90	-
1	FASCIA FR BUMPER (N)	TO REPAIR SEE LABOUR	533.20	-
	LESS 20% DISCOUNT		-113.46	-0.48
			453.84	1.92
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	RH FOG LAMP (SN)	SERVICEABLE	75.00	-
			175.00	-
	<b><u>LABOUR</u></b>			
	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	REPAIR AND RENEW FRONT BUMPER. INCLUSIVE OF THE REPAIR OF FASCIA FR BUMPER.		700.00	390.00
	S/PAINT FRONT BUMPER.		400.00	250.00
			1,148.00	688.00
	<b>GRAND TOTAL</b>		<b>1,776.84</b>	<b>689.92</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>689.92</b>

Report Ref No. CS/FCI19003627/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.