

2/29/2019

ASS. REC. BY:

REF: CS/MSG/19003636/Kqd3/n2

Special Instruction:

SMV (v/v)

Meimien

ASSIGNMENT (Office)

From (Person):

Pauline Tham

of

MS16

Date/Time:

27/2/19 @ 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTC3

To Inspect Vehicle No:

81J 5526Y

Insured:

SMF 9262

at Workshop n/s:

Massive Trading

Tel:

91082728

of

Blk 5038 #01-405 Amk Ind. Park 2

Policy No:

MSD/vpcp/18-000001

Claim No:

586226

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2019

CA / REV / REP. / REV 24 HRS

hp

01/03/19

H.O.D. Endorsement

Date/Time:

28/2/19 @ 9:26am

Person Contacted:

Anthony

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (✓) Estimate

11/3/19 @ 4:13pm revised to pauline tham via meimien.

13/3 L18m 82200d Confirmed (Red 4 2567-60, 54%)

REF MS16

01103/19

SLJ 5526X

12 16

Date: 01103/19  
 Insurance: 01103/19  
 Type: M/Cat / 14 Cycle / Bus / Van / Ferry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: SLJ 5526X  
 Colour: Massive Trading  
 Sp. Reading: BIK 6038 # 01-405 Amk Ind-park 2  
 Eng/Ho:  
 C/Ho:  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD / R/Rim or  
 Type Size: F: Lead 185/65R15  
 R: Dun

14PF  
 Insured / Std / HI / NA  
 1019PF  
 14PF  
 MR14DD 4870G P000349  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD / R/Rim or  
 Type Size: F: Lead 185/65R15  
 R: Dun

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bat. or Market Value:  
 WAC: Accident Report: Consistent? Yes or No  
 GLA / FR: Seen: Consistent? Yes or No  
 Est. Reports: 04 days: Res: Yes or No  
 Lun Sum: 20 %: 3 Val: Yes or No  
 CA / REV / REP: 24 HRS up

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front: 9 mm  
 R/Bat: 2 mm  
 L/Bat: 2 mm  
 D.O.A: 27/12/19  
 D.O.I: 11/3/19  
 Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooltop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

1/3 Will email GLA & EST over.

RECEIVED 20 MAR 2019

Date/Time: File Pass to: ☐ : Profi. Report  
 1/3/19 ☐ : Final Report  
 Date/Time: File Return to:

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Survey Fee:  
 Transportation:

Add Fee: ☐ Site Insp: \$  
☐ Interview: \$  
☐ Tech. fees: \$  
☐ Weekend: \$

Report Format: Max-T  
 Lump Sum / 11/11/19: 200

150  
 10  
 160

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 11 Mar 2019

**Preliminary Advice**

Insured Vehicle No	: SME926Z	Accident Date	: 27/02/2019
TP Vehicle No	: SLJ5526Y	Assignment Date	: 27/02/2019
Make	: HONDA MOBILIO SV 1.5 CVT	Est. Duration of Repair	: 0.00
Date of Inspection	: 01/03/2019		
Inspection At	: MASSIVE TRADING & AUTO BLK 5038 #01-405, ANG MO KIO INDUSTRIAL PK 2 SINGAPORE 569541		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,767.60
Revised Amount	:S\$	2,616.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,616.92

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2019		27 Feb 2019 16:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BlueCar East Asia Pte Ltd, Co. Reg. No.: 201617259H		
Main Claimant:	TANES UBER, Co. Reg. No.: 53367547B		
Vehicle Reg. No.:	SLJ5526Y	Date of Loss:	27/02/2019 07:00 - :59 [5 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 586226	Policy/Cover Note No.:	MSD/VPCP/18-000001 Coverage: 01/01/2019 - 31/12/2019
Vehicle Reg. No. (Insured):	SME926Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/02/2019]		
Driver/Custodian (Insured):	LIM ZHONG YAN (), NRIC: S8803360D Email:		
Adj Asg. Remarks:	on WP. OI non reporting. Liability unclear. TP agree SJE - Assign LKK Auto Consultants Pte Ltd Contact - 9108 2728 Anthony		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	7547B
<b>Vehicle Details</b>	
Vehicle No.:	SLJ5526Y
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15Z12874017
Chassis No.:	MRHDD4870GP000349
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,980.00
Original Registration Date:	15 Dec 2016
First Registration Date:	15 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$18,980.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2026
PARF Rebate Amount:	\$14,235.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$39,528.00
<b>Total Rebate Amount:</b>	<b>\$53,763.00</b>

The information contained herein is correct as at 11 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2019 10:02
Date Of Accident	27/02/2019 07:15
Exact Location Of Accident	CTE TWDS AYE AFTER YCK EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ5526Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TANES UBER
Co Reg No	53367547B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93863029
Alternative Phone No	OFFICE-93863029

### Vehicle Particulars

Manufacturer	HONDA
Model	MOBILIO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093227434-01
Cover Note Number	

### Driver

Name of Driver	TAN ENG SING (CHEN YONGSHENG)
NRIC No	S7140020D
Date Of Birth	04/11/1971
Occupation	OUTDOOR
Date Of Driving Pass	22/04/1992
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93863029
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	47 EDGEFIELD PLAINS #02-14
Postcode	828713
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WILLIAM GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT WORKSHOP
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME926Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM ZHONG YAN
NRIC/Passport Number	S8803360D
Contact Number	98412854
Address	
Postcode	
Insurance Company Name	



Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

GBF3L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

HOR CHONG WENG

NRIC/Passport Number

S2694813D

Contact Number

90922555

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


TANES UBER

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/2/2019 @ ord 07:5hrs, I was travelling along CTE towards AYE. Due to heavy traffic, I slowed down my vehicle and eventually came to a stopped. Suddenly I felt an impact from the rear of my vehicle. I got out of my vehicle and realised it was a collision of 3 vehicles.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**TANES UBER**

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

*11/3/19*

Fax : 64816131

Tanes Uber  
47 Edgefield Plains  
#02-14  
Singapore 828713

*Not with work  
11/12/18 @ 2050h 2200h  
Reboring After Paint*

Vehicle No : SLJ 5526 Y  
Make : Honda Mobilio  
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy	✓ 1125.00
1 pc	Rear tail-gate glass moulding	✓
1 pc	Rear tail-gate emblem " Mobilio "	✓
1 pc	Rear tail-gate emblem " i-Vtec "	✓
1 pc	Rear tail-gate emblem " RS "	✓
1 pc	Rear tail-gate inner lock	✓
1 pc	✗ Rear end panel	✓
1 pc	✗ Rear end panel inner garnish	7. 463.70
1 pc	Rear bumper	✓
1 pc	Rear bumper chrome moulding	✓ 112.80
1 pc	✗ Rear bumper beam	✓
2 pcs	✗ Rear bumper reflector	

Ry	\$1,255.70	✓
Mr	\$85.20	✓
Mr	\$48.10	✓
Mr	\$35.70	✓
Mr	\$26.90	✓
Mr	\$205.70	✓
Mr	\$455.60	✗
Mr	\$135.70	✗
Mr	\$493.70	✓
Mr	\$152.30	✓
Mr	\$167.20	✗
\$55.10	\$110.20	✗
	\$3,172.00	
Less 20 %	\$634.40	
	\$2,537.60	

## S. Nett Item

1 pc	Rear reverse sensor	✓
1 pc	Rear tail-gate glass selant	✓
15 pcs	Bumper clip	✓

Se	\$200.00	✗
Mr	\$40.00	✓
\$2.00	\$30.00	✓
	\$270.00	

## Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 *400h*

To putty & spray paint on accident affected portion.

\$800.00 *450h*

Check/reconnect wiring.

\$40.00 *15h*

balance c/f \$4,447.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLJ 5526 J

balance b/f      \$4,447.60

Labour Charges

To spray anti rust on accident affected portion.

\$120.00 *30%*

Remove/refit rear tail-gate glass

\$100.00 ✓

Remove/refit rear tail-gate mechanism to new door

\$100.00 *60%*

Total

\$100.00  
\$4,767.60

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003636/KQD3N2

Date: 25/03/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000001

Claimant Vehicle No: SLJ5526Y Insured Vehicle No: SME926Z

Date of Loss: 27/02/2019 Nature of Claim: TP Claim No: 586226

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLJ5526Y

Make & Model: HONDA MOBILIO SV, 1.5 CVT (A) Engine No: L15Z12874017

Reg. Date: 15/12/2016 (Man. Year: 2016) Chassis No: MRHDD4870GP000349

Colour: Metallic Grey Odometer: 101997 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Lead 9 mm Rear Left Side: Dunlop 2 mm

Front Right Side: Lead 9 mm Rear Right Side: Dunlop 2 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,807.60	1,752.48	1,055.12	37.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,055.00	905.00	46.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,767.60	2,807.48	1,960.12	41.11
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	4,767.60	2,200.00	2,567.60	53.86

## INSPECTION

Date of Assignment: 27/02/2019

Date Inspected: 01/03/2019 Inspected At: Massive Trading & Auto  
Blk 5038 #01-405, Ang Mo Kio Industrial  
Pk 2  
Singapore 569541

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2019)
<b>Parts:</b>	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLJ5526Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,255.70 FL	*1,125.00 FL
2	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	85.20 FL	*85.20 FL
3	1		*REAR TAIL-GATE EMBLEM MOBILIO	Necessary	48.10 FL	*48.10 FL
4	1		*REAR TAIL-GATE EMBLEM I-VTEC	Necessary	35.70 FL	*35.70 FL
5	1		*REAR TAIL-GATE EMBLEM RS	Necessary	26.90 FL	*26.90 FL
6	1		*REAR TAIL-GATE INNER LOCK	Distorted	205.70 FL	*205.70 FL
7	1		*REAR END PANEL	Repair	455.60 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Serviceable	135.70 FL	*- FL
9	1		*REAR BUMPER	Buckled	493.70 FL	*463.70 FL
10	1		*REAR BUMPER CHROME MOULDING	Dented	152.30 FL	*112.80 FL
11	1		*REAR BUMPER BEAM	Repair	167.20 FL	*- FL
12	2		*REAR BUMPER REFLECTOR	Serviceable	110.20 FL	*- FL
13	1		*REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
14	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
15	15		*BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
					<b>Sub Total (S\$)</b>	<b>3,442.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>634.40</b>
					<b>Total Parts (S\$)</b>	<b>2,807.60</b>
						<b>1,752.48</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	800.00	450.00
3	CHECK/RECONNECT WIRING	New	40.00	15.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	120.00	30.00
5	REMOVE/REFIT REAR TAIL-GATE GLASS	New	100.00	100.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,960.00</b>	<b>1,055.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >