

REF: CSI/ALG19003650/R9d302

Special Instruction:

From (Person): Lee Ming Yao of AIG Date/Time: 20/2/19 @ 1:04pm
Estimated Cost: _____ Bill to: _____

lump sum \$6507.

Third Parties:

Claimant:

Surveyor:

Workshop: Ann Jod

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBC 24464 Insured: 8KX 25305

at Workshop m/s Ann Joo Motor Tel: 6451 0747

of Blk 176 Sin Ming Drive # 02-17

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/11/2018
(Client's Record)

(Client's Record) _____ D.O.A. _____
28/02/2019 @ 1pm

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted; _____ Vehicle IN / OUT _____

Date/Time: 5/4/2019 Confirmed with [Signature] Final Fig days (Red \$ / %; Original days)

Date/Time: 5/14/2019 Submit Final Fig 2000 - 4 days (Red \$ 4500 / 69 %; Original 7 days)

Date/Time	Action/Instruction
	QBC 2416U-X SKX25903-C03/AIG/802/453/G1d3

Para(1) : Parts found not replaced	(To highlight R or UB, LR, Etc)
------------------------------------	---------------------------------

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
---	--

RECEIVED 05 APR 2019

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

200

200

1) Date/Time _____ File Pass to _____

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBC2446U		
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	DYNA 150 MANUAL 3SEATER		
Chassis No. :	JTFAT35Y20K201647		
Propellant :	Diesel		
Engine No. :	1KD2114190		
Engine Capacity :	2982 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3500 kg		
Unladen Weight :	1660 kg		
Year Of Manufacture :	2011		
Original Registration Date :	21 Sep 2011		
Lifespan Expiry Date :	20 Sep 2031		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$32,289.00		
COE Expiry Date :	20 Sep 2021		
Road Tax Expiry Date :	20 Sep 2019		
Inspection Due Date :	20 Sep 2019		
Intended Transfer Date :	04 Apr 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Wednesday, 20 February 2019 1:09 PM
To: Lee, Ming-Yao; assignments
Cc: SUR; Admin A
Subject: RE: - Request for Re-inspection for TPV GBC2446U DOA 24/11/2018
Attachments: TP GIA REPORT.PDF; OI GIA REPORT.PDF; TP Survey Report - 3051171702SG-003.pdf; 8115249380SG-003 - PRS.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

By copy to assignment team.

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee, Ming-Yao
Sent: Wed, 20 Feb 2019 04:02:05 +0000
To: 'SUR', Admin A
Cc:
Subject: - Request for Re-inspection for TPV GBC2446U DOA 24/11/2018

Hi Team,

Subject matter refers.

Please refer to attached email from TP Lawyer with RI details. Please arrange for re-inspection on third party vehicle.

Also attached survey docs for your kind reference.

Appreciate if you could acknowledge receipt of this email and to liaise with third party directly for the arrangement.

Regards,

George Lee
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16 Singapore 079120
Tel +(65) 6419 1769

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more.](#)

Follow us:

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: florencekohef@yahoo.com.sg
To: MingYao.Lee@aig.com
Subject: Our Ref : 8115249380SG-003 | Your Ref : CKK/ck/ACC/10426/18 | Accident Involving SKX2530S & GBC2446U on 24/11/2018
Date: Tue, 19 Feb 2019 08:57:51 +0000

Dear George

We refer to your email dated 18th February 2019.

Kindly arrange for your surveyor to reinspect our client's vehicle on the following date and time:-

Date: 28th February 2019 (Thursday)

Time: 1.00pm

Place: Ann Joo Motor Pte Ltd

Blk 176 Sin Ming Drive #02-17 Sin Ming Autocare S575721

Kindly confirm the reinspection date and time urgently.

Regards

Florence

K K CHENG & CO

Tel: 6227 1272

Fax: 6227 5563

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Wednesday, 20 February, 2019 12:02 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: - Request for Re-inspection for TPV GBC2446U DOA 24/11/2018



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-02-26 22:02 CST to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

GBC2446U [5KX253051 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)]



1/25: Front View



2/25: Front View Left



3/25: Front View Right



4/25: Chassis Number


GBC2446U [5KX25305] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



5/25: Odometer Reading



6/25: General View



7/25: General View



8/25: General View

GBC2446U [SKX2630S] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



9/25: General View



10/25: General View



11/25: General View



12/25: General View

GBC2446U [SKX25305] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/25: General View



14/25: General View




15/25: General View



16/25: General View

GBC2446U [9KX2530S1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



17/25: General View



18/25: General View



19/25: General View



20/25: General View

GBC2446U (SKX28305) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



21/25: General View



22/25: General View



23/25: General View



24/25: General View

GBC2446U (SKX25305) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/25: General View

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2018 11:45
Date Of Accident	24/11/2018 09:45
Exact Location Of Accident	KAMPUNG JAVA ROAD TURNING TO BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2446J
Insured/Policyholder	
Name Of Registered Owner	POH KHOON ELECTRICAL PTE LTD
Co Reg No	201404550Z
Email Address	SALES@POHKHOON.COM
Mobile Phone No	(LOCAL) +65-90250094
Alternative Phone No	Office-69090141

Vehicle Particulars

Manufacturer	TOYOTA
Model	UNKNOWN
Exact Purpose for which vehicle was being used at time of accident	COMPANY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29068453MKC
Cover Note Number	

Driver

Name of Driver	CHIA SWEE CHOON
NRIC No	S1479942G
Date Of Birth	22/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	16/04/1985
Driving Experience	33 YEARS AND 7 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-90250094
Fax Number	
Contact Number	
Email Address	SALES@POHKHOON.COM
Address	463 ANG MO KIO AVENUE 10 #03-1118
Postcode	560463
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

----- REFER TO ATTACHMENT -----

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX2530S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries for me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to other third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

(ii) for complying with requirements under any regulations, laws or court orders.

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-44B / 450 / 452
SINGAPORE 408701
TEL: 6396-8994 FAX: 6396-8884
Name: _____
Ref: CITN No.: _____

Sketch Plan #2

SKETCH PLAN

REFER TO ANNEX

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/1/2018 at about 0945 hrs I was driving my company lorry bearing registration number GBC2446 U along Jalan Besar turning to Bukit Timah Road when I was hit by a motor vehicle bearing registration number SKX2530 3 in the front right of my lorry.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:
26/1/2018
@ 1500 hrs

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 6742 8824 FAX: 6748 8004
Reporting Centre Personnel's Signature
Name:
NIC/PPN No.:

ANNEX A



Sketch Plan #4

MSIG
MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, Sun Centre 2, Singapore 068807
Tel: +65 6827 7800 Fax: +65 6827 7000
Co. Reg. No. 200412212G, GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form	M.T. 300	COMMERCIAL VEHICLE
Model	Carrying Vehicle - 8th 1	Comprehensive
Certificate No.	A 29068453 MKC	Excess: S\$0600
1. Index Mark and Registration Number of Vehicle	QSC2446D	
2. Name of Policyholder	Poh Khoo Electrical Pte Ltd	
3. Effective Date of the Commencement of Insurance for the purposes of the Act	09/01/2018	
4. Date of Expiry of Insurance	30/03/2019	
5. Persons or Classes of Persons entitled to drive*	Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission. * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6. Limitations as to use*	Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. Use for social domestic and pleasure purposes. The Policy does not cover: (i) Use for hire or reward or for racing pace-making reliability trial or speed testing. (ii) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle. * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.	

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

MSIG201801121208



X 90250094

X Sales @ puh.khuon.com





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2018 12:20
Date Of Accident	24/11/2018 09:30
Exact Location Of Accident	NEWTON CIRCUS BT TIMAH RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX2530S
Insured/Policyholder	
Name Of Registered Owner	TEH THUAN KOON
NRIC No	S7403097A
Email Address	ALLEN.TEH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-86936566
Alternative Phone No	Others-86936566

Vehicle Particulars

Manufacturer	AUDI
Model	Q7 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100450441-02
Cover Note Number	

Driver

Name of Driver	LOCHAYA SOPEETIDA
NRIC No	S7360140A
Date Of Birth	15/08/1973
Occupation	INDOOR
Date Of Driving Pass	30/06/2005
Driving Experience	13 YEARS AND 4 MONTHS

Gender	FEMALE
Mobile Number	(LOCAL) +65-93389895
Fax Number	
Contact Number	HOME-66508955
Email Address	SOPEETIDA@YAHOO.COM
Address	200 WATTEN RISE
Postcode	287384
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : TEH THUAN KOON Gender: : Male
Passenger 2	Name: : TEH YUANJIN HARRIGAN Gender: : Male
Passenger 3	Name: : YANTI Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TURNING OUT FROM NEWTON CIRCUS TOWARDS BUKIT TIMAH ROAD TO CITY, WHEN GBC2446U, WHO WAS ON THE MOST INNER LEFT LANE, DECIDED TO GO STRAIGHT AND WE COLLIDED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2446U
-----------------------------	----------

Vehicle Make/Model/Colour Details Of Properties	TOYOTA / DYNA / BLUE
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHIA SWEE CHOON
NRIC/Passport Number	S1479942G
Contact Number	90250094
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: Yoon Fong Gu
NRIC/FIN No.: 923211D097



Sketch map showing the location of the proposed development. The map includes labels for 'Butterfield', 'Newton Circle', 'fowards City', 'EBC2446U', and 'SKR25303'. Arrows indicate directions and connections between these points.

Turning out from Newton Circle towards Exit 7 north to say when GRC 2446W who was on the next inner left lane, decided to go straight & we collided.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Diane
NRIC/FIN No.: 554902



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



PHOTOCOPY

ANN JOO MOTOR PTE LTD

Blk 176 Sin Ming Drive # 02 -17

Sin Ming Autocare Singapore 575721

Tel No. 64510747 Fax No. 64590747

Email Address: singa_annjoo@singnet.com.sg

Co Reg. No./GST Reg. No. : 200806434E

> M/S POH KHOON ELECTRICAL PTE LTD

Cash Bill : SSP1024

Date :30-01-2019

Veh No.: GBC2446U

Make/Model: Toy. Dyna

S/N	Quantity	Particular	Unit Price	Amount S\$
		COST OF REPAIR LUMP SUM BASIS		
		AS PER AEON AUTO CONSULTANTS LLP ASSESSMENT REPORT NO. 119 / AJ011		\$ 6,500.00

E. & O.E.

Total	\$	6,500.00
GST 7 %	\$	455.00
Amount Due	\$	<u>6,955.00</u>

AS

Customer's signature / Co. stamp

for ANN JOO MOTOR PTE LTD



PHOTOCOPY

INVOICE

TO : POH KHOON ELECTRICAL PTE LTD
C/O: ANN JOO MOTOR PTE LTD
BLK 176, SIN MING DRIVE #01-17,
SIN MING AUTOCARE
SINGAPORE 575721

Invoice No.: 119/AJ011
Date: 30-Jan-2019

PARTICULARS

Vehicle Registration No.: GBC 2446 U
Date of Loss: 24-Nov-2018
Date of Assessment: 09-Jan-2019

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport.

\$400.00

TOTAL \$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: POH KHOON ELECTRICAL PTE LTD
C/O: ANN JOO MOTOR PTE LTD
BLK 176, SIN MING DRIVE #01-17.
SIN MING AUTOCARE
SINGAPORE 575721

Our Reference: 119/AJ011
Date: 30-Jan-2019

ASSESSMENT OF VEHICLE NO. GBC 2446 U
DATE OF LOSS: 24-Nov-2018

We have carried out a physical assessment at ANN JOO MOTOR PTE LTD,
Blk 176, Sin Ming Drive #01-17. Sin Ming Autocare Singapore 575721, according to your instruction
on 09-Jan-2019 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: GBC 2446 U
Make & Model: TOYOTA DYNA 150 MANUAL 3 SEATER
Year of Registration: 2011
Engine Capacity: 2982
Chassis No.: JTFAT35Y20K201647
Engine No.: 1KD2114190
Colour: BLUE
Mileage (km): 378357

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL


3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: BRIDGESTONE 195/75 R15 - 70%
LH Make/Size/Thread: BRIDGESTONE 195/75 R15 - 70%

Rear
RH Make/Size/Thread: GREEN-MAX VAN 155R12C - 70%
LH Make/Size/Thread: GREEN-MAX VAN 155R12C - 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.



5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$11,558.93
Adjusted Amount:	\$8,157.18
Lump Sum:	\$6,500.00
Estimated Repair Days:	7 days

Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. GBC 2446 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT PANEL	Repair	1,007.40	-
1	FRONT RH SIDE CORNER PANEL	Bent	279.30	X 279.30
4	FRONT RH SIDE CORNER PANEL CLIPS	Necessary	26.00	X 26.00
1	FRONT GRILLE	Cracked	445.90	X 445.90
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	74.00	X 74.00
1	FRONT LH HEADLAMP	Repair	1,132.50	-
1	FRONT RH HEADLAMP	Cracked	1,132.50	X 1,132.50
4	FRONT RH HEADLAMP CLIPS	Necessary	26.00	X 26.00
1	FRONT RH HEADLAMP LOWER RUBBER SEAL	Necessary	22.00	X 22.00
1	FRONT BUMPER	Bent	469.40	X 469.40
1	FRONT RH DOOR	Bent	1,533.40	1,533.40
1	FRONT RH DOOR CHECKER	Bent	149.40	X 149.40
1	FRONT RH DOOR GLASS	Reuse	715.30	-
1	FRONT RH DOOR GLASS OUTER MOULDING	Reuse	107.00	-
2	FRONT RH DOOR HINGES (TOP & LOWER)	Bent	179.00	X 179.00
1	FRONT RH DOOR INNER TRIM BOARD	Cracked	566.90	X 566.90
1	FRONT RH DOOR LOCK STRIKER	Bent	56.00	X 56.00
1	FRONT RH DOOR LOWER RUBBER SEAL	Necessary	96.30	96.30
1	FRONT RH DOOR MECHANISM LOCK	Bent	300.50	X 300.50
1	FRONT RH DOOR OUTER LOCK HANDLE	Repair	194.40	-
1	FRONT RH DOOR PILLAR OUTER PANEL	Repair	388.70	-
1	FRONT RH DOOR POWER WINDOW MOTOR	Faulty	580.00	X 580.00
1	FRONT RH DOOR POWER WINDOW REGULATOR	Bent	337.00	X 337.00
2	FRONT RH DOOR RUBBER GUIDE STOPPER	Bent	70.00	70.00
1	FRONT RH DOOR WEATHER STRIP	Cut	195.30	195.30
1	FRONT RH DOOR STEP GARNISH	Repair	287.00	-
1	FRONT CABIN BACK RH CORNER SIDE OUTER PANEL	Repair	156.70	-
1	FRONT CABIN BACK RH CORNER SIDE PANEL 'TOYOTA D-4D' EMBLEM	Necessary	48.00	48.00
			10,575.90	6,586.90
Less 25% discount			2,643.98	1,646.73
Parts Total:			7,931.93	4,940.18

1943
25%
1457.25

ASSESSMENT REPORT FOR VEHICLE NO. GBC 2446 U

SPECIAL NETT ITEMS

1	FRONT BUMPER NUMBER PLATE	Necessary	25.00	X	25.00
1	FRONT GRILLE CLIPS - SET	Necessary	30.00	X	30.00
1	FRONT RH HEADLAMP 'PARKING' BULB	Necessary	10.00	X	10.00
1	FRONT RH HEADLAMP 'SIGNAL' BULB	Necessary	12.00	X	12.00
1	FRONT RH HEADLAMP BULB	Necessary	40.00	X	40.00
1	FRONT RH DOOR 'COMPANY DETAIL' STICKER	Necessary	180.00	30	180.00
1	FRONT RH DOOR ADVERTISEMENT & ART WORK	Necessary	300.00	150	300.00
1	FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00		30.00
Special Nett Total:			627.00		627.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	140.00	120.00 X 11
2	To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00	140.00 80
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00 350
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,400.00	1,250.00 350
5	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00 80
Labour Total:		3,000.00	2,590.00
TOTAL (PARTS & LABOUR) \$		11,558.93	8,157.18

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$6,500.00

(SINGAPORE DOLLARS SIX THOUSAND FIVE HUNDRED ONLY)



Amas Ong
Automobile Assessor

1457.25
210.00
1600.00
3267.25
20%
2613.80
45-2,600
4 days

AUTOMOBILE ASSESSMENT REPORT

TO: POH KHOON ELECTRICAL PTE LTD
C/O: ANN JOO MOTOR PTE LTD
BLK 176, SIN MING DRIVE #01-17.
SIN MING AUTOCARE
SINGAPORE 575721

Our Reference: 119/AJ011
Date: 30-Jan-2019

ASSESSMENT OF VEHICLE NO. GBC 2446 U
DATE OF LOSS: 24-Nov-2018

We have carried out a physical assessment at **ANN JOO MOTOR PTE LTD**,
Blk 176, Sin Ming Drive #01-17, Sin Ming Autocare Singapore 575721, according to your instruction
on **09-Jan-2019** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: GBC 2446 U
Make & Model: TOYOTA DYNA 150 MANUAL 3 SEATER
Year of Registration: 2011
Engine Capacity: 2982
Chassis No.: JTFAT35Y20K201647
Engine No.: 1KD2114190
Colour: BLUE
Mileage (km): 378357

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: BRIDGESTONE 195/75 R15 – 70%
LH Make/Size/Thread: BRIDGESTONE 195/75 R15 – 70%
Rear
RH Make/Size/Thread: GREEN-MAX VAN 155R12C – 70%
LH Make/Size/Thread: GREEN-MAX VAN 155R12C – 70%

DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$11,558.93
Adjusted Amount:	\$8,157.18
Lump Sum:	\$6,500.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.
The assessment was conducted on a **"Without Prejudice"** basis.
If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer
This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. GBC 2446 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT PANEL	Repair	1,007.40	-
1	FRONT RH SIDE CORNER PANEL	Bent	279.30	279.30
4	FRONT RH SIDE CORNER PANEL CLIPS	Necessary	26.00	26.00
1	FRONT GRILLE	Cracked	445.90	445.90
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	74.00	74.00
1	FRONT LH HEADLAMP	Repair	1,132.50	-
1	FRONT RH HEADLAMP	Cracked	1,132.50	1,132.50
4	FRONT RH HEADLAMP CLIPS	Necessary	26.00	26.00
1	FRONT RH HEADLAMP LOWER RUBBER SEAL	Necessary	22.00	22.00
1	FRONT BUMPER	Bent	469.40	469.40
1	FRONT RH DOOR	Bent	1,533.40	1,533.40
1	FRONT RH DOOR CHECKER	Bent	149.40	149.40
1	FRONT RH DOOR GLASS	Reuse	715.30	-
1	FRONT RH DOOR GLASS OUTER MOULDING	Reuse	107.00	-
2	FRONT RH DOOR HINGES (TOP & LOWER)	Bent	179.00	179.00
1	FRONT RH DOOR INNER TRIM BOARD	Cracked	566.90	566.90
1	FRONT RH DOOR LOCK STRIKER	Bent	56.00	56.00
1	FRONT RH DOOR LOWER RUBBER SEAL	Necessary	96.30	96.30
1	FRONT RH DOOR MECHANISM LOCK	Bent	300.50	300.50
1	FRONT RH DOOR OUTER LOCK HANDLE	Repair	194.40	-
1	FRONT RH DOOR PILLAR OUTER PANEL	Repair	388.70	-
1	FRONT RH DOOR POWER WINDOW MOTOR	Faulty	580.00	580.00
1	FRONT RH DOOR POWER WINDOW REGULATOR	Bent	337.00	337.00
2	FRONT RH DOOR RUBBER GUIDE STOPPER	Bent	70.00	70.00
1	FRONT RH DOOR WEATHER STRIP	Cut	195.30	195.30
1	FRONT RH DOOR STEP GARNISH	Repair	287.00	-
1	FRONT CABIN BACK RH CORNER SIDE OUTER PANEL	Repair	156.70	-
1	FRONT CABIN BACK RH CORNER SIDE PANEL 'TOYOTA D-4D' EMBLEM	Necessary	48.00	48.00
			10,575.90	6,586.90
Less 25% discount			2,643.98	1,646.73
Parts Total:			7,931.93	4,940.18

ASSESSMENT REPORT FOR VEHICLE NO. GBC 2446 U

PECIAL NETT ITEMS

1	FRONT BUMPER NUMBER PLATE	Necessary	25.00	25.00
1	FRONT GRILLE CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH HEADLAMP 'PARKING' BULB	Necessary	10.00	10.00
1	FRONT RH HEADLAMP 'SIGNAL' BULB	Necessary	12.00	12.00
1	FRONT RH HEADLAMP BULB	Necessary	40.00	40.00
1	FRONT RH DOOR 'COMPANY DETAIL' STICKER	Necessary	180.00	180.00
1	FRONT RH DOOR ADVERTISEMENT & ART WORK	Necessary	300.00	300.00
1	FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
Special Nett Total :			627.00	627.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	140.00	120.00
2	To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00	140.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident	1,400.00	1,250.00
5	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00
Labour Total :		3,000.00	2,590.00
TOTAL (PARTS & LABOUR) \$		11,558.93	8,157.18

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$6,500.00

(SINGAPORE DOLLARS SIX THOUSAND FIVE HUNDRED ONLY)



Amas Ong
Automobile Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/11/2018 11:45
Date Of Accident	24/11/2018 09:45
Exact Location Of Accident	KAMPUNG JAVA ROAD TURNING TO BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBC2446U
Insured/Policyholder	
Name Of Registered Owner	POH KHOON ELECTRICAL PTE LTD
Co Reg No	201404550Z
Email Address	SALES@POHKHOON.COM
Mobile Phone No	(LOCAL) +65-90250094
Alternative Phone No	OFFICE-69090141
Vehicle Particulars	
Manufacturer	TOYOTA
Model	UNKNOWN
Exact Purpose for which vehicle was being used at time of accident	COMPANY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29068453MKC
Cover Note Number	
Driver	
Name of Driver	CHIA SWEE CHOON
NRIC No	S1479942G
Date Of Birth	22/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	16/04/1985
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90250094
Fax Number	
Contact Number	
EMail Address	SALES@POHKHOON.COM

Address 463 ANG MO KIO AVENUE 10
#03-1118
Postcode 560463
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

----- REFER TO ATTACHMENT -----

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKX2530S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that

- I understand, acknowledge, agree and consent that:
- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"); and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of my claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries to me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to any third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature
(If driver is not the policyholder)
Date & Time

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 67490924 FAX: 67490884
E-MAIL: jackcars@com.net.sg

SKETCH PLAN

REFER TO ANNEX

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/1/2018 at about 0945 hrs I was driving my company
 lorry having registration number 8KX2530 & was then
 turning to enter Timah Road when cut off by a motor vehicle
 bearing registration number 8KX2530 & hit the front right of my
 lorry.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

24/1/2018
 09:45 hrs

J&S CARS ENTERPRISE PTE LTD

215, 2007 JBI ROAD

#01-448 / 450 / 452

SINGAPORE 400701

TEL: 6748 8824 FAX: 6748 8834


Reporting Centre Personnel's Signature


Name:

NRIC/PIN No.:

Sketch Plan #3 Pg. 1

ANNEX A































LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG19003650/R1qd3e2

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-04-2019



ATTN : LEE MING YAO

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKX 2530S	Veh. Inspected	GBC 2446U
Policy No.	2100450441-02	Coverage (\$)	0.00
Claim No.	8115249380SG-003	Excess (\$)	0.00
Assign From	LEE MING YAO	Assign Date	20/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150M	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTFAT35Y20K201647	Colour	BLUE
Odometer	382595	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	7 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	7 mm
R/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	24/11/2018	Inspection Date	28/02/2019
Survey held at	ANN JOO MOTOR SERVICES BLK 176, SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 2446U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	REPAIRED SEE LABOUR	1,007.40	-
1	FRONT RH SIDE CORNER PANEL	NOT NECESSARY	279.30	-
4	FRONT RH SIDE CORNER PANEL CLIPS	NOT NECESSARY	26.00	-
1	FRONT GRILLE	NOT NECESSARY	445.90	-
1	FRONT GRILLE 'LOGO' EMBLEM	NOT NECESSARY	74.00	-
1	FRONT LH HEADLAMP	REPAIRED SEE LABOUR	1,132.50	-
1	FRONT RH HEADLAMP	NOT NECESSARY	1,132.50	-
4	FRONT RH HEADLAMP CLIPS	NOT NECESSARY	26.00	-
1	FRONT RH HEADLAMP LOWER RUBBER SEAL	NOT NECESSARY	22.00	-
1	FRONT BUMPER	NOT NECESSARY	469.40	-
1	FRONT RH DOOR	REPLACED	1,533.40	1,533.40
1	FRONT RH DOOR CHECKER	SERVICEABLE	149.40	-
1	FRONT RH DOOR GLASS	REUSE	715.30	-
1	FRONT RH DOOR GLASS OUTER MOULDING	REUSE	107.00	-
2	FRONT RH DOOR HINGES (TOP & LOWER)	NOT NECESSARY	179.00	-
1	FRONT RH DOOR INNER TRIM BOARD	NOT NECESSARY	566.90	-
1	FRONT RH DOOR LOCK STRIKER	NOT NECESSARY	56.00	-
1	FRONT RH DOOR LOWER RUBBER SEAL	REPLACED	96.30	96.30
1	FRONT RH DOOR MECHANISM LOCK	SERVICEABLE	300.50	-
1	FRONT RH DOOR OUTER LOCK HANDLE	REPAIRED SEE LABOUR	194.40	-
1	FRONT RH DOOR PILLAR OUTER PANEL	REPAIRED SEE LABOUR	388.70	-
1	FRONT RH DOOR POWER WINDOW MOTOR	NOT NECESSARY	580.00	-
1	FRONT RH DOOR POWER WINDOW REGULATOR	NOT NECESSARY	337.00	-
2	FRONT RH DOOR RUBBER GUIDE STOPPER	REPLACED	70.00	70.00
1	FRONT RH DOOR WEATHER STRIP	REPLACED	195.30	195.30
1	FRONT RH DOOR STEP GARNISH	REPAIRED SEE LABOUR	287.00	-
1	FRONT CABIN BACK RH CORNER SIDE OUTER PANEL	REPAIRED SEE LABOUR	156.70	-

Report Ref No. CS/AIG19003650/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT CABIN BACK RH CORNER SIDE PANEL 'TOYOTA D-4D' EMBLEM	REPLACED	48.00	48.00
	LESS 25% DISCOUNT		-2,643.98	-485.75
			7,931.92	1,457.25
	SPECIAL NETT ITEMS			
1	FRONT BUMPER NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT RH HEADLAMP 'PARKING' BULB (SN)	NOT NECESSARY	10.00	-
1	FRONT RH HEADLAMP 'SIGNAL' BULB (SN)	NOT NECESSARY	12.00	-
1	FRONT RH HEADLAMP BULB (SN)	NOT NECESSARY	40.00	-
1	FRONT RH DOOR 'COMPANY DETAIL' STICKER (SN)	REPLACED	180.00	30.00
1	FRONT RH DOOR ADVERTISEMENT & ART WORK (SN)	REPLACED	300.00	150.00
1	SET FRONT RH DOOR INNER TRIM BOARD CLIPS (SN)	REPLACED	30.00	30.00
			627.00	210.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING.	NOT NECESSARY	140.00	-
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		160.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	350.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT PANEL, FRONT LH HEADLAMP, FRONT RH DOOR OUTER LOCK HANDLE, FRONT RH DOOR PILLAR OUTER PANEL, FRONT RH DOOR STEP GARNISH AND FRONT CABIN BACK RH CORNER SIDE OUTER PANEL.		1,400.00	350.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	40.00
			3,000.00	820.00
	GRAND TOTAL		11,558.92	2,487.25

Report Ref No. CS/AIG19003650/R1qd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CS/AIG19003650/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.