



Your Ref: 18.25904A PD-O

Date: 13th January 2020

Our Ref : CS3/ASM18008279/Gtd3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 9481M
INSURED VEHICLE: YP 3970A
ACCIDENT DATE: 03/05/2018**

We thank you for your instruction on 04/02/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 9481M from M/s Vfix Auto Service Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLA 9481M and SGU 7805E.
- c) Police Report of Vehicles SLA 9481M.
- d) Final Repair Bill of SLA 9481M from M/s Vfix Auto Service Pte Ltd.

Pre-Repair Inspection Date : 07/05/2018 at M/s Vfix Auto Service Pte Ltd, 60 Kaki Bukit Ave 6, Ark@KB, Singapore 417892.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLA 9481M
Make & Model	: Toyota Vellfire 2.5Z CVT 2WD
Year of Registration	: 2016
Chassis Number	: AGH300030484
Engine Capacity	: 2493 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.