

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.02.2019

Time: 15:56:51

Page: 1

AXA - C/P

R TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305272433
 REGN NO : SHC1399H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.01.2017
 DATE/TIME IN : 26.02.2019 11:35
 ACCIDENT DATE : 25.02.2019

1600

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	/
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	X
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/
0004	09-01-0103-0104-G	LICENSE PLATE LAMP RH/LH	2	68.00	20.00	54.40	X
0005	09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	/
0006	04-01-0103-1150-A	REAR BUMPER MAT	1	50.00		50.00	/
0007	FNPS	NO PLATE(S)-REAR	1 N	25.00		25.00	/

SUB-TOTAL : 907.50

JOB NATURE

0000	20-05	LICENSE PLATE GARNISH	100.00	X rep
0001	20-05	Rear Fender Adv.Sticker RH/LH	200.00	/
0002	PB	PANEL BEATING	300.00	200
0003	SP	SPRAYPAINT CHARGE	300.00	200

AXA-CP(P)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305272433
REGN NO : SHC1399H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.01.2017
DATE/TIME IN : 26.02.2019 11:35
ACCIDENT DATE : 25.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L R/I REVERSE SENSOR

120.00

SUB-TOTAL : 1,020.00

TOTAL : 1,927.50

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Ra hii / UCR
27/2/19 1205L
2 Days
P/P
Before Paint photo

LKK Axiom has been notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: