

INS. CASE OWNER: CC 3 / AIG1900 2687, TIK/03/19 LKK: 2 IDAC: 21/1/19

Surveyor: TALMIKH DOI: 11/03/19 Date / Time: 21/1/19  
 Registered in Meritum: 21/1/19

Pre-assign / CCU / FTE  
 Insured Vehicle No.: SUB 3040L Claim No.: 358200974856  
 Name of Insured: MMB SIMAH S/O WAWO GIMAH Policy No.: 210065874-01  
 Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model: MAZDA  
 Excess Sec II : \$\$ \_\_\_\_\_ D.O.A.: 21/1/19 Place of Accident: BRUKHAMPOR DRIVE  
 Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_  
 If NO: Driver Name / Age: \_\_\_\_\_ OI GLA REPORT:  YES / NO ; TP GLA REPORT:  YES / NO  
 Driver Tel No.: \_\_\_\_\_ (V/L:  YES / NO ) Insured Liability: % Final ? Yes / No

SFA 1627 → → → → →  
 INSRs: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
	Non-Repairing In (1st)	
	Non-Repairing In (2nd)	
	Non-Repairing In (Final)	
	Notification In (if non-pickup)	
	Call CH	
	After call In to OI	<u>02/03/19 - 02</u>
	Documentation Check List: Handler	Typist
	Notification In (if non-pickup)	<input type="checkbox"/>
	After call In to OI	<input type="checkbox"/>
	Authorisation To Act	<input type="checkbox"/>
	Release Voucher	<input type="checkbox"/>
	Final Repair Bill	<input type="checkbox"/>
	Car Rental Invoice	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA	<input type="checkbox"/>
	Medical Bill	<input type="checkbox"/>
	PIC	<input type="checkbox"/>
	Mandate/Reject Instruction	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/>
	Post-Repair Photos	<input type="checkbox"/>
	Others	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time: _____	Sent By: _____
<b>FINALIZATION</b>	Date/Time: _____	Confirm with: _____
Repair Cost:	\$S _____	( _____ days) Reduction: % _____
<b>FINAL SETTLEMENT</b>	Date/Time: <u>26/1/19</u>	Confirm with: <u>Caroline</u>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>NL</u>
Repair Cost:	\$S <u>10912.88</u>	
Loss of Rental (LOR):	<u>(4) \$S 299.60</u>	( <u>4</u> days) x \$70
Loss of Use (LOU):	\$S -	(5 x days)
Loss of Income (LOI):	\$S -	(5 x days)
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	\$S -	
Medical	\$S -	
Disbursement	\$S -	(e.g. Tow/Independent)
Legal Cost	\$S -	
<b>Total:</b>	\$S <u>11212.48</u>	Global Sum \$S: _____
<b>FINAL PAYMENT</b>	Date/Time: _____	Confirm with: _____
Payee 1:	\$S <u>11212.48</u>	Name 1: <u>Performance Motors Limited</u>
Payee 2: (Strike if N.A.)	\$S _____	Name 2: _____
Payee 3: (Strike if N.A.)	\$S _____	Name 3: _____

Taufik

14/01/18

2018

Make/Model  
 Year  
 Color  
 VIN  
 Mileage  
 Date of Purchase  
 Date of Inspection  
 Location of Inspection  
 Name of Insurer  
 Name of Policyholder  
 Name of Driver  
 Name of Vehicle  
 Policy Condition  
 Remarks: The vehicle had commenced its repair at the time of inspection.  
 Date of Market Value  
 IDA / Accident Report  
 GDA / PIC Seen  
 Est. Repairs: 5 days  
 Time Claim  
 CA / CDV / T.C.P. / 24 HRS  
 Date  
 Person Contacted  
 Date / Time  
 Action / Instruction

Make/Model: **SFA1627J** 2018  
 Type:  Car /  Truck /  Trailer  
 Make: **BMW 216i** Year: **1499**  
 Color: **Silver** Insured / 50 / 10 / 10  
 Top Reading: **13652** Mileage: Insured / 50 / 10 / 10  
 Engine No.  
 Chassis: **WBA2X92070V011367**  
 Gen. Cond:  Good /  Fair /  Poor /  Damaged  
 Steering:  Working /  Jammed /  Leaked /  Burnt or  
 Brake:  Working /  Jammed /  Leaked /  Burnt or  
 Mod:  Hi /  STD /  A/Rim or  
 Tyre Size: **F 205/55R17**  
 IC  
 B5 /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTBU /  PIR /  SHMI /  TOYO /  YOKO or  
 Front Wheel: **C** mm  
 Rear Wheel: **G** mm  
 L Wheel: **6** mm  
 R Wheel: **6** mm  
 T.O.A.: **0.01**  
 Survey held at: **PML**  
 Date of Damages: **Fri / Rear / QRS / NIS / UIC / Rooftop or**  
**Rt/s**  
 This UIC / Chassis frame / Body Structure affected due to collision.

BE	OG

P/P - \$10198.95 (Red \$2984.65 / 23%)

Pref. Report  
 Final Report  
 Days Of Repair:  
 Resurvey No. of Trip:  
 Add Fee:  Site Trip \$  
 Inspection \$  
 Vehicle Fee \$  
 Workshop \$  
 Survey Fee:  Inspection \$  
 Mileage \$  
 Fuel \$  
 Other \$

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401599W GST Reg. No M2-0020081-X313, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438189  
Tel. 63190888 (AfterSales)  
Fax. 63449773313, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796501 (AfterSales)  
64796624 (Motorrad)Survey & repair  
11/3 @ 10am  
& survey before 12pm

GST REG. NO : M2 - 0020081 - X

27 FEB 2019

## ESTIMATE

Estimate No. : b1 50294	Page No. : 1 of 5
Date Estimated : 27/02/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR -  
Celeste Kiang Ling Zee  
43 Mimosa Road  
#07-43  
Singapore 808005

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1627J	VD11367	29/08/2018	216i AT	0

## DESCRIPTION

To replace front bumper, air duct, support right, attachments and repair fender right

3000 / 1700 = 5,100.00

Painting front bumper and fender right.

1730 = 1,923.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 = 177.00

To right headlight.

408 = 481.00

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

451 = 531.00

To supply front emboss number plate.

111 x 83.00

Sundries.

? = 150.00

Total Labour 1: 8,445.00

## DESCRIPTION

RH FOG LAMP SUPPORT

QTY PRIC

VALUE

Grate center

1 77.60

des 77.60

FRT BUMPER TOP CARRIER

1 101.20

? 101.20

RH FINISHER

1 385.65

? 385.65

RH MOLDING (SPORT)

1 49.70

nt 49.70

IMPACT ABSORBER TOP

1 67.00

nt 67.00

FRT BUMPER PRIMED PANEL (PMA)

1 49.95

des 49.95

RH GRID LATERAL (LINES/PDC)

1 880.15

des 880.15

RH SUPPORT HEADLIGHT ARM

1 103.60

des 103.60

FRT RH WHEEL ARCH COVER

1 133.05

des 133.05

AIR DUCT (UFS)

1 135.05

111 x 135.05

PLAQUE 82MM

1 206.85

111 x 206.85

RH HEADLIGHT LED TECHNOLOGY

1 71.25

nt 71.25

\* WINDSHIELD CLEANING CONTAINER

\$129.60

Total Parts : 4,609.05

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64767770280, Kampong Krang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
FAX. 63445773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190529 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796501 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**Estimate No. : b1 50294  
Date Estimated : 27/02/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1627J	VD11367	29/08/2018	216i AT	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Rep No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 11/3/19 @ 1130 Excess \$5

Surveyor's Name Tan Jia Sign: *Tan Jia*

Surveyor's Tel 97495744 Authorised Yes / No

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M.L. Yes / No

Surveyor's E-mail tan.jia@khaantown

No. of Working Days Recommend 5 days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,445.00
Parts	:	4,609.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	913.78
<b>Grand Total</b>	:	<b>13,967.83</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Thursday, 7 March, 2019 2:58 PM  
**To:** atmasmra@singnet.com.sg  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** Your Ref: SLB 3040L\_ACCIDENT INVOLVING SLB 3040L AND SFA 1627J ALONG BROCKHAMPTON DRIVE ON 23.02.2019 LKK REF CC3/AIG19003681/hb3



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

07 MARCH 2019

**ATMA SINGH S/O NAND SINGH  
NO. 2 BROCKHAMPTON DRIVE  
SINGAPORE 559051**

**By Post & By Email**

Dear Sir/Madam,

**OUR REF : CC3/AIG19003681/hb3**

**YOUR REF : SLB 3040L**

**ACCIDENT INVOLVING SLB 3040L AND SFA 1627J ALONG BROCKHAMPTON DRIVE ON 23.02.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SFA 1627J against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SFA 1627J. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## View Received Message

This mail is associated with :

**\*SFA1627J (3582009338SG)  
[SLB3040L]**

TP  
CELESTE KIANG LING ZEE  
Feb 23 2019 1:00PM  
[Atma Singh S/O Nand Singh]  
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 25/09/2019 17:23 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11212.48) - SFA1627J - Claim Handler: MdNoor, Norsiah

Approved:11212.48.

### DOCUMENTS SUMMARY

There are no documents.

IDENTITY CARD NO. S71374001



Name

CELESTE KIANG LING ZEE



江 灵 芝

Race

CHINESE

Date of Birth


18-10-1971

Sex

F

Country of Birth

SINGAPORE



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7108572D



Name

LAI KOK WENG LAWRENCE



黎 国 荣

Race

CHINESE

Date of birth

13-03-1971

Sex

M

Country of birth

SINGAPORE

S7108572D



NRIC No. S71374001



Blood Group

O+

Date of issue

03-12-1998

43 MIMOSA ROAD #07-43  
SINGAPORE 808005

NRIC No. S71374001

Date: 27/11/2017



ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

02



Licence No. S7108



NRIC No. S7108572D



Date of issue

21-02-2008

43 MIMOSA ROAD #07-43  
SINGAPORE 808005

NRIC No. S7108572D

Date: 27/11/2017

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SFA1627J	<b>Model:</b>	
<b>Date of Accident:</b>	23.02.2019		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	13,967.83	
Final Repair Cost	: \$	10,912.88	
Loss of Use	: \$	--	days at \$ per day
Rental (if any)	: \$	299.60	04 days
LTA / GIA Search Fee	: \$	--	
Others	: \$	--	
	: \$	--	
Final Settlement Sum	: \$	15,524.60	

**Is Third Party Workshop GIA Registered?**  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No  
BOLA Scenario No: \_\_\_\_\_  
BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

**Payment Instruction: Payee's Breakdown**

1)	Performance Motor Limited	: \$	10,912.88
2)	Celeste Kiang Ling Zee	: \$	299.60
3)		: \$	

\_\_\_\_\_  
Signed by appointed surveyor

\_\_\_\_\_  
Date

**Please attach all the supporting documents to the form.  
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report / Bill (if any)**



07 MARCH 2019

**ATMA SINGH S/O NAND SINGH  
NO. 2 BROCKHAMPTON DRIVE  
SINGAPORE 559051**

**By Post & By Email**

Dear Sir/Madam,

**OUR REF : CC3/AIG19003681/hb3**

**YOUR REF : SLB 3040L**

**ACCIDENT INVOLVING SLB 3040L AND SFA 1627J ALONG BROCKHAMPTON  
DRIVE ON 23.02.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SFA 1627J against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SFA 1627J. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

[atmasmra@singnet.com.sg](mailto:atmasmra@singnet.com.sg)  
(Email)



AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Celeste Kiang Ling Zee ("the third party claimant")  
of 43 Mimosa Road #07-43 S(808005) (address),  
owner of SFA 1627J (vehicle no.) hereby authorize  
Performance Motors Ltd  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SFA 1627J that was  
damaged pursuant to the accident which occurred on 23/2/19 (date) along  
2 Brockhampton Drive (location)  
involving vehicle no/s SLB 3040L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment furtherto settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 25<sup>th</sup> day of FEB (month) 20 19 (year)

Signed by "the third party claimant"

Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 10,912.88 (repair costs), S\$ 299.60 (loss of use/rental) S\$ - (search fees) for vehicle no. SFA16273 that was damaged pursuant to the accident which occurred on 23/2/19 (date) along 2 Brookhampton Drive (location) involving vehicle no/s SLB3040L.

This is pursuant to the inspection conducted on 11/3/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Celeste King King Zee ("third party claimant") of vehicle no. SFA16273 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SFA 16273 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26<sup>th</sup> day of SEP (month) 20 19 (year)



MTH

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"

**PERFORMANCE MOTORS LIMITED**

303 Alexandra Road  
#01-01 Darby Performance Centre  
Singapore 152941  
TEL: 63190100 (Sales)  
63190111 (AfterSales)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770190, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motocrrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motocrrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1343895	Page No. : 1 of 2
Date IN : 11/03/2019	Invoice Number : 2114865 / WSB
Motor Claim Advisor: Inthiran A/L Thurasamy	Invoice Date : 24/06/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

## - CUSTOMER INFORMATION -

Mdm Celeste Kiang Ling Zee  
43 Mimosa Road  
#07-43

Singapore 808005

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1627J /	VD11367	29/08/2018	216I AT	13652

## - - - - LABOUR 1 - - - -

To replace front bumper and attachments, right fog lamp support, right headlight support arm, windshield cleaning container including make good the front right fender and knock out dented area caused by the accident.	3,400.00
To respray front bumper and front right fender.	1,730.00
To check electrical wiring systems at the front section for proper function.	150.00
To replace right LED technology headlight including program and conduct tests for proper function.	408.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications.	451.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 23.02.2019. 3RD PARTY CAR : SLB3040L.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 11.03.2019 AT 11:30AM. AUTHORISED REPAIR BY MS VIC ALPEH FROM LKK AUTO ON 07.03.2019 VIA EMAIL.	
PROPOSE CAR RENTAL = \$299.60. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00

Total Labour 1: **6,289.00**

## - - - - PARTS - - - -

	Qty	Retail Price	NETT
PLAQUE 82MM	1	71.25	71.25
FRT BUMPER PRIMED PANEL (PMA)	1	880.15	880.15
RH MOLDING (SPORT)	1	67.00	67.00
RH FINISHER	1	49.70	49.70
RH HEADLIGHT LED TECHNOLOGY	1	2,348.00	2,348.00
WINDSHIELD CLEANING CONTAINER	1	129.60	129.60
RH FOG LAMP SUPPORT	1	77.60	77.60
IMPACT ABSORBER TOP	1	49.95	49.95
RH GRID LATERAL (LINES/PDC)	1	103.65	103.65
RH SUPPORT HEADLIGHT ARM	1	133.05	133.05

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401555W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190180 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Tampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190886 (AfterSales)  
FAX. 63449771

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796401 (AfterSales)  
64796424 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1343895</b>	Page No. : <b>2 of 2</b>
Date IN : <b>11/03/2019</b>	Invoice Number : <b>2114865 / WSB</b>
Motor Claim Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>24/06/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Toh Jing Xuan</b>

Total Parts : **3,909.95**

Labour Charges : <b>6,139.00</b>	Total Labour & Parts Charges : <b>S\$ 10,198.95</b>
Parts Charges : <b>3,909.95</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>150.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 10,198.95</b>
	GST @ 7% : <b>S\$ 713.93</b>
	Invoice Total Amount Include GST : <b>S\$ 10,912.88</b>

Computer generated invoice. No signature is required. Amount Payable Include GST : **S\$ 10,912.88**

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.



**TAX INVOICE****Invoice No. 55 - 513287**

Page 1 of 1

**MISS CELESTE KIANG LING ZEE**43 MIMOSA ROAD #07-43  
808005 SINGAPORE**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01  
Vantage Automotive Centre, Singapore 159942  
p (65) 6447.3388 f (65) 6345.7247  
Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4**INVOICE DATE :** 15-MAR 2019

R.A. No. 55005451 / Joe Rahman

TITLE	: MISS	KILOMETER OUT/IN	: 38901 / 39060
AUTHORIZED DRIVER	: CELESTE KIANG LING ZEE	KILOMETER DRIVEN	: 159
NRIC/PASSPORT NO.	: S7137400I	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: PEUGEOT P508 ALLURE	DATE & TIME OUT	: 11-MAR 2019 08:30
CAR REGISTRATION NO.	: SLD8510D / UNIT #: 0002769	DATE & TIME IN	: 15-MAR 2019 08:20
CAR GROUP GIVEN	: I	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: F	NO. OF DAY(S) CHARGED	: 4 DAY(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
<b>INSURANCE CLAIMS RATES 2017</b>					
4 DAY(S) @ \$70.00 / DAY			280.00	19.60	299.60
<b>SUB-TOTAL</b>			<b>280.00</b>	<b>19.60</b>	<b>299.60</b>
REMARKS: BMW OWNER: SFA1627J \$100/DAY 1600CC PML CSA: INTHIRAN		<b>TOTAL (SGD) :</b>	<b>280.00</b>	<b>19.60</b>	<b>299.60</b>
* ITEMS NOT SUBJECT TO GST		<b>VISA XXXXXXXXXXXX0676</b>			<b>-299.60</b>
		<b>BALANCE DUE</b>			<b>0.00</b>

**NOTE:**

I / WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 15-Mar-2019 9:13

Entered by Nur Ezham Omar



**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021985-4

**TO BE PAID BY**

PAYMENT : VISA - XXXXXXXXXXXX0676

**HIRER'S DETAILS**

TITLE MISS  
 NAME CELESTE KIANG LING ZEE  
 ADDRESS 43 MIMOSA ROAD  
 #07-43  
 808005  
 SINGAPORE

NRIC/PASSPORT NO S71374001 ISSUE 03/12/1998

ISSUED BY SINGAPORE  
 LICENSE S71374001 EXPIRY 12/12/2999ISSUED BY SINGAPORE  
 NATIONALITY SINGAPOREAN D.O.B. 16/10/1971

FREQUENT FLYER NO

LOCAL CONTACT 98735317

HOTEL

**COMPANY'S DETAILS**

NAME

ADDRESS

RENTAL AGREEMENT NUMBER : 55005451  
 RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY**CHECKOUT**

UNIT # / REGN NO. 00002769 / SLD8510D  
 MAKE & MODEL PEUGEOT P508 ALLURE  
 CAR GROUP GIVEN 1 CHARGE F  
 KILOMETER OUT 36,901  
 PETROL LEVEL OUT FULL  
 DATE & TIME OUT 11/03/2019 08:30  
 DUE DATE & TIME IN 16/03/2019 08:30  
 CHECKIN LOCATION SHORT TERM-HQ (SIN55)-THRIFTY

**RENTAL RATES**

AS: INSURANCE CLAIMS RATES 2017

DAILY @ S\$ 70.00  
 EXTRA DAY @ S\$ 70.00  
 EXTRA HOUR @ S\$ 14.00

**TOTAL: S\$ 299.60****FOR RATES TO APPLY**

MINIMUM 24 HOURS.  
 CAR MUST BE RETURNED TO RENTING LOCATION  
 ON THE DUE DATE

**INSURANCE**

BY INITIALS, THE HIRER  
 INCLUSIVE LDW  
 NON-WAIVERABLE DAMAGE EXCESS: S\$ 2,000.00 (SIN USE)

DECLINES PAI @ S\$ 6.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

**IMPORTANT NOTICE**

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/Intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x \_\_\_\_\_

Hirer

x \_\_\_\_\_

Additional Driver

ADDITIONAL DRIVERS:

THIS CAR IS FOR SINGAPORE USE ONLY THERE IS NO INSURANCE COVERAGE FOR USE OUTSIDE SINGAPORE

**OTHER CHARGES**

FUEL SERVICES @ S\$2.70 / LITRE

**CASH & CHEQUE DEPOSIT****REMARKS**

BMW OWNER: SFA1627J  
 \$100/DAY 1600CC  
 PML CSA, INTHIRAN

**HI RESERVATION**RES. ID# SD000005523  
 Joe RahmanTACO#:  
 REF SRC: PHONEPrinted on 15-Mar-2019  
 Entered by: Joe Rahman

9:14

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2019 <a href="#">Edit Reg</a>		11 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$10,198.95</b> <a href="#">Edit Estimates</a>	<b>S\$10,198.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	Atma Singh S/O Nand Singh, ID: S0303040G, Tel: +6597834032		
Main Claimant:	CELESTE KIANG LING ZEE, ID: S7137400I		
Vehicle Reg. No.:	SFA1627J	Date of Loss:	23/02/2019 13:00 - :59 [5 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3582009338SG	Policy/Cover Note No.:	2100458914 (Comprehensive) Coverage: 31/03/2018 - 30/03/2019
Vehicle Reg. No. (Insured):	SLB3040L	Policy No. (Claimant):	C0086811
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/03/2019]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (25/09/2019): Alert - Adj Mandate Approved (S\$11212.48) - SFA1627J - Claim Handler: MdNoor, No...</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Claim Documents

**\*SFA1627J (3582009338SG)**  
**[SLB3040L]**  
**TP**  
**CELESTE KIANG LING ZEE**  
**Feb 23 2019 1:00PM**  
**[Atma Singh S/O Nand Singh]**  
**Performance Motors Limited**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Letters/Correspondences</b>											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit			
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	24/09/19 09:38	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
2	24/09/19 09:38	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
3	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
4	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
5	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
6	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
7	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
8	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
9	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
10	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
11	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
12	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
13	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
14	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
15	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
16	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
17	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
18	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
19	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
20	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
21	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
22	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
23	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
24	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
25	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
26	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
27	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
28	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
29	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
30	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
31	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
32	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
33	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
34	24/09/19 09:38	General View							Load JPG	<input checked="" type="checkbox"/>		
35	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
36	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
37	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
38	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
39	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
40	24/09/19 09:39	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/19 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 14:49	TP ESTIMATE	 Load PDF	
2	27/02/19 14:49	TP GIA REPORT	 Load PDF	
3	07/03/19 15:02	EMAIL TO OI	 Load PDF	
4	07/03/19 15:02	LETTER TO OI	 Load PDF	
5	23/09/19 16:14	RENTAL RECEIPT	 Load PDF	
6	23/09/19 16:14	LOD	 Load PDF	
7	08/10/19 10:50	WORKSHOP INVOICE	 Load PDF	
8	08/10/19 10:50	AUTHORISATION TO ACT FORM	 Load PDF	
9	08/10/19 10:50	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/02/19 10:57	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLB3040L (Insd veh)	Model:	BMW 216I 1.5 (A)
	SFA1627J (TP veh)		
Date of Accident:	23/02/2019		

Global Sum Settlement	:	[ ] Yes	[ X ] No
Repair Estimate	: \$		<b>14,106.56</b>
Final Repair Cost	: \$		10,912.88
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		299.60    4 days
LTA / GIA Search Fee	: \$		0.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		11,212.48
Is Third Party Workshop GIA Registered?    [ X ] YES    [ ] NO    (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability _____ (%)	
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: <del>Yes</del> / No    BOLA Scenario No: _____	
		_____ NIL _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	11,212.48
2)		: \$	

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 Oct  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19003681/T1DB3Q2

Date: 08/10/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100458914  
 Claimant SFA1627J Insured Vehicle No : SLB3040L  
 Vehicle No : SFA1627J Nature of Claim: TP Claim No: 3582009338SG  
 Date of Loss: 23/02/2019

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFA1627J  
 Make & Model: BMW 216i, 1.5 (A) Engine No: 30715376B38A15A  
 Reg. Date: 29/08/2018 (Man. Year: 2018) Chassis No: WBA2X92070VD11367  
 Colour: Silver Odometer: 13652 km  
 Engine Capacity: 1499 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,971.70	4,059.95	911.75	18.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,212.00	6,139.00	2,073.00	25.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,183.70</b>	<b>10,198.95</b>	<b>2,984.75</b>	<b>22.64</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>922.88</b>	<b>713.93</b>	<b>208.93</b>	<b>22.64</b>
<b>Nett Amount (S\$)</b>	<b>14,106.56</b>	<b>10,912.88</b>	<b>3,193.68</b>	<b>22.64</b>
<b>+ Car Rental (4.0 x S\$70.00/day + 7.00% GST) (S\$)</b>		<b>299.60</b>		
	<b>Nett Liability (S\$)</b>	<b>11,212.48</b>		

## INSPECTION

Date of Assignment: 11/03/2019  
 Date Inspected: 11/03/2019 Inspected At: Performance Motors Limited  
 (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Not Necessary	83.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*RH FOG LAMP SUPPORT	Distorted	77.60 FS	*77.60 FS
4	1		*GRATE CENTER	Not Necessary	101.20 FS	*- FS
5	1		*FRT BUMPER TOP CARRIER	Not Necessary	385.65 FS	*- FS
6	1		*RH FINISHER	Cut	49.70 FS	*49.70 FS
7	1		*RH MOLDING (SPORT)	Cut	67.00 FS	*67.00 FS
8	1		*IMPACT ABSORBER TOP	Deformed	49.95 FS	*49.95 FS
9	1		*FRT BUMPER PRIMED PANEL (PMA)	Deformed	880.15 FS	*880.15 FS
10	1		*RH GRID LATERAL (LINES/PDC)	Distorted	103.65 FS	*103.65 FS
11	1		*RH SUPPORT HEADLIGHT ARM	Distorted	133.05 FS	*133.05 FS
12	1		*FRT RH WHEEL ARCH COVER	Not Necessary	135.05 FS	*- FS
13	1		*AIR DUCT (UFS)	Not Necessary	206.85 FS	*- FS
14	1		*PLAQUE 82MM	Necessary	71.25 FS	*71.25 FS
15	1		*RH HEADLIGHT LED TECHNOLOGY	Cracked	2,348.00 FS	*2,348.00 FS
16	1		*WINDSHIELD CLEANING CONTAINER	Deformed	129.60 FS	*129.60 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)      4,971.70      4,059.95**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER ,AIR DUCT ,SUPPORT RIGHT ,ATTACHMENTS AND REPAIR FENDER RIGHT	New	5,100.00	3,400.00
2	PAINTING FRONT BUMPER AND FENDER RIGHT	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO RIGHT HEADLIGHT	New	481.00	408.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
<b>Gross Labour Cost (S\$)</b>			<b>8,212.00</b>	<b>6,139.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >