

22/02/2019

ASS. REC. BY

REF

083/CTI19003710 Bcd3er

res of instruction

SURVIVOR
MEINER

Mr Lim

ASSIGNMENT (Office)

From (Person)

Ong chin kiat

of

CTI

Date/Time

28/2/19 531pm

Estimated Cost

Bill to

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVT CS

To Inspect Vehicle For

SCV1411P

Insured

PC 883M

at Workshop m/s

Elite Auto Care

Tel

6385 5884

of

25 kaki Bkt Rd 4 #01-37

Policy No

DMB1SN30645618000

Claim No

SNM19D200916102

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

22/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

Person Contacted

Enc

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SCV1411P-X

PC 883M-X

Dismantle 5/3/2019

REF: CT1

ASSIGNMENT

From: Date: 27/2/13

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCV 1411P

at Workshop m/s Elite Auto

of 25 Kaki Bukit Rd 4 # 01-37

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SCV 1411P

Yr Regn: 12/7/2006

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: DAIHATSU 1.5

C.C 1495

Colour: GREY

A/C Insured / Std / NI / NA

Sp. Reading 270416

T/Radio: Insured / Std / NI / NA

Eng/No: 1628136

C/No: JDAJ210G001010126

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65/16

R: 215/65/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A.

D.O.I. 27/2/13

Survey held at Elite Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 6000/2 - 7000/2

* No general view photos.

MV 45,000/2

PV 33,044/2

NV 11,956/2

Taim Lin
28/2/13

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee: 150

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

S + RS, SI

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

) TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$)

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019		26 Feb 2019 17:31 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	BOILERMASTER PTE LTD , Co. Reg. No.: 199203051N		
Main Claimant:	CHONG YUH WOEI , ID: S7931733J		
Vehicle Reg. No.:	SCV1411P	Date of Loss:	22/02/2019 10:00 - :59 [151 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200916C02	Policy/Cover Note No.:	DMB1SN30645618000 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019
Vehicle Reg. No. (Insured):	PC883M	Policy No. (Claimant):	P 27122256 DMV
		Excess:	S\$3,000.00
Repairer:	Elite Auto Care Club (HQ) 25 Kaki Bukit Road 4, #01-37, 417800 Kranji - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/03/2019]		
Driver/Custodian (Insured):	CHAN KWOK KEONG (/ Male), NRIC: S0162300A Email:		
Adj Asg. Remarks:	workshop located at 25 Kaki Bukit Road 4 #01-37 Synergy@KB Singapore 417800		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1733J
Vehicle Details	
Vehicle No.:	SCV1411P
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Feb 2019
Vehicle Make:	DAIHATSU
Vehicle Model:	TERIOS 1.5L 4WD MANUAL ABS AIRBAG
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	1628136
Chassis No.:	JDAJ210G001010126
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$17,788.00
Original Registration Date:	12 Jul 2006
First Registration Date:	12 Jul 2006
Transfer Count:	0
Actual ARF Paid:	\$19,567.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$45,578.00
COE Rebate Amount:	\$33,044.00
Total Rebate Amount:	\$33,044.00

The information contained herein is correct as at 28 Feb 2019

OK

COE left 7yr 3 months

AV Dep 6,000/2

MV 45,000/2

PV 33,044/2

NV 11,956/2

huc
28/2/19



Well Maintained By Owner. Most Popular Japan Make MPV In The Market. Hassle Free. No Repairs Needed. Please Call Now For More Info, Door Step Viewing Can Be Arranged!

Posted: 08-Feb-2019

Tags: 2007 Daihatsu Terios, 2007 daihatsu terios, Daihatsu Terios, daihatsu terios, Daihatsu, Terios, terios, Used Daihatsu



Daihatsu Terios 1.5A (COE till 02/2022)

-

N.A

15-Feb-2007

1,495 cc

-

SUV

SOLD

Single Owner, 54kkm Mileage Done Throughout The Years. Still Look, Feels And Drive Like New. Owner Second Car In The Family. Excellent Condition Coupled With 4 Wheel Drive For Good Stability. Cheapest...

Posted: 01-Jan-2019

Tags: 2007 Daihatsu Terios, 2007 daihatsu terios, Daihatsu Terios, daihatsu terios, Daihatsu, Terios, terios, Used Daihatsu



Daihatsu Terios 1.5M (COE till 05/2021)

-

N.A

16-Jun-2006

1,495 cc

-

SUV

SOLD

Sporty Blue Exterior With Luxury Black Leather Interior, Spacious Boots, Rear Bike Rack Which Can Hold Up To Two Bike, Road Tax Till Jun 2019, Trade In Available, Don't Miss This Opportunity, Kindly C...

360 VR Cars

Posted: 17-Dec-2018

Tags: 2006 Daihatsu Terios, 2006 daihatsu terios, Daihatsu Terios, daihatsu terios, Daihatsu, Terios, terios, Used Daihatsu



Daihatsu Terios 1.5A (COE till 05/2026)

\$45,000

\$6,260 /yr

05-May-2006

1,495 cc

220,000 km

SUV

Available

Direct 1 Owner, Maintained Meticulously.

DIRECT OWNER

Posted: 12-Feb-2019

Tags: 2006 Daihatsu Terios, 2006 daihatsu terios, Daihatsu Terios, daihatsu terios, Daihatsu, Terios, terios, Used Daihatsu

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view **Expired ads**

100 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Daihatsu Terios, Daihatsu Terios Singapore, used Daihatsu Terios Singapore, used Daihatsu Terios, used vehicles Singapore or even buy used Daihatsu Terios Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/02/2019 12:36
Date Of Accident	22/02/2019 10:15
Exact Location Of Accident	ROUNDAABOUT AT PIE(TUAS) & AYE(TUAS) INTERSECTION
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCV1411P
Insured/Policyholder	
Name Of Registered Owner	CHONG YUH WOEI
NRIC No	S7931733J
Email Address	CHONGYUHWOEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93657764
Alternative Phone No	OFFICE-93657764
Vehicle Particulars	
Manufacturer	DAIHATSU
Model	TERIOS-1.5 4WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P 27122256 DMV
Cover Note Number	
Driver	
Name of Driver	CHONG YUH WOEI
NRIC No	S7931733J
Date Of Birth	13/10/1979
Occupation	INDOOR
Date Of Driving Pass	31/01/2003
Driving Experience	16 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93657764
Fax Number	
Contact Number	OFFICE-93657764
EMail Address	CHONGYUHWOEI@GMAIL.COM

Address	87 FLORIDA DRIVE #07-57 SINGAPORE
Postcode	506889
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC883M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAN KWOK KEONG
NRIC/Passport Number	S0162300A
Contact Number	97326576
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or wilful neglect of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Financials Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be a fee to be made available upon application for interested parties.
7. By the lodgment of this report to the insurers, you hereby subject to the collection of this report to be stored and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information contained in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (a "Insurer") who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and all necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, receipts and notices to me, which could involve disclosure of certain personal data about me to third parties about the liability of the same as well as the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to the third parties service providers or agent(s) including their lawyers/law firms, which may be located outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and stored to complete claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that is statutorily evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory laws or court orders.

Policyholder's Signature

Date & Time:

22 Feb 19 12:30 PM

Driver's Signature

If driver is not the policyholder:


Date & Time

Reporting Centre Person's Signature

Name:

NRIC/IN No:

SKETCH PLAN



At about 1015 AM, I was travelling on the sliproad out of PIE towards Tans Road on my way back to the office ~~at the roundabout~~. As I was approaching the roundabout at the intersection of PIE and AYE, I stopped to check for on coming traffic. Moments later, the van (PC883M) knocked into the rear of my vehicle.

I then got out to check on the situation. The other driver, Mr. Chan, was already out of his vehicle. We both assessed the damage and exchange particulars. The damage to my vehicle was on the rear door whereas the van sustained only minor dents to the front. Both myself and the other driver did not sustain from any injury.

I/We declare the foregoing particulars are true in every respect.

2.3. 5/6/11 12:30 PM

Table 8. (continued)

VERGIL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2019		26 Feb 2019 17:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BOILERMASTER PTE LTD , Co. Reg. No.: 199203051N		
Main Claimant:	CHONG YUH WOEI , ID: S7931733J		
Vehicle Reg. No.:	SCV1411P	Date of Loss:	22/02/2019 10:00 - :59 [151 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200916C02	Policy/Cover Note No.:	DMB1SN30645618000 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019
Vehicle Reg. No. (Insured):	PC883M	Policy No. (Claimant):	P 27122256 DMV
		Excess:	S\$3,000.00
Repairer:	Elite Auto Care Club (HQ) 25 Kaki Bukit Road 4, #01-37, 417800 Kranji - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 07/03/2019]		
Driver/Custodian (Insured):	CHAN KWOK KEONG (/ Male) , NRIC: S0162300A Email:		
Adj Asg. Remarks:	workshop located at 25 Kaki Bukit Road 4 #01-37 Synergy@KB Singapore 417800		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.
















ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















Claim Documents

*SCV1411P (SNM19D200916C02)
[PC883M]
TP
CHONG YUH WOEI
Feb 22 2019 10:00AM
[BOILERMASTER PTE LTD]
Elite Auto Care Club

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)		Thumbnail	Print
1	22/02/19 12:42	Video - Accident [Linked Accident Report Documents]		Load MP4	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
2	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
3	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
17	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
18	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
19	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
20	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
21	20/03/19 15:42	General View		Load JPG	<input checked="" type="checkbox"/>
22	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
23	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
24	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
25	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
26	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
27	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
28	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
29	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
30	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
31	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	20/03/19 15:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
34	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/03/19 15:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/19 17:32	PRS email	 Load PDF	
2	26/02/19 17:32	INSD GIA Report	 Load PDF	
3	26/02/19 17:32	TP SCV1411P GIA report	 Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	22/02/19 12:42	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	22/02/19 12:46	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	22/02/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	22/02/19 12:44	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	22/02/19 12:44	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19003710/BCD3E2**Date:** 21/03/2019REFERENCE**Handling Insurer:** China Taiping Insurance
(Singapore) Pte. Ltd.**Policy No:** DMB1SN30645618000**Claimant Vehicle
No :** SCV1411P**Insured Vehicle
No :** PC883M**Date of Loss:** 22/02/2019**Nature of Claim:** TP**Claim
No:** SNM19D200916C02DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SCV1411P**Make & Model:** DAIHATSU TERIOS, 1.5 4WD**Engine No:** 1628136**Reg. Date:** 12/07/2006 (Man. Year: 2006)**Chassis No:** JDAJ210G001010126**Colour:** Grey**Odometer:** 270416 km**Engine Capacity:** 1495 cc**Market Value/New Car Price:** N/A**Sum Insured (S\$):** Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES**Front Tyre Size:** 215/65 R16**Rear Tyre Size:** 215/65 R16**Front Left Side:** Continental 7 mm**Rear Left Side:** Continental 7 mm**Front Right Side:** Continental 7 mm**Rear Right Side:** Continental 7 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION**Date of Assignment:** 26/02/2019**Date Inspected:** 27/02/2019**Inspected At:**Elite Auto Care Club (HQ)
25 Kaki Bukit Road 4, #01-37
Singapore 417800**Estimated Period of Repair:** 6.0 days**Adjuster:** Lim Teow Guan**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts:	M1-SUV	DAIHATSU TERIOS 1.5 4WD (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCV1411P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >