

REF: NTUC NS/INC19003711/Jtd307

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SH8024Z

Policy No. _____

Claims No. MT1033824-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SG1041M Yr Regn: 18 mar/2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Citaro c.c 6374

Colour multi colour A/C: Insured / Std / NI / NA

Sp. Reading 233941 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WEB62808323130295

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70 R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 23/1/19 D.O.I. 29/1/19

Survey held at Smart

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SG1041M-CC3/106/70/0804/King392 DOA: 20/1/19 1656 3549

part by part \$61205 (Red: 336.45, 35%)

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 1

1) 282 Typst

☒ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$

) S + PS SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format: OTP

Lump Sum / (B): (\$ 61205)

TOTAL

160
160

Denise Tay (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Wednesday, 27 February 2019 11:10 AM
To: Denise Tay (LKKAuto)
Subject: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

'With effect from 1 Mar 2019, we will be discontinuing mailbox, mtreg@income.com.sg.

Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, 26 February 2019 5:24 PM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Date : 26/2/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1033824-001	SMRT BUSES PTE LTD	SG 1041M	SHB8024Z	23/01/2019	07:00	948.50	612.05

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Denise Tay (LKKAuto)

From: Audrey Woo (Auto Svcs/Claims & IA/Claims & IA/Buses) <audrey@smrt.com.sg>
Sent: Tuesday, 26 February 2019 5:05 PM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses); Denise Tay (LKKAuto); Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); Sunny Tan Ah Leong (Auto Svcs/ARC/AR & SC/Buses)
Subject: Finalisation - SG1041M (BUS/01/19/1058) - NTUC
Attachments: img-226164756-0001.pdf; Silver Cab SHB8024Z.bmp

BUS/01/19/1058/AW – Bus SG1041M – DOA 23 Jan 2019, 6:55am

Dear Denise,

Above attached refer. 3rd party is silver cab SHB8024Z. Please furnish a copy of SHB8024Z's GIA report, if he has reported.

Audrey Woo | DID : 6556 3521 | FAX : 6481 9221 | Email : audrey@smrt.com.sg | Claims Department | 6 Ang Mo Kio Street 62 Singapore 569140



From: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses)
Sent: Tuesday, 26 February, 2019 10:57 AM
To: Audrey Woo (Auto Svcs/Claims & IA/Claims & IA/Buses); Denise Tay (LKKAuto)
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); AutoSvs-ARC (Bus)
Subject: FW: Finalisation - SG1041M (BUS/01/19/1058) - NTUC

Hi Audrey,

Please assist for the query from LKK.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: 26 February 2019 10:53
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses) <catherineleesc@smrt.com.sg>; Hwee Jie (LKK Auto)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/01/2019 17:28
Date Of Accident	23/01/2019 07:00
Exact Location Of Accident	SLIP RD FROM PIE TO AIRPORT BOULEVARD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SG1041M
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81111111
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	12M SINGLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-II027592MFBP
Cover Note Number	
Driver	
Name of Driver	LU SHUIPING
Passport No/FIN	G8512828R
Date Of Birth	19/01/1981
Occupation	OUTDOOR
Date Of Driving Pass	28/08/2017
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 6 ANG MO KIO ST 62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 40

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

My bus was travelling along the slip road from PIE to Airport Boulevard - bef BS: 95151 (Airport Police Stn) after the merging lanes had merged into one. A silver taxi came from behind and collided onto the right rear portion of my bus. The taxi driver drove off without exchanging particulars. No injury reported.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PEND DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] 25842

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: 23 JAN 2019
NRIC/FIN No.:

SG1041M


Unknown
(silver taxi)

3 2 1


Airport
Boulevard

Refer to report.

I/We declare the foregoing particulars are true in every respect.



6/23/2018 2:58 PM





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 31/01/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG1041M
Case Reference Number	BUS/01/19/1058
Registration Date	15/8/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Lu Shuiping
Type of Accident	Side Swipe
Accident Date and Time	23/1/2019 7:00 AM
Accident Reported Date and Time	23/1/2019 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099913
Special Instruction to ARC, if any	SG1041M - RIGHT REAR PORTION DAMAGED UNKNOWN SILVER TAXI - LEFT FRONT PORTION BC INF NO VISIBLE DAMAGE
Prepared Date and Time	29/1/2019 1:44 PM
Chassis Number	WEB62808323130295
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$324.00	\$262.00
Total Spare Part Cost	\$85.05	\$85.05
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$939.05	\$612.05
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Boon Chew Tay	Hwee Jie
ARC / Surveyor Sign Off Date	29/01/2019 4:49 PM	29/01/2019 4:51 PM
Signature		
Remarks		Photo Before Paint

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/01/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$530.00 265	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$324.00 262	\$262.00
Total Spray Painting & Panel Beating	\$324.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010012	VE	0005446911	LAMP, SIDE MARKER FOR MB CITARO O530 BUS	1.00	\$94.50	10.00	\$85.05	Replace	Replace
Total					\$94.50		\$85.05		

SLR ✓

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

968.50

27/2/19 - Finalized P/P \$612.05/- 1 day.

SL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SG1041M
Case Reference Number	BUS/01/19/1058
Registration Date	15/8/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Lu Shuiping
Type of Accident	Side Swipe
Accident Date and Time	23/1/2019 7:00 AM
Accident Reported Date and Time	23/1/2019 9:15 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1041M - RIGHT REAR PORTION DAMAGED UNKNOWN SILVER TAXI - LEFT FRONT PORTION BC INF NO VISIBLE DAMAGE
Prepared Date and Time	29/1/2019 1:44 PM
Chassis Number	WEB62808323130295
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$324.00	\$0.00
Total Spare Part Cost	\$85.05	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$939.05	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days		
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$630.00 265	
Total Labour	\$530.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$324.00 262	
Total Spray Painting & Panel Beating	\$324.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010012	VE	0005446911	LAMP, SIDE MARKER FOR MB CITARO O530 BUS	1.00	\$94.50	10.00	\$85.05	Replace	✓ SCL
Total					\$94.50		\$85.05		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie-Lkk

29/1/19

P/P 1 days

as

Photo before paint



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19003711/Jtd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 01-03-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 8024Z	Veh. Inspected	SG 1041M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1033824-001	Excess (\$)	0.00
Assign From		Assign Date	29/01/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WEB62808323130295	Colour	MULTI COLOUR
Odometer	233941	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/01/2019	Inspection Date	29/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1041M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	SCRATCHED		
	LAMP, SIDE MARKER: FOR MB CITARO O530 BUS		94.50	94.50
	LESS 10% DISCOUNT		-	-9.45
			94.50	85.05
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		530.00	265.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		324.00	262.00
			854.00	527.00
GRAND TOTAL			948.50	612.05
RECOMMENDED COST OF REPAIRS (CONFIRMED)				612.05

Report Ref No. NS/INC19003711/Jtd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.