

ASS. REC. BY:

REF:

MSG19003719/11+d302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Jenny Yong

of

MSG

Date/Time:

27/2/19 @ 2:07pm

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 67817

Insured:

Public liability

at Workshop m/s

AMA AutoCare

Tel:

8 778 3636

of

36 Joh Guan Rd East #01-36

Policy No:

Claim No:

585495PL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/2/19

CA / REV / REP. / REV 24 HRS

28/2/19 @ 11am

H.O.D. Endorsement:

Date/Time:

2:54pm @ 27/2/19

Person Contacted:

Melvin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMH 67817 - X

Tanpin

MSIG

INSURANCE

Date: 28/2/19

Estimated Cost

on (C) WS / TP RES / OD RES / EVA / IHV / MV

To inspect Vehicle No

SMH 6781T
AMA Auto

at Work Address

36 Joh Guan Rd East # 01-36

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

11am
(waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Est. of Market Value

UDAC Accident Spot

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repair

days Res: Yes or No

Lump Sum

% 3 Val: Yes or No

CA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMH 6781T Date: 28/2/19

Type: (C) M / B / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Hyundai Avante

1591

Colour

Grey

Insured / Std / NI / NA

Sp. Reading

1624

I/Ratio: Insured / Std / NI / NA

Eng/No

Chassis

KMHD 84 / CM KU845 347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modf: Nil / SRim / STD ARim or

Tyre Size:

F: 205 / 55 R16
R: 217

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / S&MI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal

6 mm

R/Bal

6 mm

L/Bal

6 mm

L/Bal

6 mm

D.O.A.

D.O.I.

28/2/19 elco

Survey held at

AMA

Des. of Damages: (C) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/10/19 4/5 \$1400, 2 days, conform with Alvin's email.

(Red: 1540, 52%)

RECEIVED 10 OCT 2019

[Signature]

5/3/2019

Date/Time: File Pass to?

Prof. Report

Days Of Repair: 2

10/10 Typist

Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to?

Add Fee:

Site Insp: \$

Transportation

2)

Interview: \$

S + P

Report Format

Tech. Inv: \$

Photo

Lump Sum / L.B. \$

14001 -

Weekend: \$

Other

190

190

150
190

Nivitha (LKK Auto)

From: Jenny Yong <jenny_yong@sg.msig-asia.com>
Sent: Wednesday, 27 February 2019 2:07 PM
To: Catherine Chong (LKK Auto)
Subject: Insured : ST Electronics (Info-Comm Systems) Pte Ltd - ACCIDENT INVOLVING SMH 6781T ON 14.2.2019 - MSIG : 585495PLY
Attachments: img-226165425.pdf
Importance: High

Hi Catherine,

Public Liability

Third party vehicle was hit by carpark barrier.

Please conduct survey on a without prejudice basis.

Attached repair quotation.

We look forward to receiving your survey report.



Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2019 16:09
Date Of Accident	14/02/2019 07:50
Exact Location Of Accident	TECH WHYE LANE CARPARK GANTRY <TW3> ENTERING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH6781T
Insured/Policyholder	
Name Of Registered Owner	CHUA TECK JOO
NRIC No	S2003139E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84338230
Alternative Phone No	OTHERS-84338230

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN030812
Cover Note Number	CN030812

Driver

Name of Driver	CHUA TECK JOO
NRIC No	S2003139E
Date Of Birth	29/11/1950
Occupation	INDOOR
Date Of Driving Pass	25/09/1979
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84338230
Fax Number	
Contact Number	OTHERS-84338230
EMail Address	NOEMAIL

Address	BLK 12 TECK WHYE LANE #22-214
Postcode	2368
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG POLICE DIVISIONAL HQ ('J' DIVISION)
Police Station Address	ROAD: NO. 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7910000 - FAX NO: 68965649
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	STEE SINGAPORE TECHNOLOGIES PTE LTD
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Common Statement

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

CERTIFICATE OF INSURANCE Pg. 1

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Centre #01-21
 Tel: 1800 8804888
 Website: www.axa.com.sg
 GST Registration Number : 199903512M
 customer.care@axa.com.sg



Original

Agent Code: **08260**

Policy No. (if any):

New Business

SmartDrive Quote Ref:

MOTOR COVER NOTE

No. CN030812

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	CHUA TECK JOO @ CHUA TECK JUNE
MAKE AND DESCRIPTION OF VEHICLE	HYUNDAI AVANTE 1.6 4DR AUTO 'S'
VEHICLE REGISTRATION NO.	TBC
YEAR OF MANUFACTURE	2018
ENGINE NO.	G4FGJU074233
CHASSIS NO.	KMHD841CMKU845347
ENGINE CAPACITY/TONNAGE	1591
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	MAYBANK SINGAPORE LTD
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 17/01/2019 TO: 16/01/2020
EXCESS (S\$)	AS PER POLICY
AXA PREMIUM WORKSHOP?	NO



I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Authorised Signature

Issued by Hock Moh Nelson TEO on 17/01/2019 5:27 pm

- Note:** This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.
- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
 - An administrative fee of S\$26.75 (inclusive of GST) will be charged :
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:
 Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.
 For Non-Individual Customers:
 Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

MTR/C/NOTE/V01/03



**SINGAPORE
POLICE FORCE**



J/20190215/7025

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190215/7025

purpose.

Subjects Involved			
Victim			
Person Name	CHUA TECK JOO		
ID Type	NRIC NO	ID No	S2003139E
Gender	Male	Age	68
Race	Chinese	Language	English
Occupation	Retiree	Address Type	
Address	APT BLK 12 TECK WHYE LANE #22-214 SINGAPORE 680012		Mobile No 84338230
Is Informant A Victim?	Yes		
Person Name	CHUA TECK JOO (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/02/2019 13:55
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Page No. 1

Vehicle No. SMH6781T

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BONNET	DEEP DENT	1540.00	dd ✓
2	FRONT BONNET INSULATOR	REFIX	0.00	
			1540.00	0.00
		20%	- 1232.	0.00
				0.00
	SPECIAL NETT ITEMS			
1set	FRONT BONNET INSULATOR CLIPS		80.00	20% ✓
		TOTAL PARTS	80.00	0.00

Taufik 97495749
 WP

28/2/19 @ 1120

02 days

Resony after repair

taufik@lkhauto.com

[Signature]
 5/3/19





AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Vehicle No. SMH6781T

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	600.00 250	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced(INNER & OUTER SURFACE)	600.00 250	
3	To provide anti-rust treatment on affected areas	120.00 30	
	Labour Total :	1320.00	0.00
	TOTAL (PARTS & LABOUR):	2940.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1782-
 1/5/1400#
 2 days





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG19003719/T1td3e2	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-10-2019	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMH 6781T
Policy No.		Coverage (\$)	0.00
Claim No.	585495PLY	Excess (\$)	0.00
Assign From	JENNY YONG	Assign Date	27/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHD841CMKU845347	Colour	GREY
Odometer	1624	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/02/2019	Inspection Date	28/02/2019
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINAGPORE 608580		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 6781T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	DENTED	1,540.00	1,540.00
2	FRONT BONNET INSULATOR (NPA)	REFIX	-	-
	LESS 20% DISCOUNT		-	-308.00
			1,540.00	1,232.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BONNET INSULATOR CLIPS (SN)	NECESSARY	80.00	20.00
			80.00	20.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS.		600.00	250.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED (INNER & OUTER SURFACE).		600.00	250.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		120.00	30.00
			1,320.00	530.00
GRAND TOTAL			2,940.00	1,782.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/MSG19003719/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.