

2007/2008

ASS. REC BY:

REF:

C81 EGI 1900374 / Ecd3er

Special Instruction:

SW/Veyat

ASSIGNMENT (Office)

From (Person):

Jeannie Cheng

of

EGI

Date/Time

26/2/19 @ 4:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS1734R

Insured:

EH 1000S (Cerato K3)

at Workshop m/s

B' Performance

Tel:

6397 5920

of

7 soon lee street #01-38

Policy No:

Claim No:

CDMPG19000307

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:39am 27/2/19

Person Contacted:

Lathan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJS1734R-x

EH 1000S-x

Dismantle: 4/3/2019

After repair: 7/3/2019

Surveyor: Steve

REF:

EGT

ASSIGNMENT

From: _____ Date: 01/3/19
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJS 1734R
 at Workshop m/s B's Performance
 of 7 Soon Lee St 1Space #01-38
 Insured: 5C627688
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJS 1734R Yr Regn: 30/07/09
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Mark X C.C. 2.5
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 174398 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GRX12030 68160
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 23/2/19 D.O.I. 1/3/19
 Survey held at B's Performance 6.07pm
 Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 19,000
 PV - 16,434
 NV - 2566

Repair large 2K-3K, 4 days

27/3/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

50

50+50

150

Report Format : PRC

Lump Sum / I.B.I. (\$) _____

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Tuesday, 26 February 2019 4:40 PM
To: admin-d@lkkauto.com
Cc: ERGO Insurance Pte. Ltd. (Claims Department); sur@lkkauto.com
Subject: RE: RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SJS1734R & EH1000S .OUR REF NO. [1902-7102(BP)(PD)]
Attachments: SJS1734R SAS.pdf; EH1000S SAS.pdf

Hi LKK,

With reference to the above matter.

Please assist to conduct this survey request from R. S. Solomon, their client's vehicle can be survey at the location as per stated in the email below.

Attached are the necessary documents for your further actions (Note: Reports not to be released to any Third Party).

Note: To survey on without prejudice basis and inform the repairer in writing, that you are require to conduct a post-repair inspection before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
jeannie.cheng@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: Tuesday, February 26, 2019 4:14 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Natalie Ng; Pearlyn Goh

Subject: Re: RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SJS1734R & EH1000S .OUR REF NO. [1902-7102(BP)(PD)]

Dear Jeannie,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your Surveyors to contact Ms. Latha of B's Performance Pte Ltd at tel No. 6397 5920 for a pre-repair survey of our client's vehicle located at 7 Soon Lee Street #01-38 iSpace Singapore 627608.

Thank you and Best Regards,

--

Yours sincerely
Wendy Jiang | Legal Executive



R. S. Solomon LLC | 正氣律師事務所

Commissioner for Oaths

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | Branch: Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Tue, Feb 26, 2019 at 3:41 PM ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg> wrote:

WITHOUT PREJUDICE

Dear Sir,

We acknowledged receipt of your Email for the PRS request as below.

In compliance with **“State Courts Practice Directions Amendment No.1 of 2016”**, do select an assessor from the list below.

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy

Kindly let us have your reply on the selection of the surveyor.

Warmest Regards,

Jeannie Cheng

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985

jeannie.cheng@ergo.com.sg

www.ergo.com.sg

ERGO



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: Tuesday, February 26, 2019 3:15 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Natalie Ng; Pearlyn Goh
Subject: RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SJS1734R & EH1000S .OUR REF NO. [1902-7102(BP)(PD)]

Dear Sirs,

We act for the owner ('our client') of vehicle no. SJS1734R.

Our client's vehicle was involved in the aforesaid accident with your insured's vehicle no. EH1000S at the material time. As a result, our client's vehicle was damaged and before our client proceeds to repair his vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our client's vehicle within the stipulated timeline, our client will proceed to repair his vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date;
2. GIA report lodged by our client.

Let us hear from you soonest.

Thank you and Best Regards,

--

Yours sincerely

Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Commissioner for Oaths

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | Branch: Blk 184
Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3538D
Vehicle Details	
Vehicle No.:	SJS1734R
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X 2.5G A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4GR0520919
Chassis No.:	GRX1203068160
Maximum Power Output:	158.0 kW (211 bhp)
Open Market Value:	\$31,392.00
Original Registration Date:	30 Jul 2009
First Registration Date:	30 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$31,392.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2019
PARF Rebate Amount:	\$15,696.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$738.00
Total Rebate Amount:	\$16,434.00

The information contained herein is correct as at 02 Mar 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



 Advanced
Search

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Toyota Mark X](#)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Tyres



Toyota Mark X

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$21,000	
Depreciation	-	?
Reg Date	09-Jun-2009 (3mths 6days COE left)	
Manufactured	2008	?
Mileage	176,000 km (18.1k /yr)	
Transmission	Auto	
Engine Cap	2,499 cc	
Road Tax	\$1,798 /yr	?
Power	158.0 kW (211 bhp) View specs of the Toyota Mark X (2005-2011)	
Curb Weight	1,500 kg	?
Features	Powerful 2.5L V6 VVT-i Engine, Smooth 6 Speed Auto Transmission, Rear Wheel Drive, ABS, SRS Airbags, Dual Zone Climatic Aircon And Immobilizer.	
Accessories	Pearl White Fresh Paintwork, Big Bake Kit, Original Leather Upholstery, LCD Player, Reverse Sensors & Camera & Electric Seats, Wear And Tear Replace	
Description	Smooth And Powerful Transmission With Stunning Paintwork Very Impressive Exterior And Interior Condition Super Cold Aircon Beautiful Is All I Can Say To Sum It Up. Feel Free To View The Car. Option With New COE Renewal 5 Years - \$38,888 10 Years - \$54,888.	
COE	\$12,901	?
OMV	\$31,083	?
ARF	\$31,083	?
Dereg Value	\$15,888 as of today (change)	?
No. of Owners	5	?
Type of Veh	Luxury Sedan	
Category	PARF Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER



Seller Information

Contact Person(s) Jhiva

Contact No. 81188925

Enquiry ☒ Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer


 GET HELP WITH
PAPERWORK


sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)
[Compare](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

500+ dealers
competed to
buy my car!



► Sell ur Car for More Cash
► Highest Price or Get \$100 Free
► Get Paid Now, Handover Later

SELL YOUR CAR



Toyota Mark

Price Range

Depreciation

2009

Vehicle Type



Advance
Search

Home » Used Cars » Kimhung Hegary & Co Pte Ltd » Toyota Mark X

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Engine Oil

FREE
ENGINE OIL
SERVICE PACKAGE
WORTH
\$98

Participating Brands:
3P YOKOHAMA
Q ROADSTONE
Bridgestone
Firestone

Terms and conditions apply.



Toyota Mark X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details


Price	\$17,800	
Depreciation	-	?
Reg Date	12-Jun-2009 (3mths 9days COE left)	
Manufactured	2008	?
Mileage	135,000 km (13.9k /yr)	
Transmission	Auto	
Engine Cap	2,499 cc	
Road Tax	\$1,798 /yr	?
Power	158.0 kW (211 bhp) View specs of the Toyota Mark X (2005-2011)	
Curb Weight	1,500 kg	?
Features	Powerful 2.5L V6 VVT-i Engine, Smooth 6 Speed Auto Transmission, Rear Wheel Drive, ABS, SRS Airbags, Dual Zone Climatic Aircon And Immobilizer.	
Accessories	100% Original Factory Condition.	
Description	Careful Owner's Reluctant Sale. Well Kept And Mostly Shelter Parked. Almost New Tires For Intended COE Renewal. Original Paintwork And Clean Interior. Reasonable Pricing For Your COE Renewal Direction! Viewing Available Daily Via Appointment Only.	
COE	\$5,700	?
OMV	\$25,422	?
ARF	\$25,422	?
Dereg Value	\$12,869 as of today (change)	?
No. of Owners	3	?
Type of Veh	Luxury Sedan	
Category	PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 28-Feb-2019 | Last Updated on: 28-Feb-2019



Location Map

Seller Information

Company	Kimhung Hegary & Co Pte Ltd » dealer's pricelist » 12 vehs sold 5 vehs available
Address	18 Sin Ming Lane #02-09 Search cars nearby this location
Location	Midview City
Office No	66100055

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

63975920
 (Bor Bi) (Zi wei)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 17:29
Date Of Accident	23/02/2019 21:00
Exact Location Of Accident	NEW BRIDGE ROAD BEFORE TEMPLE ST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS1734R
Insured/Policyholder	
Name Of Registered Owner	LOK YIM FUN
NRIC No	S7303538D
Email Address	COREEN_LOK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98572325
Alternative Phone No	OTHERS-98572325
Vehicle Particulars	
Manufacturer	TOYOTA
Model	MARK X
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80435602 QMX
Cover Note Number	
Driver	
Name of Driver	MARCUS NEO
NRIC No	S9214929G
Date Of Birth	02/05/1992
Occupation	INDOOR
Date Of Driving Pass	10/10/2012
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81330832
Fax Number	
Contact Number	
EEmail Address	MARCUSNZT@GMAIL.COM

Address	50 CHOA CHU KANG NORTH 6 #18-06 SINGAPORE
Postcode	689574
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: <input type="checkbox"/> JADE LEE GENDER: <input type="checkbox"/> FEMALE
Passenger 2	NAME: <input type="checkbox"/> NG JIE MING GENDER: <input type="checkbox"/> MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EH1000S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KIMBERLY TAN ROU QI
NRIC/Passport Number	S9240101D
Contact Number	96340056
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

25/2/19
4:56 p.m.

Driver's Signature
(If driver is not the policyholder)
Date & Time:


25/2/19
4:56 p.m.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]

A = SJS 1734R
B = EH 1000S

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Saturday 23/2/2019 at 2:00 hours along New Bridge Road before Temple Street I was travelling at 50-60 km/h at low ^{brake} my front car ~~stuck~~ and I follow to brake suddenly, my rear car p ~~fall~~ (EH 1000S) suddenly, the car behind me crash into my rear (SJS1734R) and get cause my bumper broken. She already admitted was her fault.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

23/2/19
4:50 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

23/2/19
4:50 PM

Reporting Centre Personnel's Signature

Name:

NRIC/EIN No.:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

ERGO INSURANCE PTE LTD

Ref: CS/EGI19003721/Ecd3e2

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: 04-04-2019
FIVE SINGAPORE 038985

Code: EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EH 1000S	Veh. Inspected	SJS 1734R
Policy No.		Coverage (\$)	0.00
Claim No.	CDMPG19000307	Excess (\$)	0.00
Assign From	JEANNIE CHENG	Assign Date	26/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA MARK X	c.c	2499
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GRX1203068160	Colour	WHITE
Odometer	174398 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	23/02/2019	Inspect Date / Time	01/03/2019 (06:07 PM)
Survey held at	B'S PERFORMANCE PTE LTD 7 SOON LEE STREET ISPACE #01-38 SINGAPORE 627668		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

Report Ref No. CS/EGI19003721/Ecd3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.