

2/20/19

ASS. REC. BY:

REF

CS3/CTI19003725/Ecd367

Ref Instruction:

Sub Veyor:

Steve

ASSIGNMENT (Office)

From (Person)

Irene Tay

of

CTI

Date/Time:

27/2/19 @ 11:30am

Estimated Cost:

Bill to:

OD (T) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 4174C

Insured:

SLL 9757K

at Workshop n/a

Messrs Demick Motor

Tel:

96333593

of

Blk 9002; Tampines st-93 #01-72 Tampines Ind. park A

Policy No:

DMHCSN17216818011

Claim No:

SNM19D200948C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

23/02/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:52pm @ 27/2/19

Person Contacted:

Jeremy

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLB 4174C - X
	SLL 9757K - X
	Dismantle: 1/3/2019
	After repair: 2/3/2019

Stone

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

X	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLB 4174C** Vt Regn: **7/94/16**
 Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **KIA Forte** cc: **1.6 (1591cc)**
 Colour: **Grey** A/C Insured / Std / NI / NA
 Sp. Reading: **78491** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **KNAF241MGS609740**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: Nil / **S/Rim** / STD A/Rim or
 Tyre Size: F: **225/45R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Film 29**
 Front: _____ Rear: _____
 R/Bal. **7** mm R/Bal. **7** mm
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **23/2/19** D.O.I. **27/2/19**
 Survey held at **Deereck Motor**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH front LH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction
Repair range 3K-4K, 4 days

[Signature]
20/3/2019.

Date/Time, File Pass to? : Prel. Report

4) : Final Report

Date/Time, File Return to?

2)

Report Format: **PRE**

Lump Sum / I.B.F. (\$) _____

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee: **190**

Transportation

) S + R5 St

) Photos

) Other

)

TOTAL

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		03 Jun 2019 09:19 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant: ONG KOON BENG , ID: S1428642Z									
Vehicle Reg. No.: SLB4174C		Date of Loss: 23/02/2019 21:00 - :59							
Claim Type: TP / SNM19D200948C02		Policy/Cover Note No.: DMHCSN17216818011							
Vehicle Reg. No. (Insured): SLL9757K		Policy No. (Claimant): S1428642Z							
		Excess: S\$0.00							
Repairer: Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A, 528836 Tampines - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/06/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 27 February 2019 11:28 AM
To: Elaine Toh
Cc: assignments; Admin A
Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

As you have agreed to our list of surveyors.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Elaine, Vision Law.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Wednesday, 27 February, 2019 11:18 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

Importance: High

Our Ref: SLB 4174 C (et)
WITHOUT PREJUDICE

Dear Irene,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:

1. Dennis Yap - PAL's Appraiser Pte Ltd

Please reply within 2 working days.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLB 4174 C – By email only

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: Wednesday, 27 February, 2019 11:13 AM

To: Elaine Toh

Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN

XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Thank you.

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Wednesday, 27 February, 2019 10:51 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>

Subject: FW: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

Importance: High

Our Ref: SLB 4174 C (et)
WITHOUT PREJUDICE

Dear Irene,

We refer to the above matter and our email on 25 February 2019.

Kindly note that the PRS is due today.

Please let us have your propose list of surveyors urgently.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]
Sent: Tuesday, 26 February, 2019 10:38 AM
To: 'claimsdept@sg.cntaiping.com'
Subject: FW: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS
Importance: High

Our Ref: SLB 4174 C (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to our email on 25 February 2019.

Please let us have your propose list of surveyors urgently.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]
Sent: Monday, 25 February, 2019 4:34 PM
To: 'claimsdept@sg.cntaiping.com'
Subject: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS
Importance: High

Our Ref: SLB 4174 C (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **ONG KOON BENG** to notify you of a road traffic accident on 23 February 2019 at about 2130 hours at carpark along Block 736 Tampines Street 72 involving our client's vehicle registration number SLB 4174 C and vehicle registration number SLL 9757 K driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLB 4174 C – By email only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC
Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Elaine Toh <Elainetoh@visionlawllc.com>
Sent: Wednesday, 27 February 2019 11:30 AM
To: 'Irene Tay'
Cc: 'assignments'; 'Admin A'
Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

Importance: High

Our Ref: SLB 4174 C (et)
WITHOUT PREJUDICE

Dear Irene,

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle {Kia Forte K3-1.63 (A)} can be inspected at:

**Messrs Derrick Motor Works
Blk 9002 Tampines St 93
#01-72, Tampines Ind Park A
Singapore 528836
Attention: Mr Jeromy – HP 9633 3593**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.



Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

FOR SURVEYOR	
Please initial here after completion of pre-repair inspection. Thank you.	
Appointed surveyor (Name & Signature)	:
Date & Time of Inspection	:

cc: SLB 4174 C – By email only

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]
Sent: Wednesday, 27 February, 2019 11:28 AM
To: Elaine Toh
Cc: assignments; Admin A
Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SLB 4174 C AND SLL 9757 K ON 23 FEBRUARY 2019 AT CARPARK ALONG BLOCK 736 TAMPINES STREET 72 AT ABOUT 2130 HOURS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8642Z
Vehicle Details	
Vehicle No.:	SLB4174C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A SX
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	G4FGGH612836
Chassis No.:	KNAFZ411MG5600740
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$16,747.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$16,747.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount:	\$12,560.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$32,356.00
Total Rebate Amount:	\$44,916.00

The information contained herein is correct as at 27 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 13:21
Date Of Accident	23/02/2019 21:30
Exact Location Of Accident	BLK736 TAMPINES ST 72 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4174C
Insured/Policyholder	
Name Of Registered Owner	ONG KOON BENG
NRIC No	S1428642Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96486391
Alternative Phone No	OTHERS-96486391

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S1428642Z
Cover Note Number	

Driver

Name of Driver	ONG CHIN TIN
NRIC No	S7611907D
Date Of Birth	26/04/1976
Occupation	INDOOR
Date Of Driving Pass	30/03/2000
Driving Experience	18 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96800220
Fax Number	
Contact Number	
EMail Address	ERICONG76@YAHOO.COM.SG

Address	BLK167A PUNGGOL EAST #05-413
Postcode	821167
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG YI XUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN AND POLICE REPORT ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL9757K
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RUSSAEL TAN YEH WEN
NRIC/Passport Number	S9338988C
Contact Number	97432411

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: 25/2/19

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20190225/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No. T/20190225/7014

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/02/2019 12:41	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: ONG CHIN TIN		Address: APT BLK 167A PUNGGOL EAST #05-413 SINGAPORE 821167	
ID Type / ID No.: NRIC NO / S7611907D		Contact No.: Home/Office: Mobile: 96800220	
Nationality: SINGAPORE CITIZEN		Email: ericong76@yahoo.com.sg	
Sex: Male	Age: 42	Date of Birth: 26/04/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Telecommunications engineer		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/02/2019 21:30	Type of Location: Car Park
Location: TAMPINES STREET 72				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 30 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLB4174C	Car	KIA	k3	Grey	Seriously Damaged	1
SLL9757K	Car	HONDA	VEZEL	Black	Seriously Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLB4174C	NTUC Income Insurance Co-Operative Limited	5100320166	30/04/2018	29/04/2019



**SINGAPORE
POLICE FORCE**



T/20190225/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20190225/7014

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ONG CHIN TIN	ID No.	S7611907D
Related Vehicle	SLB4174C (Car)	Contact No.	96800220
Hospital/Clinic	TAMPINES 24-HR FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	23/02/2019	Date Discharge	23/02/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious
Driver			
Name	RUSSAEL TAN YEH WEN	ID No.	S9338988C
Related Vehicle	SLL9757K (Car)	Contact No.	97432411
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was driving along beside block 736 Tampines St72 towards the car park gantry out when Vehicle SLL9757K move ahead from the rubbish chute point and collided with the front passenger side of my vehicle SLB4174C. The driver of SLL9757K came out of his vehicle and apologized to me after the incident saying he was careless and did not noticed my vehicle. We exchanged particulars and left the scene.

I suffered from neck and back pain and got a 3 days mc from Tampines 24-hr Family Clinic Pte Ltd.

Sketch Plan Pg. 5



**SINGAPORE
POLICE FORCE**



T/20190225/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190225/7014

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 25/02/2019 12:41
Officer In Charge Of Case: TP / TPHQ / SITIMARSITA BINTE BOHARI Contact No.: 65476219	Classification Of Case:

Authentication Stamp
NP168

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		03 Jun 2019 09:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	ONG KOON BENG , ID: S1428642Z			
Vehicle Reg. No.:	SLB4174C	Date of Loss:	23/02/2019 21:00 - :59 [34 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D200948C02	Policy/Cover Note No.:	DMHCSN17216818011	
Vehicle Reg. No. (Insured):	SLL9757K	Policy No. (Claimant):	S1428642Z	
		Excess:	S\$0.00	
Repairer:	Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A, 528836 Tampines - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/06/2019]			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLB4174C (SNM19D200948C02)
[SLL9757K]
TP
ONG KOON BENG
Feb 23 2019 9:00PM
[-]
Derrick Motor Works

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/> Print <input checked="" type="checkbox"/>
1	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
22	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
23	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
24	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
25	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
26	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
27	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
28	06/06/19 14:38	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
29	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
30	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
31	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
32	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
33	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
34	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
35	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
36	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
37	06/06/19 14:39	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 14:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 14:40	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	25/02/19 13:39	Accident Statement	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 13:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input type="checkbox"/>
---------------	--	--	------------	--------------------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		Falcon-Air Auto Services Pte Ltd (Tampines)			<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)		Thumbnail	Print
1	25/02/19 13:39	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19003725/ECD3E2

Date: 07/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN17216818011

Claimant Vehicle No: SLB4174C Insured Vehicle No: SLL9757K

Date of Loss: 23/02/2019 Nature of Claim: TP Claim No: SNM19D200948C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB4174C**

Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH612836

Reg. Date: 07/04/2016 (Man. Year: 2016) Chassis No: KNAFZ411MG5600740

Colour: Grey Odometer: 78401 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7 mm

Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 27/02/2019 Inspected At: Derrick Motor Works (HQ)
9002 Tampines St. 93, #01-72 Tampines Industrial Park A
Singapore 528836

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2019)
Parts: 143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4174C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >