

ASS. REF. BY

REP: 08/FCI/1003727/Evd3^{N2} (Spec of Instruction)

Sold by/for: Steve

ASSIGNMENT (Office)

From Person: AWS
Suzene fur

of: PET

Date/Time: 2:33pm 27/2/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SBM 9898A

Insured: SHA 3569G

at Workshop n/s: cycle & Camrage Kia
209 pondich Garden

Tel: 65684501

Policy No: Claim No: D19001222MF84

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A: 16/2/19

CA / REV / REP. / REV 24 HRS ^{imp}

H.O.D. Enforcement:

Date/Time: 2:54pm 27/2/19 Person Contacted: Edwin

Vehicle-IN/OUT: (OUT)

Date/Time	Action/Instruction (-) Estimate
12/4/19	Email preli revised to FCI
7/6/19	final fig \$ 2256 confirmed by email (Ref 2578, 5379)

Steve

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: **SBM 9898A** Yr Regn: **22/6/18**

Type: **M,Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **KIA Sorento** CC: **2199**

Colour: **White** A/C: Insured / Std / NI / NA

Sp. Reading: **10806** T/Ratio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: **KNA PH 81 BMJS465581**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: Nil / **S/Rim** / STD A/Rim or

Tyre Size: F: **235/60R18**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / **YOKO** or

Front: _____ Rear: _____

R/Bal. **7** mm R/Bal. **7** mm

L/Bal. **7** mm L/Bal. **7** mm

D.O.A. **16/2/19** C/C D.O.I. **11/4/19**

Survey held at: **C/C**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or **Rear RH**

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

RECEIVED 10 JUN 2019

Date/Time. File Pass to: : Prel. Report
 : Final Report

Date/Time. File Return to?

2) **1/6 - typist**

Report Format :

Lump Sum / I.B.L. (\$) **CWS 2256/2**

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation

) G-R: 21

) Photos

) Labor

)

TOTAL

135
50
50
21
256



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001222MFSH

Our ref: CS/FCI19003727/Evd3

Date : 12/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SBM 9898A


We thank you for your instruction on 27/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/4/2019 at the premises of M/s CYCLE & CARRIAGE KIA PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,834.00
Revised Estimate Amount	: S\$2,490.00
"Check" Items Amount	: S\$585.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-02-2019	Our Ref No. D19001222MFSH
Accident Date	16-02-2019	Claim Type. Third Party
Insured Vehicle	SHA3569G	Third Party Vehicle. SBM9898A
Survey Location	209 PANDAN GARDENS	
Contact Person.	EDWIN CAINA	
Contact No.	65684501/ 91819978	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT: EST. COR - \$5,172.38	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 7 June 2019 5:05 PM
To: Loi Ai Ting; Don Bong Kiong Hua; Tay Jian Ye; Songcuan JR Lauro Araos; Coco Lu Ting; Andre Chow En De; Cheng Jo Jo; SUR
Subject: RE: SBM9898A, finalisation (Kia WIP: 45158)

Dear Ms Loi,

WITHOUT PREJUDICE

Confirm finalised amount at \$2256 before GST @ 3 working days

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Sent: Friday, 7 June 2019 1:24 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>
Subject: SBM9898A, finalisation (Kia WIP: 45158)

Hi, Veron,

Please confirm finalised amount at \$2,413.92.

Attached photos for your reference.

Thanks.

Best Regards,

Loi Ai Ting
Customer Service Advisor



Exceptional Journeys



From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Friday, 7 June, 2019 11:47 AM

To: Don Bong Kiong Hua; Tay Jian Ye; Loi Ai Ting; Songcuan JR Lauro Araos; Coco Lu Ting; Andre Chow En De; Cheng Jo Jo

Subject: RE: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)
- 2) SBM 9898A-DOA: 16/2/2019 (FIRST CAPITAL TP)
- 3) SCQ 929X- DOA: 13/3/2019 (FIRST CAPITAL TP)
- 4) SMA 3559B-DOA: 14/1/2019 (EGRO TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 29 May 2019 12:09 PM

To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>

Subject: RE: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)
- 2) SBM 9898A-DOA: 16/2/2019 (FIRST CAPITAL TP)
- 3) SCQ 929X- DOA: 13/3/2019 (FIRST CAPITAL TP)
- 4) SMA 3559B-DOA: 14/1/2019 (EGRO TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 22 May 2019 4:46 PM

To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>

Subject: RE: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)
- 2) SBM 9898A-DOA: 16/2/2019 (FIRST CAPITAL TP)
- 3) SCQ 929X- DOA: 13/3/2019 (FIRST CAPITAL TP)
- 4) SMA 3559B-DOA: 14/1/2019 (EGRO TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 18 April 2019 5:44 PM

To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>

Subject: RE: PENDING FINALISE (3 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)

- 2) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 3) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 27 March 2019 1:34 PM

To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; 'Songcuan JR Lauro Araos' <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>

Subject: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)
- 2) SMF 8728X-DOA: 2/1/2019 (CHINA TAIPING TP)
- 3) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 4) SLM 2369M-DOA: 19/1/2019 (CHINA TAPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 12 April 2019 3:31 PM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001222MFSH/1, SBM 9898A
Attachments: SBM 9898A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBM 9898A
Date of survey: 11/4/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 27 February 2019 4:59 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <SereneLer@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001222MFSH/1

Dear Sir/Mdm

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 27 February 2019 2:32 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001222MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tay Sook Muay
Period of Insurance : 22 Jun 2018 To 21 Jun 2020
Engine No. : D4HBJH373798
Chassis No. : KNAPH81BMJ5465581

Vehicle No. : SBM9898A
Policy No. : 1800072362
Endorsement No. :
Issued Date : 04 Jul 2018

ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL
Engine Capacity/Tonnage : 2,199.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tay Sook Muay - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65694501
- Cycle & Carriage Authorised Service Centre Add: 241 Alexandra Road Singapore 159931 64278800
- Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624208

FULCOKICP2 - LN
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

36CS28



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
 PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



LKK Auto Consultants hence notify
 Co Reg No **199405410K** the following:
 Invoice Name & Address
 TAY SOOK MUAY
 10 CHENG SOON GARDEN
 SINGAPORE 599790
 Acknowledged by Repairer
 Contact No Mobile: 90084528
 Signature:
 Date:

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
<ul style="list-style-type: none"> To resurvey damaged portion during resurvey To display damaged portion during resurvey Part of estimate is subject to confirmation Third party survey is on a "Without Prejudice" basis No liability for consequential damage Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company 		Cust No/Name	LCV05947/TAY SOOK MUAY
		Reg No/Reg Date	SBM9898A / 22/06/201
		Date In/Mileage	/ 0
		Chassis No	KNAPH81BMJ5465581
		Engine No	D4HBJH373798
		Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
		Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	22/02/2019/ 12:45	QUE	261 / Edwin Caina	45158

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN RR DAMAGED PORTION: -RENEW RR BUMPER -REPAIR RR FENDER RH				✓ 550 1650.00
E PNT98000 RESPRAY RR BUMPER & RHR FENDER				✓ 470 900.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				✓ / 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ / 200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				X 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				✓ 80 100.00
M SUNDRY Sundries <i>ncc</i>				✓ 20 50.00
M COVER-RR BUMPER,UPR - CUT / DD	1.00	454	605.00 00.00	605.00
M COVER-RR BUMPER LWR - CUT	1.00	452	565.00 00.00	565.00
M COVER-BLANKING RR FOG,RH	1.00		44.00 00.00	44.00
M LAMP ASSY-REAR FOG & R/REFL,RH	1.00		129.00 00.00	129.00
M BRACKET-RR BUMPER SIDE LWR,RH	1.00		13.00 00.00	13.00
M BRACKET ASSY-RR BUMPER SIDE,RH	1.00		25.00 00.00	25.00
M ULTRASONIC SENSOR ASSY-BWS	2.00		187.00 00.00	374.00
M GARNISH ASSY-QTR SIDE,RH X	1.00		49.00 00.00	49.00

Estimate

SURVEYOR NAME: Sten (LKK)SURVEYOR SIGNATURE: [Signature]DATE: 11/4/19 3:15pmREMARKS: P/P Rej before spray

3 days

Confirm & accepted by [Signature]

7% GST on	Nett	4,834.00
	4834.00	338.38
Total Payable		5,172.38

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : STEVE LKK
 Claim : TP FIRST CAPITAL
 DOA : 16.02.2019
 Emailed : 07.06.2019, 1.30pm
 Date survey : 11.04.2019

VEHICLE NO : SBM 9898 A
 MODEL : KIA SORENTO 2.2 A D SX
 WIP : 45158

Material	:	\$	<u>936.00</u>
Labour	:	\$	<u>1,320.00</u>
Sub-Total	:	\$	<u>2,256.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2,256.00</u>
GST 7%	:	\$	<u>157.92</u>
Grand Total	:	\$	<u>2,413.92</u>
Finalise By/Date	:		<u>LOI / 07/06/2019</u>

REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 5


TP claim SHA3569G

Claim GIA / LTA fee _____

Claim Loss of Use / Rental

Claim Medical Fee / Others _____

Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited Motor Claims Department 36 Robinson Road #16-01 City House Singapore 068877 Contact No 11/04/	Cust No/Name	LCV05947/TAY SOOK MUAY
	Reg No/Reg Date	SBM9898A / 22/06/2018
	Date In/Mileage	11/04/2019/ 10806
	Chassis/Package	KNAPHB1BMJ5465581 /FS215N
	Engine No	D4HBJH373798
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	07/06/2019/ 13:10	TLE	260 / AiTing	45158

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 420.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 50.00
A 10028901 CONDUCT DIAGNOSTIC CHECK-USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 80.00
M SUNDRY SUNDRIES				✓ 20.00
X COVER-RR BUMPER,UPR	1.00	✓ 605.00	20.00	484.00
X COVER-RR BUMPER LWR	1.00	✓ 565.00	20.00	452.00
Z TEXT TP CLAIM FIRST CAPITAL SHA3569G DOA : 16.02.19 SURVEYOR STEVE LKK 11.04.19 REPAIR 03 DAYS				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	936.00		Nett	2,256.00
Labour	1,300.00	7% GST on	2256.00	157.92
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	2,413.92
Diagnostics Job	0.00			
Sundry/Others	20.00			
Total(w/o GST)	2,256.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003727/Evd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3569G	Veh. Inspected	SBM 9898A
Policy No.		Coverage (\$)	0.00
Claim No.	D19001222MFSH	Excess (\$)	0.00
Assign From	SEENE LER	Assign Date	27/02/2019
2. Vehicle Particulars & Condition			
Make & Model	KIA SORENTO	c.c	2199
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAPH81BMJ5465581	Colour	WHITE
Odometer	10806	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	YOKOHAMA	7 mm
L/H Front Tyre	235/60 R18	YOKOHAMA	7 mm
R/H Rear Tyre	235/60 R18	YOKOHAMA	7 mm
L/H Rear Tyre	235/60 R18	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/02/2019	Inspection Date	11/04/2019
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBM 9898A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER,UPR (SN)	CUT / DENTED	605.00	484.00
1	COVER-RR BUMPER,LWR (SN)	CUT	565.00	452.00
1	COVER-BLANKING RR FOG,RH (SN)	NOT NECESSARY	44.00	-
1	LAMP ASSY-REAR FOG & R/REFL,RH (SN)	NOT NECESSARY	129.00	-
1	BRACKET-RR BUMPER SIDE LWR,RH (SN)	NOT NECESSARY	13.00	-
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	NOT NECESSARY	25.00	-
2	ULTRASONIC SENSOR ASSY-BWS (SN)	NOT NECESSARY	374.00	-
1	GARNISH ASSY-QTR SIDE,RH (SN)	NOT NECESSARY	49.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			1,854.00	956.00
LABOUR				
RENEW & RE-ALIGN RR DAMAGED PORTION: -RENEW RR BUMPER. -REPAIR RR FENDER RH.			1,650.00	550.00
RESPRAY RR BUMPER & RHR FENDER.			900.00	420.00
CHECK WIRING ELECTRICAL SYSTEM.			50.00	50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
APPLY ANTI CORROSION ON AFFECTED AREAS.		NOT NECESSARY	80.00	-
REMOVE & REFIT REVERSE SENSOR.			100.00	80.00
			2,980.00	1,300.00
GRAND TOTAL			4,834.00	2,256.00
RECOMMENDED COST OF REPAIRS				2,256.00

Report Ref No. CS/FCI19003727/Evd3n2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.