

ASS. REC. BY:

REF:

CSB/AIG 19003729/US03<sup>SP</sup>

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

H. Yinnul

of

AIG

Date/Time: 27/2/19 @ 2:15pm

Estimated Cost:

Bill to:

OD ☒ TT / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 2354R

Insured:

8JW688B

at Workshop in/s

G.L. AUTO

Tel:

9670 6475

of

Bik 6 Defu lane 10 # 01-550

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/02/2019

After 12pm @ 28/2/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lup

Date/Time:

3:02pm @ 27/2/19

Person Contacted:

Mr. Lee

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

Marus

REF: AIG

DATE: 28/2/19

Date: 28/2/19  
 Estimated Cost:  
 OD: ☒ WS / ☐ TR RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
 Correspond Vehicle No: SKR 2354R  
 at Workshop/mile: G.L. Auto  
 at: Blk 6 Defu lane 10 # 01-550  
 Insured:  
 Policy No:  
 Claim No:  
 Sum Insured:  
 (Client's Record)  
 Make of Vehicle:


Veh No: SKR 2354R  
 Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
 Truck / Trailer or: CA/  
 Make: Mercedes 2280KL  
 Colour: S/W  
 Sp. Reading: 72654  
 Eng/Ho:  
 Chassis: W09V97226YLB.77011  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Mod: ☒ Nil / ☐ SRim / ☐ STD A/Rim or  
 Tyre Size: F: 225/55-217  
 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / ☒ ONTSU / PIR / SUMI /  
 TOYO / YOKO or

Front: 6 mm  
 R/Bal: 6 mm  
 L/Bal: 6 mm  
 D.O.A: 15/2/19  
 Survey held at: 28/2/19  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 0/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value:  
 IDAC Accident Report: Consistent? : Yes or No  
 GIA / PR. Seen: Consistent? : Yes or No  
 Est. Repairs: 4 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS up 4503m  
 Date: Person Contacted: Vehicle: IN / OUT



Date / Time: 9/3/19  
 Action / Instruction: Confirmed A/S & 4700 with MR Lee  
 (2.5% 17 - Rd 34%)

RECEIVED 11 MAR 2019

Date/Time: File Pass to:  
 11/03/19  
 Typist:  
 Date/Time: File Return to:

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Add Fee:  
☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech Invs (\$)  
☐ Weekend (\$)

Survey Fee: 250  
 Transportation:  
 ) G + RS: 50  
 ) Hubs:  
 ) Other:  
 ) :  
 TOTAL: 10

Report Format:  
 Lump Sum / L.B.L: (\$ 4,700/- H/S)

**FW: – Pre-Repair Inspection Request – SKR2354R vs SJW688B (OI) on D....**

From: Hor, Yinrul

To: 'assignments@lkkauto.com', admin-d@lkkauto.com, Admin A (admin-a@lkkauto.com)

Cc:

Sent: 27/2/2019 2:15:36 PM

Attachments:  Letter to AIG - 26.02.19.pdf

---

Resend – with attachment

---

**From:** Hor, Yinrul

**Sent:** Wednesday, February 27, 2019 1:46 PM

**To:** 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

**Subject:** aigencrypt – Pre-Repair Inspection Request – SKR2354R vs SJW688B (OI) on D.O.A.: 15/02/2019

Hi,

Please refer to the enclosed request from **Chambers Law LLP**.

Claim no : 3001839522SG003

Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.

*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Jovine Tan [mailto:jt@chamberslaw.com.sg]

**Sent:** Tuesday, February 26, 2019 4:55 PM

**To:** Hor, Yinrul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

**Subject:** Pre-Repair Inspection - Accident on 15.02.19 involving SKR 2354R and SJW 688B

Our Ref: CCL.jt.190203 GLA

Dear Sirs,

Please find attached herewith a copy of our letter to you of even date for your attention.

Yours Sincerely,

*Jovine Tan*

Legal Executive

**For and on behalf of Ms. Lew Chen Chen**

**Chambers Law LLP**

(Limited Liability Partnership UEN T07LL1103A | GST Registration No. M90367219Y)

45 North Canal Road #05-01 Lew Building Singapore 059301

Tel: (65) 65353 234 | Fax: (65) 65353 502 (Not for service of court documents)

Contents of this letter may consist of private confidential and/or privilege information which are not to be distributed. Kindly inform us if you are not the intended recipient.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

健  
博

律  
師  
行

# Chambers Law LLP

Advocates & Solicitors, Commissioner for Oaths & Notary Public  
(Limited Liability Partnership UEN T07LL1103A GST Registration No. M90367219Y)  
45 North Canal Road #05-01 Lew Building Singapore 059301  
Tel: (65) 65353 234 Fax: (65) 65353 502 (Not for service of court documents)  
Website: www.chamberslaw.com.sg

Managing Partner  
柳清清

LEW CHEN CHEN

Master of Laws (UK)

Barrister-At-Law (Lincoln's Inn)

BA (Hons) Law & Accounting (UK)

Email: cclew@chamberslaw.com.sg

Senior Partner

李济彬

LEE CHAY PIN, VICTOR

LLB (Hons) (Spore)

Email: victor@chamberslaw.com.sg

Associate

陈静娴

CHARMAINE JIN JING XIAN

BA Law & Business Studies (Hons)(UK)

Email: cj@chamberslaw.com.sg

Associate

蔡凯雯

DILYS H CHUA

LLB (Hons) (UK)

Email: dilys@chamberslaw.com.sg

Our Ref: CCL.jt.190203 GLA  
Your Ref: 3001839522SG003

26 February 2019

**BY EMAIL (yinrul.hor@aig.com) & POST ONLY**

AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Department  
78 Shenton Way  
#07-16 Chartis Building  
Singapore 079120

Attention: Ms. Viviane Hor

Dear Sirs

**ACCIDENT ON 15.02.19 INVOLVING SKR 2354R & SJW 688B**

1. We refer to your email dated 26 February 2019.
2. We have our client's instruction to appoint Mr. Marcus Chua of LKK Auto Consultants Pte Ltd as the single joint expert to conduct the pre-repair survey of our client's vehicle.
3. Kindly be informed that the pre-repair survey can be conducted at the workshop of GL Auto at **Blk 6 Defu Lane 10, #01-550 Defu Industrial Park C, Singapore 539187** within **two (2) working days** from 27 February 2019, between 9.00am to 6.00pm by prior appointment.
4. Please contact Mr. Lee Tiong Wan at 9670 6475 for an appointment.
5. Thank you.

Yours faithfully,



Dilys H Chua

c.c. Client

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/02/2019 15:00
Date Of Accident	15/02/2019 20:30
Exact Location Of Accident	GEYLANG LOR 25A ALJUNIED MRT OPEN CP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR2354R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WEE LEONG REALTY PTE LTD
Co Reg No	-
Email Address	WEELEONGRPL@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98187772

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E280T

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	LEW CHEE YIAN
NRIC No	S7202902Z
Date Of Birth	02/01/1972
Occupation	OUTDOOR
Date Of Driving Pass	21/08/1990
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98187772
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	25 JALAN SENYUM S418150
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW688B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

WEE LEONG REALTY PTE LTD

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Accident Sketch Plan Pg. 1

## SKETCH PLAN



A: SKR2354R

B: SJW688B

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS I WAS NEGOTIATING THE BEND AT THE CARPARK. I NOTICE VEHICLE B PARK AT THE DOUBLE YELLOW LINE ALONG THE BEND, OBSTRUCTING TURNING VEHICLE SUCH THE SPACE WAS LIMITED. DUE TO MY LONG VEHICLE, THE REAR RIGHT SIDE OF MY VEHICLE BRUSHES ONTO VEHICLE B'S LEFT SIDE PORTION.

VEHICLE B'S DRIVER FORCE ME TO SIGN AN ADMISSION LETTER WHICH WAS WRITTEN BY HIM AND HE WAS VERY AGGRESSIVE AS I DO NOT UNDERSTAND ENGLISH. HE ALSO FORCE ME TO GIVE HIM MY NRIC & DRIVING LICENCE BUT HE REFUSE TO GIVE ME HIS PARTICULARS.

### DECLARATION

I, HEREBY DECLARE that:-

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.

Name, Signature & Company  
Stamp (if applicable)

INSURER: AIG

VEHICLE: SKR2354

DOA: 15/02/2019

CLAIM TYPE: REPORTING

WORKSHOP: NA

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

WEE LEONG REALTY PTE LTD

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : Lew Che Yian  
VEHICLE NUMBER : SKR 2354R  
DATE/TIME OF ACCIDENT : 15/2/19 @ 8.30 pm  
PLACE OF ACCIDENT : Lor 25-A Geylang Open CP  
THIRD PARTY VEHICLE (IF ANY) : SJW 688B

\*\*\*\*\*

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

Salan Senyum - Geylang

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

NO

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Car park Collision

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO

Name: 

I Affirmed The Above Information Is Given To My Best Knowledge.

1



## POLICY SCHEDULE

## PRIVATE AUTO THIRD PARTY ONLY PRIVATE VEHICLE

Policy No. : 2100313610-06

Period of Insurance : 18 Sep 2018 to 17 Sep 2019

Issued Date : 06 Aug 2018

## ABOUT THE POLICYHOLDER

Name of Policyholder : WEE LEONG REALTY PTE LTD  
 Address : 25 Jalan Senyum  
 SINGAPORE 418150

Occupation/Nature of Business : Real Estate

## ABOUT THE VEHICLE

Registration No. : SKR2354R Engine Capacity/Tonnage : 2,799.00 CC  
 Chassis No. : W09V97226YLB77011 Engine No. : 11292130685682  
 Seating Capacity : 5 First Year of Registration : 2002 Body Type : Sedan  
 Make/Model : MERCEDES BENZ E280T  
 Hire Purchase Company/Employer's Loan : NA

## ABOUT THE COVER

Sum Insured : NA Off Peak Car : No  
 Driver Restriction : NA Insuring with COE/PAF : NA

Person or Classes of Persons Entitled to Drive :

And persons who will drive on the Policy after endorsement with their permission.  
 This Policy will indemnify the Policyholder or any authorized driver only the sum insured for the specified circumstances.

Age Condition : Not Applicable  
 Limitation as to use :

Exclusively for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving by hire, emergency, racing, drive-in racing, trial, display, or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Vehicle.

Other Key Policy Benefits :

EXCESS	PREMIUM
Section 1	Premium : \$ 707.26
	GST (7%) : \$ 49.51
Section 2 Property Damage - \$0	Total : \$ 756.77
Windscreen : NA	
	Your Premium includes the following discount(s): No Claim Discount - 50%

Page 1 of 1

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4503M
Vehicle Details	
Vehicle No.:	SKR2354R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Feb 2019
Vehicle Make:	BINZ
Vehicle Model:	E280XL AUTO
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	11292130685682
Chassis No.:	W09V97226YLB77011
Maximum Power Output:	-
Open Market Value:	\$91,233.00
Original Registration Date:	18 Sep 2002
First Registration Date:	18 Sep 2002
Transfer Count:	1
Actual ARF Paid:	\$118,603.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2022
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$86,410.00
COE Rebate Amount:	\$30,243.00
<b>Total Rebate Amount:</b>	<b>\$30,243.00</b>

The information contained herein is correct as at 28 Feb 2019

OK

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7202902Z



LEW CHEE YIAN  
(LIU ZHIYUAN)  
柳致远  
CHINESE  
02-01-1972 M  
SINGAPORE

REPUBLIC

DRIVING LICENCE



Licence Number: S7202902Z  
Name:

LEW CHEE YIAN  
(LIU ZHIYUAN)

Birth Date: 02 Jan 1972  
Issue Date: 26 Feb 2004



3139717



NRIC No: S7202902Z



Blood Group: A+ Date of issue: 23-03-2000

Address:  
25 JALAN SENYUM  
SINGAPORE 410150

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 21 Aug 1990



NP 428A

Accident Photo



# GL AUTO

Blk 6, Defu Lane 10, #01-550, Singapore 539187

Tel: 6383 0005 Fax: 62850823

Co. Reg. No.: 532162325L

SKR2354R

1 pc RH rear door	Subst	\$1893.90	—
1 pc <sup>Rear</sup> Door protector RH	DIS	\$150.87	—
1 pc <sup>Rear</sup> Door outer handle RH	grnd	\$395.90	—
1 pc RH rear fender <del>annel</del>	Subst	\$2300.50	—
To <sup>panel</sup> <del>panel</del> beating labour		\$1200.00	800
To remove and <sup>refix</sup> <del>fix</del> rear windscreen		\$180.00	120
To remove and <sup>refix</sup> <del>fix</del> back fuel tank		\$150.00	60
To putty & spray painting		\$800.00	700
Total		\$7071.17	

LKK Auto Consultants hereby notify the Reparer of the following:

- To carry out the repair work
- To ensure damaged parts are replaced
- To ensure all repairs are confirmed
- That the repair is on a "Without Prejudice" basis
- All damaged parts are replaced
- Supplementing parts must be recovered and is subject to final approval from Insurance Company

Acknowledged by Reparer:

Signature:

Date:

not Acknowledged  
2/8/18  
4 days  
28/2/18  
Take the other way

P- 4741.17  
4267.05  
4947.25



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Feb 2019 <a href="#">Edit Reg</a>		27 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TECK YONG LOH, ID: S7171951J		
Main Claimant:	-		
Vehicle Reg. No.:	SKR2354R	Date of Loss:	15/02/2019 00:00 - :59 [196 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3001839522SG	Policy/Cover Note No.:	1800040251 (Comprehensive)
Vehicle Reg. No. (Insured):	SJW688B	Policy No. (Claimant):	
		Excess:	
Repairer:	GL AUTO (HQ) BLK 6 DEFU LANE #01-550, 539187 Defu Lane - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/03/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (28/02/2019): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKR2354R (3001839522SG)**  
**[SJW688B]**

**TP**

**Feb 15 2019 12:00AM**




**[TECK YONG LOH]**











**GL AUTO**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/02/19 11:49	<b>Accident Statement</b> From: SC - Reg. No: SJW688B, Claimant: LOH TECK YONG	 Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 13:42	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 13:42	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	28/02/19 13:43	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	28/02/19 13:43	General View	 Load JPG	✓
33	28/02/19 13:43	General View	 Load JPG	✓
34	28/02/19 13:43	General View	 Load JPG	✓
35	28/02/19 13:43	General View	 Load JPG	✓
36	28/02/19 13:43	General View	 Load JPG	✓
37	28/02/19 13:43	General View	 Load JPG	✓
38	28/02/19 13:43	General View	 Load JPG	✓
39	28/02/19 13:43	General View	 Load JPG	✓
40	11/03/19 09:42	Reinspection Photo	 Load JPG	✓
41	11/03/19 09:42	Reinspection Photo	 Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003729/USD3S2  
Date: 12/03/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800040251  
Claimant Vehicle No: SKR2354R Insured Vehicle No: SJW688B  
Date of Loss: 15/02/2019 Nature of Claim: TP Claim No: 3001839522SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKR2354R**  
Make & Model: MERCEDES-BENZ E280, 2.8 (A) Engine No: 11292130685682  
Reg. Date: 18/09/2002 (Man. Year: 2000) Chassis No: W09V97226YLB77011  
Colour: Silver Odometer: 72654 km  
Engine Capacity: 2799 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,741.17	4,267.05	474.12	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,680.00	650.00	27.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,071.17</b>	<b>5,947.05</b>	<b>1,124.12</b>	<b>15.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,071.17</b>	<b>4,700.00</b>	<b>2,371.17</b>	<b>33.53</b>

## INSPECTION

Date of Assignment: 27/02/2019  
Date Inspected: 28/02/2019 Inspected At: GL AUTO (HQ)  
Singapore 539187  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Badly Dented	1,893.90 F	*1,893.90 FL
2	1		*REAR DOOR PROTECTOR RH	Distorted	150.87 F	*150.87 FL
3	1		*REAR DOOR OUTER HANDLE RH	Grazed	395.90 F	*395.90 FL
4	1		*RH REAR FENDER	Badly Dented	2,300.50 F	*2,300.50 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					4,741.17	4,741.17
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	474.12
Total Parts (S\$)					4,741.17	4,267.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEATING LABOUR.	New	1,200.00	800.00
2	TO REMOVE AND REFIX REAR WINDSCREEN.	New	180.00	120.00
3	TO REMOVE AND REFIX BACK FUEL TANK.	New	150.00	60.00
4	TO PUTTY & SPRAY PAINTING.	New	800.00	700.00
Gross Labour Cost (S\$)			2,330.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >