

ASS. REC. BY:

REF:

CS/AIG19003730/Krd307

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Hor, Yinru

of

AIG

Date/Time:

26/2/19 @ 5:10pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH1869M

Insured:

SLB4331R

at Workshop m/s

RC Auto

Tel:

97619383

of

160 Sin Ming Drive # 06-20

Policy No:

0999994758

Claim No:

54674307478G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:26am @ 27/2/19

Person Contacted:

Mr. Tan

Vehicle ~~IN~~ / OUT

Date/Time

Action/Instruction

(✓)

Estimate

5/3/19

LI & 8405A email & confirmed (Red 2185.90, 3590)

ASS. REC. BY:

REF:

1/6/1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBH 1869

Mfr Regn:

02, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

NIS NV200

c.c

1461

Colour:

N. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

35205

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 2070156375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/2/19

D.O.I.

27/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 05 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

menmen

Lump Sum / I.B.I. (\$

4050/=

10

260

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019 Edit Reg		27 Feb 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA			
Main Claimant:	-			
Vehicle Reg. No.:	GBH1869M	Date of Loss:	22/02/2019 00:00 - :59	
Claim Type:	TP / 5467430747SG	Policy/Cover Note No.:	0999994758 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLB4331R	Policy No. (Claimant):		
		Excess:		
Repairer:	RC AUTO (HQ) 18 Sin Ming Industrial Estate Sector A, #01-43, 575676 Sin Ming - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/03/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (28/02/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

– Pre-Repair Inspection Request – GBH1869M vs SLB4331R (OI) on D.O.A.: 22/02/2019

From: Hor, Yinnul
To: Admin A (admin-a@lkkauto.com), 'assignments@lkkauto.com'
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazaldina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 26/2/2019 5:10:54 PM
Attachments: 20190226162812899.pdf 20190226162812899.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Claim no : 5467430747SG007
Case Owner : KOK LEONG WILSON TAN

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: Kelly Cheng [mailto:kelly.cheng@ksteopr.com]
Sent: Tuesday, February 26, 2019 4:36 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazaldina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB4331R AND GBH1869M ON 22/02/2019

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to your email dated 26 February 2019.

We have instructions to appoint **LKK Auto Consultants Pte Ltd** as a Single Joint Expert to conduct the pre-repair survey.

Kindly arrange for Pre-Repair Survey with our client's repairer, Mr Tan, at 9761 9383, immediately.

Thank you.

On Tue, Feb 26, 2019 at 4:31 PM Hor, Yinnul <Yinnul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัส เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-03-05 16:31 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Protonmail Encryption, Copyright © 2009-2017 Protonmail, Inc. All rights reserved.

--

Best Regards,
Kelly Cheng
Tel: 6333 4222 ext 72
Fax: 6333 5675

Teo Keng Siang LLC
111 North Bridge Road

Peninsula Plaza, #29-07/08
Singapore 179098

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: kelly.cheng@ksteoptr.com

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, Baijit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.co

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB4331R AND GBH1869M ON 22/02/2019

Date: Tue, 26 Feb 2019 08:31:10 +0000

Without Prejudice

Your Reference : TKS/R469-ACC-41613.19/kc
Our Reference : 5467430747SG007

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Kelly Cheng [mailto:kelly.cheng@ksteoptr.com]

Sent: Tuesday, February 26, 2019 4:25 PM

To: Ismail, Nuraisyah; Hor, Yinrul

Subject: PRS - SLB 4331 R OUR REF: TKS/R469-ACC-41613.19/kc

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to the above matter and our PRS notification letter dated 26 February 2019, enclose herewith for your easy reference.

Kindly let us have your reply within the stipulated time frame.

Thank you.

--

Best Regards,

Kelly Cheng

Tel: 6333 4222 ext 72

Fax: 6333 5675

Teo Keng Siang LLC

111 North Bridge Road

Peninsula Plaza, #29-07/08

Singapore 179098

张景祥大律師樓
(律師兼公証及宣誓官)

TEO KENG SIANG LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098. Tel: 6333 4222 Fax: 6333 5676/5688
ROC: 201510228C GST Reg No.: 201510228C Email: KSTEOCO@singnet.com.sg

(FAX – NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKS/R469-ACC-41613.19/kc
Your Ref : **SLB 4331 R**
Date : 26th February 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16, AIG Building
Singapore 079120
Attn: Motor Claims Dept /

LCRF PTE LTD
60 Anson Road
#11-01, Mapletree Anson
Singapore 079914

Dear Sirs

NOTIFICATION OF ACCIDENT

RE: ACCIDENT INVOLVING GBH 1869 M / SLB 4331 R / SHC 8665 T / SLK 5790 U ON 22nd FEBRUARY 2019 ALONG AYE (AFTER LOWER DELTA)

We act for **HONG LAM MARINE PTE LTD** in the accident above.

We are instructed by the abovenamed Claimant to notify you of a road traffic accident on **22nd FEBRUARY 2019 at 12:35PM along AYE (AFTER LOWER DELTA)** involving our client's motor vehicle **GBH 1869 M** and motor vehicle **SLB 4331 R** driven by you or your authorized driver at the material time. A copy of the GIA/Traffic Police Report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damage vehicle, please let us know within **2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. **If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.**

Please note that our client's motor vehicle **GBH 1869 M** is now at the following workshop: -

RC AUTO
160 Sin Ming Drive
#06-20, Sin Ming AutoCity
Singapore 575722
Person I/C : Mr Tan
Contact : 9761 9383

Yours faithfully,



M/S TEO KENG SIANG LLC
cc. Clients - By Email

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

Secretary in charge: Kelly

Tel: 6333 4222 (ext 72)

Fax: 6333 5676 / 5688

Email: Kelly.cheng@ksteoptr.com

BY PDX #8181 & FAX: 6835 7416

PDX Intercompany Exchange Pte Ltd



010808638042

FROM **TEO KENG SIANG LLC**

PDX Box No. **8902**

BY POST

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 16:28
Date Of Accident	22/02/2019 12:35
Exact Location Of Accident	AYE (AFTER LOWER DELTA)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBH1869M
Insured/Policyholder	
Name Of Registered Owner	HONG LAM MARINE PTE LTD
Co Reg No	- 198103248W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97356334
Alternative Phone No	OFFICE-97356334
Vehicle Particulars	
Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCG18000589
Cover Note Number	
Driver	
Name of Driver	RAMLI BIN MORDIPI
NRIC No	S0008559F
Date Of Birth	18/07/1954
Occupation	OUTDOOR
Date Of Driving Pass	24/12/1998
Driving Experience	20 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97356334
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -

Postcode -

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured -

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB4331R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC8665T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLK5790U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along slip road from Keppel Rd into AYE (Tuas). When vehicle in front of me stopped, and I applied my brake and came to a stop too. Suddenly I felt a great impact from the rear. I quickly stopped at the road shoulder, and I walked back to the vehicle B, and I realized that it was a chain collision with total four vehicles involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

50008559F

NAME: RAMLI BIN MORDIPI

Date of Birth: 18 JUL 1954

Valid Until: 15 Feb 2006

009200338G




UBLIC OF SINGAPORE
IDENTITY CARD-NO. S0008559F



Name
RAMLI BIN MORDIPI

رملي بن موديبي

Race
MALAY
Date of birth
18-07-1954
Country of birth
SINGAPORE

Sex
M

S0008559F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3
Motorcycles not exceeding 200 cc
Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

12 Mar 1983
24 Dec 1985

NP 428A

Licence No: S0008559F



S0008559F

20-02-2006

Address
APT BLK 548 PASIR RIS STREET 51
#03-45
SINGAPORE 510548




ESTIMATE RC AUTO

Not Notchair
6/1/2019 @ 4:05pm
Resurvey After Paint
5 days

160 SIN MING DRIVE#06-20 SIN MING AUTOCITY S(575722)

Tel : 97619383 Email: RCAUTO5555@GMAIL.COM

Reg. No. 53199168K

GBH 1869 M

Date : 25/2/2019

Quantity	Description/Particular	Unit Price	Amount	
	REAR TAILGATE(L/H) <i>B1</i>	NETT	1409	20
	REAR TAILGATE(R/H) <i>B1</i>	NETT	1056	90
	REAR TAILGATE LOCK	NETT	120	00
	REAR BUMPER <i>Bu</i>	NETT	624	80
	REAR BUMPER REFLECTOR <i>my R11</i>	NETT	60	00
	REAR BUMPER BEAM <i>B1</i>	NETT	270	00
	REAR PANEL <i>B1</i>	NETT	450	00
	REAR TAILGATE HINGE(R/H) <i>R</i>	NETT	55	00
	NISSAN EMBLEM <i>108 m</i>	NETT	60	00
		TOTAL	4105	90
	SPRAY PAINTING		700	00
1 SET	REVERSE SENSORS <i>Sken</i>		280	00
	TO RENEW ABOVE PARTS		900	00
	TO REMOVE BOTH WINDSCREEN		200	00
	70 KM/H STICKER	<i>m</i>	5	00
	6 PAX STICKER	<i>m</i>	5	00
	ANTI RUST		40	00
	GRAND TOTAL		6235	90

Received the above goods in good order and condition

for RC AUTO

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary works must be resurveyed and is subject to final approval from Insurance Company

E.&O.E. Authorised Signature

Acknowledged by Repairer

Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	S\$4,050.00 Edit Estimates	S\$4,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA								
Main Claimant:	-								
Vehicle Reg. No.:	GBH1869M	Date of Loss:	22/02/2019 00:00 - :59 [11 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5467430747SG	Policy/Cover Note No.:	0999994758 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB4331R	Policy No. (Claimant):							
		Excess:							
Repairer:	RC AUTO (HQ) 18 Sin Ming Industrial Estate Sector A, #01-43, 575676 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (28/02/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH1869M (5467430747SG)**
[SLB4331R]

TP

Feb 22 2019 12:00AM
[LCRF Pte Ltd]
RC AUTO

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/02/19 11:42	Accident Statement From: SC - Reg. No: SLB4331R, Claimant: LCRF PTE LTD		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/03/19 17:48	General View		Load JPG	<input checked="" type="checkbox"/>
16	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	05/03/19 10:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/19 17:47	TP GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003730/KVD3E2

Date: 06/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994758
Claimant Vehicle No : GBH1869M **Insured Vehicle No :** SLB4331R
Date of Loss: 22/02/2019 **Nature of Claim:** TP **Claim No:** 5467430747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH1869M**
 Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KE628D413776
 Reg. Date: 26/02/2018 (Man. Year: 2017) Chassis No: VSKYBAM20Z0156375
 Colour: Metallic Silver Odometer: 35205 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 9 mm
 Front Right Side: Goodyear 9 mm Rear Right Side: Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,395.90	3,747.81	648.09	14.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,360.00	480.00	26.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,235.90	5,107.81	1,128.09	18.09
Approved Total (Overridden) (S\$)		4,050.00		
Nett Amount (S\$)	6,235.90	4,050.00	2,185.90	35.05

INSPECTION

Date of Assignment: 26/02/2019
 Date Inspected: 27/02/2019 Inspected At: 160 SIN MING DRIVE#06-20
 Repairer : RC AUTO (HQ)
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (L/H)	Bent	1,409.20 F	*1,409.20 FN
2	1		*REAR TAILGATE (R/H)	Bent	1,056.90 F	*1,056.90 FN
3	1		*REAR TAILGATE LOCK	Repair	120.00 F	*- FN
4	1		*REAR BUMPER	Buckled	624.80 F	*624.80 FN
5	1		*REAR BUMPER REFLECTOR	Mtg Distorted	60.00 F	*60.00 FN
6	1		*REAR BUMPER BEAM	Bent	270.00 F	*270.00 FN
7	1		*REAR PANEL	Bent	450.00 F	*450.00 FN
8	1		*REAR TAILGATE HINGE (R/H)	Repair	55.00 F	*- FN
9	1		*NISSAN EMBLEM	Necessary	60.00 F	*60.00 FN
10	1		*SET REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS
11	1		*70 KM/H STICKER	Necessary	5.00 FS	*5.00 FS
12	1		*6 PAX STICKER	Necessary	5.00 FS	*5.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,395.90	4,140.90
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	393.09
Total Parts (\$\$)	4,395.90	3,747.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	700.00	600.00
2	TO RENEW ABOVE PARTS	New	900.00	600.00
3	TO REMOVE BOTH WINDSCREEN	New	200.00	120.00
4	ANTI RUST	New	40.00	40.00
Gross Labour Cost (\$\$)			1,840.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >