

(08/11/13) wof

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Airtex LTA 36372 4yrs. 10m.

L/S A 9000

(\$ 10,223.95 Red 53%)

RECEIVED 20 MAR 2019

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c.

Colour:

A/C: Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

20/03/19

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) \$ + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

Independent

Lump Sum / I.B.I. (\$

9,000/- L/S)

TOTAL

9x15=135

170+135

50

50+50

121

80

656

Ref. No	: CS/TP19003733 / USD3	Res. Date:	27/2/19	Date Received:	
Veh. No	: GSC 8063B	SP:		WKSP:	
C/No	:				
Action/Instruction:					
1. File	2. Submit Photo?	YES / NO		Message:	
3. Indicate Res. Date On Photo Page?		YES / NO			
If No, due to	a) No authorisation	b) Days of repair			
others:					
Final Re-inspection	or	Progress Photos		Inspected By:	

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)**Post an Advertisement**

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**Nearly New Exe MPV for Sales!**

Low Mileage, Low Dep, Great Condition Highest Spec Alphard For Sales!!!

StarAd



Browse by Category ▼

Sort by Date Posted

1 vehicles

toyota dyna

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	toyota dyna		Any	Any	2013	Any	Any	

**Toyota Dyna 150****\$39,800****\$9,620 /yr****18-Apr-2013****2,982 cc****-****Fuel Type:** Diesel

Sliding Canopy. With Checkered Plate. In Very Good Condition. 100% Loan Available. In House - Fast Approval & Delivery. Call Now For

ABWIN (1994) Pte Ltd

Posted: 11-Feb-2019 Tags: 2013 Toyota Dyna, 2013 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view **Expired ads**
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resour](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used toyota dyna, toyota dyna Singapore, used toyota dyna Singapore, used toyota dyna, used vehicles Singapore or even buy used toyota dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotional openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)



[Advanced Search](#)
[Home](#) » [Used Cars](#) » [Car \(S\) Pte Ltd](#) » [Toyota Dyna 150](#)

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)

Commercial Vehicle

PAN PACIFIC
BRAND NEW FLEET
AVAILABLE FOR
RENT / LEASE

NISSAN NV200 **NISSAN CASTER**
\$1,200 \$1,200

CALL: 8482 3003
EMAIL: sales@panpacificleasing.com.sg

TNT

Want to keep up with the competition?

[Compare](#)

Toyota Dyna 150

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

PREMIUM AD


[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$37,800	
Depreciation	\$10,440 /yr <small>View models with similar depreciation</small>	?
Reg Date	12-Oct-2012 <small>(3yrs 7mths 14days COE left)</small>	
Manufactured	2012	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,982 cc	?
Curb Weight	1,780 kg	
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	10 Feet Lorry With Cabin Height Box! Multi Storey Carpark Friendly! Definitely A Great Deal Not To Be Missed For New Start Up! Just Serviced! Most Reliable Japan Work Horse! Up To 100% Loan Available With The Lowest Drive Away And Monthly Instalment Scheme! Cheaper Than Rental Vehicles! High Trade In Quotation Given For Your Vehicle. Contact Our Friendly Sales Consultant For Viewing Today!	
COE	\$59,334	?
OMV	\$24,970	?
ARF	\$1,249	?
Dereg Value	\$21,490 as of today (change)	?
No. of Owners	3	?
Type of Veh	Truck	
Category	Premium Ad Car	
Availability	Available	PREMIUM AD

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 26-Feb-2019 | Last Updated on: 26-Feb-2019

Tags: Toyota Dyna, toyota dyna, 2012 Toyota Dyna, 2012 toyota dyna, Toyota, Dyna, dyna, Used Toyota



Seller Information

Company	Car (S) Pte Ltd » dealer's pricelist » 59 vehs sold 136 vehs available	
Address	39 Woodlands Close #07-K1, #08-04 Search cars nearby this location	
Location	Mega @ Woodlands	
Office No	63863322	
Contact Person(s)	Winson Dennis Goh Fey Lim	83802211 88583322 91918383

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1592K
Vehicle Details	
Vehicle No.:	GBC8063B
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2347628
Chassis No.:	JTFAT35Y10K202692
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	04 Dec 2013
First Registration Date:	04 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$76,310.00
COE Rebate Amount:	\$36,372.00
Total Rebate Amount:	\$36,372.00

The information contained herein is correct as at 27 Feb 2019

OK

Mar cus

21/02/2019 THU 12:40 FAX

001/005

MSME1003a188 / BMS Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 21/02/2018 12:03
 SUBMITTED BY: Chia Pei Yeng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 21/02/2019 12:03
 Date Of Accident 20/02/2019 11:00
 Exact Location Of Accident SIN MING DRIVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC8063B
 Insured/Policyholder
 Name Of Registered Owner JT GLOBAL PTE LTD
 Co Reg No 200811592K
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-97703097
Vehicle Particulars
 Manufacturer TOYOTA
 Model DYNA
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
 Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5105817691
 Cover Note Number
Driver
 Name of Driver WANG NANNAN
 NRIC No G6886334T
 Date Of Birth 29/12/1990
 Occupation OUTDOOR
 Date Of Driving Pass 26/05/2015
 Driving Experience 3 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97184668
 Fax Number
 Contact Number
 Email Address NOEMAIL

21/02/2019 THU 12:40 FAX

002/005

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 20/02/2019 AT ABOUT 11AM, I WAS DRIVING ALONG SIN MING DRIVE ON THE LEFT LANE. VEHICLE C CAME TO A STOP. SO, I FOLLOWED. SUDDENLY, VEHICLE B CAME AND HIT THE REAR OF MY VEHICLE A. THE GREAT IMPACT CAUSED MY VEHICLE TO MOVE FORWARD AND HIT VEHICLE C IN FRONT OF ME. I ALIGHTED FROM MY VEHICLE AND FOUND OUT THAT I WAS INVOLVED IN 3 CARS CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMH3235Z

Vehicle Make/Model/Colour

Details Of Properties VEHICLE C

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (including Driver)

21/02/2019 THU 12:40 FAX

003/005

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GY4114P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

21/02 2019 THU 12:40 FAX

004/005

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer, collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 21/2/19, 10am

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/2/19, 10am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BLUNEL

Estimate

Not Authorised
N/A
9000
a/s 3
1 day

Vehicle: GBC 8063B

Make & Model: _____

Year: _____

Chassis No: _____

	Parts / Labour	Condition	Price	recommend
2pc	Rear tailamps @ 285.50	one	571.00	—
	Rear tailamp bracket als	best	119.20	—
	Rear licence plate bracket	best	145.80	—
	Rear spare tyre chain & bracket	1 mil km	392.30	—
	Rear exhaust	R	585.20	X
	Front bumper	DD/24	698.90	—
	Front bumper centre cross member	DD	845.20	—
	Front grille	one	807.92	—
	Front grille logo	one	68.10	—
2pc	headlamps @ 765.31	one	1530.62	—
	Front panel	R	959.10	X
	Front panel top garnish	one	288.31	X
2pc	Front corner panel top garnish @ 178.60	one	357.20	X
	Front door als	R	1645.10	X
			9013.95	
				5179.04
				3884.28
	S. next			
	Rear cargo box back door als	DD/best	1600.00	1400
	Rear cargo box back door matt sticker als	one	480.00	400
	Rear cargo box back door als	DD	1600.00	1400
	Rear cargo box back door matt sticker als	one	480.00	400
	Rear licence plate	best	20.00	15
1 set	Rear reverse sensor	shipped	280.00	200
	Rear 70km/h sticker	one	20.00	10
	Front licence plate	best	20.00	15
	Front door ROC sticker als	one	50.00	✓
1 set	Front matt black sticker	one	1800.00	1000

Estimate

Vehicle: GBC 8063B

Make & Model:

Year:

Chassis No:

Parts / Labour	Condition	Price	recommend
To check wiring		\$0.00 - 30	
To dismantle & replacing reverse sensor		\$0.00 - 50	
To spray rust proofing		120.00 - 50	
To Dismantle & refix front Dashboard	11	280.00	X
To Dismantle & refix front windscreen	11	120.00	X
To Dismantle & refix rear exhaust		100.00	60
labour for panel beating & replacing parts		1280.00	1100
To putty & spray painting		1800.00	1200
	TOTAL#	8223.95	

REPAIR ORDER FORM

Customer Name: _____

Vehicle Make/Model: _____

Year: _____

Engine No.: _____

VIN: _____

Date: _____

Signature: _____

MARCUS
GBC8063B

VISIONWORKZ PERFORMANCE

Showroom / Workshop: Block 176, Sin Ming Drive, #03-01, Sin Ming Autocare, Singapore 575721
Website: www.visionworkz.com.sg Email: enquiries@visionworkz.com.sg

INVOICE NO: BLUWEL_AUTOMOTIVE/MARCH/2019/001

COMPANY NAME: BLUWEL AUTOMOTIVE SERVICE PTE LTD

DATE: 05-03-2019

DATE	VEHICLE / VEHICLE NO:	JOB DESCRIPTION	REQUEST BY	PRICE
05-03	Toyota 10 foot Box Lorry GBC 8063B	Accident Replacement for Front Bumper, Front Grill and Front Bonnet, Matt Black Full Wrap including Labour and Installation Digital Printed Inkjet Sticker Wrapped on Rear Panel Doors 2 Pieces including Labour and Installation	Kenny Yap	\$800
Thank You For Your Business!				\$800.00

ISSUED BY: ALEC NEO

SIGNATURE: 

DATE: 05-03-2019

**VISIONWORKZ PERFORMANCE**www.visionworkz.com.sg

Block 176, Sin Ming Drive,
Sin Ming Autocare, #03-01, S575721
Hp: 9828 2826 / 9843 1315



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP19003733/Usd3n2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 20-03-2019



ON BEHALF OF JT GLOBAL PTE LTD

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBC 8063B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	27/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFAT35Y10K202692	Colour	BLACK
Odometer	180923	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R12 (D)	DELIUM	5/5 mm
L/H Rear Tyre	155 R12 (D)	DELIUM	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/02/2019	Inspection Date	27/02/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8063B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR TAILLAMPS @\$285.50	CRACKED	571.00	571.00
1	REAR TAILLAMP BRACKET O/S	BENT	119.20	119.20
1	REAR LICENCE PLATE BRACKET	BENT	145.80	145.80
1	REAR SPARE TYRE CHAIN & BRACKET	TWISTED / JAMMED	392.30	392.30
1	REAR EXHAUST	TO REPAIR SEE LABOUR	585.20	-
1	FRONT BUMPER	DENTED / BENT	698.90	698.90
1	FRONT BUMPER CENTRE CROSS MEMBER	DENTED	845.20	845.20
1	FRONT GRILLE	CRACKED	807.92	807.92
1	FRONT GRILLE LOGO	NECESSARY	68.10	68.10
2	HEADLAMPS @\$765.31	CRACKED	1,530.62	1,530.62
1	FRONT PANEL	TO REPAIR SEE LABOUR	959.10	-
1	FRONT PANEL TOP GARNISH	SERVICEABLE	288.31	-
2	FRONT CORNER PANEL TOP GARNISHS @\$178.60	SERVICEABLE	357.20	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,645.10	-
	LESS 25% DISCOUNT		-	-1,294.76
			9,013.95	3,884.28
<u>SPECIAL NETT ITEMS</u>				
1	REAR CARGO BOX BACK DOOR O/S (SN)	DENTED / BENT	1,600.00	1,400.00
1	REAR CARGO BOX BACK DOOR MATT STICKER O/S (SN)	NECESSARY	480.00	400.00
1	REAR CARGO BOX BACK DOOR N/S (SN)	DENTED	1,600.00	1,400.00
1	REAR CARGO BOX BACK DOOR MATT STICKER N/S (SN)	NECESSARY	480.00	400.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	15.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	FRONT LICENCE PLATE (SN)	BENT	20.00	15.00
1	FRONT DOOR ROC STICKER O/S (SN)	NECESSARY	50.00	50.00
1	SET FRONT MATT BLACK STICKER (SN)	NECESSARY	1,800.00	1,000.00
			6,350.00	4,890.00
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00

Report Ref No. CS/TP19003733/Usd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING.		120.00	50.00
	TO DISMANTLE & REFIX FRONT DASHBOARD.	NOT NECESSARY	280.00	-
	TO DISMANTLE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,FRONT PANEL AND FRONT DOOR O/S.		1,280.00	1,100.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,200.00
			3,860.00	2,490.00
GRAND TOTAL			19,223.95	11,264.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/TP19003733/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.