

7/20/2017

ASS. REC. BY:

REF:

CS/AIG/19003750/Used

Special Instruction:

SA/VE/01

Morris

ASSIGNMENT (Office)

From (Person):

Munnen

Hor. Yinnul

of

AIG

Date/Time:

27/2/19 @ 2.48pm

Estimated Cost:

Bill to:

OD PTP / AWS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJV 7905J

Insured:

SGP 2846x

at Workshop m/s

Fastech

Tel:

67465405

of

1 Kanki St Ave 6 # 01-46/48

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:19pm @ 28/2/19

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJV 7905J - CCB / Lpc 17019 277 / Ucb 382

DUA: 6/10/2017

SGP 2846x - x

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

56148

Date / Time Action / Instruction

Rec'd 8890 New KIA

20/3/19 4/5 + 6100 confirmed with Alan
(\$ 13,236.60 Rec - 68%)

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

25/03/19

1) Typ. 54

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 6,100 / 115)

Veh No:

SJ-V7905J

Yr Regn:

21 10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(19)

Make:

KIA Cerato Forte c.c 1591

Colour:

3mm

A/C:

Insured / Std / NI / NA

Sp. Reading

24275 f

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNATFW41MAS173759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/4/19

D.O.I.

27/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

250

Transportation:

Add Fee:

☐

Site Insp (\$

)

S + RS, SI

☐

Interview (\$

)

Photos

☐

Tech. Invs (\$

)

Others

☐

Weekend (\$

)

TOTAL

260

- Pre-Repair Inspection Request - SJV7905J vs SGP2846X (OI) on D.O.A.: 23/02/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 27/2/2019 2:48:39 PM
Attachments:  tmg9426.tif  tmg9426.tif

Hi,

Please refer to the enclosed request from MAHADI ABU BAKAR & PARTNERS.

Claim no : 0337837219SG003
Case Owner : CHIT YAN FOO

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: Mahadi Abu Bakar [mailto:mab_law06@yahoo.com.sg]
Sent: Wednesday, February 27, 2019 11:56 AM
To: Hor, Yinnul
Subject: YOUR REF: 0337837219SG003 ; OUR REF: MAB/10761/19/ana

ATTN: MS VIVIANE

Dear Madam

ACCIDENT INVOLVING SGP 2846 X & SJV 7905 J ALONG PIE EXPRESSWAY TOWARDS CHANGI BEFORE UPP SERANGOON ROAD EXIT ON 23/02/2019 AT ABOUT 3.30 PM

We refer to the above matter and to your email dated 27/02/2019.

Please be informed that our client prefers to have Mr Marcus Chua from LKK Auto Consultants Pte Ltd to be appointed as a single joint expert.

Kindly inform Mr Marcus Chua to do the survey as soon as possible.

Kind regards

Mr Mahadi Abu Bakar

MAHADI ABU BAKAR & PARTNERS
(UEN No. 53179837/B)
Advocates & Solicitors
#14-01 Tong Eng Building
101 Cecil Street
Singapore 069533

Telephone: (65) 6225 2355 (3 lines)
Facsimile: (65) 6227 9913

CONFIDENTIALITY NOTICE This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com
To: mab_law06@yahoo.com.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGP2846X AND SJV7905J ON 23/02/2019
Date: Wed, 27 Feb 2019 01:05:04 +0000

Without Prejudice

Your Reference : MAB/10761/19/ana
Our Reference : 0337837219SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd

Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533

TEL: 62252355 FAX: 62279913

Email: mab_law06@yahoo.com.sg

YOUR REF: SGP 2846 X

26 February 2019

OUR REF: MAB/10761/19/ana

LIM BOON LIN

Blk 113 Bukit Batok West Avenue 6

#12-176 Singapore 650113

Dear Sir

**ACCIDENT INVOLVING SGP 2846 X & SJV 7905 J ALONG PIE EXPRESSWAY
TOWARDS CHANGI BEFORE UPP SERANGOON ROAD EXIT ON 23/02/2019 AT
ABOUT 3.30 PM**

We are instructed by *Mr Azrin Bin Rahman*, the owner of motorcar no. SJV 7905 J, to notify you of a road traffic accident on the 23/02/2019 at about 3.30 pm involving our client's vehicle registration no. SJV 7905 J and vehicle registration no. SGP 2846 X driven by you at the material time. Copies of the GIA/Traffic Police Accident Reports lodged by our client is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you or your insurer within the stipulated timeline, our client shall proceed to repair the vehicle further reference to you.

Yours faithfully



Enc

cc. Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16
Singapore 079120
Your Ref: SGP 2846 X

**URGENT**FAX & MAIL
6835 7416

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5614Z
Vehicle Details	
Vehicle No.:	SJV7905J
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9H340130
Chassis No.:	KNAFW411MA5173759
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$14,423.00
Original Registration Date:	09 Feb 2010
First Registration Date:	09 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$14,423.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2020
PARF Rebate Amount:	\$7,211.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$1,899.00
Total Rebate Amount:	\$9,110.00

The information contained herein is correct as at 27 Feb 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Kia Cerato

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Kia Cerato Forte 1.6A SX

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Engine Oil

FREE
ENGINE OIL
SERVICE PACKAGE
worth
\$98

Participating Brands:
YOKOHAMA
ENIGMASTONE
Temp and conditions apply.





Kia Cerato Forte 1.6A SX

- Overview Financial Insurance Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$18,000	
Depreciation	\$9,960 /yr	?
	View models with similar depreciation	
Reg Date	31-Mar-2010	
	(1yr 1mth 3days COE left)	
Manufactured	2009	?
Mileage	107,000 km (12k /yr)	
Transmission	Auto	
Engine Cap	1,591 cc	
Road Tax	\$738 /yr	?
Power	92.7 kW (124 bhp)	
	View specs of the Kia Cerato Forte (2009-2013)	
Curb Weight	1,251 kg	?
Features	-	
Accessories	Leather Seats, Retractable Side Mirror, Reverse Sensor, Remote Alarm, Keyless Entry And Start/Stop.	
Description	1.6L 4 Cylinders 16 Valves DOHC Engine, Responsive Auto Transmission Gearbox, ABS, Auto Climatic Aircon Control, Steering Audio Control, Fog Lights.	
COE	\$28,389	?
OMV	\$14,330	?
ARF	\$14,330	?
Dereg Value	\$10,969 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist Add to Compare Add a Note

Posted on: 24-Feb-2019 | Last Updated on: 24-Feb-2019

Tags: Kia Cerato, kia cerato, 2010 Kia Cerato, 2010 kia cerato, Kia, Cerato, cerato, Used Kia



Price Analysis

Seller Information

Contact Person(s) Kelvin
Contact No. 97825608
Enquiry  Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer



GET HELP WITH
PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Compare

MVA319025717 / VAC - Kaki Bukit
ENTRY DATE & TIME: 25/02/2019 12:44
SUBMITTED BY: SITI FAHLON BIE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 12:44
Date Of Accident	23/02/2019 15:30
Exact Location Of Accident	PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV7905J
Insured/Policyholder	
Name Of Registered Owner	AZRIN BIN RAHMAN
NRIC No	S8505614Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90475589
Alternative Phone No	OTHERS-90475589
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069924602-04
Cover Note Number	
Driver	
Name of Driver	ROZIAZI BIN MOHD RAIS
NRIC No	S8132126D
Date Of Birth	25/10/1981
Occupation	INDOOR
Date Of Driving Pass	21/11/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83687466
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 603C #06-726 PUNGGOL ROAD
 Postcode 823603
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station

Police Station Name PUNGGOL N.P.C
 Police Station Address ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190223/2145:

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGP2846X
 Vehicle Make/Model/Colour TOYOTA VIOS 1.5E A
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	ROZIAZI BIN MOHD RAIS
Approximate Age	37
Injuries Sustain	
Injured person in which vehicle?	SJV7905J
Were seat belts worn?	YES
Was this Injured conveyed to hospital by ambulance?	
Address	BLK 603C #06-726 PUNGGOL ROAD
Postcode	823603

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 12:44
Date Of Accident	23/02/2019 15:30
Exact Location Of Accident	PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV7905J
Insured/Policyholder	
Name Of Registered Owner	AZRIN BIN RAHMAN
NRIC No	S8505614Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90475589
Alternative Phone No	OTHERS-90475589

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069924602-04
Cover Note Number	

Driver

Name of Driver	ROZIAZI BIN MOHD RAIS
NRIC No	S8132126D
Date Of Birth	25/10/1981
Occupation	INDOOR
Date Of Driving Pass	21/11/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83687466
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 603C #06-726 PUNGGOL ROAD
Postcode	823603
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190223/2145:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGP2846X
Vehicle Make/Model/Colour	TOYOTA VIOS 1.5E A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	ROZIAZI BIN MOHD RAIS
Approximate Age	37
Injuries Sustain	
Injured person in which vehicle?	SJV7905J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 603C #06-726 PUNGGOL ROAD
Postcode	823603

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre Road Accident
Name: **Singapore 415933**
NRIC/TEL: **67416697** Fax: **67492305**
Email: **vackb@singnet.com.sg**

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23rd Feb 2019, at
As Per Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 23 Feb 2019 at 10:00

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature
Name: Singapore 415933

Tel: 67416697 Fax: 67492305

NRIC/PR No.:
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190223/2145

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 4

Report No. T/20190223/2145

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/02/2019 19:39		Vide Report No.:		Station Diary No.: 83	
Informant's Particulars					
Name of Informant: ROZIAZI BINTE MOHD RAIS			Address: APT BLK 603C PUNGGOL ROAD #06-726 SINGAPORE 823603		
ID Type / ID No.: NRIC NO / S8132126D			Contact No.: Home/Office: Mobile: 83687466		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 37	Date of Birth: 25/10/1981	Type of Informant: Driver		
Race: Javanese			Language: English		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 23/02/2019 15:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Towards Changi before Upp Serangoon Road exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGP2846X	Car				Slightly Damaged	0
SJV7905J	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190223/2145

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No. T/20190223/2145

CONTINUATION OF REPORT

Driver			
Name	Alex Lim	ID No.	NIL
Related Vehicle	SGP2846X (Car)	Contact No.	98367875
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ROZIAZI BINTE MOHD RAIS	ID No.	S8132126D
Related Vehicle	SJV7905J (Car)	Contact No.	83687466
Hospital/Clinic	PROHEALTH MEDICAL GROUP @ PUNGGOL DAMAI PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	23/02/2019	Date Discharge	23/02/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 23/02/2019 at about 1530hrs, I was driving my car, SJV7905J on the first lane along PIE towards Changi. Upon that time, the traffic was heavy and slow moving. The car in front of me was changing to the second lane. I slowed down my car and the car in front of me completed his lane change. I realized that there 2 car stationary in front of me and I stopped my car.

Out of sudden I felt an impact from my rear. I stood in my car as I was shocked. When I open my car's door, one male Chinese in his late 40s asking me if I am okay. The driver of the car, SGP2846X approached me and checked on my condition. The driver of SGP2846X asked me how I wanted to settle the issues and the male Chinese in his late 40s interrupt our conversation. The said male Chinese explained the procedure how to settle the issues and inform me that I can head down to his workshop for repairs. I also found out that there other vehicles involved in the accident

The said male Chinese also asked me unrelated question if I have renew my car's COE which I found it suspicious. The said male Chinese also informed me and the driver of SGP2846X to exchange particulars and moved our cars as it is dangerous.

I also question the said Chinese guy if he is involved in the accident. However, he informed me that his car, SDZ51T is parked at the road shoulder which did not involved in the accident. He tell me that there two stationary car in front me.

I also discovered that there other few cars was involved in the said accident. There a lady whose car is few cars away from me who took pictures of the accident. The said Chinese guy hopped into the third car that was involved in the accident and drive to the road shoulder followed by other few cars.



**SINGAPORE
POLICE FORCE**



T/20190223/2145

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 4

Report No. T/20190223/2145

CONTINUATION OF REPORT

I wish to state that I did not took the other vehicles registration plate number that was involved in the accident as I was shocked and the said Chinese guy kept on rushing me to move off. I also wish to state that I do not have any in car camera installed. I also have seek medical attention as I felt pain on my back and neck area. I was given 3 days medical certificate, MC/89435 from 24/02/2019 to 26/02/2019



**SINGAPORE
POLICE FORCE**



T/20190223/2145

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4

Report No. T/20190223/2145

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt MUHAMMAD FARID BIN KAMIS	Signature Of Informant/
Signature Of Interpreter: Not applicable	Date/Time: 23/02/2019 19:39
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:

Authentication Stamp
NP168

not authorized
MKE
27/2/19
4/5 6100
Weights after repair
5 day.

QTY	PARTICULAR	
1 PCS	BOOTLID	929.30
1 PCS	BOOTLID REAR LOGO	52.50
2 PCS	BOOTLID REFLECTORS	@\$420.10
1 PCS	BOOTLID INNER LOCK	
1 PCS	BOOTLID WEATHERSTRIP	225
1 PCS	REAR BUMPER	601
1 PCS	REAR BUMPER SPONGE	
1 PCS	REAR BUMPER REINFORCEMENT	394
2 PCS	REAR BUMPER REINFORCEMENT STAYS	@\$105.00
5 PCS	REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS	@\$22.00
2 PCS	REAR BUMPER SIDE RETAINERS	@\$48.50
1 PCS	REAR BUMPER LOWER CENTRE GARNISH	245
1 PCS	REAR BUMPER LOWER SKIRTING	900
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOP BOARD	
2 PCS	TAILLAMPS	@\$465.00
2 PCS	TAILLAMP HOUSING PANELS	@\$215.00
2 PCS	REAR FENDERS	@\$1105.00
2 PCS	REAR FENDER INNER TRIMS	@\$399.20
1 SET	REAR FENDER INNER TRIM CLIPS	
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS	@\$45.00

Self Suc	\$1,120.30	
rec	\$66.80	✓
11	\$840.20	X
twi	\$166.30	✓
twi	\$266.50	✓
ADine	\$845.20	✓
Ton	\$209.30	✓
one	\$488.20	✓
Best	\$210.00	✓
twi/cn	\$110.00	✓
Bed	\$97.00	✓
To-1	\$310.00	✓
best/cro	\$1,500.00	✓
m/ht	\$688.20	✓
twi	\$165.00	✓
R	\$1,100.00	X
11	\$365.30	X
cnq	\$930.00	✓
11	\$430.00	X
11	\$2,210.00	X
11	\$798.20	X
11	\$50.00	X
R	\$820.10	X
11	\$90.00	X
	\$13,876.60	

102

Shed	\$280.00	200
11	\$380.00	X
11	\$50.00	✓
11	\$50.00	X
	\$50.00	30
	\$80.00	50
	\$100.00	60
	\$120.00	80
11	\$150.00	X
	\$100.00	60
11	\$380.00	X
	\$120.00	80
	\$1,800.00	600
	\$1,800.00	1100
TO	\$19,336.60	

$$\begin{array}{r} \times 9226 \\ 5330.34 \\ 7640.34 \end{array}$$






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019 Edit Reg		27 Feb 2019 00:00 Edit Adj Rpt	S\$6,100.00 Edit Estimates	S\$6,100.00 View Rpt		Pending for Survey Report Cancel Case






































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LIM BOON LIN , ID: S2590922D									
Main Claimant: AZRIN BIN RAHMAN , ID: S8505614Z									
Vehicle Reg. No.: SJV7905J		Date of Loss: 23/02/2019 15:00 - :59 [108 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0337837219SG		Policy/Cover Note No.: 1800138331 (Comprehensive)							
Vehicle Reg. No. (Insured): SGP2846X		Policy No. (Claimant):							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (01/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV7905J (0337837219SG)
[SGP2846X]
TP
AZRIN BIN RAHMAN
Feb 23 2019 3:00PM
[LIM BOON LIN]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	25/03/19 11:00	Odometer Reading										Load JPG	<input checked="" type="checkbox"/>	
2	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
3	25/03/19 11:00	Chassis Number										Load JPG	<input checked="" type="checkbox"/>	
4	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
5	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
6	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
7	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
8	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
9	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
10	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
11	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
12	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
13	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
14	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
15	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
16	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
17	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
18	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
19	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
20	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
21	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
22	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
23	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
24	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
25	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
26	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
27	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
28	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
29	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
30	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
31	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
32	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
33	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
34	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
35	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
36	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	
37	25/03/19 11:00	General View Right										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
40	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
41	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
42	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
43	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
44	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
45	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
46	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
47	25/03/19 11:00	General View Right	 Load JPG	<input checked="" type="checkbox"/>
48	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	25/03/19 11:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 10:59	TP GIA REPORT.pdf	 Load PDF	
2	25/03/19 10:59	POLICE REPORT.pdf	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/03/19 09:50	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003750/USD3E2

Date: 27/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800138331

Claimant Vehicle No : SJV7905J

Insured Vehicle No : SGP2846X

Date of Loss: 23/02/2019

Nature of Claim: TP

Claim No: 0337837219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV7905J**

Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H340130

Reg. Date: 09/02/2010 (Man. Year: 2009) Chassis No: KNAFW411MA5173759

Colour: Blue Odometer: 242758 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,636.60	5,580.34	9,056.26	61.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,060.00	2,640.00	56.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,336.60	7,640.34	11,696.26	60.49
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	19,336.60	6,100.00	13,236.60	68.45
+ GST 7.00/7.00% (S\$)	1,353.56	427.00	926.56	68.45
Nett Amount (S\$)	20,690.16	6,527.00	14,163.16	68.45

INSPECTION

Date of Assignment: 27/02/2019

Date Inspected: 27/02/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,120.30 F	*929.30 FL
2	1		*BOOTLID REAR LOGO	Necessary	66.80 F	*52.50 FL
3	2		*BOOTLID REFLECTORS	Not Necessary	840.20 F	*- FL
4	1		*BOOTLID INNER LOCK	Twisted	166.30 F	*166.30 FL
5	1		*BOOTLID WEATHERSTRIP	Twisted	266.50 F	*225.00 FL
6	1		*REAR BUMPER	Dented / Deformed	845.20 F	*601.00 FL
7	1		*REAR BUMPER SPONGE	Torn	209.30 F	*209.30 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	488.20 F	*394.00 FL
9	5		*REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS	Twisted / Cracked	110.00 F	*110.00 FL
10	2		*REAR BUMPER SIDE RETAINERS	Bent	97.00 F	*97.00 FL
11	1		*REAR BUMPER LOWER CENTRE GARNISH	Torn	310.00 F	*245.00 FL
12	1		*REAR BUMPER LOWER SKIRTING	Cracked / Bent	1,500.00 F	*900.00 FL
13	1		*REAR END PANEL	Dented / Bent	688.20 F	*688.20 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	165.00 F	*165.00 FL
15	1		*REAR FLOOR PANEL	Repair	1,100.00 F	*- FL
16	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	365.30 F	*- FL
17	2		*TAILLAMPS	Cracked	930.00 F	*930.00 FL
18	2		*TAILLAMP HOUSING PANELS	Not Necessary	430.00 F	*- FL
19	2		*REAR FENDERS	Not Necessary	2,210.00 F	*- FL
20	2		*REAR FENDER INNER TRIMS	Not Necessary	798.20 F	*- FL
21	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
22	1		*REAR EXHAUST	Repair	820.10 F	*- FL
23	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
24	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
26	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
28	2		*REAR BUMPER REINFORCEMENT STAYS	Bent	210.00 F	*210.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,636.60	6,172.60
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	592.26
Total Parts (\$\$)	14,636.60	5,580.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	TO SPRAY RUST PROOFING	New	120.00	80.00
9	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS	New	1,800.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (\$\$)			4,700.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >