

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	INSURANCE PTE	ELTD	Ref: CS/AXA19003751/Kqd3e2		
8 SHENTON WAY #24-01			Date: 16-05-2019		
AXA TOWERSINGAPORE 068811			O-d- AVA0		
	I : VALERIE LOO		Code: AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	GBH 4566S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S9L01EGA/vl	Excess (\$)	0.00	
	Assign From	VALERIE LOOI	Assign Date	27/02/2019	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI L200 (M)	c.c	2442	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MMCJYKL10JH011732	Colour	METALLIC SILVER	
	Odometer	11437	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/70 R16	BRIDGESTONE	7 mm	
	L/H Front Tyre	245/70 R16	BRIDGESTONE	7 mm	
	R/H Rear Tyre	245/70 R16	BRIDGESTONE	7 mm	
	L/H Rear Tyre	245/70 R16	BRIDGESTONE	7 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/01/2019	Inspection Date	27/02/2019	
	Survey held at	160 SIN MING DRIVE# 02-04			
	Repairer	airer CAR TIMES AUTOLUTION PTE LTD			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				