

2/10/2002

ASS. REC. BY:

REF:

C83/MSG19003756/AGcd307

Special Instruction:

Surveyor:
Munmen

Steve

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk pui

of

MSIG

Date/Time:

27/2/19 @ 4:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 8573G

Insured:

SKP 4445J

at Workshop m/s

Safe Auto

Tel:

9199 3103

of

1 kaki Bkt Ave 6 # 01-52

Policy No:

286082975MP

Claim No:

586239

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/2/19 @ 9:55am

Person Contacted:

Mr. Kong

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLZ 8573G - X

SKP 4445J - X ..

Dismantle: 5/3/2019

After repair: 7/3/2019

ASS. REC. BY:

REF:

CS7/M2G/9063756/Acd3

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL285736 Yr Regn: May / 18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson C.C. 1591Colour: White A/C: Insured / Std / NI / NASp.Reading 13060 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHJ3812VJU 754895Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 225/60R17.R: 225/60R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 04/03/18.Survey held at Safe Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front x/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MS16 PRS.

Estimate repair cost 3k-4k.

MV:

PV:

Nett:

04 Apr

25/03/18 H.S.

RECEIVED 25 MAR 2019.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Preli. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019		27 Feb 2019 16:05 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GOH HOCK LYE ERIC, ID: S1305579C		
Main Claimant:	TOH MENG WAN, ID: S7203030C		
Vehicle Reg. No.:	SLZ8573G	Date of Loss:	27/02/2019 08:00 - :59 [9 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 586239	Policy/Cover Note No.:	28608297SMP (Comprehensive) Coverage: 10/09/2018 - 09/09/2019
Vehicle Reg. No. (Insured):	SKP4445J	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY, # 01-52, 417883 Kaki Bukit - Tel: 91993103		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/02/2019]		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: MR KONG WEI LEANG 9199 3103		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3030C
Vehicle Details	
Vehicle No.:	SLZ8573G
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	TL TUCSON 1.6 GLS T-GDI DCT 2WD
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	G4FJU443732
Chassis No.:	KMHJ3812VJU754895
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$16,204.00
Original Registration Date:	22 May 2018
First Registration Date:	22 May 2018
Transfer Count:	0
Actual ARF Paid:	\$16,204.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2028
PARF Rebate Amount:	\$12,153.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$35,292.00
Total Rebate Amount:	\$47,445.00

The information contained herein is correct as at 21 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2019 10:10
Date Of Accident	27/02/2019 08:25
Exact Location Of Accident	CONDO - CARPARK - THE GARDENS AT BISHAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ8573G
Insured/Policyholder	
Name Of Registered Owner	TOH MENG WAN
NRIC No	S7203030C
Email Address	TOHMENGWAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96321441
Alternative Phone No	OTHERS-96321441

Vehicle Particulars

Manufacturer	HYUNDAI
Model	TUCSON TURBO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101286190 (DRIVO PREMIUM)
Cover Note Number	

Driver

Name of Driver	TOH MENG WAN
NRIC No	S7203030C
Date Of Birth	28/01/1972
Occupation	INDOOR
Date Of Driving Pass	17/05/1990
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96321441
Fax Number	
Contact Number	OTHERS-96321441
Email Address	TOHMENGWAN@GMAIL.COM

Address	BLK 223 #02-141 BISHAN STREET 23
Postcode	570223
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP4445J
Vehicle Make/Model/Colour	BMW 520i
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ERIC GOH HOCK LYE
NRIC/Passport Number	S1305579C
Contact Number	98178629
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

27 FEB 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 8:25 am I drove my car into my condo's basement carpark. After going down the slope of the carpark entrance I slowed down, went through a hump, then proceed to drive ahead. Suddenly, a BMW 520i, SKP 4445J, drove out from the parking lot on my left, it did not signal at all. I quickly stepped on the brake, but was too late, we collided. My left ^{front} side of vehicle ~~hit~~ ^{hit} against his right ^{front} side, ~~both~~ ^{both} vehicles suffered damages. The driver of the other vehicle came out of his vehicle, apologized for his action and asked to ~~hand~~ ^{hand} me ~~his~~ ^{his} ic ~~and~~ ^{to photograph} and told me to claim after his insurance.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

27 FEB 2019

[Signature]

Policyholder's Signature
Date & Time:

27/2 - 9:57

27 FEB 2019

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/2 - 9:57



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019		27 Feb 2019 16:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH HOCK LYE ERIC, ID: S1305579C		
Main Claimant:	TOH MENG WAN, ID: S7203030C		
Vehicle Reg. No.:	SLZ8573G	Date of Loss:	27/02/2019 08:00 - :59 [9 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 586239	Policy/Cover Note No.:	28608297SMP (Comprehensive) Coverage: 10/09/2018 - 09/09/2019
Vehicle Reg. No. (Insured):	SKP4445J	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY, # 01-52, 417883 Kaki Bukit - Tel: 91993103		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 28/02/2019]		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: MR KONG WEI LEANG 9199 3103		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ8573G (586239)
[SKP4445J]
TP
TOH MENG WAN
Feb 27 2019 8:00AM
[GOH HOCK LYE ERIC]
Safe Auto

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/03/19 11:41	Accident Statement From: SC - Reg. No: SKP4445J, Claimant: ERIC GOH HOCK LYE	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 12:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
32	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 12:44	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/03/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	25/03/19 12:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/02/19 14:01	SLZ8573G TP E-FILE REPORT	 Load PDF	
2	27/02/19 14:01	PRI - VISION LAW LLC	 Load PDF	
3	27/02/19 15:02	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003756/AGCD3E2

Date: 27/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28608297SMP

Claimant Vehicle No : SLZ8573G

Insured Vehicle No : SKP4445J

Date of Loss: 27/02/2019

Nature of Claim: TP

Claim No: 586239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ8573G

Make & Model: HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)

Engine No: G4FJJU443732

Reg. Date: 22/05/2018 (Man. Year: 2018)

Chassis No: KMHJ3812VJU754895

Colour: White

Odometer: 13060 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/02/2019

Date Inspected: 04/03/2019 Inspected At:

Safe Auto (KAKI BUKIT)
1 KAKI BUKIT AVENUE 6, AUTOBAY , #
01-52
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2019)
Parts:	M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ8573G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >