



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 24/10/2019

### Survey Details:

Date of loss	24-Feb-19
Date of appointment	28-Feb-19
Date of survey	18-Mar-19
Location of survey	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLV 5745T
Make and Model	MINI COOPER S 1.6
Date of registration	3/1/2018
Excess	
Market Value	\$52,000
Parf Rebate	\$41,448
Nett Loss	\$10,552

### Repair details:

Initial Estimate	\$	7,714.00
------------------	----	----------

### Proposed/Revised repair cost:

Parts	\$	1,514.00
Check items (estimate)		NIL
Labour	\$	1,390.00
Supplementary	\$	470.00
<b>Total</b>	<b>\$</b>	<b>3,374.00</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>-</b>

<b>Number of days for repair</b>	<b>3</b>
----------------------------------	----------



**Remarks:**

*OID reversed and hit third party parked vehicle.*

**Mandate:**

<b>Liability(TP)</b>		<b>100%</b>	
Proposed repair cost (w/GST)	\$	3,610.18	
Loss of use	\$	180.00	(3days x \$60)
Loss of rental		NIL	no. of days
Loss of income		NIL	no. of days
LTA search fees		NIL	
Others		NIL	
<b>Proposed Total</b>	<b>\$</b>	<b>3,790.18</b>	