		1 1 1 1	24 4 7000					
Tion Times	11.3c Ol	103/2019	type (4.Ca		6636.	ir Pogn ony I Fazi IP	2018 De	c
	COLLECTIVATION / MY		Truc	de/Trailer or			198	24
To the pect Vehicle No.	SMG 6663	G	Make		A588		ss (/ 8 naunat / Stit / HF/	
at West Trop on	premium		Solour	Grey	2705		r⇒ usured/Std/HL	
et .	55 Ubi Road	[]	Sp Peading	, ,	2103	101000000000		
In the f			Eng#lo C#Io	WAU	222 F54	+KAUDS	671	
Policy No.			1.352.0.000	G Gritain				
Channelle			Transpersor Art Aut	nor ge r Llami				
Sum licated	Lancers.			n Øder I Jam				
(Chent's Record)				111 / 19 0m /			1.0	
Make of Velt.	10am		Tyre Size:		245/	+2818		
(Policy Condition)	(#)	N/S O/S	ne count	R:		FORIS.	su / PIR / SUMI /	
Remark. The velichad copair at the	commenced its time of inspection.	N/S O/S		YOKO or	3.11.371-00			
Bal, or Market Value.	Consistent7 : Ye	s or No	Eront R/Bot.	06	turo	Rear R/Bal.	06	3007
IDAC Accident Eport.	Consistent7 : Ye		1./Bol.	06	1000	L/Bat.	06	mm
Est Repairs 33	HS days Res Ye		D.O.A.		0	0.01.	01/23/19	6X
Lum Sum	% 3 Val.: Ye	s or No	Survey b		ing the partners of the partners of	nien.		
GA / REV / BEP	. 1 24 HRS	Vehicle: IN / OU	r				C / Rooftop or	10225-1111
Dafe:	Pisison Contacted.		Tho U	HC / Chassi	s frame / He	ody Structure	affected due to c	ollision.
	P Chine.				,,,			
	3							
		RECEIVE	D 2 7 1	IAY 2019.				
							٠.	

Deherture. File Parts to: 27/05/15 1) Typ. 4 Conte/Time. Per Ruture to:	: Preli, Report			Of Repair: vey No, of		1	Survey Fee:	
Contr/Time, Par Ruturn to?			- position				Transportation: 1	
			Add Fee:	Site Insp	(5)	19) 5 (48) 54	
		2.50		Intergew	(\$-). Districts	8 1 1
Report Fermat				Tech log	15		A Life of	
Lump Sum / LB t: C	890.30 P/P	0.	10000	West-aut	15			ŀ
runk same	01-20 177		7				1000.04	210

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status		
Main	25 Feb 2019		27 Feb 2019 16:03 Assign					New A	ssignme I Case	ent
	Main	Re	ference		Claim Details		Documen	ts	7 [Show All
CLAIM SU	BFOLDER DE	TAILS			CONTROL CONTROL	[Create	ed by insurer]	Magnetic Services	Statement of the last of the l	No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other pa
Insured:						Lancar	ea by mourer]			
Main Claimant:	HENG CH	EE WEE								
Vehicle Reg No.:	SMG666	3G			Date of Loss:	15/02/2	2019 00:00 - :59			
Claim Type		/ SNM19D200932C01			Policy/Cover Note No.:	DMCVSN3055218000				
Vehicle Reg No. (Insured):	GBD187A				Policy No. (Claimant):					
Repairer:	Dramium	Automobiles Dt.	114 (1157) 55 1		Excess:	\$\$0.00				
Handling Insurer:	1.100.00	Automobiles Pto ping Insurance (28/9827/9911 Indled by Irene Tay	Hui Ping	- 63898	61921
Adjuster:	The second secon	Consultants Pte								
Adj Asg. Remarks:		RVEY AND REVER								
ASSOCIAT	TED MAIL RE	CEIVED						View All	Compos	e Case Ma
There are n	o mail for this	case.					_	7.11	compos	e cose ma
ALL ASSO	CIATED TAS	KS⊟				View A	II Search Tasks	Create N	ow Tark I	Complet
Due Dat	e Priority	Type Task	Group Subi	ect Han	dler Assign		Completed On			
No results.		10.40000			Masign	ed by	completed on	Cre	ated On	Done

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Monday, 27 May 2019 11:13 AM

To:

'Boo seng yak'

Cc:

'Adrian Ling'; 'cs-a@lkkauto.com'; 'admin-a@lkkauto.com'; 'Carrine Leong';

'jiayee.yap@premiumauto.com.sg'; 'Chang Chee Sing'

Subject:

RE: FINAL REVISION - SMG6663G - TP CHINA- SURVEYED 1 MAR 19

Dear Mr. Boo.

Confirmed final fig \$ 890.30 @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 6 May 2019 1:10 PM

To: Adrian Ling <adrianling@lkkauto.com>; cs-a@lkkauto.com; admin-a@lkkauto.com; Carrine Leong

<carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SMG6663G - TP CHINA- SURVEYED 1 MAR 19

Hi Adrian and all.

Revised estimate is attached.

Please confirm repair cost of \$890.30 @ 3 days.

Your early closure is well appreciated.

Best regards - jb

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	16/02/2019 08:21	
Date Of Accident	15/02/2019 10:45	
Exact Location Of Accident	THE TRILING CONDOMINIUM CAR PARK	
Country/State of Loss	SINGAPORE	

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMG6663G	

Insured/Policyholder

Name Of Registered Owner HENG CHEE WEE

NRIC No S8011288B

Email Address CHRISHENG07@YAHOO.COM.SG

Mobile Phone No. (LOCAL) +65-82000340 Alternative Phone No OFFICE-82000340

Vehicle Particulars

Manufacturer AUDI

Model A5 SB 2.0 TFSI S TRONIC

Exact Purpose for which vehicle was being used at PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Insurance Company

Vehicle Category

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number

Cover Note Number

Driver

Name of Driver HENG CHEE WEE

NRIC No S8011288B Date Of Birth 11/04/1980 Occupation INDOOR Date Of Driving Pass 03/07/2008

Driving Experience 10 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82000340

Fax Number

Contact Number OFFICE-82000340

EMail Address CHRISHENG07@YAHOO.COM.SG Address

28 JALAN LEMPENG #31-06

Postcode

128807

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

970

NO

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

y

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

n(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT TO EXIT THE CARPARK OF "THE TRILING "CONDOMINIUM WHEN I NOTICED A VEHICLE BEARING REGISTRATION PLATE NO. GBD 187 A ATTEMPTING TO REVERSE OUT FROM A PARKING LOT/ I SOUND MY HORN TO ALERT HIM TO STOP VEHICLE GBD 187 A FINALLY CAME TO A STOP, REALIZED THAT THE VEHICLE HAD HIT MY RIGHT FRONT BUMPER AND FENDER. MY VEHICLE SUB STAIN MINOR DAMAGES TO HE RIGHT FRONT FENDER AND RIGHT FRONT BUMPER.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD187A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared / disclosed;
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 16/02/19 12:05 pm (If driver is not the policyholder)

Driver's Signature

Date & Time:

Reporting Centre Personnel's Signature Name work known Stall, Gaza NRIC/FIN NO .. 629 17 1434

8-GBD 187A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was drive	Straight to	exit the Co	rport of	The Triking"	_
work shall	W GBD 1874	antemptine	TO YOURY	e out from a	
parking lo	t. I boost St	I you bow	nova to a	led him to B	OP
out the ve	alcle continu	e to veue	se backwa	vds. When the	110
servicle GB	0 1874 fla	My Came	to a graf	, I realised the	4
the volice	e had him ,	my vest	right for	it bumper and	
Sender M.	uptacle cuse	Half when	/ damage	s to the your	1
furt le	der and via	in four	bumpar. J	d	
1		, ,	1		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 15 or 19

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature
Name: week killer SEAS frage
NRIC/FIN No.: 627871434

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Accident Repairs Workshop : Ubi Road 1 Contact No 6366 2323 Fax No : 6841 1183

Reference PA/TP/0244/2019/GW

Date 22-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your Insured Vehicle No. : GBD 187 A

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name Mr. Heng Chee Wee Address 28 Jalan Lempang

#31-06

Singapore 128807

82000340 Telephone

Type of Claim Third Party Claims

Policy No.

Vehicle No SMG 6663 G Model Code A5 SB 2.0 TFSI S Tronic

Model / Year Dec-18 **Engine No** CVK 073178

Chassis No WAUZZZF54KA009671

Mileage

Date In

Liability **Excess Cost**

Estimated By Allan Wu **Accident Date** 15-Feb-19

Place of Accident The Triling Condominium Car Park

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 6663 G

S/N	Nature of Jobs		Estimated Charges	
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00 ×	
2	To dismantle and renew front bumper and renew rhs front fender. Re-organise crash management components reinstall all parts removed.		\$ 2,100.00 X.	
3	To respray front fender rhs.		\$ 990:00 7	د ر
4	To carry out diagnostic check .	5/N	\$ 192.00 ×.	
	TOTAL LABOUR CHARGES	:	\$ 3,672.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6663 G

S/N	Parts Description		S	Damag /NETT	ge Parts & Prices REMARKS
1	FRONT FEDNER-RH REN		\$	968	3.00 X.
2	FRONT FENDER CLOSING ELEMENT-RH 14 12		\$	68	3.00×
3	FRONT STONE CHIP GUARD-RH		\$	46	5.00 - 45.80
4	FRONT FENDER TRIM-RH		\$	145	144.50
5	SUNDRIES Jue 2		\$	300	0.00-24
	SUB- TOTAL SPARE PARTS		\$	1,527	.00
	TOTAL LABOUR CHARGES	;	\$	3,672	.00
	GRAND TOTAL	:	\$	5,199	.00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (tem(s)) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

: Mre Authorised, 03 omp.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/TP/0244/2019/GW

Date

22-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your Insured Vehicle No.

GBD 187 A

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name

Mr. Heng Chee Wee

Address

28 Jalan Lempang

#31-06

Singapore 128807

Telephone

82000340

Type of Claim

Third Party Claims

Policy No.

Vehicle No

SMG 6663 G

Model Code

A5 SB 2.0 TFSI S Tronic Dec-18

Model / Year

Engine No

CVK 073178

Chassis No

WAUZZZF54KA009671

Mileage

Date In

Liability

Excess Cost

Estimated By

Allan Wu

Accident Date

15-Feb-19

Place of Accident

The Triling Condominium Car Park

Hi Adrian

3 days - ok - jb - 6 May 19

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 6663 G

S/N	Nature of Jobs		Estimated Charges	_	
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00		
2	To dismantle and renew front bumper and renew rhs front fender. Re-organise crash management components reinstall all parts removed.		\$ 2,100.00		
3	To respray front fender rhs.		\$ 900.00	\$	700.00
4	To carry out diagnostic check .	S/N	\$ 192.00		
	TOTAL LABOUR CHARGES	;	\$ 3,672.00	\$	700.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6663 G

S/N	Parts Description		SI	<u>Damage Pa</u> NETT R	irts & F	
				1000		
1	FRONT FEDNER-RH		\$	968.00		
2	FRONT FENDER CLOSING ELEMENT-RH		\$	68.00		
3	FRONT STONE CHIP GUARD-RH		\$	46.00	\$	45.80
4	FRONT FENDER TRIM-RH		\$	145.00	\$	144.50
5	SUNDRIES		\$	300.00		
4.500	SUB- TOTAL SPARE PARTS	1	\$	1,527.00	\$	190.30
	TOTAL LABOUR CHARGES		\$	3,672.00	\$	700.00
	GRAND TOTAL	Ī	\$	5,199.00	\$	890.30
	THE THE THE PROPERTY OF THE PR					

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Surveyed Date :

Authorised Date :

Excess Cost :

Liability : Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19003789/ASD3N2

Date:

28/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN3055218000

Claimant Vehicle No :

SMG6663G

Insured Vehicle No :

GBD187A

Date of Loss:

15/02/2019

Nature of Claim:

TP

Claim No:

SNM19D200932C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMG6663G

Make & Model:

AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A)

Engine No: Chassis No: CVK073178

Reg. Date:

12/12/2018 (Man. Year: 2018)

Odometer:

WAUZZZF54KA009671 2705 km

Colour: Engine Capacity:

gine Capacity:

Grey 1984 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: 245/40R18 Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 245/40R18 Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,527.00	190.30	1,336.70	87.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,672.00	700.00	2,972.00	80.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,199.00	890.30	4,308.70	82.88
+ GST 7.00/7.00% (S\$)	363.93	62.32	301.61	82.88
Nett Amount (S\$)	5,562.93	952.62	4,610.31	82.88

INSPECTION

Date of Assignment:

27/02/2019

Date Inspected:

01/03/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2019)

Parts: 143 AUDI A5 SPORTBACK 2.0 TFSI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG6663G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
4		*ERONT FENDER-RH	Repair	968.00 FS	*- FS
1			Not Necessary	68.00 FS	*- FS
1		*FRONT STONE CHIP GUARD-RH	Necessary Necessary	46.00 FS 145.00 FS	*45.80 FS *144.50 FS
1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
nchise	part. S=SpcN	lett.	Total Parts (S\$)	1,527.00	190.30
	1 1 1 1	1 1 1 1	1 *FRONT FENDER-RH 1 *FRONT FENDER CLOSING ELEMENT-RH 1 *FRONT STONE CHIP GUARD-RH 1 *FRONT FENDER TRIM-RH	1 *FRONT FENDER-RH Repair 1 *FRONT FENDER CLOSING ELEMENT-RH Not Necessary 1 *FRONT STONE CHIP GUARD-RH Necessary 1 *FRONT FENDER TRIM-RH Necessary 1 *SUNDRIES Not Necessary nchise part. S=SpcNett.	1 *FRONT FENDER-RH Repair 968.00 FS 1 *FRONT FENDER CLOSING ELEMENT-RH Not Necessary 68.00 FS 1 *FRONT STONE CHIP GUARD-RH Necessary 46.00 FS 1 *FRONT FENDER TRIM-RH Necessary 145.00 FS 1 *SUNDRIES Not Necessary 300.00 FS

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	ahour
Recommended	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		10000	
1	TO REMOVE AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASS AND FRONT PARKING AID		480.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RENEW RHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARREMOVED	New H RTS	2,100.00	0.00
3	TO RESPRAY FRONT FENDER RHS	New	900.00	700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
	Gross Labour Cost (S\$)		3,672.00	700.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >