

7/10/2002

ASS. REC. BY:

REF:

CS/ASM19003794/Rqd301

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of

ASM (AXA)

Date/Time:

28/2/19

Estimated Cost:

Bill to:

☒

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFM 32T

Insured:

at Workshop m/s

Sng Ah Tee

Tel:

6268 6183

of

Blk 3 pioneer Rd North #01-18

Policy No:

Claim No:

S9M01FFW

Sum Insured:

Excess:

\$1,300.00

Make of Veh:

D.O.A.

(Client's Record)

22/02/19

CA / ☒

REV /

REF. / REV 24 HRS

1/3/19

H.O.D. Endorsement:

Date/Time:

320pm @ 28/2/19

Person Contacted:

Janice

Vehicle ☒

IN/OUT

Date/Time

Action/Instruction

☒

Estimate

OI front hit TP rear portion.

also the Bonnet looks like Bum.

SFM 32T-X

04/3/19 @ 5:30pm revert to Kitty Teo via Smart Claim.

05/3/19 @ 3:00pm 2nd revert to Kitty Teo via Smart Claim.

06/3/19 Janice (Vesp) informed that the engine may have damage.

CPLs <sup>previously</sup> check with Janice whether the owner will withdraw claim due excess

*Paul*

REF:

40306

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SFM 32T**

at Workshop n/s **SNA HT TEE**

of **3, Pioneer RD North AD1-18**

Insured: **AXA**

Policy No.:

Claims No.:


Sum Insured: Excess: **1300**

(Client's Record)

Make of Veh:

**01 FRONT HIT TP REAR PORTION**  
(Policy Condition) **and also the bonnet.**  
**set some burn marks**

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: **85K**

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

**SFM 32T**

Yr Regn: **2013 / July**

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **JAGUAR XF 2.0L**

C.C. **1999**

Colour: **BROWN**

A/C: Insured / Std / NI / NA

Sp. Reading: **41658**

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **SAJAC05M8DPS 97637**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: **245/452R18**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **6** mm

R/Bal. **6** mm

L/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **22/02/18**

D.O.I. **01/03/19**

Survey held at **SNA HT TEE**

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

**12/31/19** received email from Samantha (exsp) that the owner cancel on claim  
**12/31/19** Submit Prelim report

RECEIVED 12 MAR 2019

Date/Time, File Pass to?

**12/31/19** *Paul*

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☒ Prel. Report

☐ Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee

Transportation

☐ S.P.R. / S

☐ Photos

☐ Others

TOTAL

100

100



## Service Request Details

Claim

S9M01FFW

Reference

None 

Loss Date

February 22, 2019

Report Date

Feb 28, 2019 1:02:29 PM

Request Date

February 28, 2019

Due Date

March 7, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

SFM32T

Model  
XF 2.0

### Service Address

---

Blk 3 Pioneer Road North, , , 628457

### Primary Contact/Insured

---

WANG KUN  
31 HINDHEDE WALK, #04-12 SOUTHAVEN 2, 587967, Singapore

CATCATWANG@ME.COM

### Claim Handler

---

TEO Kitty  
6568804602  
kitty.teo@axa.com.sg

Additional Instructions  
EXCESS \$800+\$500(UNNAMED)=\$1300

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

---

New Message

TYPE



SENT

2/28/19 2:40 PM

FROM

TEO Kitty

SUBJECT

WP Survey

BODY

Hi Please advise surveyor's findings on the damag...



## RATAN BHOSALE Pragati

---

**From:** SAMANTHA TAN <sam@sngahtee.com>  
**Sent:** Thursday, February 28, 2019 12:02 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** SNG AH TEE - Samantha / GA130198 / DOA:22/02/2019 / OD:SFM32T / ESTIMATE:TBA  
**Attachments:** SFM32T.PDF  
**Categories:** Pragati

Hi All,

Kindly arrange to survey the above vehicle on 28/2/19 as vehicle is in workshop.

Thank you.

Best Regards

---

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



DATE: \_\_\_\_\_

TO WHOM IT MAY CONCERN

AXA Insurance P/L

RE: ACCIDENT INVOLVING MY VEHICLE NO. SFM 32 T ON 22/2/19 ALONG  
Jurong East Central

I, Yap Geok Eng Richard (the <sup>driver</sup> owner of vehicle SFM 32 T) wish to cancel  
my claim under :-

- ☒ own insurance policy no. GA130198
- ☐ third party against vehicle \_\_\_\_\_
- ☐ windscreen claim under policy \_\_\_\_\_

Acknowledge by Owner



SIGNATURE OF OWNER

Name: Yap Geok Eng Richard

Contact: 96366686



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

5/3/2019

### Survey Details:

Date of loss	22-Feb-19
Date of appointment	28-Feb-19
Date of survey	1-Mar-19
Location of survey	SNG AH TEE MOTOR

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFM 32T
Make and Model	JAGUAR XF 2.0L GTDI
Date of registration	30/7/2013
Excess	\$ 1,300.00
Market Value	\$ 85,000.00
Parf Rebate	\$ 77,315.00
Nett Loss	\$ 7,685.00

### Repair details:

Initial Estimate	\$ 558.50
------------------	-----------

### Proposed/Revised repair cost:

Parts	\$ 441.50
Check items (estimate)	\$ -
Labour	\$ 117.00
<b>Total</b>	<b>\$ 558.50</b>
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE  
HAVE NOT AUTHORISE REPAIR.

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>	<b>#VALUE!</b>	





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

4/3/2019

### Survey Details:

Date of loss	22-Feb-19
Date of appointment	28-Feb-19
Date of survey	1-Mar-19
Location of survey	SNG AH TEE MOTOR

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFM 32T
Make and Model	JAGUAR XF 2.0L GTDI
Date of registration	30/7/2013
Excess	\$ 1,300.00
Market Value	\$ 85,000.00
Parf Rebate	\$ 77,315.00
Nett Loss	\$ 7,685.00

### Repair details:

Initial Estimate	\$ 157.00
------------------	-----------

### Proposed/Revised repair cost:

Parts	\$ 40.00
Check items (estimate)	\$ -
Labour	\$ 117.00
<b>Total</b>	<b>\$ 157.00</b>
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

DAMAGES CONSISTENT. PENDING FOR PARTS PRICES.  
REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE  
REPAIR.

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4030E
<b>Vehicle Details</b>	
Vehicle No.:	SFM32T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2019
Vehicle Make:	JAGUAR
Vehicle Model:	XF 2.0L GTDI
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	130513190106204PT
Chassis No.:	SAJAC05M8DPS97637
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$50,238.00
Original Registration Date:	30 Jul 2013
First Registration Date:	30 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$62,429.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2023
PARF Rebate Amount:	\$43,700.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Jul 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$76,389.00
COE Rebate Amount:	\$33,615.00
<b>Total Rebate Amount:</b>	<b>\$77,315.00</b>

The information contained herein is correct as at 04 Mar 2019

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4030E
<b>Vehicle Details</b>	
Vehicle No.:	SFM32T
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	JAGUAR
Vehicle Model:	XF 2.0L GTDI
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	130513190106204PT
Chassis No.:	SAJAC05M8DPS97637
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$50,238.00
Original Registration Date:	30 Jul 2013
First Registration Date:	30 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$62,429.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2023
PARF Rebate Amount:	\$43,700.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Jul 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$76,389.00
COE Rebate Amount:	\$33,676.00
<b>Total Rebate Amount:</b>	<b>\$77,376.00</b>

The information contained herein is correct as at 28 Feb 2019

OK

85,000  
77,376  
-----  
7,624  
-----

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/02/2019 15:26
Date Of Accident	22/02/2019 22:30
Exact Location Of Accident	JURONG EAST CENTRAL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFM32T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WANG KUN
NRIC No	S7284030E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90083012
Alternative Phone No	OFFICE-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	JAGUAR
Model	XF-2.0 L GTDI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA130198
Cover Note Number	
<b>Driver</b>	
Name of Driver	YAP GEOK ENG RICHARD
NRIC No	S1402694J
Date Of Birth	07/10/1960
Occupation	INDOOR
Date Of Driving Pass	15/09/2012
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96366686
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	31 HINDHEGE WALK #04-12
Postcode	587967
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WANG KUN GENDER: : FEMALE
Passenger 2	NAME: : YAP JIAN LIANG RYAN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL

# Sketch Plan Pg. 2



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/01/19 @ around 22.30 pm, vehicle was stopped along Jurong East Central when smoke and burning smell was discovered. Before that when we travel along Bukit Batok East Ave 6 we felt the car went over something / unknown followed by a rather large "pop" sound. Unknowingly we carried on our journey and along the way we started to sense smoke smell though no signs of smoke was yet seen. But when we turn left onto Jurong East Central, we smelled more burning smell as well as smoke coming out from the ~~hood~~ <sup>hood</sup> section which we stopped immediately, open the hood then call for assistance. Note: By the time we reached Jurong East Central, the vehicle had stalled.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

☒ Claim own policy  
☐ Claim third party  
☐ Claim OD / TP at other works hop  
☐ For record purpose  
Policy No. GA130191  
Insurer AXA Veh.No. SFM327

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

STANDARD SUBSCRIPTION V2



**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

**Claim Reference:**

**Assessment number: SFM32T-AXA-OD**

**Version: 1810**

**Date calculated: 02/28/2019 12:06 PM**

**Full Report**

**Registration: SFM32T**

**Printed: 28/02/2019 12:06 PM**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	JAGUAR
Model:	XF (X250)
Sub Model:	BASE MODEL
Model Sheet Number:	29 21 01
Registration:	SFM32T
VIN number:	SAJAC05M8DPS97637
Odometer:	

**Model Specs**

FROM VIN S 93359	ELECTRIC DOOR MIRROR	ELEC INTERIOR MIRROR	KEYLESS ENTRY/START
FOLDING DOOR MIRRORS	D/MIRROR WITH MEMORY	BLUETOOTH INTERFACE	NAVIGATION SYSTEM
RADIO WITH CD	REARVIEW CAMERA	XENON HEADLAMP	L/6-WAY SEAT ADJUSTM
R/6-WAY SEAT ADJUSTM	PEDESTRIAN PROTECT	FRONT PARKING SYSTEM	DESIGN RADIAT GRILLE
FRT BUMPER MLDG CHR	REAR PARKING SYSTEM	2.0 LTR 177KW	REAR WHEEL DRIVE
8-GEAR AUTOMATIC	CRUISE CONTROL	TYRES 245/45 WR 18	EMERGENCY WHEEL 18"
WHEELS 8.5J X 18 ALU	SALOON	RR SPOILER BUMPER	TWO COAT METALLIC

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

Claim Reference:  
 Assessment number: SFM32T-AXA-OD  
 Version: 1810  
 Date calculated: 02/28/2019 12:06 PM

Full Report  
 Registration: SFM32T  
 Printed: 28/02/2019 12:06 PM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
10-10-10	PREPARATION TIME		1.0	4.50
76-11-41	R + R LOWER ENGINE PROTECTION		2.0	9.00
19-10-31	R + R AIR FILTER INTAKE		2.0	9.00
12-10-43	R + R ACCESSORY DRIVE BELT		2.0	9.00
NO NUMBER	R + R CRANKSHAFT VIBRATION DAMPER		8.0	36.00
12-29-43	R + R CAMSHAFT COVER		11.0	49.50
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>2.60</b>	<b>26.0</b>
<b>Total of Labour</b>				<b>117.00</b>

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01
				Price SGD

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

Claim Reference:  
 Assessment number: SFM32T-AXA-OD  
 Version: 1810  
 Date calculated: 02/28/2019 12:06 PM

Full Report  
 Registration: SFM32T  
 Printed: 28/02/2019 12:06 PM

Code	Description	Part Number	Supplier	Price SGD
7961	CYL HEAD COVER GSKT	JDE27464	Rec	0.00
8271	CRANKSHAFT GEAR pulley	AJ813107	Burnt	0.00
8433	V-BELT	C2D19766	cut	0.00
f: OEM Parts				0.00
n: Non-OEM Parts				
u: Used parts				
<b>Savings</b>				
<b>Subtotal</b>				0.00
<b>Total</b>				0.00

**Extras**

Code	Description	Price SGD
1000	COOLANT COOLANT Rec	40.00*
<b>Total Extras</b>		40.00

**Final Calculation**

	SGD	SGD
<b>Labour Time Base 10 WU/h</b>		
Total 26.0 WU X 45.00 SGD/h	117.00	
<b>Total of Labour</b>		117.00
<b>Total Of Extras</b>		40.00
<b>Repair Cost Excludes GST</b>		157.00
GST (+7.0%)		10.99
<b>Repair Cost Included GST</b>		167.99

**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

5 days  
 P/P  
 01/03/19 @ 1430  
 EXCESS: 1300  
 REVERT  
 Resurvey before paint

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

**Claim Reference:**

**Assessment number: SFM32T-AXA-OD**

**Version: 1810**

**Date calculated: 03/05/2019 01:41 PM**

**Full Report**

**Registration: SFM32T**

**Printed: 05/03/2019 1:41 PM**

## Summary Information

### Claim

**Location:** Singapore (SG)

**Printed by:** DARREN SNG

**Claim Reference:**

**Estimated Repair Time:**

**Actual Repair Days:**

**Work Provider:**

**Currency:**

**Date of Incident:**

**Hire Car Start:**

**Hire Car End:**

**AXA Insurance Pte Ltd**

**SGD**

**2019-02-22**

## Vehicle Details

### Vehicle

**Manufacturer:**

**JAGUAR**

**Model:**

**XF (X250)**

**Sub Model:**

**BASE MODEL**

**Model Sheet Number:**

**29 21 01**

**Registration:**

**SFM32T**

**VIN number:**

**SAJAC05M8DPS97637**

**Odometer:**

### Model Specs

**FROM VIN S 93359**

**FOLDING DOOR MIRRORS**

**RADIO WITH CD**

**R/6-WAY SEAT ADJUSTM**

**FRT BUMPER MLDG CHR**

**8-GEAR AUTOMATIC**

**WHEELS 8.5J X 18 ALU**

**ELECTRIC DOOR MIRROR**

**D/MIRROR WITH MEMORY**

**REARVIEW CAMERA**

**PEDESTRIAN PROTECT**

**REAR PARKING SYSTEM**

**CRUISE CONTROL**

**SALOON**

**ELEC INTERIOR MIRROR**

**BLUETOOTH INTERFACE**

**XENON HEADLAMP**

**FRONT PARKING SYSTEM**

**2.0 LTR 177KW**

**TYRES 245/45 WR 18**

**RR SPOILER BUMPER**

**KEYLESS ENTRY/START**

**NAVIGATION SYSTEM**

**L/6-WAY SEAT ADJUSTM**

**DESIGN RADIAT GRILLE**

**REAR WHEEL DRIVE**

**EMERGENCY WHEEL 18"**

**TWO COAT METALLIC**

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

**Claim Reference:**  
**Assessment number: SFM32T-AXA-OD**  
**Version: 1810**  
**Date calculated: 03/05/2019 01:41 PM**

**Full Report**  
**Registration: SFM32T**  
**Printed: 05/03/2019 1:41 PM**


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
10-10-10	PREPARATION TIME		1.0	4.50
76-11-41	R + R LOWER ENGINE PROTECTION		2.0	9.00
19-10-31	R + R AIR FILTER INTAKE		2.0	9.00
12-10-43	R + R ACCESSORY DRIVE BELT		2.0	9.00
NO NUMBER	R + R CRANKSHAFT VIBRATION DAMPER		8.0	36.00
12-29-43	R + R CAMSHAFT COVER		11.0	49.50
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>2.60</b>	<b>26.0</b>
<b>Total of Labour</b>				<b>117.00</b>

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01
				Price SGD

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

**Claim Reference:**

**Assessment number: SFM32T-AXA-OD**

**Version: 1810**

**Date calculated: 03/05/2019 01:41 PM**

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Full Report**

**Registration: SFM32T**

**Printed: 05/03/2019 1:41 PM**

Code	Description	Part Number	Supplier	Price SGD
7961	CYL HEAD COVER GSKT	JDE27464	nee ✓	45.00
8271	CRANKSHAFT GEAR	AJ813107	Burnt ✓	250.00
8433	V-BELT	C2D19766	CUT ✓	70.00
f: OEM Parts				0.00
n: Non-OEM Parts				365.00
u: Used parts				36.50
<b>Savings</b>				
<b>Subtotal</b>				365.00
<b>Addition(+10.00%)</b>				36.50
<b>Total</b>				401.50

**Extras**

Code	Description	Price SGD
1000	COOLANT COOLANT nee ✓	40.00*
<b>Total Extras</b>		40.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	365.00	
<b>Total Parts</b>	36.50	401.50
<b>Labour Time Base 10 WU/h</b>		
Total 26.0 WU X 45.00 SGD/h	117.00	
<b>Total of Labour</b>		117.00
<b>Total Of Extras</b>		40.00
<b>Repair Cost Excludes GST</b>		558.50
GST (+7.0%)		39.10
<b>Repair Cost Included GST</b>		597.60

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
Acknowledged by Repairer  
Signature:  
Date:

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

Claim Reference:

Assessment number: SFM32T-AXA-OD

Version: 1810

Date calculated: 03/05/2019 01:41 PM

Full Report

Registration: SFM32T

Printed: 05/03/2019 1:41 PM

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS