

ASS. REF. NO.

REF: CS3/FCI/19003796/Tld302

and Instruction

Car/Vehicle

ASSIGNMENT (Office)

CWS

From (Person)

Henry KAO

of

FCI

Date/Time:

27/2/19 @ 4:55pm

Estimated Cost:

Bill for

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 19772

Insured

SHC 0988P

at Workshop n/o:

SKM Motor Works

Tel:

96407853

of

10 kaki Bukit Rd 2 #03-31

Policy No:

Claim No:

D1900408MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/2/2019

CA / REV / REP. / REV 24 HRS

(up)

11/3/19 @ afternoon.

(I.O.D. Endorsement)

Date/Time:

28/2/19 @ 10:03am

Person Contacted:

Yoke peng

Vehicle IN/OUT

(C)

Date/Time

Action/Instruction (X) Estimate

SKM19772 - X

SHC 988P - NS/INC13082771/Hlgm

D.O.A. 5/2/13

After repair: 7/3/2019

Dismantle: 5/3/2019

Barcode

Tanpin

REF: FCI

PPS

ASSIGNMENT

From: Date: 1/3/19
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLP 19772
at Workshop m/s SKM Motor works
of 10kaki Bkt Rd 2 #03-31

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Afternoon

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLP 19772 Yr Regn: 2017 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

C.C. 1498

Colour:

Black

A/C Insured / Std / NI / NA

Sp. Reading

3071

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

344 MGK58504.X201395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

01/03/19 533p

Survey held at

SKM Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

45000 - 46000, 6 days

RECEIVED 15 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: PRE

Lump Sum / I.B.I. (\$

150

150

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8750F
Vehicle Details	
Vehicle No.:	SLP1977Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B31191023
Chassis No.:	JHMGK5850HX201395
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,910.00
Original Registration Date:	29 May 2017
First Registration Date:	29 May 2017
Transfer Count:	0
Actual ARF Paid:	\$12,910.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2027
PARF Rebate Amount:	\$9,682.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$41,489.00
Total Rebate Amount:	\$51,171.00

The information contained herein is correct as at 15 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 15:09
Date Of Accident	25/02/2019 09:25
Exact Location Of Accident	SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP1977Z
Insured/Policyholder	
Name Of Registered Owner	PECK KENG YEOW
NRIC No	S7818750F
Email Address	KY.PECK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97978342
Alternative Phone No	OTHERS-93374235

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	29081988-DUP
Cover Note Number	

Driver

Name of Driver	CHENG SIEW PING
NRIC No	S7972016Z
Date Of Birth	02/07/1979
Occupation	INDOOR
Date Of Driving Pass	12/02/2010
Driving Experience	9 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93374235
Fax Number	
Contact Number	
EEmail Address	CSPGIRL@HOTMAIL.COM

Address	BLK 721 TAMPINES ST 71 #05-218
Postcode	520721
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REQUEST FROM OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC988P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	VEHICLE B
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC978T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	VEHICLE C
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJX1544X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VEHICLE D
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	








DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SHD9874V
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	VEHICLE E
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Sketch Plan #2

SKETCH PLAN


Vehicle				
A -				
B -				
 98A77Z	 SHC 988P	 SHC 978T	 SJX 1544X	 SHD 9874V
Legend				
 Vehicle  Motorcycle				

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along SLE towards woodlands. The car in front of me suddenly slow down, therefore I slow down too at a safety distance. The car behind me hit me by the back along with another 3 cars.


DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.


 Policyholder's Signature


Date & Time:

25/04/17 3 pm


 Driver's Signature
 (If driver is not the policyholder)

Date & Time:

25/04/17 250 pm


 Reporting Centre Personnel's Signature

Name:

NRIC/EPN No.:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI19003796/T1cd3e2 Date: 22-04-2019 Code: FCI2	
			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 988P	Veh. Inspected	SLP 1977Z
Policy No.		Coverage (\$)	0.00
Claim No.	D19001408MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	27/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMGK5850HX201395	Colour	BLACK
Odometer	30791 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	6 mm
L/H Front Tyre	185/55 R16	DUNLOP	6 mm
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	25/02/2019	Inspect Date / Time	01/03/2019 (05:30 PM)
Survey held at	SKM MOTOR WORKS 10 KAKI BUKIT ROAD 2 #03-31 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$70,000.00			

Report Ref No. CS3/FCI19003796/T1cd3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.