Ass rec.m.	es FCI	19003798	Agd302	Heitan franc	
Outs 200	AUGUS	NMENT (Office	(-)		
CWS Journ	ne yorg	FCI	Da	10/1mm 27/2/19	@3.06pm.
Listimated Cost		Bill to:			
	OF RESTEVATING IM	V7CS			
To Inspect Vehicle Ho	4.1	9667L		SHB 4/67>	
at Workshop m/s	AAK LOO	gistics	Tel	66650190/6	6776227
of	13 lk 153 13 l	Ct Butok s	+.11 #03-	292	
Policy No:		Claim Ho	2500	1430MPSH	
Sum Insured		Excess		100 1101	
Make of Veh: (Client's Record)		. *0	D.C	100 10 25 A.	9
CA / REV / REP. / RI	6V 24 HRS /up?			113/19	
Date/Time 28/2/190	10.07am · Person Contact	ed pei ju	AUN Vehic	is IN OTT	
YP9.	nuction (~) Estim 667 L-CCA/ASM10	1001806/N	663	DUA: 25/1	119
SAB	4167x-cc4/AS	M 1900180	6/Neb3	DUA: 21	11/10
13/19 (018.1400	rensed to To	anne yore	by ene	1-	Luberteinfam
16/10/19 Intere	rensed to Jo. A preli-report		1		
	1,000				

RFF;

Aberl	GSMEST.
To Inspect Vehicle No. 49 9667L	Well 16 49967L Truck /
at Workshop unto AME LOUSTICS	Colour NATE A/C Insured / Std / NI / NA
H, Parjurn Close	Sp.Reading 979/ T/Radio: Insured / Std / NI / NA
H, Parnen Close	Eng/No:
PolicyHo	CINO. FES 21 EA 25370.
Claims No.	Gen. Good (Fa) / Poor / Burnt
Sum Insured: Excess:	Steering: mordey/ Jammed / Leakod / Burnt or
(Gleen's Record)	Brake: morder / Jammed / Leaked / Burnt or
Make of Veh	Modi: AiD S/Rim / STD A/Rim or
(Policy Condition) Remark The veh had commenced its repair at the time of inspection. Bal or Market Value: IDAC Accident Prort: GIA APR Seen: Consistent? Yes or No Consistent? Yes or No Lum Sum: Ways Res: Yes or No Lum Sum: Ways Res: Yes or No Vehicle: IN / OUT Date Fersen Contacted:	R: BS / DRIV EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO OF Front Rear R/Bal. 7 mm R/Bal. 7/7 mm L/Bal. 7/7 mm D.O.A. 25/61/19 D.O.I. 01/03/19 Survey held at #KK LOS LS RC Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or PST N/S The U/C / Chassis frame / Body Structure affected due to collision.
Date : Time Action / Instruction	
RECEIVE	D 1 6 OCT 2019
1,00	

Date/Time, File Pass to? : Prell. Report	Days Of Repair:		
1 16 10 MMer : Final Report	Resurvey No. of Trip:	Survey Fee:	130
Oales/hine, Fale Return In/	Add Fee: Site Ipsp (\$	Transportation) STARS G	60
	 Interview (\$	1 Thous	36
Report Format :	Carry true (\$	Y Ciffical	
Lump Sum / LE Line	W/2 1 (\$	and the second	•
	Transaction of the Control of the Co	trobj	216



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

26-02-2019

Our Ref No. D19001430MFSH

Accident Date

25-01-2019

Claim Type. Third Party

Insured Vehicle

SHB4167X

Third Party Vehicle. YP9667L

Survey Location

BLK 153 BT BATOK ST 11 #03-292

Contact Person.

PEIJUAN

Contact No.

66650190/66776227

Fax No. 65619509

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AAK LOGISTICS

SERVICES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Rasul (LKKAuto)

From:

Peijuan <auto@aakls.com>

Sent:

Tuesday, 15 October, 2019 5:45 PM

To:

Rasul (LKKAuto)

Subject:

RE: YP 9667L DOA: 25/01/19

Hi Rasul,

Confirm at \$ 1,900.00 / 4 days lump sum

Best regards, Peijuan AAK 4 Penjuru Close Singapore 608574 Tel: 66776227

From: Rasul (LKKAuto) < Rasul@lkkauto.com> Sent: Tuesday, 15 October 2019 5:37 PM

To: Peijuan <auto@aakls.com>

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

But need to confirm the finalised amount

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

From: Peijuan [mailto:auto@aakls.com] Sent: Tuesday, 15 October, 2019 4:40 PM

To: Rasul (LKKAuto)

Subject: RE: YP 9667L DOA: 25/01/19

Hi Rasul,

Close case. No claim.

Best regards, Peijuan AAK 4 Penjuru Close Singapore 608574

Tel: 66776227

From: Rasul (LKKAuto) < Rasul@lkkauto.com> Sent: Tuesday, 15 October 2019 2:47 PM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Any update?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

From: Rasul (LKKAuto)

Sent: Wednesday, 24 July, 2019 9:57 AM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Kindly assist to finalise

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

From: Rasul (LKKAuto)

Sent: Thursday, 20 June, 2019 9:25 AM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Kindly confirm the amount

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth Print only when necessary

From: Rasul (LKKAuto)

Sent: Wednesday, 12 June, 2019 5:55 PM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Kindly confirm the amount

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

From: Rasul (LKKAuto)

Sent: Thursday, 23 May, 2019 10:03 AM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Kindly confirm the finalised amount

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

From: Rasul (LKKAuto)

Sent: Friday, 17 May, 2019 5:54 PM

To: auto@aakls.com

Subject: RE: YP 9667L DOA: 25/01/19

Hi Peijuan,

Kindly assist

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

From: Rasul (LKKAuto)

Sent: Thursday, 4 April, 2019 4:38 PM

To: 'auto@aakls.com' Cc: Shiau Chan (LKKAuto)

Subject: YP 9667L DOA: 25/01/19

Hi Peijuan,

Refer to attachment Finalise amount is at \$ 1,900.00 / 4 days lump sum Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 11 March 2019 12:14 PM

To:

'CWS Motor Claims'; assignments

Cc:

'Joanne Yong Lai fong'; SUR

Subject:

RE: SURVEY ASSESSMENT - D19001430MFSH/1

Attachments:

CSFCI19003798R1qd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of YP 9667L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 28 February 2019 10:09 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19001430MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 27 February 2019 3:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19001430MFSH/1

Dear Sir/Mdm,



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Your Ref: D19001430MFSH

Date: 11 March 2019

Our Ref: CS/FCI19003798/R1qd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. YP 9667L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on $\underline{01/03/2019}$ at the premises of M/s <u>AAK LOGISTICS</u>, and have the following to report:-

Workshop Estimate Amount	: S\$	3,671.00	
Revised Estimate Amount	: S\$	2,971.00	
"Check" Items Amount	: <u>S</u> \$	-	
Market Value	: <u>S</u> \$:=:	
LTA Reimbursement Value	: <u>S\$</u>	•	
Nett Value	: <u>S\$</u>	3=3	

Description of Damage:

<u>The vehicle sustained damages</u>
at the front n/s portion.



Yours faithfully

Rasul Automotive Assessor Vehicle Registration Number of Driver's Own Vehicle (if applicable)

Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Unknown - TP REVERSED Type Of Accident

Weather Conditions Clear Road Surface Dry

Other Information

Was any body injured in the Accident? No Was any other material or property damaged?

Yes

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

GW6512X Vehicle Registration Number Vehicle Make/Model/Colour NISSAN,

Details Of Properties

CHEN YI Name of Driver G8180098M NRIC/Passport Number 91233551 Contact Number

BLK 76 BEDOK NORTH RD Address

#05-184 460076 Postcode

Insurance Company Name Chartis Singapore Insurance Pte Ltd NO VISIBLE DAMAGED Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number **Email Address**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	11/02/2019 10:44
Date Of Accident	25/01/2019 20:00
Exact Location Of Accident	ALONG PIE CHANGI
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	YP9667L
Insured/Policyholder	
Name Of Registered Owner	AAK LOGISTICS SERVICES PTE LTD
Co Reg No	201325787M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66650190
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FEB21EA25370
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCX/P2219280
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD SHAFIIE BIN ROSLAN
NRIC No	S9630271A
Date Of Birth	03/09/1996
Occupation	OUTDOOR
Date Of Driving Pass	21/08/2017
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92397439
Fax Number	

NOEMAIL

Address BLK 731 JURONG WEST ST 72

#03-35

Postcode 640731

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Number of Passengers (including

2 NAME:

: AIDIL

Passenger 1

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON MENTIONED DATE AND TIME, I WAS TRAVELLING ALONG PIE TOWARDS CHANGI ON THE THIRD LANE, WHEN A TAXI SHB4167X FROM FILTER LANE JOIN THE MERGING LANE TO THE EXPRESSWAY. THE TAXI DRIVER LIM TIONG HO ADMITTED HIS FAULT FOR DASHING IN MY LANE AND WANTED TO DO PRIVATE SETTLEMENT AND TOLD ME THAT HE WOULD CALLED ME AND BEAR THE COST FOR MY DAMAGE REPAIR, SO I GAVE HIM MY CONTACT NUMBER. I WAS IN A RUSH AND FORGET TO TAKE HIS CONTACT NUMBER. SO I WAITED FOR MORE THAN 5 DAYS WHEN MY COMPANY TOLD ME THE TAXI MAKE A THIRD PARTY CLAIM INSURANCE REPORT AGAINST ME.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB4167X

Vehicle Make/Model/Colour

Details Of Properties

TAXI

Vehicle Category

LIM TIONG HO

Name of Driver NRIC/Passport Number

S1329131D

Contact Number

Address

BLK 559 ANG MO KIO AVE 10 #03-1850

Postcode

560559

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

KETCH PLAN		
Fu Then I a		A-SHB4167 V B-YP9667 L
- CIES ON	E FAT	
FILTER LAN	BD	5- 2F 7667L
SCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
	OF THE ACCIDENT	
Refer report		
ECLARATION	15.5	55 3ERV(C)
We declare the foregoing partic	ulars are true in every respect.	(auto)
	- 1 455	S S S
No.	- A 000	7
The street of th	Driver's Signature	Reporting Centre Personnel's Signature
licyholder's Signature ste & Time:	(If driver a not the policyholder)	Name: JAMIANA

AAK LOGISTICS SERVICES PTE LTD Bik 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

CDG Claims Control

claimscontrol@comfortdelgro.com

Quotation

DATE: 26-Feb-19 TERMS: 30 Days PAGE NO.: Page 1 of 1

1 F 2 F 3 S 4 H 5 H	Front Bumper 34/ Front Bumper Cover LH M15 Signal Lamp LH CAA Headlamp LH CAA Headlamp Garnish LH CAA CABOUR CHARGES To Spray Painting To Panel Beat To dismantle/replace above-mentioned parts	Mineral Do	\$949.00 \$ \$333.00 \$ \$251.00 \$ \$471.00 \$ \$217.00 \$	949.00 333.00 5 251.00 471.00 217.00
2 F 3 S 4 H 5 H 1 T 2 T	Front Bumper Cover LH M15 Signal Lamp LH CAA Headlamp LH CAA Headlamp Garnish LH CAA LABOUR CHARGES To Spray Painting To Panel Beat	11/3/	\$333.00 S \$251.00 S \$471.00 S	333.00 251.00 471.00
2 F 3 S 4 H 5 H 1 T 2 T	Front Bumper Cover LH M15 Signal Lamp LH CAA Headlamp LH CAA Headlamp Garnish LH CAA LABOUR CHARGES To Spray Painting To Panel Beat	(1/3/	\$333.00 S \$251.00 S \$471.00 S	333.00 251.00 471.00
3 S 4 H 5 H 1 T 2 T	ABOUR CHARGES To Spray Painting To Panel Beat	(1/3/10)	\$471.00 S	471.0
5 E	ABOUR CHARGES To Spray Painting To Panel Beat	(1/3)		
1 T 2 T	ABOUR CHARGES To Spray Painting To Panel Beat	(1/3)	9750 (450 4	\$500.0
1 T 2 T	To Spray Painting To Panel Beat	11/3/	9750 (450 4	\$500.0
2 T	To Panel Beat	1 11/3	9 950 4	\$500.0
-		1 /1/21	1 430 4	
	o distinuity replace doors institutioned parts			\$200.0
				\ J200.0
		'K ASUL		
			46	
		40 ground	68	
	LKK Auto Consultants hence notify	1		
	the Repairer of the following:	tr Day	Λ	
	To resurvey before spray painting	4 CXWY	D	
	To display damaged part(s) during resurvey	.1/		
	Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	4>		
	No Illegal modification(s) is allowed	1 1	0	
	Supplementary item(s) must be resurveyed and	01/03/19	@1050	
	is subject to final approval from Insurance Company	01/03/19 Rasm af		
	and the second s			
	Acknowledged by Repairer	& cun 9 F	to your	
	Signature:	10.	•	
	Dates			
		E. & O. E.	SUB-TOTAL	\$3,671.0
D . T	THEE THOUGAND BLY HUNDRED BEVENTY ONE AND OFFICE	NINETY OF YEAR ONLY	7% GST	\$256.9
5U. I	HREE THOUSAND SIX HUNDRED SEVENTY-ONE AND CENTS	NINE I Y-SEVEN ONLY.	TOTAL	\$3,927.9

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd.".

AAK LOGISTICS SERVICES PTE LTD

Authorised Signature

1665.75 750100 2415.75 2020 1932.60 4 day

Page 1 of 1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	M T T T T T T T T T T T T T T T T T T T	Affiliated to Federation Internation	onale Des Experts En Automo	bile
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI19003798	/R1qd3e2
	ROBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 17-10-2019 Code: FCI2	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SHB 4167X	Veh. Inspected	YP 9667L
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19001430MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	27/02/2019
2.		Vehicle Parti	culars & Condition	
	Make & Model	MITSUBISHI CANTER FEB21	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	FEB21EA25370	Colour	WHITE
	Odometer	9791	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3.		Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	DUNLOP	7 mm
	L/H Front Tyre	195/85 R15	DUNLOP	7 mm
	R/H Rear Tyre	195/85 R15 (D)	DUNLOP	7/7 mm
	L/H Rear Tyre	195/85 R15 (D)	DUNLOP	7/7 mm
4.			on of Damages	
		STAINED DAMAGES AT THE FR	CONT N/S PORTION.	
5.	DAMAGES SEE D		I Information	A CHARLES TO SERVE
	Accident Date	25/01/2019	Inspection Date	01/03/2019
	Survey held at	4 PENJURU CLOSE	ep.aanan/ aana	SENSORE STREET STREET
	Repairer	AAK LOGISTICS SERVICES PI	Ĺ	
5a.		R	emarks	
	B)THE INSPECTION	ISISTENT TO ACCIDENT REPOR ON WAS CONDUCTED ON A"WI" DE TO YOUR INSTRUCTIONS, V	THOUT PREJUDICE" BASIS	
5b.		Estimate	Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9667L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BENT	949.00	949.00
1	FRONT BUMPER COVER LH	MISSING	333.00	333.00
1	SIGNAL LAMP LH	CRACKED	251.00	251.00
1	HEADLAMP LH	CRACKED	471.00	471.00
1	HEADLAMP GARNISH LH	CRACKED	217.00	217.00
	LESS 25% DISCOUNT			-555.25
			2,221.00	1,665.75
	LABOUR			
	TO SPRAY PAINTING.		500.00	300.00
	TO PANEL BEAT.		750.00	450.00
	TO DISMANTLE/REPLACE ABOVE-MENTIONED PARTS.	NOT NECESSARY	200.00	-
			1,450.00	750.00
	GRAND TOTAL		3,671.00	2,415.75
Service Control	DECOMMENDED COST OF LUMP SUM DEPAIRS			1 900

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		
(REPAIR COST NOT CONCLUDE)		

Report Ref No. CS/FCI19003798/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

XXX.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.