

Number

Auto Body No.

Auto Year

CWS

From Person

Meina Chien

CS/FCI 19003807 / 1/3/2019

ASSIGNMENT (Office)

FCI

Date/Time

9:47am @ 28/2/19

Estimated Cost

Bill No.

OD / IT / WS / IT RES / OD RES / EVA / INV / MY / CS

To Impact Vehicle No.

SDE 7123J

Insured

SHA 9232M

at Workshop on

Kah Motor
15 Ubi Rd 4

Tel

8100 6306

Policy No.

Claim No.

D19001450MF SH

Sum Insured

Excess

Make of Veh

(Client's Record)

N

D.O.A

26/02/2019

CA / REV / REP / REV 24 HRS DS

H.O.D. Endorsement

Date/Time

11:00am @ 28/2/19

Person Contacted

Any

Vehicle

IN LOU

Date/Time

Action/Instruction (✓) Estimate

SDE 7123J - X

SHA 9232M - CS/FCI 15001154 / 1/1/2019

DoA: 14/1/19

07/03/19 @

10:14 p.m. received RA to Meina via email

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

5132.64

Veh No:

SDE71237

Yr Regn:

5117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HR-V

cc

1496

Colour

S. blue

A/C:

Insured / Std / NI / NA

Sp. Reading

49662

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1810GX202158

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

26/4/19

D.O.I.

4/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 11 MAR 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

5132.64

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

11x15

170+60

50

50

34

364

MOTOR SURVEY ASSIGNMENT

Date	27-02-2019	Our Ref No. D19001450MFSH
Accident Date	26-02-2019	Claim Type. Third Party
Insured Vehicle	SHA9232M	Third Party Vehicle. SDE7123J
Survey Location	15 UBI ROAD 4	
Contact Person.	ARY CHUA WAI NGEE	
Contact No.	81006306/ 81006306	Fax No. 67480770
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8642C
Vehicle Details	
Vehicle No.:	SDE7123J
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	L15B4532158
Chassis No.:	JHMRU1810GX202158
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,951.00
Original Registration Date:	03 May 2017
First Registration Date:	03 May 2017
Transfer Count:	0
Actual ARF Paid:	\$14,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2027
PARF Rebate Amount:	\$11,213.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$42,422.00
Total Rebate Amount:	\$53,635.00

The information contained herein is correct as at 04 Mar 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.68% P.A Low Interest @ GY
Finance: \$0 Admin Fees. \$2500
Downpayment Monthly \$638
GY Credit Pte Ltd StarAd



HIN LUNG AUTO

Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category

3 vehicles

Honda HR-V

Advanced Search Submit

Sort by Date Posted

20 results/page

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda HR-V		Any	Any	2017	Any	Any	Any	Available
	Honda	HR-V 1.5A DX	\$77,999	\$8,420 /yr	19-Jul-2017	1,496 cc	40,000 km	SUV	Available
Just Arrive! 1 Owner, Beautiful Black On Black Interior.Fully Agent Unit 5 Years Warranty (Kah Motor), Very Low Depre, Peace Of Mind Getting From Us, Premium Pre-Owned 110 Points Certification. Flex...									
Premium Automobiles									
Posted: 28-Feb-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda	HR-V 1.5A DX	\$73,800	\$8,360 /yr	19-Jan-2017	1,496 cc	-	SUV	Available
1 Owner January/2017 Sporty White Honda Hrv On Sale Now! \$8k+ Depreciation For This HRV! Much Better And Quiet Driving Honda SUV! Kah Motor Fully Maintained! Kah Motor Warranty Intact! High Loan Avail...									
Posted: 27-Feb-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda	HR-V 1.5A DX	\$73,400	\$8,280 /yr	06-Feb-2017	1,496 cc	23,000 km	SUV	Available
Agent Warranty (5 Years), Well-Maintained, Very Good Condition. Includes First 3 Years Servicing From Kah Motor, Very Low Mileage. Original Leather Seats, Rims, DVD Audio System, Front And Reverse Cam...									
Carro									
Posted: 25-Feb-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 7 March 2019 4:14 PM
To: 'Merina Chia San San'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001450MFSH/1
Attachments: SDE 7123J - Preli Advise .pdf

Dear Merina,

Enclosed preliminary revised of vehicle SDE 7123J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 28 February 2019 11:42 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001450MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 28 February 2019 9:46 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001450MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001450MFSH

Date: 07 March 2019

Our Ref: CS/FCI19003807/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SDE 7123J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/03/2019 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,466.50</u> .
Revised Estimate Amount	: S\$ <u>5,358.32</u> .
"Check" Items Amount	: S\$ <u>133.19</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 - 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/02/2019 19:52
Date Of Accident	26/02/2019 12:55
Exact Location Of Accident	MOUNTBATTEN RD (L/P 74) @ TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDE7123J
Insured/Policyholder	
Name Of Registered Owner	OH HONG LYE
NRIC No	S6938642C
Email Address	HONGLYE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97573069
Alternative Phone No	OFFICE-97573069
Vehicle Particulars	
Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MU005473-R00
Cover Note Number	
Driver	
Name of Driver	TEO CHEE LENG
NRIC No	S7148682F
Date Of Birth	23/12/1971
Occupation	INDOOR
Date Of Driving Pass	05/01/1990
Driving Experience	29 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97503446
Fax Number	
Contact Number	
Email Address	SGLIZARD@YAHOO.COM.SG

Address	BLK 250C COMPASSVALE ST #14-57
Postcode	S543250
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA9232M
Vehicle Make/Model/Colour	HYUNDAI/I40/YELLOW/TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YEO SAIK HWEE
NRIC/Passport Number	S1715816C
Contact Number	96969293
Address	
Postcode	
Insurance Company Name	MS FIRST CAPITAL INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

Vehicle Number: SDE 7123J

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened at the traffic junction of Mountbatten Road towards Fort Road/Kompong Som Road. It was red light and my vehicle SDE 7123J was stopped in front of the traffic light. As the first vehicle, while the third party vehicle, SHA 9232M was stopped behind as the second vehicle, while all were waiting, before the light turned green and it was still red light, the third party vehicle, SHA 9232M moved forward and hit the rear of my vehicle. According to the driver of third party vehicle, he was sweeping away a cockroach on his leg thus releasing the brake pedal. This caused his vehicle to move forward.


DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 26 Feb 2019
4pm



Driver's Signature

(If driver is not the policyholder)

Date & Time: 26 Feb 2019
4pm

17:17pm
26 FEB 2019



Reporting Centre Personnel's Signature

Name: ARY CHUA
NRIC/FIN No.:

Sketch Plan Pg. 1

Vehicle Number: SDE 7123J

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26 Feb 2019
4pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 26 Feb 2019
4pm

Reporting Centre Personnel's Signature

Name: ARY CHUA

NRIC/FIN No.:

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg No.: M7-000023-4)
 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046
 T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmi@sokiomarine.com.sg W: www.sokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP
FORM MX1

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 17-MU005473-R00 (Private Motor Car 24 Months)

1. **Index Mark and Registration Number of Vehicle** SDE7123J **Chassis No.:** JHMRU1810GX202158
2. **Name of Policyholder** MR OH HONG LYE
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 03/05/2017
4. **Date of Expiry of Insurance** 02/05/2019
5. **Persons or Class of Persons entitled to drive***
 - (a) The Policyholder.
 - (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: E2316DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600	
	Windscreen Excess	SGD 100	

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT19000930	Page	1
	36 ROBINSON ROAD	Date	: 26. Feb 2019		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SDE7123J	Engine No	: L15B4532158		
Chassis No	: JHMRU1810GX202158	Date Time	: 26. Feb 2019 7:54:31 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	: D/D : +65 6846 5573		
Owner's Name	: OH HONG LYE	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: 17-MU005473-R00	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 26/2/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72246)						
	OWNER: OH HONG LYE						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 26-02-2019@12.55PM						
	ACC: MOUNTBATTEN RD (LP 74) TRAFFIC JUNCTION						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHA9232M - HYUNDAI/I40/YELLOW/TAXI						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
33502-T7A-J01	LAMP UNITR.	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSY,LID	1	269.90	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
74890-T7A-J12ZS	GARNISH ASSYRR.LICENSE	1	189.80	25	142.35	9.96	152.31
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM.RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
73211-T8N-T01	GLASS SETRR.WINDSHIELD	1	739.80	25	554.85	38.84	593.69
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
71501-T7B-000	FACE RR.BUMPER	1	777.90	25	583.42	40.84	624.26
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51

Printed on 26/2/2019 8:30:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SDE7123J

Chassis No : JHMRU1810GX202158

Model : HRV DX-SIN CVT YM 2016

Owner's Name : OH HONG LYE

Ins Policy No. : 17-MU005473-R00

Date of Accident : 26/2/2019

Document No. : SQT19000930 Page 2

Date : 26. Feb 2019

Customer No. : WZF002

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4532158

Date | Time : 26. Feb 2019 7:54:31 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04718-T7A-000ZZ	FACEL RR BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
71593-T7A-J00	SPACER R,RR,BPR S	1	16.90	25	12.67	0.89	13.56
71598-T7A-J00	SPACER L,RR,BPR S	1	16.90	25	12.67	0.89	13.56
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	156.30	25	117.22	8.21	125.43
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18	79.20
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
Sum Item					3966.50	277.67	4,244.17
BOSUN	SUNDRIES	1	60.00	20	60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	X	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00	80	160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	130	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	X	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION (N)	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	X	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	380	550.00	38.50	588.50
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	2800.00	1350	2800.00	196.00	2996.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	4800.00	1120	4800.00	336.00	5136.00
Sum Labor					10500.00	735.00	11,235.00

Printed on 26/2/2019 8:30:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SDE7123J

Chassis No : JHMRU1810GX202158

Model : HRV DX-SIN CVT YM 2016

Owner's Name : OH HONG LYE

Ins Policy No. : 17-MU005473-R00

Date of Accident : 26/2/2019

Document No. : SQT19000930 Page 3

Date : 26. Feb 2019

Customer No. : WZF002

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4532158

Date | Time : 26. Feb 2019 7:54:31 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<i>mercus llye</i>						
Date & Time	<i>4/3/19 @ 12.15</i>						
Excess							
Status	<i>not insured</i>						
Signature	<i>Take photo before repair</i>						
	<i>S. Lye</i>						
Total Amount					14,466.50	1,012.67	15,479.17
Total (Inclusive of GST)							<u>15,479.17</u>

Limit of Compensation hence notify the Insurer of the following:

- To ensure satisfactory spray painting
- To ensure damaged part(s) during delivery
- Part prices are subject to confirmation
- The Insurer is not liable for "without Prejudice" basis
- No other compensation is allowed
- Should any damage must be accepted and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Printed on 26/2/2019 8:30:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMRU1810GX202158
License No: SDE7123J
Mileage: 49664
Engine No: L15B4532158

Document No: SVO19013344
Printed By: ARYCHUA
Order Date: 4. March 2019
Order Time: 7:54:31 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 72246) OWNER: OH HONG LYE OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 26-02-2019@12.55PM ACC: MOUNTBATTEN RD (L/P 74) TRAFFIC JUNCTION SURVEYED BY: MARCUS CHUA(LKK) 04/03/2019@12.12PM REF NO: D19001450MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA9232M - HYUNDAI/H40/YELLOW/TAXI						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
68100-T8P-U10ZZ	TAILGATE COMP	1	655.70	25	641.77	44.92	686.69
	SUM PARTS:				1,152.84	80.68	1,233.52
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00		80.00	5.60	85.60
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM(N)	1	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION(N)	1	300.00		300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00		380.00	26.60	406.60
BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40
BP03R	EXT-YBH	1	1,350.00		1,350.00	94.50	1,444.50

WD=5



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMRU1810GX202158
License No: SDE7123J
Mileage: 49664
Engine No: L15B4532158

Document No: SVO19013344
Printed By: ARYCHUA
Order Date: 4. March 2019
Order Time: 7:54:31 PM
Service Advisor: ARY CHUA WAI NGEE

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(3P)

SUM LABOUR:	3,960.00	278.60	4,238.60
TOTAL SGD	5,132.64	359.28	5,491.92

Total Payable (SGD) 5,491.92

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003807/Usd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9232M	Veh. Inspected	SDE 7123J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001450MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	28/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1810GX202158	Colour	SILVER	
Odometer	49662	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	7 mm	
L/H Front Tyre	215/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2019	Inspection Date	04/03/2019	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDE 7123J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	LAMP UNITR. (SN)	NOT NECESSARY	331.12	-
1	LIGHT ASSY,R.LID (SN)	NOT NECESSARY	202.42	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	202.42	-
1	LAMP UNITL (SN)	NOT NECESSARY	331.12	-
1	GARNISH ASSYRR.LICENSE (SN)	NOT NECESSARY	142.35	-
1	EMBLEMRR. (SN)	NECESSARY	9.97	9.97
1	EMBLEM, RR.I-VTEC (SN)	NECESSARY	10.87	10.87
1	GLASS SETRR.WINDSHIELD (SN)	NOT NECESSARY	554.85	-
1	RUBBER CR.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	DAMPER STD 5X5 (SN)	NECESSARY	6.37	6.37
1	RUBBER CL.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (SN)	NECESSARY	15.90	15.90
2	FASTENER B (SN)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.70	5.70
1	FACE RR.BUMPER (SN)	DENTED	583.42	347.77
6	CLIP, BUMPER (SN)	NECESSARY	13.80	13.80
1	FACER.RR.BUMPER CORNER (SN)	NOT NECESSARY	70.57	-
1	FACEL.RR.BUMPER CORNER (SN)	NOT NECESSARY	70.57	-
1	SPACER R.RR.BPR S (SN)	NOT NECESSARY	12.67	-
1	SPACER,L.RR.BPR S (SN)	NOT NECESSARY	12.67	-
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	117.22	-
1	REFLECTOR ASSYL.RR. (SN)	NOT NECESSARY	117.22	-
1	PANEL COMPRR. (SN)	TO REPAIR SEE LABOUR	279.82	-
1	LOCK ASSYTAILGATE (SN)	NOT NECESSARY	59.17	-
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	74.02	-
1	TAIL GATE COMP (SN)	DENTED / BENT	641.77	641.77
1	SUNDRIES (SN)	NECESSARY	60.00	20.00
			4,026.50	1,172.64

Report Ref No. CS/FC119003807/Usd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	BODY JOINT SEALANT.	NOT NECESSARY	100.00	-
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		160.00	80.00
	REMOVE & RENEW REVERSE SENSORS-4PCS.		180.00	130.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR.WINDSCREEN.		350.00	300.00
	RESET VEHICLE SMART KEY ACCESS / ENTRY SYSTEM.		350.00	300.00
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		350.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.	NOT NECESSARY	450.00	-
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		550.00	380.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)		2,800.00	1,350.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF PANEL COMPRR.		4,800.00	1,120.00
			10,440.00	3,960.00
	GRAND TOTAL		14,466.50	5,132.64
RECOMMENDED COST OF REPAIRS				5,132.64

Report Ref No. CS/FCI19003807/Usd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.