

Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

000 Front View Right.JPG



001 Front View Left.JPG



002 Rear View Right.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

003 Rear View Left.JPG



004 Photographs of Damaged Parts.JPG



005 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

006 Photographs of Damaged Parts.JPG



007 Photographs of Damaged Parts.JPG



008 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

009 Photographs of Damaged Parts.JPG



010 Photographs of Damaged Parts.JPG



011 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

012 Photographs of Damaged Parts.JPG



013 Photographs of Damaged Parts.JPG



014 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)


015 Photographs of Damaged Parts.JPG



016 Photographs of Damaged Parts.JPG



017 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

018 Photographs of Damaged Parts.JPG



019 Photographs of Damaged Parts.JPG



020 Photographs of Damaged Parts.JPG




021 Photographs of Damaged Parts.JPG



022 Photographs of Damaged Parts.JPG




023 Photographs of Damaged Parts.JPG





027 Photographs of Damaged Parts.JPG



028 Photographs of Damaged Parts.JPG



029 Photographs of Damaged Parts.JPG





031 Photographs of Damaged Parts.JPG



032 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

033 Photographs of Damaged Parts.JPG



034 Photographs of Damaged Parts.JPG



035 Photographs of Damaged Parts.JPG




Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

036 Photographs of Damaged Parts.JPG



037 Photographs of Damaged Parts.JPG



038 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

039 Photographs of Damaged Parts.JPG



040 Photographs of Damaged Parts.JPG



041 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

042 Photographs of Damaged Parts.JPG



043 Photographs of Damaged Parts.JPG



044 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

045 Photographs of Damaged Parts.JPG



046 Photographs of Damaged Parts.JPG



047 Photographs of Damaged Parts.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

048 Photographs of Damaged Parts.JPG



049 Photographs of Damaged Parts.JPG



050 Photographs of Damaged Parts.JPG



051 Photographs of Damaged Parts.JPG



052 Photographs of Damaged Parts.JPG



053 Photographs of Damaged Parts.JPG



054 Photographs of Damaged Parts.JPG



055 Photographs of Damaged Parts.JPG



056 Photographs of Damaged Parts.JPG




Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)

057 Photographs of Damaged Parts.JPG



058 Photographs of Damaged Parts.JPG



059 Photographs of Damaged Parts.JPG





061 Photographs of Damaged Parts.JPG



062 Photographs of Damaged Parts.JPG



063 Odometer Reading.JPG



064 Chassis Number.JPG



065 Engine Compartment.JPG



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JFJ5557)
066 Road Tax.JPG

