

Vilvan

C 7.48K
R 8.48K

REF:

II

DAY/DATE

62

ASSIGNMENT

6BD3835T

25 Sep 2014

From: _____ Date: _____
Estimated Cost: _____
OD / IP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop n/s: N/S 1
at: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal on Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: 4 days Res: Yes or No

Est. Repairs: 20 % 3 Val: Yes or No

Lum Sum: _____

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle IN / OUT

Veh Title: _____
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Track / Trailer n/s

Make: Nissan cabstar 2953

Colour: Silver Insured / Std / NI / NA

Sp Reading: 160927 Radio: Insured / Std / NI / NA

Eng/No: JN1SC2F2480856515

C.No: _____
Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/70R15

R: 165R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habibead / FALKEN
(nt) (Ren)

Front: _____ R/Bal: S mm

R/Bal: S mm L/Bal: S mm

L/Bal: S mm D.O.I. 11-07-19

D.O.A. w/s 5:30 pm

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Wt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

11/3 Estimate given later.

18/9 Finalized \$2200 with Kheng.

(Reel \$3659.65 / 62%)

4 + 1

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time File Return to?

11

Report Format:

Lump Sum / I.B.F. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Workshop (\$)

Survey Fee:

Transportation

1. S + R. (\$)

2. Phone

3. Other

4. Other

5. Other

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 (Heavy Vehicle #01-08 / Spare Parting #01-27)
Singapore 417921 Tel No. : +65 6841 0051 Fax No. : +65 6541 0510
E-Mail : sales@twin-car.com.sg
Company Reg. No. : 200714910M
GST Registration No. : 200714616M

68416315.
→ Artr. Mr. Quo Quing
21/3/19

COMBI GALLERY PTE LTD

SINGAPORE

Contact : 98002975 - 85253471

ESTIMATE

Repair Code : CLM14432

Date is : 29/12/2018

Vehicle Num : QBD1835T

Model : NISSAN CAHSTAR 3.0 3M/T ABS 2DR 2WD EURO 5

Chassis/Eng# : JN1SC2P24Z0856315/ZD30342098K

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / Cut	1	945.10	945.10
FRONT HEADLAMP LOWER GARNISH - BR.	1	75.00	75.00
FRONT LH CORNER PANEL - Bnc	1	389.90	389.90
FRONT LH DOOR X Repair	1	1396.50	1396.50
FRONT LH DOOR HINGE X	1	56.10	56.10
FRONT LH DOOR STEP GARNISH X SNN	1	139.40	139.40
FRONT LH HEADLAMP / Cut	1	473.40	473.40
FRONT LH SIDE MIRROR X SNN	1	171.80	171.80
FRONT LH UPPER CORNER GARNISH X SNN	1	111.20	111.20
FRONT PANEL 'CAHSTAR' EMBLEM X MC	1	30.00	30.00
Subtotal before discount		1568.3	1568.3
Percentage discount : 10%		10%: 141.47	378.85
Sub-total 1		1722.06	1722.06
FRONT BUMPER CLIPS - SET X SNN	1	50.00	50.00
FRONT GRILLE CLIPS - SET X	1	30.00	30.00
FRONT LH DOOR ART STICKER / MC	1	300.00	100.00
FRONT LH DOOR COMPANY DETAIL STICKER / MC	1	40.00	25 40.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET X SNN	1	50.00	50.00

*** This is a computer-generated document which requires no signature ***

TwinCar AUTOMOTIVE PTE LTD

Kaly's Auto Hub
2 Kall Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6862 0051 Fax No. : +65 6741 0310
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

COMBI GALLERY PTE LTD
SINGAPORE

Contact : 98002975 : 55253471

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE acknowledged by Repairer

Repair Code : CLM14432

Date in : 28/12/2018

Vehicle Num. : GBD3835T

Model : NISSAN CABSTAR 3.0 SM/T ABS 2DR 2WD EURO 5

Chassis/Eng# : IN1SC2P24Z0856515/ZD30342098K

FRONT PANEL ART STICKER - SET

X / 16L

200.00 *50* 200.00

Subtotal before discount

670.00

Percentage discount : 10%

155 0.00

Sub-total 2

670.00

Parts-total

175 4,879.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

30 50.00

To remove, reinstall window glass. (to FR)

NN *X* 50.00

To transfer door glass, regulator gear, motor, ruting, channel, trim board, mechanism lock and handle.

X 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

450 *400* *250* 800.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400 700.00

To apply anti-rust chemical on repaired and replaced panel.

680 *X* 80.00

Labour Total

1,780.00

Parts & Labour Total

5,859.65

850

*** This is a computer-generated document which requires no signature.***

page 2

2196.47 *2557.06* *2747.06*

20%: 1750 2050 2200

4 Days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7298D
Vehicle Details	
Vehicle No.:	GBD3835T
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	ZD30342098K
Chassis No.:	JN1SC2F24Z0856515
Maximum Power Output:	-
Open Market Value:	\$25,386.00
Original Registration Date:	25 Sep 2014
First Registration Date:	25 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$1,270.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$54,009.00
COE Rebate Amount:	\$29,884.00
Total Rebate Amount:	\$29,884.00

The information contained herein is correct as at 12 Mar 2019

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 1 March 2019 9:27 AM
To: Chio Ziting; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Manivel Priyadarshini
Subject: RE: GBD3835T & SHA7925K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: 28022019145649-0001.pdf; 3835.pdf

11:13am 1/3/19
vNI
ziting

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBD3835T and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chio Ziting [mailto:ziting@n51.com.sg]
Sent: 28 February, 2019 5:26 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: GBD3835T & SHA7925K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir / Madam,

We appoint your surveyor from LKK Auto Consultants Pte Ltd.

Please see attached.

Thank you.

On Thu, Feb 28, 2019 at 3:34 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: 28 February, 2019 3:08 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: GBD3835T & SHA7925K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,


Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SKJ3543Y (2608751903SG)**
[SMG6905J]

TP

CHOW MAN JUN, GRACE

Feb 21 2019 6:00AM

[MARIC & PARTNERS PTE LTD]

Volkswagen Centre Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/02/2019 11:08 AM.
To LKK_HQ
CC NoorMariesa,AbuKassim@aig.com
Subject NO OI GIA REPORT

Hi

Kindly be informed that OI has not reported yet. OI details as below :

Name : MARIC & PARTNERS PTE LTD

Address : 19 TAGORE LANE #03-04 9 @ TAGORE SINGAPORE 787472

Thanks

Mariesa

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***GBD3835T (MCT18120797)**
[SHA7925K]

TP

COMBI GALLERY PTE LTD
Dec 28 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Twincar Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/03/2019 14:13 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - GBD3835T - Claim Handler: Priya

Approved:0.00.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 2 April 2019 2:20 PM
To: Sabrina (N-51)
Subject: Accident Involving GBD 3835T & SHA 7925K on 28/12/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: GBD 3835T
Our Ref: CC4/III19003831/Geb3

Dear Sir/Madam,

Accident Involving GBD 3835T & SHA 7925K on 28/12/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Friday, 1 November 2019 9:19 AM
To: Hsiao Tong (LKKAUTO)
Subject: FW: LOD of GBD3835T - Accident Involving GBD3835T & SHA7925K on 28/12/2018
Attachments: GBD3835T.pdf

Reassign case

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin Hui Xin <huixin@n51.com.sg>
Sent: Thursday, 31 October 2019 4:32 PM
To: Admin A <admin-a@lkkauto.com>
Subject: LOD of GBD3835T - Accident Involving GBD3835T & SHA7925K on 28/12/2018

Dear Sir / Madam,

We refer to the above subject.

Attached LOD for your kind perusal.

The original documents will be mailed to your.

Kindly revert to us once received the documents.

Thank you

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Mar 2019 14:07	Clim Veh Model Changed	(202897) NISSAN CABSTAR 2.0 (M).	[A] Lau Shu Pei
2	01 Mar 2019 14:07	Clim Created	Reg No: GBD3835T, Acct Date: 2018/12/28, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Twincar Automotive Pte Ltd (Kaki Bukit)	[A] Lau Shu Pei
3	01 Mar 2019 14:07	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	01 Mar 2019 14:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/12	[A] Lau Shu Pei
5	01 Mar 2019 14:07	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	01 Mar 2019 14:07	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	01 Mar 2019 14:07	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	06 Mar 2019 09:21	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	06 Mar 2019 09:21	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	07 Mar 2019 12:45	Adj Mandate Request	Cur.Reg:0.00:PODS: LIABILITY: 100% REMARK: B:NIL OID REVERSED HIT TP	[A] Asher Sng Rong Yi
11	07 Mar 2019 14:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/12	[I] Priya
12	07 Mar 2019 14:13	Adj Mandate Set	Approved:0.00.	[I] Priya
13	13 Mar 2019 12:01	Adj Adjuster Assigned	ADRIAN LING -> XING GUO QIANG	[A] Lau Shu Pei
14	20 Nov 2019 12:09	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
15	20 Nov 2019 12:09	Clim Dtl Modified	Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
16	20 Nov 2019 12:09	Clim Dtl Modified	JPJ Reg. Date: -> 2014/09/25.	[A] JOANNE LEE KHANG MIN
17	20 Nov 2019 12:09	Clim Details Notified		[A] JOANNE LEE KHANG MIN
18	22 Nov 2019 08:53	Adj Mandate Request	Cur.Reg:2883.00:PODS Liability: 100% *Quantum: (a)CORw/GST: \$2,354.00 + (b)LOU (5days x \$100.00): \$500.00 + (c)LTA/GIA search fee: \$29.00 = Total: \$2,883.00 *Vehicle Model: Nissan Cabstar (2953cc) *4 recommendation repair days + 1PRS = 5days *Factor	[A] CHEW HSIANG TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2351152	20 Nov 2019 12:09:32	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD3835T	SHA7925K	11.77

Print Received Message

This mail is associated with :

*GBD3835T (MCT18120797)
[SHA7925K]

TP

COMBI GALLERY PTE LTD
Dec 28 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Twincar Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/11/2019 10:51 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2883.00) - GBD3835T - Claim Handler: Priya

Approved:2883.00:Request TP WS to issue Tax invoice for Repairs in III's favour

Hsiao Tong (LKKAuto)

From: Chin Hui Xin <huixin@n51.com.sg>
Sent: Tuesday, 17 December 2019 10:29 AM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: Re: LOD of GBD3835T - Accident Involving GBD3835T & SHA7925K on 28/12/2018
//LKK REF: CC4/III19003831/Gpb3

Dear Hsiao Tong,

Refer to the above subject.

We agreed as per offer \$2,783.00

Kindly proceed for payment.

Regards,
Melody Chin
N-51 Automotive Pte Ltd
TWINCAR Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Sat, Nov 30, 2019 at 9:17 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,354.00
2. Loss of Use (5days x \$80.00)	\$ 400.00
3. LTA/GIA Search Fee	\$ 29.00
Total	\$ 2,783.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin Hui Xin <huixin@n51.com.sg>

Sent: Thursday, 31 October 2019 4:32 PM

To: Admin A <admin-a@lkkauto.com>

Subject: LOD of GBD3835T - Accident Involving GBD3835T & SHA7925K on 28/12/2018

Dear Sir / Madam,

We refer to the above subject.

Attached LOD for your kind perusal.

The original documents will be mailed to your.

Kindly revert to us once received the documents.

Thank you

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



...CLAIM SUBFOLDER...(Pending for Survey Report)











































Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2019 Edit Reg		01 Mar 2019 00:00 Edit Adj Rpt	\$52,200.00 Edit Estimates	\$52,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	COMBI GALLERY PTE LTD, Co. Reg. No.: 201527298D								
Vehicle Reg. No.:	GBD3835T	Date of Loss:	28/12/2018 15:00 - :59 [51 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120797	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA7925K	Policy No. (Claimant):	P1817376						
		Excess:							
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (22/11/2019): Alert - Adj Mandate Approved (\$2883.00) - GBD3835T - Claim Handler: Priya III_SG (07/03/2019): Alert - Adj Mandate Approved (\$0.00) - GBD3835T - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD3835T (MCT18120797)
[SHA7925K]
TP
COMBI GALLERY PTE LTD
Dec 28 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Twincar Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
2	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	16/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	16/09/19 17:25	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
16	16/09/19 17:25	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
17	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
18	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
19	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	16/09/19 17:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 14:07	EMAIL FROM III DD 01032019		Load PDF
2	01/03/19 14:07	NOTICE & GIA REPORT		Load PDF
3	21/11/19 16:29	WORKSHOP INVOICE		Load PDF
4	21/11/19 16:29	GIA SEARCH		Load PDF
5	21/11/19 16:29	LOD		Load PDF
6	09/01/20 10:41	AUTHORISATION TO ACT FORM		Load PDF
7	09/01/20 10:41	DISCHARGE VOUCHER		Load PDF
8	09/01/20 10:41	GIROFORM		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 09:27	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19003831/GPA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: GBD3835T Insured Vehicle No: SHA7925K
 Vehicle No: GBD3835T Date of Loss: 28/12/2018 Nature of Claim: TP Claim No: MCT18120797

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD3835T
 Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Engine No: ZD30342098K
 EURO 5 (A)
 Reg. Date: 25/09/2014 (Man. Year: 2014) Chassis No: JN1SC2F24Z0856515
 Colour: Silver Odometer: 160927 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15 Rear Tyre Size: 165 R13
 Front Left Side: Habilead 5 mm Rear Left Side: Falken 5 mm
 Front Right Side: Habilead 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,079.65	1,897.06	2,182.59	53.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	880.00	900.00	50.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,859.65	2,777.06	3,082.59	52.61
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	5,859.65	2,200.00	3,659.65	62.46
+ GST 7.00/7.00% (S\$)	410.18	154.00	256.18	62.46
Nett Amount (S\$)	6,269.83	2,354.00	3,915.83	62.46
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,783.00		

INSPECTION

Date of Assignment: 01/03/2019

Date Inspected: 11/03/2019 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Nov 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3835T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	945.10 FL	*945.10 FL
2	1		*FRONT HEADLAMP LOWER GARNISH	Broken	75.00 FL	*75.00 FL
3	1		*FRONT LH CORNER PANEL	Buckled	389.90 FL	*389.90 FL
4	1		*FRONT LH DOOR	Repair	1,396.50 FL	*- FL
5	1		*FRONT LH DOOR HINGE	Not Necessary	56.10 FL	*- FL
6	1		*FRONT LH DOOR STEP GARNISH	Not Necessary	139.40 FL	*- FL
7	1		*FRONT LH HEADLAMP	Cut	473.40 FL	*473.40 FL
8	1		*FRONT LH SIDE MIRROR	Not Necessary	171.80 FL	*- FL
9	1		*FRONT LH UPPER CORNER GARNISH	Not Necessary	111.30 FL	*- FL
10	1		*FRONT PANEL CABSTAX EMBLEM	Necessary	30.00 FL	*30.00 FL
11	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
12	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
13	1		*FRONT LH DOOR ART STICKER	Necessary	300.00 FS	*100.00 FS
14	1		*FRONT LH DOOR COMPANY DETAIL STICKER	Necessary	40.00 FS	*25.00 FS
15	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*SET FRONT PANEL ART STICKER	Necessary	200.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,458.50	2,088.40
- List Item Discount on L Items 10.00/10.00% (S\$)	378.85	191.34
Total Parts (S\$)	4,079.65	1,897.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (TO FR)	New	50.00	30.00
2	TO REMOVE,REINSTALL WINDOW GLASS (TO FR)	New	50.00	0.00
3	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANAEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	450.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	400.00
6	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	0.00
Gross Labour Cost (S\$)			1,780.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >