

ASS. REC. BY:

REF: CS/SMO19003833/R1td3

n2

Special Instruction:

Surveyor's

Rasul

ASSIGNMENT (Office)

From (Person):

Wong Lee Sintonience

SMO

Date/Time:

28/2/19 @ 4:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTCS

To Inspect Vehicle No:

SLD 2000Z

Insured:

SKT 9255L

at Workshop m/s:

Stuttgart Auto

Tel:

6331 0683

of

27 A Tanjong Penjun

Policy No:

D18MTRENT000070

Claim No:

CMTD1901063

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/02/2019

CA / REV / REP. / REV 24 HRS

1/3/19 @ 11-2pm

H.O.D. Endorsement:

Date/Time:

28/2/19 @ 5:17pm

Person Contacted:

EV9

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 2000Z - X

SKT 9255L - X..

7/3/2019 - Revised via maniman preli advise

Confirm final figure \$7789.73 (Red: 6558.36, 45%)

Case

2271F

INSURANCE

From: _____ Date: _____

Insured: _____

CU: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SLD 20002**

at Workshop no: **TRANSEUROKARS**

at: **JIA, TANJONG Pagar**

Insured: **SMO**

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

11am - 2pm
(Policy Condition) **EVA**

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PH Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days: Rep: Yes or No

Turn Turn: _____ %: 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

Vehicle: **SLD 20002** Y Regn: **2016 Jun**

Type: ☒ Motor / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **PORSCHE CAYENNE V6** cc: **3598**

Colour: **BLACK** A/C: _____ Insured / Std / NI / NA

Sp. Reading: **34442** TRadio: Insured / Std / NI / NA

Eng/No: _____

Chassis: **WP1ZZZ92Z6KA36.208**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt or

Brake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / ☒ R / STD A/Rim or

Tyre Size: F: **295/35R21**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	22/02/19	D.O.A.	01/03/19

Survey held at: **TRANSEUROKARS**

Des. of Damages: Frl / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 24 APR 2019

Date/Time: File Pass to? ☐ : Profl. Report

24/4/19 ☒ : Final Report

Date/Time: File Return to? _____

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Serv (\$) ☐ Workshop (\$)

Report Format: **TP**

Lump Sum: **7789.73**

Survey Fee: _____

Transportation: _____

Subs: _____

Other: _____

TOTAL: _____

350
10
360

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: WONG, LEE SIN LORRIANCE

Date: 07 Mar 2019

Preliminary Advice

Insured Vehicle No : SKT9255L
TP Vehicle No : SLD2000Z
Make : PORSCHE CAYENNE
Date of Inspection : 07/03/2019
Inspection At : STUTTGART AUTO PTE LTD
27A TANJONG PENJURU
SINGAPORE 609042

Accident Date : 22/02/2019
Assignment Date : 28/02/2019
Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,342.15
Revised Amount	:S\$	7,789.01
Check Items (Estimated)	:S\$	168.84
Total	:S\$	7,957.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2019		28 Feb 2019 16:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	SUNIL NAIR, ID: S1722271F		
Vehicle Reg. No.:	SLD2000Z	Date of Loss:	22/02/2019 13:00 - :59
Claim Type:	TP / CMTD1901063	Policy/Cover Note No.:	D18MTRENT000070 (Third Party Only)
Vehicle Reg. No. (Insured):	SKT9255L	Policy No. (Claimant):	
		Excess:	
Repairer:	Stuttgart Auto Pte Ltd () 27A Tanjong Penjuru, 609042 West Coast - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by WONG, LEE SIN LORRIANCE - 6329 5175]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/03/2019]		
Driver/Custodian (Insured):	YEO HEE CHOON (), NRIC: S0554210C, Tel: +6590663133 Email:		
Adj Asg. Remarks:	WS: 6331 0683 EVA - please arrange survey tmr 1/3 (11-2pm)		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 24 April 2019 11:29 AM
To: jessica@eurokars.com.sg; Rasul (LKKAUTO)
Cc: CS A Team; Admin A; Olivia Lau (LKKAUTO)
Subject: RE: FINALIZATION SOMPO TP - SLD2000Z.xlsx

Dear Jessica,

Confirm final figure \$7,789.73, 5days before GST.

Please submit all your relevant document to Sompo Insurance

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessica@eurokars.com.sg <jessica@eurokars.com.sg>
Sent: Monday, 22 April 2019 9:44 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Subject: RE: FINALIZATION SOMPO TP - SLD2000Z.xlsx

Dear Rasul,

Please assist and let us have your instruction to close our invoice.

Thank you very much

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessica@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Jessica Harry Shastri
Sent: 17 April 2019 5:48 PM
To: 'Rasul (LKKAUTO)' <Rasul@lkkauto.com>
Cc: Janice Syn <janice.syn@porsche.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>; 'CS A Team' <cs-a@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: FINALIZATION SOMPO TP - SLD2000Z.xlsx

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 14:12
Date Of Accident	22/02/2019 13:30
Exact Location Of Accident	ALONG UPPER THOMAS RD & YIO CHU KANG RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD2000Z
Insured/Policyholder	
Name Of Registered Owner	SUNIL NAIR
NRIC No	S1722271F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91442000
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYENNE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA362246/1
Cover Note Number	

Driver

Name of Driver	SUNIL NAIR
NRIC No	S1722271F
Date Of Birth	28/01/1965
Occupation	INDOOR
Date Of Driving Pass	03/02/1983
Driving Experience	36 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91442000
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address	56 TUNG PO AVENUE SINGAPORE 787187
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LETHIKA DEVI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT9255L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR YEO
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Upper Thompson Rd.



Yio Chu Kang Rd.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 1.30 PM on the 22nd of February 2019, I was halted at the junction of Upper Thompson Road and Yio Chu Kang Road, to turn right into Yio Chu Kang Road from Upper Thompson Road at the turn right lane, waiting for the Green Turn Right Arrow to come on.

Less than 30 seconds after I had halted, a car had hit me at the rear, and felt a big ~~fast~~ Jolt. The registration number of the car is SK7 9255 L, and it was driven by Ms YEO HEE CHUAN, LICENCE NO: S0554210 C.

My car had a big scratch and dent in the door to the boot and rear bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Edwin Alegre
NRIC/FIN No.: G5954667N



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

Sompo Insurance		NAME : Mr Sunil Nair		WIP : 43077	
05-01/06 Land Tower, Raffles Place, Singapore Land Tower, Singapore 048623		ADDRESS : 56 Tung Po Avenue Singapore 787187		EXCESS :	
ATTN. : MOTOR CLAIM DEPT		TEL :		DATE: 27.02.2019	
FAX :					
VEH NO :	SLD2000Z	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ92ZGKA36208	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayenne	DATE REG.:	10.06.2016	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			QTY	REVISED	PRICES
1	REAR BUMPER	✓		1	✓	\$ 1,085.20
2	REAR BUMPER LOWER COVER	X SVC		1	X	\$ 996.60
3	TAIL PIPE TRIM COVER LH	see / 3 photo		1	✓	\$ 143.10
4	TAIL PIPE TRIM COVER RH	see / 3 photo		1	✓	\$ 143.10
5	U-CLAMP	see /		4	2.20	\$ 8.00
6	BLIND RIVET	see /		6	9	\$ 9.00
7	TAILGATE	repair		1	X	\$ 3,115.10
8	BLIND RIVET	* ?		8	X	\$ 44.00
9	SEALING RUBBER	* ?		2	X	\$ 5.00
10	CAVITY PRESERVATION	? nn		1	X	\$ 75.30
11	BLIND RIVET NUT	? nn		6	X	\$ 25.80
12	CLAMP	? nn		2	X	\$ 13.00
13	VELCRO STRIP	? nn		1	X	\$ 8.70
14	SUPPORT	? nn		2	X	\$ 15.80
15	LOGO PORSCHE CHROME	see /		1	210.50	\$ 210.50
16	GASKET REAR WINDOW LOWER	* X nn		1		\$ 165.30
TOTAL PARTS						\$ 6,063.50
LESS 10%						\$ 606.35
TOTAL PARTS COST						\$ 5,457.15
Labour Description						
1	TO REPLACE TAILGATE, REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.				3120	\$ 3,900.00
2	TO RESPRAY TAILGATE, REAR BUMPER & PORSCHE (BLACK).				2400	\$ 2,600.00
3	TO TRANSFER THE TAILGATE MECHANISM.				NETT 17	\$ X 780.00
4	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.				NETT 27	\$ X 560.00
5	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.				NETT 17	\$ X 195.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 200.00	
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00	
8	SUNDRIES.	NETT	\$ 30 50.00	net
		TOTAL LABOUR	\$ -	\$ 8,885.00
		TOTAL PARTS	\$ -	\$ 5,457.15
		TOTAL	\$ -	\$ 14,342.15
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

RASUL
HP 90010068

4-5 days

P/P

01/03/19 @ 1130

Resub by paint

14348.09



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

Sompo Insurance		NAME : Mr Sunil Nair	WIP : 43077
05-01/06 Land Tower, Raffles Place, Singapore Land Tower, Singapore 048623		ADDRESS : 56 Tung Po Avenue Singapore 787187	EXCESS :
ATTN. : MOTOR CLAIM DEPT		TEL :	DATE: 27.02.2019
FAX :			
VEH NO :	SLD2000Z	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ92ZGKA36208	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	Cayenne	DATE REG.: 10.06.2016	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	P958-505-417-60-G2X	\$ 1,085.20	\$ 1,085.20
2	REAR BUMPER LOWER COVER	1	P958-505-834-55-989	\$ -	\$ 996.60
3	TAIL PIPE TRIM COVER LH	1	P958-505-837-10-989	\$ 143.10	\$ 143.10
4	TAIL PIPE TRIM COVER RH	1	P958-505-838-10-989	\$ 143.10	\$ 143.10
5	U-CLAMP	1	P955-505-897-00-	\$ 2.20	\$ 8.00
6	BLIND RIVET	6	PN -908-550-01-	\$ 9.00	\$ 9.00
7	TAILGATE	1	P958-512-011-10-GRV	\$ -	\$ 3,115.10
8	BLIND RIVET	8	PN -016-206-1 -	\$ -	\$ 44.00
9	SEALING RUBBER	2	P958-545-359-00-	\$ -	\$ 5.00
10	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 75.30
11	BLIND RIVET NUT	6	PN -906-481-02-	\$ -	\$ 25.80
12	CLAMP	2	P958-731-633-00-	\$ -	\$ 13.00
13	VELCRO STRIP	1	P958-612-852-00-	\$ -	\$ 8.70
14	SUPPORT	2	P958-612-890-00-	\$ -	\$ 15.80
15	LOGO PORSCHE CHROME	1	P958-559-687-01-	\$ 210.50	\$ 210.50
16	GASKET REAR WINDOW LOWER	1	P958-545-260-00-	\$ -	\$ 165.30
SUPPLEMENTARY PARTS					
1	U CLAMP,F/PROTECTION	3	955-505-897-01	\$ 6.60	
TOTAL PARTS				\$ 1,599.70	\$ 6,063.50
LESS 10%				\$ 159.97	\$ 606.35
TOTAL PARTS COST				\$ 1,439.73	\$ 5,457.15
Labour Description					
1	TO REPLACE TAILGATE, REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 3,120.00	\$ 3,900.00
2	TO RESPRAY TAILGATE, REAR BUMPER & PORSCHE (BLACK).			\$ 2,400.00	\$ 2,600.00
3	TO TRANSFER THE TAILGATE MECHANISM.			\$ -	\$ 780.00
4	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			\$ -	\$ 560.00
5	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			\$ -	\$ 195.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
8	SUNDRIES.	\$ 30.00	\$ 50.00
TOTAL LABOUR		\$ 6,350.00	\$ 8,885.00
TOTAL PARTS		\$ 1,439.73	\$ 5,457.15
TOTAL		\$ 7,789.73	\$ 14,342.15
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 7,789.73	
GST 7%		\$ 545.28	\$ -
GRAND TOTAL		\$ 8,335.01	\$ -

NUMBER OF DAYS: 5 WORKING DAYS (EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

STUTTGART AUTO PTE LT
27A TANJONG PENJURU, SINGAPORE
FINALIZATION COST OF REF

Sompo Insurance 05-01/06 Land Tower, Raffles Place, Singapore Land Tower, Singapore 048623 ATTN. : MOTOR CLAIM DEPT FAX :		NAME : Mr Sunil Nair ADDRESS : 56 Tung Po Avenue Singapore 787187 TEL :	
VEH NO :	SLD2000Z	DATE IN :	
CHASSIS NO :	WP1ZZZ92ZGKA362	MILEAGE :	
MODEL :	Cayenne	DATE REG.:	10.06.2016
<u>NATURE OF WORKS</u>			
S/NO	<u>Parts Description</u>		
		QTY	
1	U CLAMP,F/PROTECTION	3	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003833/R1TD3N2

Date: 02/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTRENT000070
Claimant Vehicle No :	SLD2000Z	Insured Vehicle No :	SKT9255L
Date of Loss:	22/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901063

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD2000Z	Engine No:	020059
Make & Model:	PORSCHE CAYENNE, 3.0 (A)	Chassis No:	WP1ZZZ92ZGKA36208
Reg. Date:	10/06/2016 (Man. Year: 2016)	Odometer:	34442 km
Colour:	Black		
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/35R21	Rear Tyre Size:	295/35R21
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,513.09	1,469.73	4,043.36	73.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,835.00	6,320.00	2,515.00	28.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,348.09	7,789.73	6,558.36	45.71
+ GST 7.00/7.00% (\$\$)	1,004.37	545.28	459.09	45.71
Nett Amount (\$\$)	15,352.46	8,335.01	7,017.45	45.71

INSPECTION

Date of Assignment:	28/02/2019	Inspected At:	Stuttgart Auto Pte Ltd
Date Inspected:	01/03/2019		27A Tanjong Penjuru
			Singapore 609042
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2019)
Parts: M1-SUV	PORSCHE CAYENNE 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD2000Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,085.20 FL	*1,085.20 FL
2	1		*REAR BUMPER LOWER COVER	Serviceable	996.60 FL	*- FL
3	1		*TAIL PIPE TRIM COVER RH	Necessary	143.10 FL	*143.10 FL
4	1		*TAIL PIPE TRIM COVER LH	Necessary	143.10 FL	*143.10 FL
5	1		*U-CLAMP	Necessary	8.00 FL	*2.20 FL
			(4 Pcs)			
6	6		*BLIND RIVET	Necessary	9.00 FL	*9.00 FL
7	1		*TAILGATE	Repair	3,115.10 FL	*- FL
8	8		*BLIND RIVET	Not Necessary	44.00 FL	*- FL
9	2		*SEALING RUBBER	Not Necessary	5.00 FL	*- FL
10	1		*CAVITY PRESERVATION	Not Necessary	75.30 FL	*- FL
11	6		*BLIND RIVET NUT	Not Necessary	25.80 FL	*- FL
12	2		*CLAMP	Not Necessary	13.00 FL	*- FL
13	1		*VELCRO STRIP	Not Necessary	8.70 FL	*- FL
14	2		*SUPPORT	Not Necessary	15.80 FL	*- FL
15	1		*LOGO PORSCHE CHROME	Necessary	210.50 FL	*210.50 FL
16	1		*GASKET REAR WINDOW LOWER	Not Necessary	165.30 FL	*- FL
17	3		*U-CLAMP PROTECTION	Necessary	6.60 FL	*6.60 FL
18	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,120.10	1,629.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	607.01	159.97
Total Parts (\$\$)	5,513.09	1,469.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE TAILGATE, REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,900.00	3,120.00
2	TO RESPRAY TAILGATE, REAR BUMPER & PORSCHE (BLACK)	New	2,600.00	2,400.00
3	TO TRANSFER THE TAILGATE MECHANISM	New	780.00	0.00
4	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS	New	560.00	0.00
5	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS	New	195.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (\$\$)			8,835.00	6,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >