

REF: CS/SMD19003138/GCA39

Special Instruction:

ASSIGNMENT (Office)

Meitman
SUPERVISOR:

From (Person): Enoch Pau Loop of SMD Date/Time: 01/31/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: SKW 1932C Insured: GBC 3558Z

at Workshop m/s HANIP Tel: _____

of LARI BUNT

Policy No: D18MTHCNE000155 Claim No: CMTD1805626

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS imp H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>SKW 1932C X</u>
	<u>GBC 3558Z X</u>
	<u>Dismantle: 5/3/2019</u>
	<u>After repair: 12/3/2019</u>


PPS
Xkl.

REF: SMO

B 4062E

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKW 1932C
 at Workshop n/s: Hanip Auto.
 of: 1 Kaki Bukit Ave 6 #01-72
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKW 1932C Yr Regn: 21 Oct 2015
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan Qashqai c.c. 1197
 Colour: Brown A/C Insured / Std / NI / NA
 Sp. Reading: 54751 TR: Radio Insured / Std / NI / NA
 Eng No: _____
 C/No: SJNFEAJ11K1481584
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / ARim or
 Tyre Size: F: 215/60 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. df - 03-19
 Survey held at w/s 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$4000 - \$5000</u>

RECEIVED 21 MAR 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 Report Format: PRS
 Lump Sum / L.B.L. (\$) _____

Days Of Repair: 5
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Inv. (\$) _____
 Weekend (\$) _____

Survey Fee: _____
 Transportation: _____
 S - P: _____
 Phone: _____
 Other: _____
 TOTAL: _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2018		01 Mar 2019 16:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H								
Main Claimant:	BUTIK NONA , Co. Reg. No.: 53244062E								
Vehicle Reg. No.:	SKW1932C	Date of Loss:	20/12/2018 18:00 - :59						
Claim Type:	TP / CMTD1805626	Policy/Cover Note No.:	D18MTHCVE000155 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBC3558Z	Policy No. (Claimant):							
		Excess:							
Repairer:	HANIP AUTOMOBILES ENGINEERING (HQ) 1, KAKI BUKIT AVENUE 6, #01-72/73,, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/03/2019]								
Driver/Custodian (Insured):	MOHAMED ZAINI BIN AHMAD (), NRIC: S8119132H, Tel: +6587515370 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(1n)

Steve.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 1 March 2019 4:25 PM
To: Hui Ting; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Corene; Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1805626/GPL - SUV(LKK)/ GBC3558Z & SKW1932C (HANIP) ACC ON 20.12.18

Our Reference : CMTD1805626/GPL
Your Reference: AJ.tk.HANIP (SKW1932C)

Date: 01/03/2019

Without Prejudice
EMAIL ONLY

Attention:
M/S CROSSBORDERS LLC

Dear Hui Ting,

ACCIDENT INVOLVING GBC3558Z & SKW1932C ON 20.12.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.


The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Hui Ting [mailto:huiting@crossbordersllc.com]

Sent: Friday, March 01, 2019 4:10 PM

To: Teo, Grace

Cc: Corene; Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James

Subject: RE: CMTD1805626/GPL - PRI/ GBC3558Z & SKW1932C (HANIP) ACC ON 20.12.18

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Grace

1. We refer to your email dated 1 March 2019.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Andrew How Prominent Appraiser Services
 - b) Dennis Yap PAL'S Appraiser Pte Ltd
 - c) Yap Teck Lee LCW Appraiser Pte Ltd
 - d) Yap Teck Chye MC-Coy Appraiser Pte Ltd
 - e) Dixon Yeo Treasure Appraiser Pte Ltd
 - f) Marc Ananda United Appraisal and Management Pte Ltd
 - g) Alan Cheong K.H. C L Appraiser Pte Ltd
 - h) T.T. Rajan ST Appraisal Services
 - i) Sebastian Lim Constanct Appraiser Services
 - j) Aeon Auto Consultants LLP
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards

Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Friday, 1 March 2019 4:08 PM

To: Hui Ting <huiting@crossbordersllc.com>

Cc: Corene <corene@crossbordersllc.com>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1805626/GPL - PRI/ GBC3558Z & SKW1932C (HANIP) ACC ON 20.12.18

Our Reference : CMTD1805626/GPL

Your Reference: AJ.tk.HANIP (SKW1932C)

Without Prejudice

EMAIL ONLY

Date: 01/03/2019

Attention:

M/S CROSSBORDERS LLC

Dear Hui Ting,

ACCIDENT INVOLVING GBC3558Z & SKW1932C ON 20.12.2018

We refer to your Notice of Accident dated 01/03/2019.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	

2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	


Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Friday, March 01, 2019 3:42 PM

To: Claims - Motor Survey

Cc: Corene

Subject: Our client's vehicle no. SKW1932C (HANIP); Your insured's vehicle no. GBC3558Z - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 1 March 2019 for your kind attention.

2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.HANIP (SKW1932C)
Your Ref: GBC3558Z

1 March 2019

Sompo Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department

BY FAX: 6221 3302 & EMAIL

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: BUTIK NONA
TRAFFIC ACCIDENT ON 20 DECEMBER 2018 AT 18:50 HRS ALONG KPE TOWARDS
TAMPINES ROAD INVOLVING VEHICLES NO. SKW1932C & GBC3558Z

We are instructed by Butik Nona to notify you of a road accident 20 December 2018 at about 18:50 hrs along KPE towards Tampines Road involving our client's vehicle registration number SKW1932C and vehicle registration number GBC3558Z driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Hanip Automobiles Engineering
Address: 1 Kaki Bukit Avenue 6
#01-73 Autobay @ Kaki Bukit
Singapore 417883
Contact: Hanip Abdul @ 8100 2121 / 6747 0513

Please liaise with the above workshop directly.

Yours faithfully

CROSSBORDERS LLC
Crossborders LLC
Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/12/2018 11:43
Date Of Accident	20/12/2018 18:50
Exact Location Of Accident	KPE TWDS TAMPINES RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW1932C
Insured/Policyholder	
Name Of Registered Owner	BUTIK NONA
Co Reg No	53244062E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94789478
Vehicle Particulars	
Manufacturer	NISSAN
Model	PULSAR-1.2 L DIG-T (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MPC0002328
Cover Note Number	
Driver	
Name of Driver	FAUZI OMAR ABDAT
NRIC No	S1203484I
Date Of Birth	03/07/1956
Occupation	INDOOR
Date Of Driving Pass	08/07/1975
Driving Experience	43 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94789478
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 84A LORONG MELAYU S(417008)

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : RAHMAH BTE HYDER

GENDER: : FEMALE

Passenger 2 NAME: : ATIN KAR TINI BT HASAN SUJAN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC3558Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ran be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(s) including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Nonaa

1 Joo Chiat Road
#03-1055
Singapore 420001
Tel: 6842 3723


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/Fin No.

Sketch Plan #2

SKETCH PLAN

→ KPE TOWARD TAMMISARA 2.



ASKW1937C

B. GBC ~~355~~ 355.

Juan Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Juan
I was travelling along toward KPE when front car stopped. I stop my car but the rear vehicle can't stop and hit the rear of my vehicle.

DECLARATION

I/We declare the foregoing part **Nonea** true in every respect.

1 Joo Chiat Road
#02 1056
Singapore 420001

Juan
Policyholder's Signature
Date & Time

Tel: 6842 8723
Signature
 If driver is not the policyholder's
Date & Time

Reporting Centre Personnel's Signature
Name
NIC/ID No

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4062E
Vehicle Details	
Vehicle No.:	SKW1932C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	HRA2187920A
Chassis No.:	SJNFEAJ11U1481584
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,413.00
Original Registration Date:	21 Oct 2015
First Registration Date:	21 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$13,413.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2025
PARF Rebate Amount:	\$10,059.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$37,813.00
Total Rebate Amount:	\$47,872.00

The information contained herein is correct as at 05 Mar 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2018		01 Mar 2019 16:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H		
Main Claimant:	BUTIK NONA , Co. Reg. No.: 53244062E		
Vehicle Reg. No.:	SKW1932C	Date of Loss:	20/12/2018 18:00 - :59 [37 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1805626	Policy/Cover Note No.:	D18MTHCVE000155 (Third Party Only)
Vehicle Reg. No. (Insured):	GBC3558Z	Policy No. (Claimant):	
		Excess:	
Repairer:	HANIP AUTOMOBILES ENGINEERING (HQ) 1, KAKI BUKIT AVENUE 6, #01-72/73,, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/03/2019]		
Driver/Custodian (Insured):	MOHAMED ZAINI BIN AHMAD (), NRIC: S8119132H, Tel: +6587515370 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKW1932C (CMTD1805626)
[GBC3558Z]**

TP

BUTIK NONA

Dec 20 2018 6:00PM

[ETHOZ GROUP LTD]

HANIP AUTOMOBILES ENGINEERING

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/19 16:25	Accident Statement From:SC - Reg. No: GBC3558Z, Claimant: ETHOZ GROUP LTD	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/03/19 09:27	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
28	05/03/19 09:27	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
29	07/03/19 09:08	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	07/03/19 09:08	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	07/03/19 09:08	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/03/19 09:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	21/03/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	21/03/19 08:57	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
80	21/03/19 08:57	Photo After Spray	 Load JPG	✓
81	21/03/19 08:57	Photo After Spray	 Load JPG	✓
82	21/03/19 08:57	Photo After Spray	 Load JPG	✓
83	21/03/19 08:57	Photo After Spray	 Load JPG	✓
84	21/03/19 08:57	Photo After Spray	 Load JPG	✓
85	21/03/19 08:57	Photo After Spray	 Load JPG	✓
86	21/03/19 08:57	Photo After Spray	 Load JPG	✓

Documentation			1 per page	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/19 15:59	Pre-Repair Survey+SAS	 Load PDF	
2	01/03/19 16:26	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003938/GQD3S2

Date: 22/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE000155
Claimant Vehicle No :	SKW1932C	Insured Vehicle No :	GBC3558Z
Date of Loss:	20/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1932C	Engine No:	HRA2187920A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Chassis No:	SJNFEAJ11U1481584
Reg. Date:	21/10/2015 (Man. Year: 2015)	Odometer:	54751 km
Colour:	Brown		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/03/2019		
Date Inspected:	04/03/2019	Inspected At:	HANIP AUTOMOBILES ENGINEERING (HQ) 1, KAKI BUKIT AVENUE 6, #01-72/73, Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2019)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW1932C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >