

01/01/2008

ASS. REC. BY:

REF: CS/CT/19003940/THD3

Original Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chong Boon Sam

of

CTI

Date/Time:

04/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 1177L

Insured:

SKG 3366S

at Workshop m/s

PML

Tel:

of

Policy No:

DM/CSN 3 0037618000

Claim No:

SMM/9D 200860C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

W/P

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	SKS 1177L x
	SKG 3366S x
	Part by part \$3211.15 (Red: 986.80; 23%)

Taufik

CTI

CTI

Name: \_\_\_\_\_ Date: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Insured:  WP /  RES /  FOR RES /  LVA /  HW /  HW  
 Insured's Name: \_\_\_\_\_  
 Address: \_\_\_\_\_  
 City: \_\_\_\_\_  
 State: \_\_\_\_\_  
 Zip: \_\_\_\_\_  
 Make of Vehicle: \_\_\_\_\_  
 Model: \_\_\_\_\_  
 Year: \_\_\_\_\_  
 Color: \_\_\_\_\_  
 Description: \_\_\_\_\_  
 Make of WH: \_\_\_\_\_  
 Policy Condition: \_\_\_\_\_  
 Remarks: The veh had commenced its repair at the time of inspection.  
 Est. of Market Value: \_\_\_\_\_  
 Date of Accident: \_\_\_\_\_ Consistent? Yes or No: \_\_\_\_\_  
 Date of Repair: \_\_\_\_\_ Consistent? Yes or No: \_\_\_\_\_  
 Days of Repair: \_\_\_\_\_ Yes or No: \_\_\_\_\_  
 Total Cost: \_\_\_\_\_ Yes or No: \_\_\_\_\_  
 CA / TRV / REP / 24 HRS: \_\_\_\_\_  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Date / Time: \_\_\_\_\_ Action / Instruction: \_\_\_\_\_



Vehicle: **SKS1177L** License: **2018 Dec.**  
 Type:  Car /  Bicyclo /  Bus /  Van /  Lorry /  Truck /  Heavy Motor /  Truck /  Trailer or  
 Make: **BMW X1** CC: **1499**  
 Color: **Black** All:  Insured /  SR /  TH /  HA  
 Sp (Reading): **4764** -  Radio /  Insured /  SR /  TH /  HA  
 Reg No: **WBA 59120 703976290**  
 Gen. Cond:  Good /  Fair /  Poor /  Worst  
 Steering:  Smooth /  Jammed /  Leaked /  Burnt or  
 Brake:  Smooth /  Jammed /  Leaked /  Burnt or  
 Mod:  Nil /  Airin /  STD Airin or  
 Tyre Size: **F: 225/55R17**  
**R: 225/55R17**  
 BS / DIN / EXNOVA / OY / PS / LIZA / MIC / CHITSA /  PIR /  SAMI /  TOYO /  YOKO or  
 Front: **6** mm Rear: **6** mm  
 Wheel: **6** mm Wheel: **6** mm  
 L Wheel: **6** mm R Wheel: **6** mm  
 D.O.A.: \_\_\_\_\_ D.O.A.: **4/3/19**  
 Survey held at: **PMI**  
 Des. of Damage:  Fr /  Rep /  CR /  MS /  HC /  Rooftop or  
 Has HC / Chassis frame / Body Structure affected due to collision: \_\_\_\_\_

RECEIVED 27 FEB 2019

RECEIVED 29 MAR 2019

Insured: Mr/Pn: \_\_\_\_\_  
 Prof. Report  
 Final Report  
 Date: **29/3 Typst**

Days Of Repair: **3**  
 Resurvey No. of Trip: **1**

Repair Payment: **TP**  
 Lump Sum: **3211.15**

Add Fee:  Late Trip:   
 Late Rep:   
 Late Sur:   
 Late Insur:

Survey Fee: \_\_\_\_\_  
 Inspection: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Mar 2019		04 Mar 2019 10:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	<b>SIM SONG KAI, ID: S7900403J</b>		
Vehicle Reg. No.:	<b>SKS1177L</b>	Date of Loss:	17/02/2019 15:00 - :59
Claim Type:	<b>TP / SNM19D200860C02</b>	Policy/Cover Note No.:	DMPCSN30037618000
Vehicle Reg. No. (Insured):	<b>SKJ3366S</b>	Policy No. (Claimant):	UNAVAILABLE
		Excess:	\$0.00
Repairer:	<b>Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174</b>		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</b>		
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288</b>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/03/2019]</b>		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

*Taufik*

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 4 March 2019 8:44 AM  
**To:** assignments  
**Subject:** FW: OUR REF: SNM19D200860 / YOUR REF" REQUEST FPR DORECT SETTLEMENT - SKS1177L AND SKJ3366S ON 17.2.19  
**Attachments:** VID-20190217-WA0029.mp4

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

*Tau Pei*

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 1 March 2019 6:12 PM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: OUR REF: SNM19D200860 / YOUR REF" REQUEST FPR DORECT SETTLEMENT - SKS1177L AND SKJ3366S ON 17.2.19

Without Prejudice

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** PBSP [<mailto:pml-pbsp@simedarby.com.sg>]  
**Sent:** Tuesday, 26 February, 2019 11:43 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject:** Re: OUR REF: SNM19D200860 / YOUR REF" REQUEST FPR DORECT SETTLEMENT - SKS1177L AND SKJ3366S ON 17.2.19

Dear Boon Sen

Please refer to attach video and kindly confirm liability.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Monday, 25 February 2019 5:00:49 PM

**To:** PBSP

**Subject:** OUR REF: SNM19D200860 / YOUR REF" REQUEST FPR DORECT SETTLEMENT - SKS1177L AND SKJ3366S ON 17.2.19

Without Prejudice

Dear Caroline,

We offer 50% liability as our insured did mentioned your client approached our client, though our Insured reversed.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/02/2019 12:52
Date Of Accident	17/02/2019 15:20
Exact Location Of Accident	THOMSON RD (CALTEX)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS1177L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIM SONG KAI
NRIC No	S7900403J
Email Address	JOTHAN79@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92769979
Alternative Phone No	OTHERS-92769979

### Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	

### Driver

Name of Driver	SIM SONG KAI
NRIC No	S7900403J
Date Of Birth	17/01/1979
Occupation	OUTDOOR
Date Of Driving Pass	02/08/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92769979
Fax Number	
Contact Number	OTHERS-92769979
EEmail Address	JOTHAN79@HOTMAIL.COM

Address	9 SEMBAWANG CRESCENT #07-17
Postcode	757057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident.	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SIM LE XIN GENDER: : FEMALE
Passenger 2	NAME: : SIM JIE YI GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ3366S
Vehicle Make/Model/Colour	TOYOTA ALTIS BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM AH SIONG
NRIC/Passport Number	
Contact Number	87528711
Address	
Postcode	

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

18/02/19 (10.06am)

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN

Caltex Upper Thomson. 555 Upper Thomson Rd.  
(Petrol Station)





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While waiting in queue for car wash. SKJ 3366S suddenly reverse and banged into the front of my car (SKS1177L). This happened on 17/2/19 at about 1520 hrs at 555 Upper Thomson Rd.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

18/02/19 (10.06am)

Mon 04/03 @ 10am  
S&R

SKS1177L



BMW Dealer: **Performance Motors Limited**  
A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Esompong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

18 FEB 2019

**ESTIMATE**

**LKK Auto Consultants hence notify the Repairer of the following:**  
 Page No: 1 of 4  
 • To resurvey before respray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modifications  
 • Supplementary items must be resurveyed and subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

Estimate No. : **b1 50153**  
 Date Estimated : **18/02/2019**  
 Prepared By : **Han Kwan Yong**

**- ESTIMATE REPAIR FOR -**  
**Sim Song Kai**  
**9 Sembawang Crescent**  
**#07-17**  
**Singapore 757057**

**- ACCOUNT - 40000**  
**Cash Sales - Service**  
**Singapore**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS1177L	3G76690	10/12/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace front bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray front bumper	934 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To supply front emboss number plate.	66 83.00
Sundries	? 80.00

Total Labour 1: **2,653.00**

DESCRIPTION	QTY	PRIC	VALUE
IMPACT ABSORBER TOP	1	43.70	43.70
FRT BUMPER TOP CARRIER	1	373.95	373.95
# FRT BUMPER PANEL PRIMED (PDC)	1	734.70	734.70
# FRT BUMPER PANEL LOWER SECTI	1	281.80	281.80
# LICENCE PLATE HOLDER ECE	1	70.65	70.65
EXPANDING RIVET	30	1.35	40.50

*Signature*  
11/3/19

Total Parts : **1,545.30**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.                      Claim No.                     

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97498419 Authorised Yes / No

Authorised Date 18/2/19 Time                     

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail TanJiah@llk.com.sg

No. of Working Days Recommended 3 days

Labour 1	:	2,653.00
Parts	:	1,545.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	293.88
<b>Grand Total</b>	<b>:</b>	<b>4,492.18</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770380, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Tel. 63190888 (AfterSales)  
Fax. 63449773111, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 50153**  
Date Estimated : **18/02/2019**  
Prepared By : **Han Kwan Yong**Page No. : **2 of 4**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKS1177L</b>	<b>3G76690</b>	<b>10/12/2018</b>	<b>X1 sDrive18i</b>	<b>0</b>

**Terms & Conditions of Service**

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401599W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64767770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190228 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 50153  
Date Estimated : 18/02/2019  
Prepared By : Han Kwan Yong

Page No. : 3 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS1177L	3G76690	10/12/2018	X1 sDrive18i	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
  - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
  - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
  - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next subsequent date/mileage for routine service for the Vehicle;
  - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
  - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
  - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
  - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
  - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
  - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
  - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
  - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
  - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
  - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Tel. 63190888 (AfterSales)  
Fax. 63449775115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No.	: b1 50153
Date Estimated	: 18/02/2019
Prepared By	: Han Kwan Yong

Page No. : 4 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS1177L	3G76690	10/12/2018	X1 sDrive18i	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- put his request in writing;
  - provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
  - specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- put his request in writing by way of an email sent to the Vendor;
  - provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
  - if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer  
Performance Motors Limited

Address:  
Sime Darby Performance Centre  
303 Alexandra Road  
Singapore 159941

Email address:  
dataprotection@pmi.com.sg

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 19740153W. GST Reg. No. M2-000001-4



## FINAL REPORT

Estimate No. : b1 50153  
Date Estimated : 18/02/2019  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Sim Song Kai  
9 Sembawang Crescent  
#07-17  
  
Singapore 757057

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKS1177L	3G76690	10/12/2018	Xi sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dented areas caused by the accident	850.00		850.00
To respray front bumper	934.00		934.00
To check electrical wiring systems at the front section for proper function	150.00		150.00
To supply front emboss number plate	83.00		83.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PDC/PMA)	734.70	1.00		734.70
# FRT BUMPER PANEL LOWER SECTION (PDC *	281.80	1.00		281.80
LICENCE PLATE HOLDER ECE	70.65	1.00		70.65
EXPANDING RIVET	1.35	20.00		27.00

### # SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,114.15
Total Labour & Parts :	3,211.15
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,211.15
GST @7%:	224.78
<b>Grand Total :</b>	<b>3,435.93</b>

# Performance Motors Limited

A member of the Sino Dairy Group  
Co. Reg. No. 197401589W, GST Reg. No. M2-0020081-K



## SUPPLEMENTARY

Estimate No. : b1 50153  
Date Estimated : 18/02/2019  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Sim Song Kai  
9 Sembawang Crescent  
#07-17

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 757057

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SKS1177L	3G76690	10/12/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# FRT BUMPER PANEL LOWER SECTION (PDC *	281.80	1.00		281.80
---	--------	------	--	--------

Total Labour :	
Total Parts :	281.80
Total Labour & Parts :	281.80

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Mar 2019		04 Mar 2019 10:58 <a href="#">Edit Adj Rpt</a>	<b>S\$3,211.15</b> <a href="#">Edit Estimates</a>	<b>S\$3,211.15</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by insurer]							
Insured:	-, ID: -								
Main Claimant:	<b>SIM SONG KAI</b> , ID: S7900403								
Vehicle Reg. No.:	<b>SKS1177L</b>	Date of Loss:	17/02/2019 15:00 - :59 [2 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D200860C02</b>	Policy/Cover Note No.:	DMPCSN30037618000						
Vehicle Reg. No. (Insured):	<b>SKJ3366S</b>	Policy No. (Claimant):	UNAVAILABLE						
		Excess:	S\$0.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 13/03/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>   <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKS1177L (SNM19D200860C02)  
[SKJ3366S]  
TP  
SIM SONG KAI  
Feb 17 2019 3:00PM  
[-]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View <span style="float: right;">View in Browser</span>	
<b>Video</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print					
1	18/02/19 12:58	<b>Video - Accident</b> [Linked Accident Report Documents]		Load MP4						
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print					
1	18/02/19 13:04	<b>Accident Statement</b>		Load HTM						
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print					
1	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	18/02/19 12:58	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
2	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
3	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
4	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
5	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
6	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
7	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
8	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
9	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
10	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
11	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
12	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
13	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
14	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
15	29/03/19 10:44	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
16	29/03/19 10:44	<b>Reinspection Photo</b>		Load JPG						

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				<input checked="" type="checkbox"/>
17	29/03/19 10:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	29/03/19 10:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	18/02/19 12:58	Sketch Plan [Linked Accident Report Documents]	Load TIF	

### Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	18/02/19 12:58	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	18/02/19 13:04	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	18/02/19 12:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	18/02/19 12:58	Sketch Plan	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119003940/T1TD3Q2

**Date:** 04/04/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30037618000	
Claimant Vehicle No: SKS1177L	Insured Vehicle No: SKJ3366S	
Date of Loss: 17/02/2019	Nature of Claim: TP	Claim No: SNM19D200860C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SKS1177L</b>	Engine No: 40075455B38B15A
Make & Model: BMW X1, 1.5 SDRIVE 18i (A)	Chassis No: WBAJG120703G76690
Reg. Date: 10/12/2018 (Man. Year: 2018)	Odometer: 4764 km
Colour: Black	
Engine Capacity: 1499 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,708.30	1,277.15	431.15	25.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,198.30</b>	<b>3,211.15</b>	<b>987.15</b>	<b>23.51</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>293.88</b>	<b>224.78</b>	<b>69.10</b>	<b>23.51</b>
<b>Nett Amount (S\$)</b>	<b>4,492.18</b>	<b>3,435.93</b>	<b>1,056.25</b>	<b>23.51</b>

#### INSPECTION

Date of Assignment:	04/03/2019	
Date Inspected:	04/03/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
<b>Parts:</b> M1-SUV	BMW X1 1.5 SDRIVE 18i (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKS1177L)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*IMPACT ABSORBER TOP	Not Necessary	43.70 FS	*- FS
3	1		*FRT BUMPER TOP CARRIER	Not Necessary	373.95 FS	*- FS
4	1		*FRT BUMPER PANEL PRIMED (PDC)	Deformed	734.70 FS	*734.70 FS
5	1		*FRT BUMPER PANEL LOWER SECTI	Cut	281.80 FS	*281.80 FS
6	1		*LICENCE PLATE HOLDER ECE	Deformed	70.65 FS	*70.65 FS
7	1		*EXPANDING RIVET (30 PCS)	Necessary	40.50 FS	*27.00 FS
8	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
<b>Total Parts (\$\$)</b>					<b>1,708.30</b>	<b>1,277.15</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,490.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >