

12/03/2002

ASS. REC. BY:

REF:

CS/CN19003941/Red367

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Bansen

of

CTE

Date/Time:

1/3/19 @ 3/4pm

Estimated Cost:

Bill to:

OD/TP/AWS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLN 77532

Insured:

GW 4344C

at Workshop m/s:

96 Motorsports

Tel:

67026996

of

62/64 Keiki Blk Ave 6

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh.

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:55pm @ 1/3/19

Person Contacted:

Jade

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

called more than 3 times x answer.

SLN 77532 - x


GW 4344C - x

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SUN77532 Yr Regn: 2010 / Jan  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Volkswagen - Polo c.c. 1380  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 183460 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_

C/No: WWZZ26RZA4006715Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 26 mm R/Bal. 26 mmL/Bal. 26 mm L/Bal. 26 mmD.O.A. \_\_\_\_\_ D.O.I. 04/03/19Survey held at 96 MotorsportsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Claim.</u>
	<u>Vehicle has not repair. Submit Total Loss due to not economical for repair.</u>
	<u>MV: 15K</u>
	<u>PV: 9K</u>
	<u>Nett: 6K</u>
	<u>MV - \$15,000/-</u>
	<u>LTA - \$ 8,999/-</u>
	<u>Nett - \$ 6,001/-</u>

RECEIVED 25 MAR 2019

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) <u>25/03/19</u> <u>Typist</u>	2) _____	IN _____ OUT _____	Basic & Add.	<u>220</u>
3) _____	4) _____		___ S + RS, ___ SI	
5) _____	6) _____		Photos	
Prel. Report:			Others	
Final Report: <u>Total Loss</u>			TOTAL	<u>220</u>

Resurvey No. of Trip: 1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	2180D	
Vehicle Details		
Vehicle No.:	SLN7753Z	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	04 Mar 2019	
Vehicle Make:	VOLKSWAGEN	
Vehicle Model:	POLO 1.4 AT 6R13E7	
Primary Colour:	Grey	
Manufacturing Year:	2009	
Engine No.:	CGG224932	
Chassis No.:	WVWZZZ6RZAU006715	
Maximum Power Output:	63.0 kW (84 bhp)	
Open Market Value:	\$14,856.00	
Original Registration Date:	11 Jan 2010	
First Registration Date:	11 Jan 2010	
Transfer Count:	1	
Actual ARF Paid:	\$14,856.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	10 Jan 2020	
PARF Rebate Amount:	\$7,428.00	
Intended COE Rebate Details		
COE Expiry Date:	10 Jan 2020	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$18,502.00	
COE Rebate Amount:	\$1,571.00	
Total Rebate Amount:	\$8,999.00	

The information contained herein is correct as at 04 Mar 2019

OK



POLO 1.4 A

Price Range ▾

Depreciation ▾

2011 ▾

Vehicle Type ▾



Advanced Search

Home » Used Cars » Presto Expat Motoring Services Pte Ltd » Volkswagen Polo 1.4A

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



Ad ▾

## Volkswagen Polo 1.4A

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price	\$30,800	
Depreciation	\$8,940 /yr View models with similar depreciation	?
Reg Date	07-Oct-2011 (2yrs 7mths 8days COE left)	
Manufactured	2011	?
Mileage	77,200 km (10.4k /yr)	
Transmission	Auto	
Engine Cap	1,390 cc	
Road Tax	\$620 /yr	?
Power	63.0 kW (84 bhp) View specs of the Volkswagen Polo (2009-2018)	
Curb Weight	1,129 kg	?
Features	1.4L 4 Cylinders 16 Valves DOHC Engine, 7 Speed DSG Automatic Transmission With Tiptronic, ABS, 4 Disc Brakes, SRS Airbags.	
Accessories	Leather Upholstery, Factory Fitted Audio System, Reverse Sensors, Sport Rims	
Description	The Volkswagen Polo Is One Of The Most Practical Hatchbacks Out In The Market. Fitted With A Reliable 1.4L Engine That Is Mated To VW's Iconic 7 Speed DSG Transmission, The Polo Is Both A Fun And Fuel Efficient Car To Drive. This Unit Has Been Well Maintained By It's Previous Owners And Under Utilized. Call Now To View!	
COE	\$48,006	?
OMV	\$14,999	?
ARF	\$14,999	?
Dereg Value	\$21,507 as of today (change)	?
No. of Owners	2	?
Type of Veh	Hatchback	
Category	PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 16-Jan-2019 | Last Updated on: 16-Feb-2019

Tags: Volkswagen polo, volkswagen polo, 2011 Volkswagen Polo, 2011 volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen



## Seller Information

Company	Presto Expat Motoring Services Pte Ltd » dealer's pricelist » 34 vehs sold   25 vehs available	
Address	491 River Valley Road #01-04 Search cars nearby this location	
Location	Valley Point Shopping Centre	
Office No	67327737	
Contact Person(s)	Lionel Chin	85117181 96857377

## Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

## Upfront Payment

» more Financial info


Transfer Fee	\$25	?
Down Payment	3)	Maximum 70% Loan ?

Compare



**FIXED PRICE AS LOW  
AS \$0.1797/KWH**


PACIFICLIGHT.COM.SG 644 1110




**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

**2011 Lamborghini Gallardo LP550.**







Immaculate Condition. Cheapest  
In Town.  
Direct Owner StarAd




**AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category  Save Search  Print Sort by Date Posted 20 results/page


**2 vehicles** | **Search** polo  Advanced Search  Search  View All


Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	polo	Any	Any	2010	Any	Any	Any	Available



☐ **Volkswagen Polo 1.4A** **\$17,500** **\$7,650 /yr** **17-Jun-2010** **1,390 cc** **-** **Hatchback** **Available**


Well Maintained, Low Mileage, Original Stock Condition, No Repairs Needed. Powerful And Yet Light On Fuel, Call Now For Viewing!


 Posted: 04-Mar-2019 Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen



☐ **Volkswagen Polo 1.2A TSI** **\$20,800** **\$8,090 /yr** **09-Sep-2010** **1,197 cc** **112,000 km** **Hatchback** **Available**

Well Maintained 1.2A TSI Model. Turbo Model. Not The 1.4 Non Turbo Version. Powerful Yet Fuel Savings. Accident Free, Welcome For Test Drive. High Perf Rebate, Safe Buy. New Road Tax Till 9/2019. New ...

 Posted: 22-Feb-2019 Tags: 2010 Volkswagen Polo, 2010 volkswagen polo, Volkswagen Polo, volkswagen polo, Volkswagen, Polo, polo, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.  Save Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads 20 results/page

> Back to OneMotoring



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2180D
Vehicle Details	
Vehicle No.:	SLN7753Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Feb 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	CGG224932
Chassis No.:	WVWZZZ6RZAU006715
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$14,856.00
Original Registration Date:	11 Jan 2010
First Registration Date:	11 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$14,856.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2020
PARF Rebate Amount:	\$7,428.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$1,591.00
<b>Total Rebate Amount:</b>	<b>\$9,019.00</b>

The information contained herein is correct as at 28 Feb 2019

OK

MV. 15155  
 COE. 9014  
 limit 6136.  
 ≈ 6000,

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Friday, 1 March 2019 3:14 PM  
**To:** assignments  
**Subject:** FW: PRI FOR SLN 7753Z; YOUR INSURED GW 4344C - PRS

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 1 March 2019 3:14 PM  
**To:** Claims 96 <claims@96motorsports.com>  
**Cc:** Gary Chang <gary.chang@96motorsports.com>; andysonckl <andysonckl@yahoo.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: PRI FOR SLN 7753Z; YOUR INSURED GW 4344C - PRS

Without prejudice

Save as to costs

Dear Sir,

We pri. Pls assist to provide all necessary documents details.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Claims 96 [mailto:claims@96motorsports.com]

**Sent:** Friday, 1 March, 2019 3:11 PM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Cc:** Gary Chang <gary.chang@96motorsports.com>; andysonckl <andysonckl@yahoo.com>

**Subject:** Re: PRI FOR SLN 7753Z; YOUR INSURED GW 4344C - PRS

Hi. We would like adrian ling from Lkk.

Thank you

On Fri, 1 Mar 2019, 3:05 pm Chong Boon Sen, <boonsen.chong@sg.cntaiping.com> wrote:

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909



Cq. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** [claims@96motorsports.com](mailto:claims@96motorsports.com) [<mailto:claims@96motorsports.com>]

**Sent:** Thursday, February 28, 2019 2:31 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** Gary 96 <[gary.chang@96motorsports.com](mailto:gary.chang@96motorsports.com)>; Andyson <[andysonckl@yahoo.com](mailto:andysonckl@yahoo.com)>

**Subject:** PRI FOR SLN 7753Z; YOUR INSURED GW 4344C

**WITHOUT PREJUDICE**

Dear CN TAIPING ,

**ACCIDENT INVOLVING SLN 7753Z and GW 4344C on 27.02.2019**

**AT / ALONG AMK AVE 6 TWDS LENTOR AVE**

We act for **SEE HUP SENG TIN FACTORY PTE LTD**, whose vehicle registration number **SLN 7753Z** was damaged in the above accident.

Kindly let us have your list of surveyors within **2 working days** of your receipt of this notice should you like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Jade Lim



**62/64 Kaki Bukit Avenue 6**

**Ark @ KB Singapore 417893**

**Tel** : 6702 6996

**Fax** : 6384 6996

**Email** : [claims@96motorsports.com](mailto:claims@96motorsports.com)

**Website:** [www.96motorsports.com](http://www.96motorsports.com)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/03/2019 16:10
Date Of Accident	27/02/2019 10:30
Exact Location Of Accident	ANG MO KIO AVE 6 TOWARDS LENTOR AVENUE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN7753Z
Insured/Policyholder	
Name Of Registered Owner	SEE HUP SENG TIN FACTORY PTE. LTD.
Co Reg No	197602180D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85710878
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	POLO 1.4 AT 6R13E7
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA218179/1
Cover Note Number	
Driver	
Name of Driver	SEBASTIAN SEE ZHI HERNG
NRIC No	S9448877Z
Date Of Birth	26/12/1994
Occupation	OUTDOOR
Date Of Driving Pass	03/02/2014
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85710878
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	299 YISHUN STREET 20 #08-31 SPORE 760299
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SARIPAH GENDER: : FEMALE
Passenger 2	NAME: : TAN AH MOI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW4344C
Vehicle Make/Model/Colour	TOYOTA HIACE M.
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name SEBASTIAN SEE ZHI HERNG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLN7753Z

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name SARIPAH

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLN7753Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 3

Name TAN AH MOI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLN7753Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Suhaimi  
NRIC No: S8040377A

.....

refer to police report. T / 20190227 / 2121

I/We declare the foregoing particulars are true in every respect.



5

12



redefining / insurance

AXA Insurance Pte Ltd  
 1800 880 4888 (Within Singapore)  
 (65) 6880 4888 (International)  
 (65) 6880 4740  
 customer.care@axa.com.sg  
 www.axa.com.sg

## Certificate of Insurance

account number  
 04437

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)  
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

### Policy details

Policyholder name	SEE HUP SENG TIN FACTORY PTE. LTD.	Certificate number	GA218179 / 1
Cover	Comprehensive	Chassis number	WVWZZZ6RZAU006715
Plan name	Essential	Engine number	CGG224932
NCD applicable	50%		
Vehicle registration number	SLN77532		
Period of insurance	from 11/07/2018 to 10/07/2019 (both dates inclusive)		
Finance loan company	HENLY ENTERPRISES CO (PTE) LTD		

### Persons or classes of persons entitled to drive\*

- (a) Any Named Driver as stated in the Policy:  
 1. LOW SEOH KEOW  
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

<b>EXCESS</b>	Basic Own Damage Excess	\$GD 400.00
	Windscreen Excess	\$GD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

### Additional clauses & endorsements to your policy

Nil

/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



Driving License

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S9448877Z**  
Name: **SEBASTIAN SEE ZHI HERNG**

Birth Date: **26 Dec 1994**  
Issue Date: **03 Feb 2014**




 002271530E

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

	EFFECTIVE DATE
<b>Class 3</b> Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg	<b>03 Feb 2014</b>

NP 428A

Licence No: S9448877Z 

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190227/2121

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190227/2121

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/02/2019 16:52		Vide Report No.: F/20190227/0070		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: SEBASTIAN SEE ZHI HERNG			Address: 299 YISHUN STREET 20 #08-31 SINGAPORE 760299		
ID Type / ID No.: NRIC NO / S9448877Z			Contact No.: Home/Office: Mobile: 85710878		
Nationality:			Email:		
Sex: Male	Age: 24	Date of Birth: 26/12/1994	Type of Informant: Driver		
Race:			Language:	Institution / School Name:	
Occupation: OTHERS			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/02/2019 10:30	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 6 TOWARDS LENTOR AVE X ANG MO KIO AVE 8				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GW4344C	Van					1
SLN7753Z	Car					2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190227/2121

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190227/2121

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	SEBASTIAN SEE ZHI HERNG	ID No.	S9448877Z
Related Vehicle	SLN7753Z (Car)	Contact No.	85710878
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/02/2019	Date Discharge	27/02/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL
<b>Passenger</b>			
Name	TAN AH MOI	ID No.	S0308675E
Related Vehicle	SLN7753Z (Car)	Contact No.	NIL
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/02/2019	Date Discharge	27/02/2019
No. of Days granted Medical Leave	10	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE MENTIONED TIME, DATE AND LOCATION.

I WAS TRAVELLING ALONG ANG MO KIO AVENUE 6 ON THE 3RD LANE OF 4. I WAS APPROACHING THE JUNCTION OF LENTOR AVENUE BY ANG MO KIO AVENUE 8. THE TRAFFIC LIGHT WAS AMBER AND TURNED RED ABOUT 2 SECONDS LATER, SO I SLOWED DOWN TO COME TO A STOP BEFORE THE JUNCTION. I CAME TO A STOP AS THE LIGHT ALREADY TURNED RED. THE VAN MENTIONED CAME FROM BEHIND AND COLLIDED INTO THE REAR OF MY CAR. MY CAR MOVED ABOUT 2 CAR LENGTH FORWARD DUE TO THE IMPACT. MY GRANDMOTHER AND I WERE INJURED AS A RESULT OF THE ACCIDENT. SHE WAS CONVEYED BY AMBULANCE TO KHOO TECK PUAT HOSPITAL. I WAITED FOR TOWING TO SETTLE MY CAR AND THEN I ALSO PROCEEDED TO KHOO TECK PUAT FOR TREATMENT.

Police Report



SINGAPORE  
POLICE FORCE



T/20190227/2121

3 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190227/2121

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /  
KHALED AMR HASSAN MOHSSEN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
27/02/2019 16:52

Officer In Charge Of Case:  
TP / GIT /  
Sgt 2 HO JIEKANG, IVAN  
Contact No.: 65476170

Classification Of Case:



SINGAPORE  
POLICE FORCE

Authentication Stamp  
NP168

Signature:

Date of Accident : 27-2-19 Accident Time: 1030. (24-HR-Format)  
Accident Place : Ang Mo Kio Ave 6 towards Lendar Avenue.  
Vehicle No. (Car Plate No.) : SLN 77 53Z Make/Model: Volkswagen Polo.  
Insurance Company : AXA Policy No: 6A218179/1.  
Owner or Company Name /IC No. : See Hup Seng Tin Factory Pte. Ltd. 1926021800.  
Owner or Company Contact No. : 8571 0878 Owner's Hp Company Tel  
DRIVER'S Name / IC No. : Sebastian See Zhi Herng. S944 8877Z.  
DRIVER'S Date Of Birth : 26-Dec-1994 DRIVER'S License Pass Date 3-2-2014.  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others:  
DRIVER'S Address : Blk 299 Yishun St 20 #08-31 S(760299).  
DRIVER'S Contact No./ Alt No. : 1) 8571 0878. 2)  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address :  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 03  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): YES. Driver & Both passengers

Other Party Driver's Particular (if any)

Vehicle No: B: GW4344C	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: Ng Ah Keong	Name Driver: _____
IC No. Driver/Contact: 57468688E	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:

2 female - (1) Tan Ah Moi

(2) Saripah.

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: **Suhaimi**  
NRIC/FIN No: **S8040377A**



# SINGAPORE POLICE FORCE



T/20190227/2121

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190227/2121

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/02/2019 16:52	Vide Report No.: F/20190227/0070	Station Diary No.:
--	-------------------------------------	--------------------

**Informant's Particulars**

Name of Informant: SEBASTIAN SEE ZHI HERNG			Address: 299 YISHUN STREET 20 #08-31 SINGAPORE 760299		
ID Type / ID No.: NRIC NO / S9448877Z			Contact No.: Home/Office: Mobile: 85710878		
Nationality:			Email:		
Sex: Male	Age: 24	Date of Birth: 26/12/1994	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/02/2019 10:30	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 6  TOWARDS LENTOR AVE X ANG MO KIO AVE 8				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GW4344C	Van					1
SLN7753Z	Car					2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190227/2121

3 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190227/2121

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
TP /  
KHALED AMR HASSAN MOHSSEN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
Sgt 2 HO JIEKANG, IVAN  
Contact No.: 65476170

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
27/02/2019 16:52

Classification Of Case:



**SINGAPORE  
POLICE FORCE**

Signature: \_\_\_\_\_



TP Chim.  
Shirley.

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 1,769.00	✓
2	TAIL GATE WINDSCREEN <i>Shattered</i>	1	\$ 1,142.00	✓
3	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 96.00	✓
4	TAIL GATE WINDSCREEN INNER SEAL <i>m</i>	1	\$ 50.00	✓
5	TAIL GATE WIPER MOTOR <i>Re m</i>	1	\$ 567.40	✓
6	TAIL GATE WIPER ARM <i>Bit</i>	1	\$ 98.50	✓
7	TAIL GATE WIPER ARM COVER <i>Could</i>	1	\$ 35.00	✓
8	TAIL GATE WIPER BLADE <i>cut</i>	1	\$ 66.30	✓
9	TAIL GATE BADGE WITH OPENER SWITCH <i>Damaged</i>	1	\$ 698.00	✓
10	TAIL GATE EMBLEM (GOLF) <i>new</i>	1	\$ 167.00	✓
11	TAIL GATE ENBLEM (1.4) <i>m</i>	1	\$ 126.00	✓
12	TAIL GATE INNER LOCK <i>Damaged</i>	1	\$ 590.00	✓
13	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 156.00	✓
14	TAIL GATE WEATHERSTRIP <i>cut</i>	1	\$ 365.00	✓
15	TAIL GATE INNER TRIM <i>Damaged</i>	1	\$ 379.00	✓
16	TAIL GATE INNER TRIM CLIP <i>m</i>	10	\$ 40.00	✓
17	TAIL GATE HINGE L+R <i>new</i>	2	\$ 120.00	✓
18	TAIL GATE ABSORBER L+R <i>new</i>	2	\$ 400.00	✓
19	TAIL LAMP L+R <i>LH Could RH Could</i>	2	\$ 746.00	✓
20	TAIL LAMP INNER SEAL L+R <i>new</i>	2	\$ 80.00	✓
21	TAIL LAMP CLIP <i>m</i>	10	\$ 20.00	✓
22	TAIL LAMP PANEL L+R <i>RH Dented</i>	2	\$ 260.00	130
23	REAR BUMPER <i>Distorted</i>	1	\$ 1,368.00	✓
24	REAR BUMPER SIDE RETAINER L+R <i>m</i>	2	\$ 210.00	✓
25	REAR BUMPER CLIP <i>m</i>	10	\$ 50.00	✓
26	REAR BUMPER CENTER RETAINER <i>Damaged</i>	1	\$ 287.00	✓
27	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 698.00	✓
28	REAR BUMPER NUMBER PLATE LAMP L+R <i>Could</i>	2	\$ 246.00	✓
29	END PANEL <i>Distorted</i>	1	\$ 1,345.00	✓
30	END PANEL TOP TRIM <i>Dented</i>	1	\$ 287.00	✓
31	END PANEL TOP TRIM CLIP <i>m</i>	10	\$ 40.00	✓
32	SPARE TYRE PANEL <i>Repair</i>	1	\$ 876.00	✓

1	SPARE TYRE PANEL TOP BOARD <i>del</i>	1	\$	354.00	<i>2</i>
2	SPARE TYRE TOP TOOL SPONGE <i>men</i>		\$	210.00	<i>x</i>
3	REAR KEY ANTENNER SENSOR <i>del</i>	1	\$	365.00	<i>2</i>
4	REAR EXHAUST SILENSER <i>men</i>	1	\$	1,327.00	<i>x</i>
5	REAR EXHAUST MOUNTING <i>men</i>	2	\$	280.00	<i>x</i>
6	REAR EXHAUST GASKET <i>men</i>	1	\$	58.00	<i>x</i>
7	REAR FENDER RH <i>Buckled</i>	1	\$	892.00	<i>✓</i>
8	REAR FENDER INNER TRIM L+R <i>del</i>	2	\$	458.00	<i>2</i>
9	REAR FENDER INNER TRIM CLIP <i>men</i>	10	\$	30.00	<i>2</i>
10	REAR FENDER INNER SHIELD L+R <i>men</i>	2	\$	210.00	<i>x</i>
11	REAR FENDER INNER SHIELD CLIP <i>men</i>	10	\$	30.00	<i>x</i>
				<i>13343.80</i>	
				<i>12009.42</i>	
SUBTOTAL			\$	17,592.20	\$ -
5%			\$	879.61	\$ -
PARTS TOTAL			\$	16,712.59	\$ -
SPECIAL NETT		QTY	PRICE		PRICE
1	REAR WINDSCREEN SEALANT <i>men</i>	1	\$	50.00	<i>-</i>
	REAR WINDSCREEN SOLAR FLIM <i>men</i>	1	\$	<del>300.00</del>	<i>200</i>
2	REAR NUMBER PLATE WITH COVER <i>Best</i>	1	\$	<del>120.00</del>	<i>50</i>
3	REVERSE SENSOR <i>David</i>	1	\$	<del>350.00</del>	<i>200</i>
4	BODY PANEL JOINT SEALANT <i>men</i>	1	\$	<del>150.00</del>	<i>60</i>
SPECIAL NETT 1			\$	970.00	\$ -
LABOUR		QTY	PRICE		PRICE
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$	<del>2,200.00</del>	<i>1400</i>
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	<del>2,000.00</del>	<i>1100</i>
3	TO RUST PROOF ACCIDENT AFFECTED ARAE	1	\$	<del>120.00</del>	<i>50</i>
4	TO R & R REAR WINDSCREEN	1	\$	<del>150.00</del>	<i>120</i>
5	TO R & R TAIL GATE PARTS	1	\$	<del>150.00</del>	<i>80</i>
6	TO R & R REVERSE SENSOR	1	\$	<del>150.00</del>	<i>50</i>
7	TO R & R CARPET AND SEAT	1	\$	<del>250.00</del>	<i>80</i>
8	TO R & R REAR EXHAUST	1	\$	<del>200.00</del>	<i>x</i>
9	TO REPROGRAM AND REDIANOS FAULT CODE	1	\$	<del>600.00</del>	<i>100</i>
LABOUR TOTAL			\$	5,820.00	\$ -
GRAND TOTAL COST			\$	23,502.59	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE 2 OF 2

*total: 13549.42* *Adrian L*  
*2/5: 6K* *1/5 24/03/19*  
*total loss.* *10 Days.*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)
























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2019 11:46		25 Mar 2019 09:24 <a href="#">Edit Adj Rpt</a>	<b>S\$6,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	<b>SEE HUP SENG TIN FACTORY PTE. LTD.,</b> Co. Reg. No.: 197602180D								
Vehicle Reg. No.:	<b>SLN7753Z</b>	Date of Loss:	27/02/2019 10:00 - :59 [109 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>GW4344C</b>	Policy No. (Claimant):	GA218179/1						
		Excess:	S\$0.00						
Repairer:	<b>96 Motorsports Pte Ltd (HQ)</b> 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 03/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLN7753Z  
[GW4344C]  
TP  
SEE HUP SENG TIN FACTORY PTE. LTD.  
Feb 27 2019 10:00AM  
[-]  
96 Motorsports Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:29	Accident Statement	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 16:27	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 16:27	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 16:28	Insurancepolicy [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 16:28	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 16:28	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 16:28	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 16:28	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 11:52	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 11:52	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
15	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/03/19 09:23	PRI CONTCT	 Load PDF	
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:29	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 16:29	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:29	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 16:27	Driving License	 Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 16:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 16:27	Accident Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
10	04/03/19 16:28	Insurancepolicy	Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 16:28	Driving License	Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 16:28	Police Report	Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 16:28	Police Report	Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 16:28	Police Report	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 16:29	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 16:29	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003941/ASD3E2

Date: 04/04/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No: SLN7753Z

Insured Vehicle No: GW4344C

Date of Loss: 27/02/2019

Nature of Claim: TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLN7753Z

Make &amp; Model: VOLKSWAGEN POLO, 1.4 AT 6R13E7 (A)

Engine No: CGG224932

Reg. Date: 11/01/2010 (Man. Year: 2009)

Chassis No: WWWWZZ6RZAU006715

Colour: Grey

Odometer: 153460 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,682.59	12,569.42	5,113.17	28.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,820.00	2,980.00	2,840.00	48.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,502.59</b>	<b>15,549.42</b>	<b>7,953.17</b>	<b>33.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>(S\$)</b>	<b>23,502.59</b>	<b>6,000.00</b>	<b>17,502.59</b>	<b>74.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,645.18</b>	<b>420.00</b>	<b>1,225.18</b>	<b>74.47</b>
<b>Nett Amount (S\$)</b>	<b>25,147.77</b>	<b>6,420.00</b>	<b>18,727.77</b>	<b>74.47</b>

## INSPECTION

Date of Assignment: 25/03/2019

Date Inspected: 04/03/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)  
62/64 Kaki Bukit Avenue 6  
Singapore 417893

Estimated Period of Repair: 0.0 days

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



**TOTAL LOSS ASPECT**

The total amount incurred will be Market Value \$ 15,000.00 minus Total Rebate \$ 8,999.00 = \$ 6,001.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b>	144	VOLKSWAGEN POLO 1.4 AT 6R13E7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN7753Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	1,769.00 FL	*1,769.00 FL
2	1		*TAIL GATE WINDSCREEN	Shattered	1,142.00 FL	*1,142.00 FL
3	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	96.00 FL	*96.00 FL
4	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	50.00 FL	*50.00 FL
5	1		*TAIL GATE WIPER MOTOR	Not Necessary	567.40 FL	*- FL
6	1		*TAIL GATE WIPER ARM	Cut	98.50 FL	*98.50 FL
7	1		*TAIL GATE WIPER ARM COVER	Cracked	35.00 FL	*35.00 FL
8	1		*TAIL GATE WIPER BLADE	Cut	66.30 FL	*66.30 FL
9	1		*TAIL GATE BADGE WITH OPENER SWITCH	Damaged	698.00 FL	*698.00 FL
10	1		*TAILGATE EMBLEM (GOLF)	Necessary	167.00 FL	*167.00 FL
11	1		*TAIL GATE EMBLEM (1.4)	Necessary	126.00 FL	*126.00 FL
12	1		*TAIL GATE INNER LOCK	Jammed	590.00 FL	*590.00 FL
13	1		*TAIL GATE LOCK CATCH	Damaged	156.00 FL	*156.00 FL
14	1		*TAIL GATE WEATHERSTRIP	Cut	365.00 FL	*365.00 FL
15	1		*TAIL GATE INNER TRIM	Deformed	379.00 FL	*379.00 FL
16	10		*TAIL GATE INNER TRIM CLIP	Necessary	40.00 FL	*40.00 FL
17	2		*TAIL GATE HINGE L+R	Not Necessary	120.00 FL	*- FL
18	2		*TAIL GATE ABSORBER L+R	Not Necessary	400.00 FL	*- FL
19	2		*TAIL LAMP L+R	Cracked	746.00 FL	*746.00 FL
20	2		*TAIL LAMP INNER SEAL L+R	Necessary	80.00 FL	*40.00 FL
21	10		*TAIL LAMP CLIP	Necessary	20.00 FL	*20.00 FL
22	1		*TAIL LAMP PANEL L+R	O/S Dented	260.00 FL	*130.00 FL
23	1		*REAR BUMPER	Distorted	1,368.00 FL	*1,368.00 FL
24	2		*REAR BUMPER SIDE RETAINER L+R	Necessary	210.00 FL	*210.00 FL
25	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
26	1		*REAR BUMPER CENTER RETAINER	Damaged	287.00 FL	*287.00 FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	698.00 FL	*698.00 FL
28	2		*REAR BUMPER NUMBER PLATE LAMP L+R	Cracked	246.00 FL	*246.00 FL
29	1		*END PANEL	Distorted	1,345.00 FL	*1,345.00 FL
30	1		*END PANEL TOP TRIM	Deformed	287.00 FL	*287.00 FL
31	10		*END PANEL TOP TRIM CLIP	Necessary	40.00 FL	*40.00 FL
32	1		*SPARE TYRE PANEL	Repair	876.00 FL	*- FL
33	1		*SPARE TYRE PANEL TOP BOARD	Deformed	354.00 FL	*354.00 FL
34	1		*SPARE TYRE TOP TOOL SPONGE	Not Necessary	210.00 FL	*- FL
35	1		*REAR KEY ANTENNER SENSOR	Damaged	365.00 FL	*365.00 FL
36	1		*REAR EXHAUST SILENCER	Not Necessary	1,327.00 FL	*- FL
37	2		*REAR EXHAUST MOUNTING	Not Necessary	280.00 FL	*- FL
38	1		*REAR EXHAUST GASKET	Not Necessary	58.00 FL	*- FL
39	1		*REAR FENDER RH	Buckled	892.00 FL	*892.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR FENDER INNER TRIM L+R	Deformed	458.00 FL	*458.00 FL
41	10		*REAR FENDER INNER TRIM CLIP	Necessary	30.00 FL	*30.00 FL
42	2		*REAR FENDER INNER SHIELD L+R	Not Necessary	210.00 FL	*- FL
43	10		*REAR FENDER INNER SHIELD CLIP	Not Necessary	30.00 FL	*- FL
44	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
45	1		*REAR WINDSCREEN SOLAR FILM	Necessary	300.00 FS	*200.00 FS
46	1		*REAR NUMBER PLATE WITH COVER	Bent	120.00 FS	*50.00 FS
47	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
48	1		*BODY PANEL JOINT SEALANT	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>18,562.20</b>	<b>13,903.80</b>
<b>- List Item Discount on L Items 5.00/10.00% (\$\$)</b>	879.61	1,334.38
<b>Total Parts (\$\$)</b>	<b>17,682.59</b>	<b>12,569.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	2,200.00	1,400.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,000.00	1,100.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	50.00
4	TO R & R REAR WINDSCREEN	New	150.00	120.00
5	TO R & R TAIL GATE PARTS	New	150.00	80.00
6	TO R & R REVERSE SENSOR	New	150.00	50.00
7	TO R & R CARPET AND SEAT	New	250.00	80.00
8	TO R & R REAR EXHAUST	New	200.00	0.00
9	TO REPROGRAM AND REDIANOS FAULT CODE	New	600.00	100.00
Gross Labour Cost (\$\$)			5,820.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >