

03/2002

ASS. REC. BY:

REF CS/MSG/19003946/Ed3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Monta Chung

of

MSK

Date/Time:

04/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9845H

Insured:

EZ 8108A

at Workshop m/s

Kok Wang Car Grooming

Tel:

of

1 Soon Lee St #06-40 Pioneer Centre

Policy No:

C000677630

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction

() Estimate

*SLR 9845H x**EZ 8108A x**Dismantle: 5/3/2019**After repair: 8/3/2019*

Warranty Steve

REF: MSIG

ASSIGNMENT

From _____ Date: _____
Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
To Inspect Vehicle No: _____
at Workshop m/s: _____
of _____
Insured _____
Policy No. _____
Claims No _____
Sum Insured _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X	X	X
N/S	O/S		

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No SLR 9845 H 31/08/17

Type: M. Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour Blue A/C Insured / Std / NI / NA

Sp. Reading 82932 T/Radio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: R4 112 09455

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 215 / 60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 25/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 4/3/19

Gok Wang

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction
MV- 75,000
PV- 45,840
NV- 29,160

Repair large SK-6K, 6 days

27/3/2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation

) S + R: \$

) Photos

) Other:

TOTAL

120
10
130

Report Format:

PRE

ump Sum / I.B.I. (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		04 Mar 2019 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: NA			
Main Claimant:	ANDRIC AGENCIES PTE LTD, Co. Reg. No.: 200804611D			
Vehicle Reg. No.:	SLR9845H	Date of Loss:	25/02/2019 10:00 - :59 [17 Months and 25 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	1000677630 (Comprehensive) Coverage: 29/04/2018 - 28/04/2019	
Vehicle Reg. No. (Insured):	EZ8108A	Policy No. (Claimant):		
		Excess:		
Repairer:	Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/03/2019]			
Driver/Custodian (Insured):	POON CHAY YEN (/ Female) , NRIC: S7521570C Email:			
Adj Asg. Remarks:	on WP Liability 80%. SJE disagree - assign LKK. Contact : Mr Kok at 91839633.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4611D
Vehicle Details	
Vehicle No.:	SLR9845H
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4409455
Chassis No.:	RU11209455
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,921.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$12,690.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$9,517.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$36,323.00
Total Rebate Amount:	\$45,840.00

The information contained herein is correct as at 04 Mar 2019

OK



Posted: 02-Mar-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X **\$80,800** **\$9,240 /yr** **22-Aug-2017** **1,496 cc** **29,100 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Posted: 01-Mar-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$75,800** **\$8,340 /yr** **25-Aug-2017** **1,496 cc** **-** **SUV** **Available**

One Owner, Nice Double Digit Nos Plate, Car Like New. Buy With A Peace Of Mind. High Trade In And In House Available. Kindly Contact Our Friendly Sale Staff For Viewing And Test Drive.

Posted: 01-Mar-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$72,800** **\$8,250 /yr** **26-Apr-2017** **1,496 cc** **32,000 km** **SUV** **Available**

Very Low Mileage With Servicing Record! Come With One Year Premium Warranty. Brand New Tyres! Perfect Condition! Look Like Brand New! High Loan At Low Interest Rate! Trade In Available. Viewing By App...

PREMIUM AD

Posted: 28-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Save up to 25% on petrol

Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.

Find out more!



Honda Vezel Hybrid 1.5A X **\$78,800** **\$9,220 /yr** **06-Jun-2017** **1,496 cc** **31,652 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Low Interest Rate. In-house Financing Available. Consignment Unit. Viewing By Appointment Only. Just Been Serviced And Replaced Transmission Oil. Balloon Scheme, In House Financing Options Available. ...

CONSIGNMENT

GOWheeler Pte Ltd

Posted: 28-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$78,888** **\$8,700 /yr** **29-Aug-2017** **1,496 cc** **2,000 km** **SUV** **Available**

Posted: 28-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$72,900** **\$8,360 /yr** **31-Mar-2017** **1,496 cc** **-** **SUV** **Available**

Elegant White SUV, One Owner Only, Comes With Warranty, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 27-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$69,800** **\$7,910 /yr** **02-Feb-2017** **1,496 cc** **-** **SUV** **Available**

Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need Gu...

PREMIUM AD

B8 Motor Trading

Posted: 25-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$71,900** **\$8,460 /yr** **25-Jan-2017** **1,496 cc** **-** **SUV** **Available**

Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 25-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X **\$80,800** **\$9,400 /yr** **03-Feb-2017** **1,496 cc** **27,000 km** **SUV** **Available**

High Loan Approval And Only \$5000 Can Driver Away With Flexible Bank And In House Financing Options. View Today!Inclusive! STA Certified Accident Free Quality Pre Owned With Low Mileage.

Posted: 25-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X **\$83,800** **\$9,210 /yr** **29-Dec-2017** **1,496 cc** **9,999 km** **SUV** **Available**

Fuel Type: Petrol-Electric

1 Owner Only. Not PHV Vehicle. 100% Accident Free. Low Mileage Done. Still Under 2 Year Warranty. Excellent Condition Inside Out, Upgraded Sports Rims, Expensive Tyres, Fully Soundproof. Call Now Befor...

Posted: 25-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

[Compare](#)

SUPREME



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 Toyota Wish 1.8 with very low mileage of 13K.



As good as new. Borneo Motor warranty. High trade in. Price Neg! Call us now...
Speedo Motoring 50646

PRIME MOTOR & LEASING
[CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES]
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

25 vehicles

Honda Vezel

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	2017	Any	Any	Any	Available

**Honda Vezel 1.5A X****\$72,800****\$8,110 /yr****13-Jul-2017****1,496 cc****20,000 km****SUV****Available**

Lowest Price Tag Need No Compare With Others Yet Low Mileage Done, Regular Service, 1 Owner Only Non Previous Rental Unit, New Car Conditions With Original Cushion Seats, Prosperity Original Paintwork...

AL Autocar Pte Ltd

Posted: 04-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Honda Vezel Hybrid 1.5A X
Honda Sensing****\$81,800****\$9,070 /yr****29-Nov-2017****1,496 cc****15,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Up To 90% Loan Available! Flexible Scheme With In House Financing. Trade-In Available. Owning A Car Make Easier With Us. See It For Yourself. Call Us For A Viewing Now.

Posted: 04-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$78,000****\$9,580 /yr****20-Jan-2017****1,496 cc****24,000 km****SUV****Available****Fuel Type:** Petrol-Electric

One Owner. Well Maintained. Viewing By Appointment! Don't Miss This Beautiful White Car!

360 VR Cars

Posted: 04-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Honda Vezel 1.5A X****\$69,800****\$8,020 /yr****03-Feb-2017****1,496 cc****-****SUV****Available**

Full Loan Available At \$1.1k+/ Month We Can Help To Conver To Z10 Usage If Needed. In House Loan / Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMar...

88 Motor Trading

Posted: 03-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Exhaust Muffler Tip**

Exhaust tip to enhance look. Sporty look after installation. Free installation.

More info about this product

**Honda Vezel Hybrid 1.5A X****\$76,800****\$9,270 /yr****10-Mar-2017****1,496 cc****4,900 km****SUV****Available****Fuel Type:** Petrol-Electric

3 Years On 100000Km Warranty. High Trade In.

Prime Motor & Leasing

Posted: 02-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X Honda
Sensing****\$72,800****\$8,440 /yr****03-Jan-2017****1,496 cc****32,952 km****SUV****Available**

Easy In-House Loan And Balloon Scheme Available, No Gimmicks! 1 Owner, Honda Sensing, Lane Departure Warning, Full Body Kits, Side Step, CMBS, Auto Start/Stop, Multi-Function Steering Wheel, Electric ...

Posted: 02-Mar-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

Compare

Honda Vezel 1.5A X**\$68,688****\$7,770 /yr****15-Mar-2017****1,496 cc****129,000 km****SUV****Available**

Well Maintained By Owner. Accident Free. No Repairs Needed. Consignment Unit. High Loan And Trade In Available.

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2019 17:02
Date Of Accident	25/02/2019 10:40
Exact Location Of Accident	PORTSDOWN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9845H
Insured/Policyholder	
Name Of Registered Owner	ANDRIC AGENCIES PTE LTD
Co Reg No	200804611D
Email Address	ANDRICLEASING@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97546341

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994252
Cover Note Number	

Driver

Name of Driver	NG CHIN LYE
NRIC No	S1605564F
Date Of Birth	12/11/1963
Occupation	OUTDOOR
Date Of Driving Pass	25/09/1981
Driving Experience	37 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97546341
Fax Number	
Contact Number	
EMail Address	ANDRICLEASING@SINGNET.COM.SG

Address	APT BLK 47 TEBAN GARDENS ROAD #10-223
Postcode	600047
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EZ8108A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	POON CHAY YEN
NRIC/Passport Number	S7521570C
Contact Number	96205922
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to www.mva.com.sg
2. This form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any false information stated could result in the insurer being able to **repudiate policy liability**
4. Insurance and re-insurance companies may work with the police to identify the driver of the vehicle involved in the accident.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurer to the Traffic Police, Singapore Police Force, and the relevant authorities in the event of an accident involving a vehicle registered in Singapore.
7. The report will be used by the insurer to settle the claim and for other purposes. The insurer may use the report for the purpose of settling the claim and for other purposes.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - a. I have read and understand the above information and I agree to provide my personal information to the insurer for the purpose of settling the claim and for other purposes.
 - b. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - c. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - d. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - e. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - f. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - g. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - h. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - i. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - j. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - k. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - l. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - m. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - n. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - o. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - p. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - q. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - r. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - s. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - t. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - u. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - v. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - w. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - x. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.
 - y. I agree to the insurer disclosing my personal information to the relevant authorities for the purpose of settling the claim and for other purposes.
 - z. I agree to the insurer using my personal information for the purpose of settling the claim and for other purposes.

Policyholder's Signature
Date & Time


Driver's Signature
Date & Time



Refused to sign
Name: **CHRISTINA**
Date/Time: **28/1/19**

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On date 25/02/2019 time 10:43 I was driving along Portsmouth Road to send my passenger to her location. While I was driving I saw one car "EZ 8008 A" come from opposite without signal and turn right and hit the rear of SLR 9845 H.

DECLARATION

I declare the foregoing particulars are true and correct.

Witness's Signature
Date & Time

Driver's Signature
If Driver is not the Declarant
Date & Time

Reporting Officer's Signature
Name
Date & Time






































...CLAIM SUBFOLDER...(Pending for Survey Report)















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2019		04 Mar 2019 09:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: NA									
Main Claimant: ANDRIC AGENCIES PTE LTD , Co. Reg. No.: 200804611D									
Vehicle Reg. No.: SLR9845H		Date of Loss: 25/02/2019 10:00 - :59 [17 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 225259		Policy/Cover Note No.: 1000677630 (Comprehensive) Coverage: 29/04/2018 - 28/04/2019							
Vehicle Reg. No. (Insured): EZ8108A		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 05/03/2019]									
Driver/Custodian (Insured): POON CHAY YEN (/ Female) , NRIC: S7521570C Email:									
Adj Asg. Remarks: on WP Liability 80%. SJE disagree - assign LKk. Contact : Mr Kok at 91839633.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR9845H (225259)
[EZ8108A]
TP
ANDRIC AGENCIES PTE LTD
Feb 25 2019 10:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Kok Wang Car Grooming

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
15	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
16	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
17	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
18	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
19	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
20	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
21	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
22	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
23	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
24	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
25	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
26	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
27	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
28	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
29	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
30	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
31	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
32	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
33	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
34	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
35	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
36	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>
37	04/03/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/03/19 19:11	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
46	04/03/19 19:11	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
47	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/03/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
94	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
100	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
101	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
102	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
103	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
104	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
105	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
106	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
107	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
108	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
109	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
110	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
111	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
112	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
113	28/03/19 15:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
114	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
115	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
116	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
117	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
118	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
119	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
120	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
121	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
122	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
123	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
124	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
125	28/03/19 15:47	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/19 15:29	SLR9845H E-file report	Load PDF	
2	01/03/19 15:36	PRI from R.S. Solomon LLC	Load PDF	
3	01/03/19 16:16	Survey disagree - assign LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003946/ESD3E2

Date: 29/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000677630

Claimant Vehicle No: SLR9845H

Insured Vehicle No: EZ8108A

Date of Loss: 25/02/2019

Nature of Claim: TP

Claim No: 225259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9845H

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4409455

Reg. Date: 31/08/2017 (Man. Year: 2016)

Chassis No: RU11209455

Colour: Blue

Odometer: 82932 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/03/2019

Date Inspected: 04/03/2019 Inspected At:

Kok Wang Car Grooming (HQ)
1 SOON LEE STREET #06-40 PIONEER
CENTRE
Singapore 627605

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9845H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >