

AIG



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 01/03/2019

User ID : BoonChewTay

### Section A - Accident Details


Registration Number	SMB257L
Case Reference Number	BUS/02/19/1061
Registration Date	11/4/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Kim Seong
Type of Accident	Side Swipe
Accident Date and Time	18/2/2019 6:30 PM
Accident Reported Date and Time	18/2/2019 8:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB257L - RIGHT REAR PORTION DAMAGED SJL7977D - TP INSURED WITH AIG - LEFT FRONT PORTION DAMAGED
Prepared Date and Time	1/3/2019 11:36 AM
Chassis Number	WMAA22ZXC7001280
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00 132.5
Total Spray Cost	\$616.00	\$0.00 528
Total Spare Part Cost	\$160.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$2,366.00</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$3,200.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	01/03/2019 11:49 AM	
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/03/2019

User ID : BoonChewTay

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00 <b>1325</b>	
<b>Total Labour</b>	<b>\$1,590.00</b>	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00 <b>528</b>	
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$616.00</b>	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE:R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	
6010062	Body	F01001-CW273	COVER: REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
6009988	BODY RH	A01001-CW567	PANEL, SIDE:R7, FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	
6009990	BODY RH	A01001-CW565	PANEL, SIDE:R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	
6009989	BODY RH	A01001-CW566	PANEL, SIDE:R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	<b>hee</b>
<b>Total</b>					<b>\$3,294.30</b>		<b>\$200.00</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

**LKK Auto Consultants** be the Repairer of the

- To resurvey before repair
- To display damaged parts
- Parts prices are reasonable
- Third party claims are handled
- No hidden charges
- Satisfaction guaranteed and
- Repairs are covered by insurance company

Accepted by Repairer

Signature:

Date:

**Hwee Jie - LKK**  
**1/3/19**  
**1/3 3days.**

**Photo after paint**