

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Abdul Rahim Bin Mohamad

Accident Date : 12-Feb-19

Vehicle No : FBF 415 G

Vehicle Model : Piaggio Vespa

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 12 160.00 X
1	Front fork assy	\$ 840.00 780.00 X
1	Front shock absorber	\$ 310.00 310.00 X
1	Front fork chrome cover	\$ 60.00 60.00
1	Front cowling	\$ 328.00 328.00 X
2	Front cowling mouldings	\$ 250.00 250.00
1	Front signal -L/H	\$ 75.00 75.00 X
2	Side mirrors	\$ 310.00 310.00 X
1	Handle bar	\$ 320.00 320.00 X
1	Hand grip set	\$ 90.00 90.00 X
1	Brake lever	\$ 39.00 39.00 X
1	Clutch lever	\$ 38.00 38.00 X
1	Lower belly panel	\$ 198.00 198.00
2	Footstep panel chrome mouldings	\$ 250.00 250.00 X
1	Rider footstep panel	\$ 550.00 550.00
1	Engine cover -R/H	\$ 360.00 360.00 X
2	Rear footrests	\$ 220.00 220.00 X
1	Exhaust	\$ 750.00 750.00 X
1	Exhaust protector	\$ 90.00 90.00
		\$ 5,178.00
		\$ 517.80
		\$ 4,660.20

Less 10%

not Actual

2/3 # 2400

5 day.

11/3/19

the phd RTH up

202

c/f: \$ 4,660.20

Special Nett Items

- | | |
|---|-----------------------|
| 1 | Number plate (1 set) |
| 1 | Steering cone (1 set) |
| 1 | "VESPA" emblem |
| 1 | Helmet |

\$	mer	28.00	10
\$	m	120.00	0
\$	mer	38.00	
\$	2	120.00	X
\$		306.00	

S/No. **Labour**


- | | |
|---|--|
| 1 | To provide towing service. |
| 2 | To check wiring and reset headlamp focusing. |
| 3 | To provide labour. |
| 4 | To respray painting. |

\$		50.00	35
\$	17	80.00	X
\$		380.00	350
\$		800.00	100
\$		1,310.00	

Grand Total

\$ 6,276.20

Dollars: Six Thousand Two Hundred Seventy-Six And Twenty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: