

1/1w

1/1e

Not Ashanti

11 Bmp & 6000h

Running After Rain

7 days



SLR 29482

Date

No.

Mitsubishi Lancer

JMYSREYIAGU006853

Rear Bumper	Sn	815 (N)	X
Rear Bumper Clips	nn	30 (N)	X
Rear Bumper Side Holder x02	Sn	38x2=76(N)	X
Rear RH Fender	Ry	885 (N)	✓
Rear RH Door 879	Ry	1038 (N)	✓
Rear RH Door Lock	R	238 (N)	X
Rear RH Door Weatherstripe	cm	159 (N)	306sn 79.50sn
Rear RH Door Inner Trim Board 422	mgcm	448 (N)	✓
Rear RH Door Inner Trim Board Clips	m	30 (N)	✓
Rear RH Door Glass Regulator Gear	Ry	295 (N)	✓
Rear Tyre x02	ol Rear cm	280x2=560(SN)	806sn 224sn
Rear Wheel Rim x02	Rear 95 Rd	650x2=1300(SN)	350sn
Rockler Panel RH	R	627 (N)	X
Front Tyre x02	Rear ol 95 Rd	280x2=560(SN)	X
Front Wheel Rim x02	ol 95 Rd	650x2=1300(SN)	350sn
Fuel Tank	Sn	1266 (N)	X
Rear Windscreen Moulding	m	65 (N)	✓
Rear Windscreen Sealant	m	60 (SN)	40sn
Front Lower Arm x02	ol 95 Rd	284x2=568(N)	✓
Front Shock Absorber x02	Sn	302x2=604(N)	X
Front Knuckle Arm x02	ol 95 Rd	391x2=782(N)	✓
Front Wheel Hub c/w Bearing x02	ol 95 Rd	195x2=390(N)	✓
Rear Lower Arm x02 C249	ol 95 Rd	329x2=658(N)	✓
Rear Knuckle Arm x02	ol 95 Rd	414x2=828(N)	✓
Rear Shock Absorber x02	Sn	214x2=428 (N)	X
Rear Wheel Hub c/w Bearing x02	ol 95 Rd	282x2=564(N)	✓
Rear Steering Arm x02	Sn	64x2=128 (N)	X
Rear Crossmembers	Sn	949 (N)	X

-10%



SLR2948R.

	Date	No.
Panel Beating	1500	9001
Spray Painting	1300	10001
Wiring	50	201
To remove reverse sensor	nn 100	X
To transfer rear door fittings.	150	1206
To remove rear windscreen.	180	1206
To remove upholstery.	250	1001
To remove fuel tank	nn 150	X
To remove front LH and RH undercarriages.	700	1401
To remove rear entire undercarriage.	880	1206
To perform wheel alignment.	150	801

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: