

ASS. REC. BY:

REF:

C9/LPC19004102/Gvd3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

05/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD2709M

Insured:

SLV 3617T

at Workshop m/s

KING'S AUTO

Tel:

6457-8629

of

BLK 176 S/m Drive

Policy No:

Claim No:

18/19/19/VP05/021471

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	SLD 2709M x
	SLV 3617T x
15/3/19	@ 1223pm Alex said est not ready
3/4/19	@ 306pm Repairer said pending supplier parts prices
12/9/19	@ 356pm LS \$ 2500 confirmed with Annie (Red 3677.76, 6090)

REF: **L8C**

**YME**

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s **King's Auto**  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **54** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **SLD2709M** Yr Regn: **10 Jun 2016**  
 Type: **M/Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **Honda odyssey** c.c. **2356**  
 Colour: **Black** A/C: Insured / Std / NI / NA  
 Sp. Reading: **27388** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JHMRC18806C200218**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **In order** / Jammed / Leaked / Burnt or  
 Brake: **In order** / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **25/55R17**  
 R: **11**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front  
 R/Bal. **6** mm R/Bal. **6** mm  
 L/Bal. **6** mm L/Bal. **6** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **05-03-19**  
 Survey held at **W/S** **5:30pm**  
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
**05/3** Estimate given later

**17/9/2019**

RECEIVED 18 SEP 2019

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?

Days Of Repair: **5**  
 Resurvey No. of Trip: **1**

Survey Fee:  
 Transportation:

2) **18/9 - typst**

Add Fee: ☐ : Site Insp. (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

) S + RS St  
 ) Photos  
 ) Others

Report Format : **TP**  
 Lump Sum / I.B.I. (\$) **2500/-**

TOTAL

**350**

**Veron Chen (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 12 September 2019 8:34 AM  
**To:** Veron Chen (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019. [External Confidential]

**Lonpac External - Confidential**

Dear Veron,

Our reference is 18/19/19/VP05/021471


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 11 September, 2019 5:54 PM  
**To:** GERALD POH WEE BIN; Admin A  
**Cc:** MT\_Claim\_SG; SUR  
**Subject:** RE: ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019. [External Confidential]

Dear Gerald,

Please provides claims number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 5 March 2019 12:47 PM  
**To:** Admin A <admin-a@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>; SUR <sur@lkkauto.com>; Alfred Ng <alfred\_ng@juseq.com.sg>  
**Subject:** FW: ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019. [External Confidential]

## Lonpac External - Confidential

Dear Catherine,

Kindly proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Alfred Ng [[mailto:alfred\\_ng@juseq.com.sg](mailto:alfred_ng@juseq.com.sg)]

**Sent:** Tuesday, 5 March, 2019 12:38 PM

**To:** GERALD POH WEE BIN

**Subject:** ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019.

Your ref: 19/19/19/VP05/021471

Our ref: JEQ/SLD2709M/KA

Dear Gerald,

We refer to your letter dated 5 March 2019.

Our client is agreeable to appoint the following surveyor as our single joint expert.

### 2. Mr Xing Guo Qiang

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

**King's Auto Air-Conditioning Service**

**Blk 176 Sing Ming Drive**

**#02-10.**

**Singapore 575721**

**Tel: 6457-8629**

**Fax: 6451-7651**

**Person In Charge: Alex**

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road  
#02-01/02/06 Singapore 169877  
Tel : 6536 9339  
Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Tuesday, 5 March 2019 12:49 PM  
**To:** assignments  
**Subject:** FW: ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019.  
[External Confidential]

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

NGR

(M)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 5 March 2019 12:47 PM  
**To:** Admin A <admin-a@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>; SUR <sur@lkkauto.com>; Alfred Ng <alfred\_ng@juseq.com.sg>  
**Subject:** FW: ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019. [External Confidential]

## Lonpac External - Confidential

Dear Catherine,

Kindly proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Alfred Ng [[mailto:alfred\\_ng@juseq.com.sg](mailto:alfred_ng@juseq.com.sg)]  
**Sent:** Tuesday, 5 March, 2019 12:38 PM  
**To:** GERALD POH WEE BIN  
**Subject:** ACCIDENT INVOLVING SLD2709M AND SLV3617T ON 1 MARCH 2019.

Your ref: 19/19/19/VP05/021471

Our ref: JEQ/SLD2709M/KA

Dear Gerald,

We refer to your letter dated 5 March 2019.

Our client is agreeable to appoint the following surveyor as our single joint expert.

2. Mr Xing Guo Qiang

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

SLD 2709M

**King's Auto Air-Conditioning Service**

**Blk 176 Sing Ming Drive**

**#02-10.**

**Singapore 575721**

**Tel: 6457-8629**

**Fax: 6451-7651**

Person In Charge: Alex

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road

#02-01/02/06 Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5020E
Vehicle Details	
Vehicle No.:	SLD2709M
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	K24W72010134
Chassis No.:	JHMRC1880GC200218
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$25,413.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$27,579.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2026
PARF Rebate Amount:	\$20,684.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$35,679.00
<b>Total Rebate Amount:</b>	<b>\$56,363.00</b>

The information contained herein is correct as at 06 Mar 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/03/2019 15:50
Date Of Accident	01/03/2019 16:40
Exact Location Of Accident	WOODLANDS CHECKPOINT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD2709M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	XI ZHENJIE
NRIC No	S8205020E
Email Address	VICTORZXI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96607724
Alternative Phone No	OFFICE-96607724

### Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4 EX-S CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10745059
Cover Note Number	

### Driver

Name of Driver	XI ZHENJIE
NRIC No	S8205020E
Date Of Birth	28/02/1982
Occupation	INDOOR
Date Of Driving Pass	23/05/2003
Driving Experience	15 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96607724
Fax Number	
Contact Number	OFFICE-96607724
Email Address	VICTORZXI@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : KEE ZONG HAN LUKE GENDER: : MALE
Passenger 2	NAME: : KEE ZONG BIN MICAH GENDER: : MALE
Passenger 3	NAME: : LEE SI YING GILLIAN GENDER: : FEMALE
Passenger 4	NAME: : CHONG CHOON NGOR GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was at queuing at the WOODLANDS CHECKPOINT entering towards SINGAPORE when a car SLV3617T hit onto rear of my car SLD2709M twice. At that point of time my car was stationary. No injuries were involved. That's all.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV3617T
Vehicle Make/Model/Colour	MERCEDES BENZ / E 250CGI



Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	GOH EAU TOH GARY
NRIC/Passport Number	S0230506B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Sketch Plan

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The date and assistance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of the report at the centre and to copies of the report being made available at least.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) my insurer, my workplace and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively for "Personal Information"; and disclose and transfer such Personal Information to all insurer(s) who have insured vehicles involved in the accident (all insurers); who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Statutory Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages, should;  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";  
(b) all insurers who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*

**VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHD FADZLY BIN ISMAIL**

Policyholder's Signature / Date & Time      Officer's Signature (if driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

### Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was at queuing at the WOODLANDS CHECKPOINT entering towards SINGAPORE when a car SLV3617T hit onto rear of my car SLD2709M twice. At that point of time my car was stationary. No injuries were involved. That's all.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

2 March 2019 at 12:28 PM

Date/Time:

2 March 2019 at 12:28 PM

Acc Verone

**KING'S AUTO AIR-CONDITIONING SERVICE**

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721  
 TEL: 6457-8629 FAX: 451-7651  
 Reg. No. 005950100W

DATE 8th Apr 2019  
 OUR REF SLD 2709 M  
 TO Xi Zhenjie  
 30 Kampong Eunus  
 #05-01  
 Singapore 417777

RE QUOTATION FOR VEHICLE SLD 2709 M - Honda  
 Odyssey

LKK Auto Consultants hence notify  
 the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Quantity	Item	Unit Price (\$)	Amount (\$)
1	Rear Boot Door / DM		1,216.80 / 1070.8
1	Rear Boot Door Lock X GNN		185.40 X
1	Rear Boot Door Catch X GNN		27.70 X
1	Rear Boot Door Inner Board / ee		206.30 X
1	Rear Boot Door Chrome Garnish / SCR		185.80 X
1	Rear Glass Moulding		53.80 X
1	Rear Bumper / DM		612.30 X 568.3
2	Rear Bumper Reflector X NN	45.40	90.80
1	Rear Bumper Side Retainer X NN		19.10 X
2	Parking Sensor / DM	267.80	535.60 200 (SN)
1	Rear License Plate Garnish X NN		230.40 X
1	End Panel X REPAIR		460.80 X
1	Rear Boot Weatherstrip X NN		117.40 X
1	Buzzer / DM		93.80 X
1	Remote Key Control / DM		98.70 X
			4,134.70
		LESS 20% DISCOUNT	826.94
		SUBTOTAL	3,307.76

**FOR SPECIAL NETT ITEMS**

Quantity	Item	Unit Price (\$)	Amount (\$)
	Sealant for glass / NBC		80.00 40
	Sealant for end panel X NN		100.00 X
		SUBTOTAL	180.00

**FOR LABOUR CHARGES**

Quantity	Item	Unit Price (\$)	Amount (\$)
	Panel beating		1,200.00 400
	Spray painting		900.00 400
	To check all lightings and wiring		50.00 30
	To supply and apply anti rust proof NN		100.00 X
	To remove and refit glass		180.00 100
	To remove, clean and refit upholstery		180.00 60
	To transfer door parts		80.00 60
		SUBTOTAL	2,690.00

GRAND TOTAL FOR THIS QUOTATION 6,177.76 1050

3131.6

20% : 2500

4 Days




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC19004012/Gvd3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-09-2019		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLV 3617T	Veh. Inspected	SLD 2709M	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021471	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	05/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMRC1880GC200218	Colour	BLACK	
Odometer	27388	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/03/2019	Inspection Date	05/03/2019	
Survey held at	KING'S AUTO AIR-CONDITIONING SERVICE BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 2709M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT DOOR	BUCKLED	1,216.80	1,070.80
1	REAR BOOT DOOR LOCK	NOT NECESSARY	185.40	-
1	REAR BOOT DOOR CATCH	NOT NECESSARY	27.70	-
1	REAR BOOT DOOR INNER BOARD	DEFORMED	206.30	206.30
1	REAR BOOT DOOR CHROME GARNISH	SCRATCHED	185.80	185.80
1	REAR GLASS MOULDING	NECESSARY	53.80	53.80
1	REAR BUMPER	DEFORMED	612.30	568.30
2	REAR BUMPER REFLECTOR @\$45.40	N/S CRACKED / O/S NOT NECESSARY	90.80	45.40
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	19.10	-
1	REAR LICENSE PLATE GARNISH	NOT NECESSARY	230.40	-
1	END PANEL	TO REPAIR SEE LABOUR	460.80	-
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	117.40	-
1	BUZZER	DAMAGED	93.80	93.80
1	REMOTE KEY CONTROL	DAMAGED	98.70	98.70
	LESS 20% DISCOUNT		-719.82	-464.58
			2,879.28	1,858.32
2	PARKING SENSOR @\$267.80 (SN)	DAMAGED	535.60	200.00
	LESS 20% DISCOUNT		-107.12	-
			428.48	200.00
<b>SPECIAL NETT ITEMS</b>				
1	SEALANT FOR GLASS (SN)	NECESSARY	80.00	40.00
1	SEALANT FOR END PANEL (SN)	NOT NECESSARY	100.00	-
			180.00	40.00
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF END PANEL.		1,200.00	400.00
	SPRAY PAINTING.		900.00	400.00
	TO CHECK ALL LIGHTINGS AND WIRNG.		50.00	30.00
	TO SUPPLY AND APPLY ANTI RUST PROOF.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT GLASS.		180.00	100.00

Report Ref No. CS/LPC19004012/Gvd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE CLEAN AND REFIT UPHOLSTERIES.		180.00	60.00
	TO TRANSFER DOOR PARTS.		80.00	60.00
			2,690.00	1,050.00
GRAND TOTAL			6,177.76	3,148.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/LPC19004012/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.