

Signature

Steve

REF:

AIG

ASSIGNMENT

From:

Date:

06/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 9899K

at Workshop m/s

VW

of

Alexandra

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11 AM owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 9899K

Yr Regn:

29/08/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Jetta

c.c

1.4

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

92554

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ16ZGM005255

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

"1"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/3/19

D.O.I.

6/3/19

Survey held at

Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 68,900

PL - 53,019

NV - 14,990

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$))

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) S + RS. St

) Photos

) Others

TOTAL