

 $51\; UBI\; AVE\; 1,\, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; FAX: \\ (065)\; 62564315\;\; PAYA\; UBI\; PARK,\; PAR$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 23/04/2019

Survey Details:

Date of loss	2-Mar-19
Date of appointment	5-Mar-19
Date of survey	5-Mar-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHA 9073E
Make and Model	HYUNDAI 140
Date of registration	9/10/2014
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	Ś	1.595.46

Proposed/Revised repair cost:

Parts	\$	628.10
Check items (estimate)	-	
Labour	\$	430.00
Total	\$	1,058.10
Lump Sum(if applicable)	\$	850.00