

NATIONAL Assessment Centre Services

[wef 1 Jan'05] MWA 119 03086

Date In: 5/2/19 - 16:18	Job description	Date & Time Completed	Done by
Ref No: NA/INC 17004056/C24	SAS e-filing		
Veh No: 8J1K6269B	E-mail (within 8hrs, AIG 2hrs)		
D.O.A: 2/2/19, 2:35	i-Motor Claim Form	NA/1035123-002	5/2/19, 16:54
OD: TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel: (	Fax: (
TP Particulars:	Veh No: unknown	INC () / Non-INC ()
Owner / Driver: (	Tel: (	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date: (	Time: (
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-
() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.
() Total Loss Case: to e-mail Insurer URGENTLY.
Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

NA1901251	Invoice Preparation Checklist	Am't (\$) Est Bill	Am't (\$) Add Bill
Claimant's Particulars:-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
QC Checked by (Engr-In-Charge):	QD*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
Auditors' Comments:-	TP (N11): TP (Non INC) against INC \$20		
Pat. 1:	9) N12: Idac Mobile 30		
Pat. 2 / 3:	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2019 16:18
Date Of Accident	20/02/2019 12:35
Exact Location Of Accident	PIE (CHANGI) AFTER BEDOK NORTH RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK6269B
Insured/Policyholder	
Name Of Registered Owner	ATARY
Co Reg No	53388542J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96904269
Alternative Phone No	OFFICE-96904269

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104711083
Cover Note Number	

Driver

Name of Driver	LUQMAN-NUL HAKKIM BIN MISIRI
NRIC No	S8819161G
Date Of Birth	25/05/1988
Occupation	INDOOR
Date Of Driving Pass	19/12/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96904269
Fax Number	
Contact Number	OFFICE-96904269
Email Address	NOEMAIL

Address	BLK 216A COMPASSVALE DRIVE #04-534
Postcode	541216
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	WKG9906 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : ATIYAH BINTE LUQMAN-NUL HAKKIM GENDER: : FEMALE
Passenger 2	NAME: : NUR JANE BTE JUMARI GENDER: : FEMALE
Passenger 3	NAME: : ARYAN BIN LUQMAN-NUL HAKKIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190221/2088. I WISH TO STATE THAT I TRIED TO AVOID COLLISION HOWEVER MY VEHICLE RIGHT PORTION SIDE SWIPED VEHICLE C REAR LEFT PORTION AND MY VEHICLE MOVED TO LANE 2 AND MY VEHICLE FRONT PORTION COLLIDED ONTO VEHICLE D REAR RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	WGK9906
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHB8691Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : GENDER: :
Passenger 2	NAME: : GENDER: :

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SKS6467S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	ATIYAH BINTE LUQMAN-NUL HAKKIM
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SJK6269B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	ARYAN BIN LUQMAN-NUL HAKKIM
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SJK6269B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report - 7/20/90221/2086

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190221/2088

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 4

Report No. T/20190221/2088

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/02/2019 15:16	Vide Report No.:	Station Diary No.: 116
--	------------------	---------------------------

Informant's Particulars

Name of Informant: LUQMAN-NUL HAKKIM BIN MISIRI			Address: APT BLK 216A COMPASSVALE DRIVE #04-534 SINGAPORE 541216	
ID Type / ID No.: NRIC NO / S8819161G			Contact No.:	Mobile: 96904269
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 30	Date of Birth: 25/05/1988	Type of Informant: Driver	
Race: Javanese			Language:	Institution / School Name:
Occupation: Self-Employed			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/02/2019 12:35	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE Changi Airport after the exit of bedok north				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB8691Y	Car				Slightly Damaged	2
SJK6269B	Car				Slightly Damaged	3
SKS6467S	Car				Slightly Damaged	0
WKG9906	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190221/2088

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 4

Report No. T/20190221/2088

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	0	ID No.	0
Related Vehicle	SHB8691Y (Car)	Contact No.	98283442
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LUQMAN-NUL HAKKIM BIN MISIRI	ID No.	S8819161G
Related Vehicle	SJK6269B (Car)	Contact No.	96904269
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	0	ID No.	0
Related Vehicle	WGK9906 (Car)	Contact No.	82828103
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/02/2019 at about 1235hrs while I was driving my car vehicle registration number SJK6269B along PIE Changi Airport after the exit of bedok north when suddenly the first car SKS6467S emergency brake causing the 2nd car which is the taxi SHB8691Y swerved left to avoid the collision. Following which, the 3rd car which is a Malaysian car WGK9906 swerved right. Afterwhich, my car SJK6269B was hit by a car from behind (unknown plate number as the car did not stop) and my car hit onto the malaysian car and also hit onto the taxi. Police and ambulance came to scene and my son and daughter were conveyed to hospital. The taxi driver passenger was also conveyed to hospital. I have no in-car camera footage. Hence, I am here to lodge this traffic accident report.



**SINGAPORE
POLICE FORCE**



T/20190221/2088

Police Station Of Origin:

Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE

545025

Tel No: 1800-343 8999

3 of 4

Report No. T/20190221/2088

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190221/2088

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

4 of 4

Report No. T/20190221/2088

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 TEO JIA HAO, KENNETH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt RAZIZ BIN TAHAR

Contact No.: 65476200

Signature Of Informant:

Date/Time:

21/02/2019 15:16

Classification Of Case:

Authentication Stamp

NP168

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of ATARY (53388542J)

Date: 11/10/2018

The Following Are The Brief Particulars of :

Name of Business	: ATARY
Former Name(s) if any	:
Date of Change of Name	:
Registration No.	: 53388542J
Registration Date	: 11/10/2018
Commencement Date	: 11/10/2018
Status of Business	: Live
Status Date	: 11/10/2018
Renewal Date	:
Expiry Date	: 11/10/2021
Renewal via GIRO	: NO
Constitution of Business	: Sole-Proprietor
Principal Place of Business	: 216A COMPASSVALE DRIVE #04-534 COMPASSVALE MAST SINGAPORE (541216)
Date of Change of Address	:

Principal Activities

Activities (I)	: PASSENGER LAND TRANSPORT N.E.C. (EG PRIVATE CARS FOR HIRE WITH OPERATOR AND TRISHAWS) (49219)
Description	:
Activities (II)	: RENTING AND LEASING OF PRIVATE CARS WITHOUT OPERATOR (77101)
Description	:

Particulars of Authorised Representative(s)

Name	ID	Nationality	Address	Address Source	Date of Appointment
------	----	-------------	---------	----------------	---------------------

Authentication No. : S18728390J

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of ATARY (53388542J)

Date: 11/10/2018

Existing Sole-Proprietor(s) / Partner(s)

Name	ID	Nationality/Place of incorporation/Origin	Address	Address Source	Date of Entry Position
LUQMAN-NUL HAKKIM BIN MISIRI	S8819161G	SINGAPORE CITIZEN	216A COMPASSVALE DRIVE #04-534 COMPASSVALE MAST SINGAPORE (541216)	ACRA	11/10/2018 Owner

Withdrawn Partner(s)

Name	ID	Nationality/Place of incorporation/Origin	Address	Address Source	Date of Entry Position	Date of Withdrawal
------	----	---	---------	----------------	---------------------------	--------------------

Abbreviation

OSCARS - One Stop change of Address Reporting Service by Immigration & Checkpoint Authority.

Note :

- The information contained in this Business Profile is extracted from lodgements filed by this entity with ACRA.
- The list of officers for this entity is available for online authentication within 30 days from the date of purchase of this Business Profile. Please scan the QR code available on the last page of this profile to access the authentication page. For more information, please visit www.acra.gov.sg.

FOR REGISTRAR OF COMPANIES AND BUSINESS NAMES
SINGAPORE

RECEIPT NO. : ACRA181011092215 (Free Business Profile by ACRA)

DATE : 11/10/2018

This is computer generated. Hence no signature required.



Authentication No. : S18728390J

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MNA119030086 Vehicle Registration No: SJK6269B
Name(as shown in NRIC) : LUQMAN-NUL HAKKIM BIN MISIRI NRIC/FIN/Passport No : S8819161G
(*Vehicle Driver / ~~Vehicle Owner~~) (*) Please delete as appropriate
Address : BLK 216A COMPASSVALE DRIVE #04-534 Singapore(541216)
Contact (Tel) : _____ Mobile No. : 96904269
Email Address : _____
Date of Accident : 20/02/2019 Time of Accident : 12:35
Place of Accident : PIE (CHANGI) AFTER BEDOK NORTH RD EXIT
Insurance Company: NTUC Income Insurance Co-operative Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I wish to state that I tried to avoid collision however my vehicle right portion side swiped vehicle C
rear left portion and my vehicle moved to lane 2 and my vehicle front portion collided onto vehicle D
rear right portion.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8819161G



Name
LUQMAN-NUL HAKKIM BIN MISIRI

Race
JAVANESE

Date of birth
25-05-1988

Country/Place of birth
SINGAPORE

Sex
M




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8819161G


Name
LUQMAN-NUL HAKKIM BIN MISIRI

Birth Date: 25 May 1988

Issue Date: 30 Aug 2016



002604263G



5586165



NRIC No. S8819161G



Date of Issue
23-03-2016

Address
APT BLK 216A COMPASSVALE DRIVE #04-534
SINGAPORE 541216

NRIC No. S8819161G Date: 18/05/2016


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE
19 Dec 2009

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$

NP 428A

Licence No. S8819161G



eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5104711083		ATARY	53388542J	GPC	drivo CLASSIC	SJK6269B	SJK6269B	17/10/2018	16/10/2019

Claim Handling

Exit

Accident MT/1033123

Policy No.	S104711083	Vehicle No.	SJK52698	GST Registration No.	
Certificate No.					
Policyholder Name	ATARY			Policyholder NRIC	533885423
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Leading	0
Contact No.(Mobile)	NA	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	
KPI	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	Not available

✚ Accident Details

Report Date	21/02/2019 18:02	Accident Report Within 24 hrs	Yes	Accident Type	Chain Collision
Date of Accident	20/02/2019	Time of Accident hh:mm	12:10	Country of Accident	Singapore
Reporting Centre	Administrator	Orange Force	Yes	ICM No.	3896098
Accident Location	PIE - CHANGI AIRPORT (BEF TAMPINES AVE 5)				

✚ Excess

Own damage Excess	2,000.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess	2,000.00		
Third Party Excess	1,500.00	Outside Singapore TP Excess	1,500.00		

✚ Benefits

✚ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History: 22/02/2019 10:22:02 Karthiyn Yuan changed GST Status Verified from No to Yes			

✚ Policyholder Mailing Address

Address 1	BLK 216A #04-534	Address 2	COMPASSVALE DRIVE	Address 3	COMPASSVALE MAST
Address 4	SINGAPORE 541216	Address Type	Singapore address	Post Code	541216
Unit No.	04-534	Related Policy Number	S104711083		

✚ OT Driver Info

Driver Name	Unnamed driver Name	Driver Type		Driver DOB	
Register Date of Driver License		Driver NRIC		Driving Experience	
Contact No.(Mobile)		Driver Age		Contact No.(Office)	
Address 1		Contact No.(Office)		Contact No.(Home)	
Address 4		Address 2		Address 3	
Unit No.		Address Type	Foreign address	Post Code	
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Modification History

Claim 002 New

Claim Type *	OD-MD	Insured Name	ATARY	Insured NRIC	533885423
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	NIL
Email Address		OT Vehicle Number	SJK52698	TP Vehicle Number	UNKNOWN
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	SJK52698 / UNKNOWN ON 20 Feb 2019				
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault	Name of Preferred Workshop	
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	05/03/2019 16:54	Claim Close Date		Date Received	05/03/2019 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	

☒ Print AK letter

Save Submit

Attachment

✚

Accident No.	MT/1033123	Claim No.	002
Last Doc. Received	☒ Yes ☐ No	Upload Date	05/03/2019 16:56

Path *	Category *	Confidential	Urgency *	Description *

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 8542J

Vehicle Details

Vehicle No.: SJK6269B

Vehicle to be Exported: No

Intended Deregistration Date: 07 Mar 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: 3ZZ4800525

Chassis No.: MR053ZEE106119997

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,084.00

Original Registration Date: 29 Oct 2008

First Registration Date: 29 Oct 2008

Transfer Count: 3

Actual ARF Paid: \$16,084.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Oct 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$15,142.00

COE Rebate Amount: \$14,051.00

Total Rebate Amount: \$14,051.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Mar 2019

OK

ASSIGNMENT (IDAC)

CUE Expired: 28/10/2023

By CSO: Nature of Accident:

By Assessor- 1) Vehicle Information

Veh No: **5JK6269B** Yr Regn: **29 Oct 2018**
 Type: ☒ M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / ☐ Truck / Trailer or

Make & Model: **Toyota Corolla Altis 1.6 1598**

Colour: **Silver** Transmission Type: ☒ Auto / Manual

Eng/No: Sp. Reading: **134828**

C/No: **MR053 ZEE106119997**

Gen. Cond: ☒ Good / Fair / Poor / Burnt or

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: **215/50 R 17**

R: **215/50 R 17**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. **4** mm R/Bal. **5** mm
 L/Bal. **4** mm L/Bal. **5** mm

Parallel Import: Yes / ☒ No

Towed-In: ☒ Yes / No

Repair Type: ☒ LS / I.B.I

Towing Required: ☒ Yes / No

No of Repair Days: **12**

Vehicle in Idac: ☒ Yes / No

D.O.I. **6/3/2019**

Time: **9.20am**

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 e. Animal () f. Govm Object () g. Road Work Object ()
 h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time

1) Vehicle hit Vehicle:

2) Vehicle hit ?

a) Motorcar ()

a) Pedestrian ()

b) M/cycle ()

b) Animal ()

c) Bicycle ()

3) Vehicle hit Road Side Objects:

a) Govm Property ()

b) Road Work Object ()

(E.g. signboard, barrier, etc.)

c) Private Property ()

4) Vehicle drop into drain ()

5) Damage due to Act of God:

a) Fallen Object ()

b) Flood ()

c) Other:

6) Parked & Found Damaged:

a) Vandalism ()

b) Hit by Moving Object ()

7) Theft Case

a) Stolen ()

b) Damage found when recovered ()

8) Fire

a) Whilst driving ()

b) Parked ()

9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

1) Potential Total Loss ()

2) SRS Light on ()

3) ABS Light on ()

(01)Bent (02)Damaged (03)Distorted (04)Cracked (05)Cup (06)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (✓) (3)Check (✓)
(4)Not Consistent (N/C)

275

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NES	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RH DIS		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJK 6269 R

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

Condition (CNS)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched

(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing

(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (ASC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)

(4) Not Consistent (NC)

Aug 2005

375

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	SCR	R	
1317	991654	Frt RH Door Protector	CUT		
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

Vehicle No: SJK 6269B

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	BVC		
1351	993284	Rear RH Door Protector	CUT		
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Stuffed (09) Buckled (10) Broken (11) Loose (12) Missing
(13) Torn (14) Unconfined (15) Not Working

MOTOR CAR (LH)

ACTOR (AC)

(1) Replace (2) Repair (3) Check (4) Not Confirmed (5) OK

4855

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	BUC		
1256	995140	Frt LH Door Protector	DIS		
1257	995104	Frt LH Door Hinge	BT		2
1258	995142	Frt LH Door Wing Mirror	LT		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding	DIS		
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator	?		
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber	TN		
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker	?		
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar	DR		
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH	?		
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SJK 6269 B

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION LAG

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Vehicle No:

SJK 6269R

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber		?	
1373	991944	Frt LH Shock Absorber Mounting		?	
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm		?	
1376	995199	Frt LH Knuckle Arm Bearing		?	
1377	995178	Frt LH Lower Arm		?	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod		?	
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage LH		?	
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

No of Items: _____ Assessor: _____

Original copy

Claim Handling

Task Transfer Exit

LOS SAL SUB

Accident MT/1033123

Policy No.	S104711083	Vehicle No.	S3K6269B	GST Registration No.	
Certificate No.					
Policyholder Name	ATARY			Policyholder NRIC	S33885423
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	NA	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	Not available

Accident Details

Report Date	21/02/2019 18:02	Accident Report Within 24 hrs	Yes	Accident Type	Chain Collision
Date of Accident	20/02/2019	Time of Accident hh:mm	12:10	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	3896098
Accident Location	RIE - CHANGI AIRPORT (BEF TAMPINES AVE S)				

Excess

Own damage Excess	2,000.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess	2,000.00		
Third Party Excess	1,500.00	Outside Singapore TP Excess	1,500.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History:	22/02/2019 10:22:02 Karthiyn Yuen changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	BLK 216A #04-534	Address 2	COMPASSVALE DRIVE	Address 3	COMPASSVALE MAST
Address 4	SINGAPORE 541216	Address Type	Singapore address	Post Code	541216
Unit No.	04-534	Related Policy Number	S104711083		

OI Driver Info

Driver Name		Driver Type		Driver DOB	
Unnamed driver Name		Driver NRIC		Driving Experience	
Register Date of Driver License		Driver Age		Contact No.(Home)	
Contact No.(Mobile)		Contact No.(Office)		Address 3	
Address 1		Address 2		Post Code	
Address 4		Address Type	Foreign address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Modification History

25/02/2019 13:31 a993011 Modify Orange Force(-->Y)

25/02/2019 13:31 a993011 Modify ICM No(-->3896098)

Investigation

Claim 002 OD-MD

Claim Case Officer Ng Hak Joo

LOS SAL SUB

Claim Type	OD-MD	Insured Name	ATARY	Insured NRIC	S33885423
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	NIL
Email Address		OI Vehicle Number	S3K6269B	TP Vehicle Number	UNKNOWN
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	S3K6269B / UNKNOWN ON 20 Feb 2019			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	income to assign workshop	GIA report	Received
Date Registered	05/03/2019 16:57	Claim Close Date		Date Received	05/03/2019 00:00
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

☒ Print AK letter

Modification History

Special Claim Creation Approval

Approval:	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	COROLLA ALTIS	Engine Capacity	
Date of Registration	29/10/2008	Class No.	MR0532EE106119997		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		

Windscreen Parts & Labour
Cost

Total Loss *

☐ Yes ☒ No

Market Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark

REMARK: NO OF REPAIR DAY: 12 DAYS. 1 X FRT BUMPER TOP RUBBER - REPLACE. 1 X FRT GRILLE CHROME MOULDING - REPLACE. 1 X AIR CON SUCTION PIPE (LOW PRESSURE) - UNCONFIRM. 1 X AIR CON LIQUID PIPE - UNCONFIRM. 1 X AIR DUCT - REPLACE. 1 X FRT LH FENDER EMBLEM - REPLACE. 1 X FRT RH FENDER EMBLEM - REPLACE. 1 X REAR BUMPER REFLECTOR - UNCONFIRM. 1 X REAR END PANEL - REPAIR. 1 X FRT LH DOOR WING MIRROR - REPLACE. 1 C FRT LH DOOR OUTER PILLAR - REPAIR. 1 X FRT LH TIE ROD - UNCONFIRM.

Remark for Supplementary

Damage Listing

Find a Part

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace	X
ACCELERATOR	4	160002401	BUMPER CLIPS (FRONT)	1	Replace	X
ACTUATOR	5	160005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
ADVERTISEMENT STICKER	6	160005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR BAG	7	160008001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR BLOWER	8	160001102	BUMPER (REAR)	1	Replace	X
AIR BOX	9	16002402	BUMPER CLIPS (REAR)	6	Replace	X
AIR CHAMBER BOX	10	160005104	BUMPER RETAINER (REAR RIGHT)	1	Replace	X
AIR CLEANER	11	353001101	REVERSE SENSOR (LEFT)	1	Unconfirm	X
AIR COMPRESSOR	12	420001102	TAIL LAMP (RIGHT)	1	Replace	X
AIR CON	13	23300202	DOOR (FRONT RIGHT)	1	Repair	X
AIR CON (VAN)	14	233005302	DOOR PROTECTOR (FRONT RIGHT)	1	Replace	X
AIR COOLER	15	23300204	DOOR (REAR RIGHT)	1	Replace	X
AIR DISTRIBUTOR	16	233005304	DOOR PROTECTOR (REAR RIGHT)	1	Replace	X
AIR FILTER	17	23303104	DOOR HINGE (UPPER) (REAR RIGHT)	1	Unconfirm	X
AIR FLOW	18	23302404	DOOR GLASS REGULATOR (REAR RIGHT)	1	Unconfirm	X
AIR GRILLE	19	23306104	DOOR RUBBER (REAR RIGHT)	1	Unconfirm	X
AIR HORN	20	16002601	BUMPER EMBLEM (FRONT)	1	Replace	X
AIR INTAKE	21	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR RESONATOR BOX	22	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace	X
AIR THROTTLE BODY AND SENSOR	23	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	X
ALARM	24	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Replace	X
ALTERNATOR	25	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Replace	X
ALUMINIUM PANEL - SIDE	26	27100101	GRILLE (FRONT)	1	Replace	X
AMPLIFIER	27	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
ANTENNA	28	28500101	HORN (LEFT)	1	Unconfirm	X
ANTI ROLL	29	15600101	BRACE PANEL (FRONT)	1	Replace	X
APRON	30	27700101	HEAD LAMP (LEFT)	1	Replace	X
ARCH	31	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	X
ARM REST	32	149001	BONNET	1	Replace	X
ASH TRAY	33	14903401	BONNET LOCK (LOWER)	1	Unconfirm	X
AUTO CLUTCH	34	14902201	BONNET HINGE (LEFT)	1	Replace	X
AUTO COOLER PIPE	35	14902202	BONNET HINGE (RIGHT)	1	Replace	X
AUTO CRUISE MOTOR	36	149041	BONNET RUBBER (CENTRE)	1	Unconfirm	X
AUTO TRANSMISSION	37	112023	AIR CON CONDENSER	1	Unconfirm	X
AXLE	38	344001	RADIATOR	1	Unconfirm	X
BACK REST (MC)	39	11001302	AIR CLEANER HOSE (CENTRE)	1	Replace	X
BACK SEAT	40	110037	AIR CLEANER RESONATOR	1	Replace	X
BALANCER	41	141001	BATTERY	1	Unconfirm	X
BATTERY	42	141002	BATTERY BRACKET	1	Repair	X
BEADING (MC)	43	141007	BATTERY TRAY	1	Unconfirm	X
BELT COVER (MC)	44	243014	ENGINE LOWER COVER	1	Replace	X
BELT TENSIONER	45	19600501	CHASSIS MEMBER (FRONT LEFT)	1	Unconfirm	X
BODY	46	25400102	FENDER (FRONT LEFT)	1	Replace	X
BODY (MC)	47	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Replace	X
BOLT CAP (MC)	48	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
BOLT HEAD COVER (MC)	49	448014	WHEEL RIM	1	Replace	X
BONNET	50	43600101	TYRE (FRONT LEFT)	1	Replace	X
BOOT	51	25400103	FENDER (FRONT RIGHT)	1	Repair	X
BOX (MC)	52	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
BOX BRACKET (MC)	53	454009	WIPER PANEL GARNISH	1	Replace	X
BOX CARRIER (MC)	54	23300201	DOOR (FRONT LEFT)	1	Replace	X
BOX DOOR	55	23305301	DOOR PROTECTOR (FRONT LEFT)	1	Replace	X
BOX STICKER (MC)						
BRACE PANEL						
BRAKE						
BRAKE - ABS						
BRAKE (MC)						
BUMPER						
CABIN						
CAMBER						
CAMSHAFT						
CAR AUDIO SYSTEM						
CAR JACK						
CARBURATOR						
CARGO						
CARRIAGE						
CARRIER MOUNTING						
CASTOR						
CATALYTIC CONVERTOR						
CD CHANGER						
CD PLAYER						
CD UNIT (MC)						
CENTRE BOTTOM						
CENTRE BRACKET						
CENTRE CONSOLE						
CENTRE COWLING (MC)						
CENTRE CROSS MEMBER						
CENTRE EXHAUST						
CENTRE FARING (MC)						
CENTRE FOOTREST COVER (MC)						

56	23303001	DOOR HINGE (BOTTOM) (FRONT LEFT)	1	Replace	☒
57	23303002	DOOR HINGE (BOTTOM) (FRONT RIGHT)	1	Replace	☒
58	23302201	DOOR GLASS OUTER MOULDING (FRONT LEFT)	1	Replace	☒
59	23302401	DOOR GLASS REGULATOR (FRONT LEFT)	1	Unconfirm	☒
60	23301604	DOOR CHECKER (REAR RIGHT)	1	Unconfirm	☒
61	23305101	DOOR RUBBER (FRONT LEFT)	1	Replace	☒
62	23301601	DOOR CHECKER (FRONT LEFT)	1	Unconfirm	☒
63	35500901	ROCKER PANEL GARNISH (LEFT)	1	Unconfirm	☒
64	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm	☒
65	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	☒
66	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	☒
67	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	☒
68	30500101	LOWER ARM (FRONT LEFT)	1	Unconfirm	☒
69	12800401	ANTI ROLL BAR LINK (FRONT)	1	Unconfirm	☒

Save Submit

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Thursday, 7 March 2019 11:50 AM
To: Hock Wah Motor Pte Ltd
Cc: LKK Paya Ubi
Subject: FW: SJK6269B UNDER OD CLAIM: MT/1033123
Attachments: UIL CLAIM FORM.doc

Dear Hock Wah

Please tow this vehicle from Idac and contact owner Mr Louman of Atary at 96904269 when the repair is done, OD excess \$2000/-.

please assist the owner to complete the attached UIL Form and email to our Recovery Team at: motor@income.com.sg

Please also high lite to the owner that how long and how much our Recovery Team can recover, we unable to commit, therefore, you may advise the owner to email to motor@income.com.sg for any Recovery query.

Our Ref: MT/CA/OD/051/1033123-002/NHJ
07 Mar 2019
HOCK WAH MOTOR WORKSHOP PTE LTD
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1033123-002

REPAIR OF VEHICLE NUMBER: SJK6269B

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 07 Mar 2019

Make: TOYOTA

Model: COROLLA ALTIS

Estimated Repair Days: 6

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 2000.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank You

Ng Hak Joo
Executive
Motor Insurance

T +65 64307890

www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)
51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SJK 6269 B Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: HOCK WAH BEDOK

Collection Date: 07-03-19 Time: 1405 HRS with Keys: Yes / No

Tow Truck No: YP 6632 G Tow Man: SELVA NRIC: SG909822Z

Signature: [Signature] 8255 4501

For office use

Attended by: ROSLINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____