

ASS. REC. BY:

REF: CS3

C711 9004062/Gid 302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Chong Boon Sen of C71 Date/Time: 5/3/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMG 3411 L Insured: XD 29824at Workshop m/s Sat Motors Tel: _____of NO 24 Defu lane 12 S'pore 539131Policy No: DMCVSN1H375218044 Claim No: SNM190200997605

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 75/2/19
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SMG 3411 L x</u>
	<u>XD 29824 x</u>
	<u>After repair: 15/3/2019</u>
	<u>No Meritman (Send email)</u>

PRS
Xhl.

REF:

CTI

0576E


ASSIGNMENT

(-2022)

13 Feb 2012

From: _____ Date: _____
Estimated Cost: _____
OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
To Inspect Vehicle No: SMG3411 L
at Workshop m/s SAT Motors
of 24 Dehu Lane 12
Insured _____
Policy No. _____
Claims No. _____
Sum Insured _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No. SMG3411 L Yr Regn: 13 Feb 2012
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Jetta C.C. 1390
Colour: white A/C Insured / Std / Nil / NA
Sp. Reading: 77403 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: WVWZZZ16Z CM078606
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / M/Rim or
Tyre Size: F: 205/55 R16
R: "



Remark: The veh had commenced its repair at the time of inspection.

BS, DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value: \$26k
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 05-03-19

CA / REV / REP. / 24 HRS

Survey held at w/s
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
ds rear

Date: _____ Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation

Report Format: PRS

☐ : Interview (\$

1) Photo

Lump Sum / L.B.L. (\$

☐ : Tech. Insp (\$

1) Other

☐ : Weekend (\$

TOTAL

190

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019		16 May 2019 08:52 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CLEON WONG WEI JIN, ID: S8770576E		
Vehicle Reg. No.:	SMG3411L	Date of Loss:	25/02/2019 17:00 - :59
Claim Type:	TP / SNM19D200997C02	Policy/Cover Note No.:	DMCVSN14375218044
Vehicle Reg. No. (Insured):	XD2982Y	Policy No. (Claimant):	PNPV2018-00016870
		Excess:	S\$0.00
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 4 March 2019 4:10 PM
To: assignments
Subject: FW: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT - PRS

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

XGQ

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 4 March 2019 4:00 PM
To: cordell@advlawllc.com
Cc: jonathan@satmotors.com; Admin A <admin-a@lkkauto.com>
Subject: RE: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT - PRS

Dear Cordell,

We use LKK, pls assist to provide all relevant details for us to upload.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: cordell@advlawllc.com [mailto:cordell@advlawllc.com]

Sent: Thursday, 28 February, 2019 6:32 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: jonathan@satmotors.com

Subject: RE: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT - PRS

Dear Boon Sen,

We have instructions to reject using your motor surveyor. We propose to use our motor surveyor as below:-

1. Allin Appraisals

Kindly see attached our letter and the workshop details as below:-

Workshop name: Sat Motors

Address: No. 24 Defu Lane 12 Singapore 539131

Contact Person: Jessie (HP: 9859 9677), Jonathan (HP: 9126 9987)

Kindly liaise with the workshop directly for the PRS on an urgent basis.
Thank you.

Thanks & Regards,

Cordell Chan

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 28 February 2019 6:00 PM

To: cordell@advlawllc.com

Cc: jonathan@satmotors.com

Subject: RE: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT - PRS

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: cordell@advlawllc.com [mailto:cordell@advlawllc.com]
Sent: Thursday, 28 February, 2019 5:28 PM
To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: jonathan@satmotors.com
Subject: RE: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT

Dear Sir,

Kindly note that if we do not receive any reply in regards to the PRI of SMG3411L,

We shall commence repair of the said vehicle without further notice to you.

Thanks & Regards

Cordell Chan

From: cordell@advlawllc.com <cordell@advlawllc.com>
Sent: Wednesday, 27 February 2019 5:33 PM
To: 'e-claims@sg.cntaiping.com' <e-claims@sg.cntaiping.com>; 'lucas.lee@sg.cntaiping.com' <lucas.lee@sg.cntaiping.com>
Cc: 'jonathan@satmotors.com' <jonathan@satmotors.com>
Subject: Urgent: Accident involving our client's vehicle SMG3411L and CNTP insured vehicle XD2982Y on 25/02/2019 at 1755 hours; Our ref: SMG3411L/SAT

Without Prejudice

Dear Sir/Mdm,

ACCIDENT INVOLVING SMG3411L & XD2982Y ALONG ALONG DEFU AVE 1 ON 25/02/2019 1755

1. We are instructed to notify you of a road accident on 25 February 2019 at about 1755 hours along Defu L registration number SMG3411L and vehicle registration number XD2982Y driven by your insured at the material enclosed.

2. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the vehicle within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks & Regards

Cordell Chan

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

 > Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0576E
Vehicle Details	
Vehicle No.:	SMG3411L
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623G5
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CAX972246
Chassis No.:	WVWZZZ16ZCM078606
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,678.00
Original Registration Date:	13 Feb 2012
First Registration Date:	13 Feb 2012
Transfer Count:	2
Actual ARF Paid:	\$20,678.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2022
PARF Rebate Amount:	\$12,406.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,112.00
COE Rebate Amount:	\$16,466.00
Total Rebate Amount:	\$28,872.00

The information contained herein is correct as at 06 Mar 2019

OK

▶ jetta Used Vehicle List (16 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Volkswagen Jetta 1.4A TSI	\$36,800	\$9,670 /yr	13-Jan-2012	1,390 cc	119,000 km	Autorol Pte Ltd	Availal

Car Is Very Well Maintained & Excellent Condition! Major Servicing Just Done By Agent! New Road Tax! Drive With A Peaceful Mind! Trade In And High Loan Available. Please Call For Appointment.

Office No. - -

Hari - 94594812 | Roland Lim - 97666881

Volkswagen Jetta 1.4A TSI	\$36,000	\$8,870 /yr	16-Jan-2012	1,390 cc	63,000 km	Absolute Wheels Leasing Pte Ltd	Availal
---------------------------	----------	-------------	-------------	----------	-----------	---------------------------------	---------

1 Owner Low Mileage Vehicle Well Maintained! Original Paintwork And Interior! Reliable Engine! No Major Repairs Needed! Low Depreciation No Obligations! In House And Bank Loans Available! Kindly Cont...

Office No. - 92269616

Mike - 92269616 | Augustine - 97540677

Volkswagen Jetta Sport 1.4A TSI	\$43,000	\$9,880 /yr	13-Apr-2012	1,390 cc	-		Availal
---------------------------------	----------	-------------	-------------	----------	---	--	---------

Excellent And Original Condition, Smooth Driving, Meticulously Well Maintained Interior And Exterior, Accident-Free, Sheltered Parking, Low-Mileage, Call Now For Viewing.

Office No. - -

Jameson Wong - 91000472 | Wong Kwee Lian - 81005231

Volkswagen Jetta Sport 1.4A TSI	\$39,800	\$8,930 /yr	16-Apr-2012	1,390 cc	-	Caz Auto Pte Ltd	Availal
---------------------------------	----------	-------------	-------------	----------	---	------------------	---------

Well Maintain, Regular Servicing On Time, No Modification, Original Condition, Powerful Yet Fuel Economy With Cheap Road Tax, Big Boot Space, Sheltered Parking, High Trade In Bank / In House Flexible ...

Office No. - -

Mr Yuen - 97665566

Volkswagen Jetta Sport 1.4A TSI	\$39,700	\$8,660 /yr	04-May-2012	1,390 cc	-	Hua Hong Motoring	Availal
---------------------------------	----------	-------------	-------------	----------	---	-------------------	---------

Latest Arrival! Cheapest Unit Avail With \$8000 Depre Yearly Only. High Paper Value, Selling Slight Above Export Value As Car Is Too Nice To Scrap Early. In House High Loan Avail With 100% Approval. Ba...

Office No. - -

Terence - 81608080 | Randy Chan - 96949339

Volkswagen Jetta 1.4A TSI	\$37,800	\$8,510 /yr	17-May-2012	1,390 cc	87,000 km	1axis	Availal
---------------------------	----------	-------------	-------------	----------	-----------	-------	---------

100% Loan Available, Rear Aircon, Beautiful Interior And Sleek Finish. Call To View And Test Drive Now! Extremely Low Mileage Done! Accid Free. Loan Can Be Arranged.

Office No. - -

Jack - 84306433 | Viki - 90270337 | Evan Yang - 90917321 | Kervin Chia - 88113768

Volkswagen Jetta 1.4A TSI	\$40,800	\$9,410 /yr	22-May-2012	1,390 cc	-	Classic Credit Pte Ltd	Availal
---------------------------	----------	-------------	-------------	----------	---	------------------------	---------

Office No. - 68412076 / 68481203 / 68414849

Rodney - 91431853 | Roland - 97479331 | Mr Chen - 90044461

Volkswagen Jetta Sport 1.4A GLI	\$43,800	\$9,840 /yr	24-May-2012	1,390 cc	141,000 km	Car Search	Availal
---------------------------------	----------	-------------	-------------	----------	------------	------------	---------

1 Owner Only! Serviced Regularly. Powerful Yet Fuel Efficient Sedan, Well Maintained By Previous Owner! Flexible Loan And Trade-In Availat Viewing By Appointment Only.

Office No. - 62620728

Rachel - 91126538 | Kelvin - 97593539 | Justin - 91827511 | Lester - 96192666

Volkswagen Jetta Sport 1.4A TSI	\$41,800	\$8,980 /yr	28-Jun-2012	1,390 cc	-	Go-Go Carz Pte Ltd	Availal
---------------------------------	----------	-------------	-------------	----------	---	--------------------	---------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2019 13:46
Date Of Accident	25/02/2019 17:55
Exact Location Of Accident	ALONG DEFU AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG3411L
Insured/Policyholder	
Name Of Registered Owner	CLEON WONG WEI JIN
NRIC No	S8770576E
Email Address	WWJ_WREN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97548333
Alternative Phone No	OTHERS-97548333

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA 1.4 TSI AT 1623G5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNPV2018-00016870
Cover Note Number	19/12/2018 - 18/12/2019

Driver

Name of Driver	CLEON WONG WEI JIN
NRIC No	S8770576E
Date Of Birth	28/07/1987
Occupation	INDOOR
Date Of Driving Pass	02/02/2017
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97548333
Fax Number	
Contact Number	OTHERS-97548333
Email Address	WWJ_WREN@HOTMAIL.COM

Address BLK 336A ANCHORVALE CRESCENT #13-20
 Postcode 541336
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PHUA XUE YING RACHAEL
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD2982Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver PHUA PUAY SENG
 NRIC/Passport Number S0029802F
 Contact Number 97472944
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name CLEON WONG WEI JIN
Approximate Age
Injuries Sustain SHOULDER PAIN
Injured person in which vehicle? SMG3411L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode


DETAILS OF INJURED PERSON 2

Name PHUA XUE YING RACHAEL
Approximate Age
Injuries Sustain BACK PAIN
Injured person in which vehicle? SMG3411L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan Pg. 1

Date of accident: 25/2/2019 Time: 17:55 Location: Defu Ave 1
 My Vehicle A: SMG 3411L Vehicle B: XD 0982Y Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 17:55, 25/2/2019, SMG3411L was travelling along defu ave 1, at speed of around 50 km/h on the left lane. It was a two lane road.

Truck XD 0982Y, ~~on the~~ traveling on the right lane suddenly swift to the left while we were travelling parallel to each other. The truck hit the back of SMG3411L. ~~The car~~ We stopped the car immediately after the impact.

~~truck~~ The driver acknowledge it's his fault and there's a video footage taken by ~~the~~ another driver.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

(1 per Name)
26/2/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

(ALLIUM MOTOR COMPANY)




























...CLAIM SUBFOLDER...(Pending for Survey Report)










CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 May 2019		16 May 2019 08:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	CLEON WONG WEI JIN , ID: S8770576E								
Vehicle Reg. No.:	SMG3411L	Date of Loss:	25/02/2019 17:00 - :59 [84 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200997C02	Policy/Cover Note No.:	DMCVSN14375218044						
Vehicle Reg. No. (Insured):	XD2982Y	Policy No. (Claimant):	PNPV2018-00016870						
		Excess:	S\$0.00						
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














Claim Documents


***SMG3411L (SNM19D200997C02)**
[XD2982Y]
TP
CLEON WONG WEI JIN
Feb 25 2019 5:00PM
[-]
Sat Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:25	Video - Accident [Linked Accident Report Documents]	 Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:42	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	26/02/19 14:40	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
15	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/05/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
23	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
24	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
25	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
26	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
27	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
28	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
29	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
30	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
31	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
32	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
33	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	21/05/19 12:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/19 08:53	pri contact	 Load PDF	
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:40	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:25	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	26/02/19 14:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	✓
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
Documentation			1 per page	✓
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/02/19 14:40	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004062/GCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN14375218044

Claimant Vehicle
No: SMG3411LInsured Vehicle
No: XD2982Y

Date of Loss: 25/02/2019

Nature of Claim: TP

Claim
No: SNM19D200997C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG3411L

Make & Model: VOLKSWAGEN JETTA, 1.4 (A)

Engine No: CAX972246

Reg. Date: 13/02/2012 (Man. Year: 2011)

Chassis No: WVVZZZ16ZCM078606

Colour: White

Odometer: 77403 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/05/2019

Date Inspected: 05/03/2019

Inspected At:

Sat Motors (HQ)
24 Defu Lane 12
Singapore 539131

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 24 May 2019)

Parts: 143 VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG3411L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >