

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #05-00

IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476105 MEENA CHI Fax No. : 62244174

Estimate : ES000862

Date : 06/03/2019

Vehicle Num. : SGF 8684 J

Make/Model : TOYOTA ALTIS-2006

Chassis/Eng# : MR053ZC107118317/3ZZ4561824

Accident Date : 16/02/2019

Claim No. :

Reference :

Policy No. : (25/04/2006)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.

List Total S\$:

LABOUR :

REPAIR AND SPRAY PAINTING ON FRONT LH DOOR , REAR LH DOOR, REAR LH FENDER AND REAR BUMPER

Labour Total S\$:

1,000.00

1,000.00

*Not Withdraw
Returning After Paint
3 days*



E. & O.E.

Total S\$:

1,000.00

for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: