



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving 1 2015 VOLKSWAGEN JETTA 1.4 TSI (SJK1725J)

Date of Loss 26 February 2019

Time of Loss 13.45

Loss Description SJK1725J (INSD) C/W PEDESTRIAN

Comment

### Workshop Details

Total Rebate Amount 47233

Nett Loss Amount \$5,767.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion \* 44



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Vehicle &amp; Driver Details

Vehicle Registration# SJK1725J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

26/05/2015



Mileage

101257

Age of Vehicle

3

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2015

2015

Make

VOLKSWAGEN

VOLKSWAGEN

Model

JETTA 1.4 TSI

JETTA GP 1.4 TS

## Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

BAN SIONG (BERNARD HUANG  
WANXIONG) BERNARD HUANG

Date of Birth

27 August 1980

dd/mm



Age

38

| CATEGORY        | POLICY INFORMATION | ASSESSMENT INFORMATION                   |
|-----------------|--------------------|------------------------------------------|
| Type            |                    | <input type="text" value="▼"/>           |
| Type of Paint   |                    | <input type="text"/>                     |
| Chassis No      | WWWZZZ16ZFM028645  | <input type="text" value="WWWZZZ16ZFM"/> |
| Engine No       | CAXF50188          | <input type="text" value="CAXF50188"/>   |
| Engine Capacity |                    | <input type="text" value="1390"/>        |
| Sum Insured     | 0                  | <input type="text" value="0"/>           |
| Market Value    | 0                  | <input type="text" value="53000"/>       |

| CATEGORY                | FNOL INFORMATION                                                   | POST SURVEY INFORMATION                                                                                                  |
|-------------------------|--------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|
| Occupation              | Unknown                                                            | <input type="text"/>                                                                                                     |
| Education Qualification | Other                                                              | <input type="text" value="▼"/>                                                                                           |
| Driving Experience      | 6                                                                  |                                                                                                                          |
| Driver License #        |                                                                    | <input type="text"/>                                                                                                     |
| License Type            |                                                                    | <input type="text" value="▼"/>                                                                                           |
| License Issue Date      |                                                                    | <input type="text" value="dd/mm"/>    |
| License Expiration Date |                                                                    | <input type="text" value="dd/mm"/>  |
| Address                 | 234 WESTWOOD AVENUE,<br>#12-35 THE FLORAVALE,<br>648361, Singapore | <input type="text"/>                                                                                                     |
| Address type            | Residential                                                        | <input type="text" value="▼"/>                                                                                           |

| CATEGORY         | FNOL INFORMATION | POST SURVEY INFORMATION |
|------------------|------------------|-------------------------|
| Gender           | Male             | <input type="text"/>    |
| Marital status   | Married          | <input type="text"/>    |
| Identification # | S8025602G        | <input type="text"/>    |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

05/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40ZR18

Rear Tyre Size

225/40ZR18

Front left side

PIRELLI6mm

Rear left side

PIRELLI7mm

Front right side

PIRELLI6mm

Rear right side

PIRELLI7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Parts

Add Approve Deny Submit All

|                          | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME                       | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR/ BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|--------------------------|------|-------|----------|----------|------|---------------------------------|-------------|------------------------|-----------|------------|-------------|-----------|----------|-----------------|----------------|--------|
| <input type="checkbox"/> |      | 1     | 1        |          |      | R/F BUMPER GUIDE (WCP) (10%)    |             |                        | Damaged   | 27.5       |             |           |          | 27.5            | Reviewing      |        |
| <input type="checkbox"/> |      | 2     | 1        |          |      | BONNET (WCP) (10%)              |             |                        | Bent      | 632.5      |             |           |          | 632.5           | Reviewing      |        |
| <input type="checkbox"/> |      | 3     | 1        |          |      | RIGHT HEADLAMP ASSY (WCP) (10%) |             |                        | Cracked   | 396        |             |           |          | 396             | Reviewing      |        |
| <input type="checkbox"/> |      | 4     | 1        |          |      | R/F WING (WCP) (10%)            |             |                        | Bent      | 352        |             |           |          | 352             | Reviewing      |        |
| <input type="checkbox"/> |      | 5     | 1        |          |      | R/LOCK CARRIER STRUT            |             |                        | Repair    | 0          | 0           | 0         | 0        | 0               | Deny           |        |
| <input type="checkbox"/> |      | 6     | 1        |          |      | WINDSCREEN (WCP) (10%)          |             |                        | Cracked   | 715        |             |           |          | 715             | Reviewing      |        |

## Labour

Add Approve Deny Submit All

|                          | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME             | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|--------------------------|------|-------|-------------------------|-----------------------|------------|---------------|-------|-----------------|---------|--------|
| <input type="checkbox"/> |      | 1     |                         | 87.0 WU X 45.00 SGD/H | 301.5      | 0             | 0     | Reviewing       |         |        |



|                                                                                   | EDIT                                                                              | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                           | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE                                                                              |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------|-------------------------|-------------------------------------|------------|---------------|-------|-----------------|---------|-------------------------------------------------------------------------------------|
|  |  | 2     |                         | LABOUR COST 100.0 WU<br>45.00 SGD/H | 450        | 0             | 0     | Reviewing       |         |  |
|  |  | 3     |                         | MATERIAL COST                       | 192.72     | 0             | 0     | Reviewing       |         |  |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR  
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS  
OF  
REPAIR  
: 5  
DAYS

Reviewing





SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Claim Amount

\$3,067.22

Claim Amount

\$3,067.22

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$2,123.00

\$2,123.00

Labour

\$944.22

\$944.22

[Submit for Review](#)