

ASS. REP. BY:

REF:

03/MSG19004089/God352

Special Instruction:

Subveyor

ASSIGNMENT (Office)

From (Person): Pauline Tham

of

MSG.

Date/Time:

5/3/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GGG6748B

Insured: YP5816A

at Workshop m/s:

Soon Leng

Tel:

of 160 sm #04-05

Policy No: 29070374MKE

Claim No: 586303

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

56/2/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GGG6748B-X
	YP5816A-X
	Demantle: 6/3/2019
	After repair: 11/3/2019

REF:

MSG

C1936w

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBG6748B

Yr Regn: 29 Sep 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV200

C.C. 1461

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

12067

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSKY BAm2020145803

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

11

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

05-03-19

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

RECEIVED 21 MAR 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

PRE

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2019		05 Mar 2019 09:57 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	OAKGREEN HOLDINGS PTE LTD, Co. Reg. No.: 201103679K		
Main Claimant:	RMG TOURS PTE LTD, Co. Reg. No.: 197401936W		
Vehicle Reg. No.:	GBG6748B	Date of Loss:	26/02/2019 11:00 - :59 [16 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 586303	Policy/Cover Note No.:	29070274MKC (Comprehensive) Coverage: 07/03/2018 - 06/03/2020
Vehicle Reg. No. (Insured):	YP5816A	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Seng Company () 160 Sin Ming Drive, #04-05 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/03/2019]		
Driver/Custodian (Insured):	WOO KOK HENG (), NRIC: S1483924J, Tel: +6596149002 Email:		
Adj Asg. Remarks:	Liability 100% TP reject SJE - Assign LKK Auto Consultants Pte Ltd Contact - Mr Lim 9731 7794 TP request survey asap		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

(14)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2019 13:33
Date Of Accident	26/02/2019 10:50
Exact Location Of Accident	SIN MING IND EST SECTOR A BEF TURN INTO SECTOR B
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG6748B
Insured/Policyholder	
Name Of Registered Owner	RMG TOURS PTE LTD
Co Reg No	197401936W
Email Address	PHLIM@RMGTOURS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97317794
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200-1.5 D L ABS AIRBAG 2WD 6DR (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V03921/VCV/R01
Cover Note Number	
Driver	
Name of Driver	LIM PENG HUCK
NRIC No	S1655175I
Date Of Birth	11/11/1964
Occupation	INDOOR
Date Of Driving Pass	08/09/1985
Driving Experience	33 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97317794
Fax Number	
Contact Number	
EMail Address	PHLIM@RMGTOURS.COM.SG

Address	BLK 115 BUKIT PURMEI#12-252
Postcode	090115
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5816A
Vehicle Make/Model/Colour	FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WOO KOK HENG
NRIC/Passport Number	S1483924J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 27-02-2019
 @ 1030 hrs.


 Lim P. H.
 Hp 9731 7794
 Fleet Maintenance Manager
 RMG TOURS PTE LTD
 109B Amoy Street Reporting Centre Personnel's Signature
 Singapore 069929
 Name: Name:
 Date & Time: 27-02-2019
 @ 1030 hrs.

Sketch Plan





On 26-02-2019 @ 1050 hrs, I was driving GBG 6748B along Sin Ming Industrial Estate Sector A beside BKK 22. While approaching Sector B junction I can see a lorry follow me behind very closely seems to be in a hurry. Thus I keep left move into the vacant car park lot to give way to the lorry. I also can hear a short horn from the rear & noticed it overtake from my rear right. I almost came to a stop in the lot & suddenly the lorry YP5816A swing to its left & cut into my front right. as a result the lorry LHS body guard frame has grazed onto my right front portion and it continues to turn into left (Sector B) & stop 20m away. I quickly alight & saw the lorry has move forward & stop 50m away & driver approach me. I questioned him why I give way to him & he purposely swing towards me & cause the accident (He did not answer). I then request for his particulars & he just say you go to make a report & ignore me walk back towards his lorry. Upon seeing his act, I then follow him & start to take photos first. Suddenly he get into lorry & drive off. I immediately foot chase & manage to stand in front & stop him for leaving. After he notice I am going to call for police assistant he then alighted but given to me a defaced Driving licence as particulars. After photos has been taken he refuse to give his NRIC but I have a glance & return to him. After that I left the scene as lorry also left without much conversation.

I declare the foregoing particulars are true & correct.


Date & Time
27-02-2019
@ 1030 hrs.




Date & Time
27-02-2019
@ 1030 hrs.


Reporting Centre Personnel's Signature
Date & Time
27-02-2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1936W
Vehicle Details	
Vehicle No.:	GBG6748B
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	K9KC400D057238
Chassis No.:	VSKYBAM20Z0145803
Maximum Power Output:	-
Open Market Value:	\$20,119.00
Original Registration Date:	29 Sep 2017
First Registration Date:	29 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,006.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$34,425.00
Total Rebate Amount:	\$34,425.00

The information contained herein is correct as at 06 Mar 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2019		05 Mar 2019 09:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	OAKGREEN HOLDINGS PTE LTD, Co. Reg. No.: 201103679K		
Main Claimant:	RMG TOURS PTE LTD, Co. Reg. No.: 197401936W		
Vehicle Reg. No.:	GBG6748B	Date of Loss:	26/02/2019 11:00 - :59 [16 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 586303	Policy/Cover Note No.:	29070274MKC (Comprehensive) Coverage: 07/03/2018 - 06/03/2020
Vehicle Reg. No. (Insured):	YP5816A	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Seng Company () 160 Sin Ming Drive, #04-05 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 06/03/2019]		
Driver/Custodian (Insured):	WOO KOK HENG (), NRIC: S1483924J, Tel: +6596149002 Email:		
Adj Asg. Remarks:	Liability 100% TP reject SJE - Assign LKK Auto Consultants Pte Ltd Contact - Mr Lim 9731 7794 TP request survey asap		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


***GBG6748B (586303)**
[YP5816A]
TP
RMG TOURS PTE LTD
Feb 26 2019 11:00AM
[OAKGREEN HOLDINGS PTE LTD]
Soon Seng Company

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports
















































1 per page ▼ ☒




No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/03/19 13:50	Accident Statement From: SC - Reg. No: YP5816A, Claimant: OAKGREEN HOLDINGS PTE LTD	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	06/03/19 17:42	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	06/03/19 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/03/19 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/03/19 17:43	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
35	06/03/19 17:43	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
36	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/03/19 17:43	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	12/03/19 10:53	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	12/03/19 10:53	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/03/19 13:50	TP PRI REQUEST & GIA REPORT	 Load PDF	
2	04/03/19 16:16	TP reject SJE - Assign LKK	 Load PDF	
3	04/03/19 16:38	2nd PRS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004089/GCD3S2

Date: 22/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29070274MKC

Claimant Vehicle No : GBG6748B

Insured Vehicle No : YP5816A

Date of Loss: 26/02/2019

Nature of Claim: TP

Claim No: 586303

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG6748B

Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M)

Engine No: K9KC400D057238

Reg. Date: 29/09/2017 (Man. Year: 2017)

Chassis No: VSKYBAM20Z0145803

Colour: White

Odometer: 12067 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14

Rear Tyre Size: 175/70R14

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/03/2019

Date Inspected: 05/03/2019 Inspected At:

160 Sin Ming Drive, #04-05 Sin Ming Autocity

Singapore 575722

Repairer: Soon Seng Company

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Mar 2019)

Parts: N/A NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG6748B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >