

ASS. REC. BY:

REF:

CS/CTI 19004094/A9d3/

Special Instructions:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Boon Sen (mer:men) of

Date/Time:

5/3/19

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 1964 R

Insured:

SKT 1881 G

at Workshop m/s

Leang Automotive

Tel:

9028 6516

of

1 Keki Bukit Ave 6 #01-68

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

1/3/19

CA / REV / WP / REP. / REV 24 HRS

6/3/19

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle- IN / OUT

Date/Time	Action/Instruction () Estimate
	SJS 1964R
	SKT 1881G / SJS 1964R NBA/CTI 19003897/1 REP: 01/3/19
	US \$2800, 5 days (red to 5366-40, 59%)

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Ret: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJJ1964R Yr Regn: 2008 / Sept
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: honda Fit c.c 1339
 Colour: Red AC: Insured / Std / NI / NA
 Sp.Reading: 120032 Tr/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GE61096434
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / STD A/Rim / STD A/Rim or _____
 Tyre Size: F: 195/55R15
 R: 195/55R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>06/03/19</u>	

Survey held at Leang
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Claim.
	COE Expiry : 31/08/28
	RECEIVED 29 MAR 2019
	MV : 45K
	PV : 32.4K
	Nett: 12.6K

Date/Time, File Pass to? <u>1/29/3 by N/S</u>	Date/Time, File Return to? <u>2)</u>	Part Prices Check: IN OUT	Survey Fee:	Date:			
3)	4)		Basic & Add.	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>			
5)	6)	_____ S + RS, _____ SI					
Prel. Report		Photos					
Final Report		Others					
		TOTAL					

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7954I
Vehicle Details	
Vehicle No.:	SJJ1964R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4107044
Chassis No.:	GE61096434
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,439.00
Original Registration Date:	04 Sep 2008
First Registration Date:	04 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$11,439.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$32,431.00
Total Rebate Amount:	\$32,431.00

The information contained herein is correct as at 06 Mar 2019

OK

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A

 2.68% P.A. Low Interest @ G.V. Finance. 2 Years Warranty. \$2000 Down Monthly From \$56. [View Details](#) | [StarAd](#)

• Free VICOM evaluation
 • Free grooming and 8 months maintenance
 • In-house workshop ensures quality service
 • Member of SYTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category  [Save Search](#)  [Print](#) [Back \(1 2 3 4 5 \) Next](#) [Sort by Date Posted](#) [20 results/page](#)

92 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	Honda Fit		Any	Any	> 10 year(s) old	Any	Any	Any	Available

 **Honda Fit 1.3A (COE till 01/2021)** **\$14,500** **\$7,590 /yr** **02-May-2006** **1,339 cc** **-** **Hatchback** **Available**

[View Details](#) | [Compare](#) | [Share](#) | [Print](#) | [StarAd](#)

 **Honda Fit 1.3A (COE till 12/2021)** **\$19,800** **\$7,130 /yr** **15-Dec-2006** **1,339 cc** **139,000 km** **Hatchback** **Available**

1 Of The Popular Hatchback For Your Family And Daily Usage. Back Spacious For Goods Delivery! Fuel Saving Yet Powerful Drive. Smooth Engine. Easy To Maintain Unit, Consignment Unit. Viewing Strictly B...

[Car Search](#) [Consignment](#)

 **Honda Fit 1.3A (COE till 05/2022)** **\$22,800** **\$7,170 /yr** **10-May-2007** **1,339 cc** **110,000 km** **Hatchback** **Available**

[View Details](#) | [Compare](#) | [Share](#) | [Print](#) | [StarAd](#)

 **Honda Fit 1.3A (COE till 10/2022)** **\$23,800** **\$6,540 /yr** **26-Oct-2007** **1,339 cc** **119,432 km** **Hatchback** **Available**

Beautifully Fitted J's Racing Bodykit In Hardo Grey. Low Mileage, Taken Care Extremely Well By Owner. View To Believe! Trade-Ins Available, Viewing By Appointment Only!

[Car Search](#) [Consignment](#)

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

 **Honda Fit 1.3A G (COE till 03/2023)** **\$20,800** **\$5,180 /yr** **12-Mar-2008** **1,339 cc** **133,000 km** **Hatchback** **Available**

Fuel Efficient, Fun & Reliable Hatchback Up For Sale. An Under Utilised Unit With Very Low Mileage. Selling Off Due To Lack Of Usage. Passing It Off To The Next Owner With A Peace Of Mind. Consignment...

[View Details](#) | [Compare](#) | [Share](#) | [Print](#) | [StarAd](#)

 **Honda Fit 1.3A G Skyroof (COE till 03/2023)** **\$22,800** **\$5,600 /yr** **15-Apr-2008** **1,339 cc** **180,000 km** **Hatchback** **Available**

Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Costs! In House Loan Or Bank Loan Available! Fast And Easy Loan Approval! High Loan Or Over Trade...

[View Details](#) | [Compare](#) | [Share](#) | [Print](#) | [StarAd](#)

 **Honda Fit 1.3A G (COE till 05/2028)** **\$48,000** **\$5,200 /yr** **30-May-2008** **1,339 cc** **108,000 km** **Hatchback** **Available**

[Compare \(3 \)](#) [Consignment](#)



Honda's Signature Compact And Nimble VTEC Hatchback In Factory Black Exterior And Red On Black Leather Upholstery. Buy With A Peace Of Mind. Always Parked Under Shelter. Regularly Serviced At Reputabl...

Monster Motors Pte Ltd

Phone: 03-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A G (New 5-yr COE) \$22,200 \$5,430 /yr 11-Jul-2008 1,339 cc - Hatchback Available

Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive. In House Loan Available, At Low Monthly Installment. Flexible Loan Available. 100% Accident Free. Trade In Are Welcome, View To Be...

Phone: 03-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A G (COE till 08/2023) \$22,800 \$5,140 /yr 11-Aug-2008 1,339 cc - Hatchback Available

Excellent Condition, Reverse Sensors, Reverse Camera, DVD Player, Sports Rims, Leather Seats, No Repairs Needed, Bank Or In House Loan Available.

Phone: 04-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.5A RS (COE till 08/2028) \$46,800 \$4,950 /yr 19-Aug-2008 1,496 cc 162,000 km Hatchback Available

Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

Carro

Phone: 05-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Free Valuation by sgCarMart Quotz

Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.

Find out more!



Honda Fit 1.3A G (COE till 08/2023) \$25,800 \$5,760 /yr 27-Aug-2008 1,339 cc 102,000 km Hatchback Available

Excellent Condition! Cheapest In The Market And Definetly Best Condition. Free 6 Months Road Tax, High Loan Available, No Gimmicks, 1 Year Comprehensive Warranty With 24/7 Breakdown Recovery Service. ...

Phone: 07-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A G (COE till 08/2023) \$24,999 \$5,580 /yr 27-Aug-2008 1,339 cc 122,000 km Hatchback Available

\$500 For Monthly Installment, New Paintwork, New Rims And Tyres, 2 Owners. Low Mileage Done, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.

Phone: 08-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A L Skyroof (COE till 08/2023) \$28,600 \$6,370 /yr 01-Sep-2008 1,339 cc 105,000 km Hatchback Available

Excellent And Original Condition, Well Maintained Interior And Exterior, Low Mileage Done, Original Sporty Red Paintwork, Call Now For Viewing.

Phone: 09-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A G (OPC) (New 5-yr COE) \$27,800 \$5,550 /yr 04-Sep-2008 1,339 cc 93,000 km Hatchback Available

AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner Only! Price Inclusive Of Conversion To Normal Plate! Low Fuel Consumption! Low Maintenance Cost! Smooth And Responsive ...

AA Trust Automotive

Phone: 06-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A G (COE till 09/2023) \$24,600 \$5,440 /yr 12-Sep-2008 1,339 cc - Hatchback Available

Beautiful Car Number. Tip Top Condition, No Repair Needed.

Phone: 07-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda



Honda Fit 1.3A GF (COE till 10/2023) \$26,500 \$5,760 /yr 10-Oct-2008 1,339 cc 105,000 km Hatchback Available

In-house Loan Or Bank Loan Available At 3.18% Only! No Gimmicks, Choice Of Units Available To Choose And Test Drive. In-house 6 Months Comprehensive Warranty With 24/7 Breakdown Recovery Service. We W...

Phone: 08-440-2114 Tags: 2008 Honda FL, 2008 Honda FL, Honda FL, Honda FL, Honda FL, FL, Used Honda

Honda Fit 1.3A G (COE till 10/2023) \$25,800 \$5,580 /yr 20-Oct-2008 1,339 cc 125,000 km Hatchback Available

House Loan Or Bank Loan Available At 3.18% Only! No Gimmicks.

WARRANTY 12 MONTH

Compare (2)

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Wednesday, 6 March, 2019 11:10 AM
To: 'Shu Pei (LKKAuto)'; 'assignments'
Cc: 'sur@lkkauto.com'
Subject: RE: Urgent: PRE-REPAIR INSPECTION: Your Vehicle: SKT 1881 G; Leang Auto's Vehicle: SJJ 1964 R; ACCIDENT INVOLVING SJJ 1964 R & SKT 1881 G ON 1 March 2019

Dear Boon Sen,

Thank you for your assignment.

Kindly create claim in merimen.

Best Regards,

Veron Chen | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 5 March 2019 4:37 PM
To: bonnie kwok <litigation@bonniekwok.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Urgent: PRE-REPAIR INSPECTION: Your Vehicle: SKT 1881 G; Leang Auto's Vehicle: SJJ 1964 R; ACCIDENT INVOLVING SJJ 1964 R & SKT 1881 G ON 1 March 2019

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]

Sent: Tuesday, 5 March, 2019 4:23 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Urgent: PRE-REPAIR INSPECTION: Your Vehicle: SKT 1881 G; Leang Auto's Vehicle: SJJ 1964 R; ACCIDENT INVOLVING SJJ 1964 R & SKT 1881 G ON 1 March 2019

Dear Sirs,

Our client agrees to Adrian Ling as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, M/s Leang Automotive at 9028 6516 to make the necessary arrangements.

Regards,
ST

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 5 Mar 2019 at 16:13, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/03/2019 11:30
Date Of Accident	01/03/2019 01:50
Exact Location Of Accident	GUILIN VIEW CONDOMINIUM BUKIT BATOK ST 52 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ1964R
Insured/Policyholder	
Name Of Registered Owner	ONG HUEY DAISY
NRIC No	S1567954I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94561791
Alternative Phone No	OFFICE-94561791

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0018959-MVA
Cover Note Number	

Driver

Name of Driver	HON ZHI HAO, GABRIEL
NRIC No	S9239675D
Date Of Birth	02/11/1992
Occupation	INDOOR
Date Of Driving Pass	09/01/2014
Driving Experience	5 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94561791
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	20 BUKIT BATOK STREET 52 #12-01
Postcode	659244
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT1881G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Licensed Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material information may entitle insurance companies to rescind the policy/cover.
4. The filling and acceptance of this form by insurance companies is not an admission of driver liability on the part of the insurance companies.
5. Any dispute regarding this report may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by the affected party.
7. By the signing of this report to the insurers, you hereby consent to the storing of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - a. I understand and I hereby agree and consent that:
 - i. My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, process and/or process my personal data/personal information about in this form and any other personal information provided to me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Insurance Authority of Singapore and any relevant government agencies/authorities (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - investigating the accident and/or my claims;
 - carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external issue of envelopes/mail packages), and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - ii. Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to do so; use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - iii. Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
 - iv. Personal Information will also be collected and used to compile a claims history for the purpose of fraud detection, investigation and management in present and/or future claims;
 - v. The information so collected under (d) above may be shared / disclosed:
 - to i. Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud (eg. State law enforcement and government agencies as reasonably required for the purposes stated); or
 - ii. complying with requirements under any regulations, laws or court orders.


Insurer's Signature
Date & Time


Driver's Signature
(Driver is not the policyholder)
Date & Time


Recording Centre Personnel's Signature
Name:
NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

I was in the multi-story concrete going straight, when I saw a vehicle turning up the ramp. I stopped my car and honked, but the other vehicle continued moving and collided into my car.

DECLARATION

I declare that the foregoing particulars are true to the best of my knowledge.

Witness's Signature
Date & Time:

AW
Driver's Signature
(If driver is not the complainant)
Date & Time

[Signature]
Reporting Officer's Signature
Date & Time

TP Chiam.
Xiao Chen

Subject: SGT/S642

Date: / /

Honda Fit
GE61056434

Front Number Plate	Best	30(SN)	✓
Front Number Plate Holder	Rehd	30(SN)	✓
Front Bumper	Rehd	573.70	✓
Front Bumper Lips	new	30	✓
Front Bumper Side Holder x02	RH new	24.9 x 2 = 49.80	24.50
Front Bumper Reinforcement	Best	253.90	✓
Front Bumper Lower Grille	Rehd	162	✓
Front Grille	rehd	158.80	✓
Front Grille Logo	new	30.50	✓
Front Grille Lips	new	15	✓
Headlamp x02	rehd	585 x 2 = 1170	✓
Headlamp lower Bracket x02	RH rehd	27.5 x 2 = 55	27.50
Bonnet	Rehd	543.90	✓
Bonnet lock	new	95.10	X
Front Support Panel	Dishd	594.80	✓
Air Car Condenser	new	762.80	X
Radiator	new	3657.90	1382.60 X
Wiper Washer Tank	Dishd	2926.32	72.90 ✓
Front RH Fender	Rehd S.N. 60	375.60	X

Panel Beating

~~1200~~ 800

Spray Painting

~~1200~~ 800

W/ Way

~~50~~ 30

(800)

To condenser

~~150~~ 50

To remove condenser, radiator

~~180~~ 120

and to change

total: 4786.32

L/S: 3-810 05 days

TP Consultants hence notify the Repairer of the following:

- To display our logo on the car during re-service
- Parts prices are subject to confirmation
- The repair work is on a "Warranty" basis
- No illegal modifications are allowed
- Supplementary work(s) must be authorized and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2019 09:12		25 Mar 2019 17:45 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, ID: -								
Main Claimant:	ONG HUEY DAISY , ID: S1567954I								
Vehicle Reg. No.:	SJJ1964R	Date of Loss:	01/03/2019 01:00 - :59 [125 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SKT1881G	Policy No. (Claimant):	8-V0018959-MVA						
		Excess:	S\$0.00						
Repairer:	Leang Automotive (HQ) BLK 1 KAKI BUKIT AVE 6 #02-12 AUTOBAY@ KAKI BUKIT, 417883 Kaki Bukit - Tel: 9028 6516								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/04/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ1964R
 [SKT1881G]
 TP
 ONG HUEY DAISY
 Mar 1 2019 1:00AM
 [-]
 Leang Automotive

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	02/03/19 11:35	Accident Statement	1	Load HTML						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	02/03/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
2	02/03/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
3	02/03/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
4	02/03/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
2	26/03/19 09:33	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>					
3	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
4	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
5	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
6	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
7	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
8	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
9	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
10	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
11	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
12	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
13	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
14	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
15	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
16	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
17	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
18	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
19	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
20	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
21	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
22	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
23	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
24	26/03/19 09:33	General View	1	Load JPG	<input checked="" type="checkbox"/>					
25	26/03/19 09:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>					
26	26/03/19 09:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>					
27	26/03/19 09:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>					
28	26/03/19 09:34	Reinspection Photo	1	Load JPG						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
29	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	26/03/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/03/19 17:45	PRI CONTACT	Load PDF	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	02/03/19 11:34	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	02/03/19 11:34	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	02/03/19 11:35	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	02/03/19 11:34	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	02/03/19 11:34	Accident Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
3	02/03/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/03/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	02/03/19 11:34	Sketch Plan	 Load TIF	
2	02/03/19 11:34	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004094/AQD3Q2
Date: 04/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SJJ1964R

Insured Vehicle No : SKT1881G

Date of Loss: 01/03/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1964R	Engine No:	L13A4107044
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61096434
Reg. Date:	04/09/2008 (Man. Year: 2008)	Odometer:	120032 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,386.40	2,986.32	3,400.08	53.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,800.00	980.00	35.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,166.40	4,786.32	4,380.08	47.78
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	9,166.40	3,800.00	5,366.40	58.54

INSPECTION

Date of Assignment: 25/03/2019

Date Inspected: 06/03/2019 Inspected At:

Leang Automotive (HQ)
BLK 1 KAKI BUKIT AVE 6 #02-12
AUTOBAY@ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ1964R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Deformed	573.70 F	*573.70 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	1		*FRONT BUMPER SIDE HOLDER	O/S Necessary	49.80 F	*24.90 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	253.90 F	*253.90 FL
7	1		*FRONT BUMPER LOWER GRILLE	Deformed	162.00 F	*162.00 FL
8	1		*FRONT GRILLE	Cracked	158.80 F	*158.80 FL
9	1		*FRONT GRILLE LOGO	Necessary	30.50 F	*30.50 FL
10	1		*FRONT GRILLE CLIPS	Necessary	15.00 F	*15.00 FL
11	2		*HEADLAMP	Cracked	1,170.00 F	*1,170.00 FL
12	1		*HEADLAMP LOWER BRACKET	O/S Cracked	55.00 F	*27.50 FL
13	1		*BONNET	Buckled	543.90 F	*543.90 FL
14	1		*BONNET LOCK	Not Necessary	95.10 F	*- FL
15	1		*FRONT SUPPORT PANEL	Distorted	594.80 F	*594.80 FL
16	1		*AIR CON CONDENSER	Not Necessary	762.80 F	*- FL
17	1		*RADIATOR	Not Necessary	1,382.60 F	*- FL
18	1		*WIPER WASHER TANK	Distorted	72.90 F	*72.90 FL
19	1		*FRONT RH FENDER	Repair	375.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	6,386.40	3,717.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	731.58
Total Parts (\$\$)	6,386.40	2,986.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	50.00
5	TO REMOVE CONDENSER ,RADIATOR AND TO RE-GAS	New	180.00	120.00
			Gross Labour Cost (S\$)	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >