

ASS. REC. BY:

REF: CS 1CT119004096/Ea/302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CAI

Date/Time: 11/3 @ 3:08pm

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH1972D

Insured: SME 2480P

at Workshop m/s: Tan Chong Motor

Tel:

of 911 Bukit Merah Terrace

Policy No: DMPCSN30612218000

Claim No: SNM19D200977C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 23/2/2019

CA / REV / REP. / REV 24 HRS

11/3 @ 10am

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
07/5/19 @	1st confirmed with Super final fig to 3087.32, 3 days. (Cost \$ 3453.38, 51%)

Steve

CTI

Reg No: **SLH 1972D**
 Reg. Type: **Passenger**
 Reg. Date: **11/3/2019**
 Reg. Authority: **Penang**
 Reg. Status: **Valid**
 Reg. Category: **Passenger**
 Reg. Sub-Category: **Passenger**
 Reg. Class: **Passenger**
 Reg. Sub-Class: **Passenger**
 Reg. Code: **Passenger**
 Reg. Sub-Code: **Passenger**
 Reg. Fee: **11/3/2019 10am**
 Reg. Status: **Valid**
 Reg. Remarks: **The veh had commenced its repair at the time of inspection.**
 Reg. Val. or Market Value: **XXX**
 Reg. Acc. or Dam. Report: **Consistent? Yes or No**
 Reg. Ins. or Rep. Seen: **Consistent? Yes or No**
 Reg. Est. Report: **3 days** Yes or No
 Reg. Ins. or Rep. Seen: **3 days** Yes or No
 Reg. CA / REV / REP / 24HRS
 Reg. Date: **Person contacted**
 Reg. Date: **Person contacted**

Reg No: **SLH 1972D**
 Reg. Type: **Passenger**
 Reg. Date: **26/10/16**
 Reg. Authority: **Penang**
 Reg. Status: **Valid**
 Reg. Category: **Passenger**
 Reg. Sub-Category: **Passenger**
 Reg. Class: **Passenger**
 Reg. Sub-Class: **Passenger**
 Reg. Code: **Passenger**
 Reg. Sub-Code: **Passenger**
 Reg. Fee: **2.0 (199700)**
 Reg. Val. or Market Value: **45546**
 Reg. Acc. or Dam. Report: **Consistent? Yes or No**
 Reg. Ins. or Rep. Seen: **Consistent? Yes or No**
 Reg. Est. Report: **225/60R18** Yes or No
 Reg. Ins. or Rep. Seen: **225/60R18** Yes or No
 Reg. CA / REV / REP / 24HRS
 Reg. Date: **Person contacted**
 Reg. Date: **Person contacted**



Steve
 parts
 Pls state the damaged condition.
 RECEIVED 02 MAY 2019
 Days Of Repair: **3**
 Resurvey No. of Trip:
 Add Fee: Late Fee:
 Inspection:
 Survey Fee:
 Report:
 Report Format: **MSR-2**
 Equip. / Ann. / H.P. / : **3287-32**
 Survey Fee: **220**
220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2019		01 Mar 2019 15:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
Insured:																								
Main Claimant:	ARUMUGAM SRIGANESHAKANTHA ID: S7485662D																							
Vehicle Reg. No.:	SLH1972D	Date of Loss:	23/02/2019 21:00 - :59																					
Claim Type:	TP / SNM19D200977C02	Policy/Cover Note No.:	DMPCSN30612218000																					
Vehicle Reg. No. (Insured):	SME8480P	Policy No. (Claimant):	GA134075/1																					
		Excess:	S\$0.00																					
Repairer:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road, 589622 Bukit Timah - Tel: 64601694																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]																							
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/03/2019]																							
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail																			
There are no mail for this case.																								
<div style="border: 1px solid black; padding: 5px;"> <p>ALL ASSOCIATED TASKS</p> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Appt 11/3/19 @ 10am

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 2 May 2019 12:00 PM
To: Norsipah; Shu Pei (LKKAuto)
Cc: Admin A; CS A Team; SUR
Subject: RE: COR Final SLH1972D doa 23.02.2019

Dear Sipah,

WITHOUT PREJUDICE

Confirm final fig \$3,287.32 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>
Sent: Tuesday, 30 April 2019 4:03 PM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: COR Final SLH1972D doa 23.02.2019

Re-Finalized attached.

Thank you.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589623

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, April 29, 2019 10:13 AM
To: Norsipah <norsipah@tanchong.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: COR Final SLH1972D doa 23.02.2019

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5662D
Vehicle Details	
Vehicle No.:	SLH1972D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	MR20908015B
Chassis No.:	JN1JANT32Z0002680
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$23,227.00
Original Registration Date:	26 Oct 2016
First Registration Date:	26 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$24,518.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$18,388.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$42,989.00
Total Rebate Amount:	\$61,377.00

The information contained herein is correct as at 11 Mar 2019

OK

etc

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 10:52
Date Of Accident	23/02/2019 21:10
Exact Location Of Accident	SEMBAWANG ROAD FILTER LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1972D
Insured/Policyholder	
Name Of Registered Owner	ARUMUGAM SRIGANESHAKANTHA
NRIC No	S7485662D
Email Address	ASIRIGANESH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90108547
Alternative Phone No	OTHERS-90108547

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA134075/1
Cover Note Number	

Driver

Name of Driver	ARUMUGAM SRIGANESHAKANTHA
NRIC No	S7485662D
Date Of Birth	27/05/1974
Occupation	INDOOR
Date Of Driving Pass	15/08/2001
Driving Experience	17 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90108547
Fax Number	
Contact Number	OTHERS-90108547
Email Address	ASIRIGANESH@GMAIL.COM

Address	54 SENGKANG SQUARE #01-11
Postcode	544832
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SRIGANESHAKANTHA MEERA GENDER: : FEMALE
Passenger 2	NAME: : SRIGANESHAKANTHA SHIDIKSHA GENDER: : FEMALE
Passenger 3	NAME: : SRIGANESHAKANTHA SHIVESH GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME8480P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

4

Passenger 1

NAME: :

GENDER: :

Passenger 2

NAME: :

GENDER: :

Passenger 3

NAME: :

GENDER: :

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Your vehicle no. _____



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 14299

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1967 - Road Transport Act, 1967 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	ARUMUGAM SRIGANESHAKANTHA	Certificate number	GA134075 / 1
Cover	Comprehensive	Chassis number	JN1JANT32Z0002680
Plan name	Flexi	Engine number	MR209080358
NCD applicable	50%		
Vehicle registration number	SLH19720		
Period of insurance	from 26/10/2018 to 25/10/2019 (both dates inclusive)		
Finance loan company	OCBC BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 400.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

- \$4500 for unnamed Authorized Driver
- \$4500 for declared Young and Inexperienced Driver
- \$45,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$42,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

[We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 ☎ (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

ARUMUGAM SRIGANESHAKANTHA
 54 SENGKANG SQUARE
 #01-11, LA FIESTA
 SINGAPORE 544832

Renewal

date
18/09/2018

your servicing distributor
**(A/C TERMINATED)ST INSURANCE
 AGENCY PTE LTD / 14299**

your servicing distributor contact
64649098

Policy Schedule

Your SmartDrive Comprehensive Flexi

Your policy snapshot

Policyholder name	ARUMUGAM SRIGANESHAKANTHA	Policy number	VA1 / GA134075
Cover	Comprehensive	FIN / NRIC	S7485662D
Period of Insurance	from 26/10/2018 to 25/10/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 1,055.45
Total Discounts	- SGD 56.28
7% GST	SGD 69.94
Final Premium	SGD 1,069.11

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Flexi Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

Add-on Benefits

- No Claim Discount Protector

Vehicle details

Make & Model of Vehicle	NISSAN X-TRAIL 2.0	Year of manufacture	2016
Vehicle registration number	SLH1972D	Type of Use	Private use
Body type	SUV	Engine capacity (c.c.)	1997
Seating capacity (excl driver)	5	Engine number	MR20908015B
Off-Peak car	No	Chassis number	JN1JANT32Z0002680

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	OCBC BANK LIMITED

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 400.00
Windscreen Excess	SGD 100.00

Drivers details

Driver type	Driver name	Date of birth	Driving experience
Main Driver	ARUMUGAM SRIGANESHAKANTHA	27/05/1974	13 year(s)

Additional clauses & endorsements to your policy

Nil

What you should do

- Keep this Policy Schedule as record of insurance cover for your vehicle
- This Schedule should be read in conjunction with the Terms and Conditions of the Policy Wording

AXA Insurance Pte Ltd

This is an auto-generated document and hence no signature is required

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7485662D



Name
**ARUMUGAM
SRIGANESHAKANTHA**
அ. முற்கேசகாந்தா
Race
SRI LANKAN
Date of birth **27-05-1974** Sex **M**
Country of birth
SRI LANKA

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S7485662D**

Name:

**ARUMUGAM
SRIGANESHAKANTHA**

Birth Date: **27 May 1974**

Issue Date: **02 Jul 2005**



4092621



NRIC No: **S7485662D**

Date of issue
27-08-2007

54 SENKANG SQUARE #01-11
LA FIESTA SINGAPORE 544832

NRIC No: **87485662D** Date: **C9/06/2016**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B Motorcycles \leq 200 cc
Class 3 Motor cars \leq 3000 kg with \leq 7 passengers,
exclusive of the driver, and motor tractors
/vehicles \leq 2500 kg

15 Aug 2001
15 Aug 2001



NP 428A

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

en
16364

28/02/19

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0118/2019
DATE : 28-FEB-2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : ARUMUGAM SRIGANESHAKANTHA
ADDRESS : 54 SENGKANG SQUARE
#01-11 LA FIESTA
S(544832)
TELEPHONE NO : 90108547

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SME8480P
VEHICLE NO : SLH1972D
MODEL CODE : JDRNRHET32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20908015B
CHASSIS NO : JN1JAMT32E0002680
MILEAGE : 1 KM
DATE IN : 28/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/02/2019

HV4774
CLIK
68411972

[Signature]
12/3/19

Steve (CLIK) with PIP/under
83228513
11/3/19 10am
PIP 4 days
Req before & Afl spay

en
11/03/19
(now)
heaving/over
9-00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAR W/SKOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH1972D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
①	1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL S120/PANEL X 03	360.00	170 ✓
②	2 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓ ✓
③	3 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA S100/PANEL X 02	200.00	100 ✓
④	4 22/001	REPAIR TAILGATE, END PANEL AND RENEW REAR BUMPER 280	1000.00	700 ✓
⑤	5 22/002	S/PAINT REAR BUMPER (2 TONE), END PANEL AND TAILGATE with 1-p1	1000.00	850 ✓
⑥	6 22/003	CHECK LIGHTING	48.00	✓ ✓
	7 22/004	CHECK REAR BOOTLID LOCKING SYSTEM AND RESET	120.00	9? x
	8 22/005	RENEW ELECTRONIC PART BACKDOOR	240.00	9 x
TOTAL LABOUR CHARGES			3078.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH1972D

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
①	1 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 / BR /
②	2 SUNDRIES	NPN			200/100.00 80/ NEC
	3 SW-ASSY TRUNK OPENING	25380-4BA1A			70.00 ? x NAI
	4 CONTROLLER ASSY POWER BACKDOOR	28400-4BA1A			508.10 ? x NAI
③	5 CLIP ARC \$3.00 EA X 10	76892-JG10A	30.00	/ NEC /	
④	6 GROMMET ARC REAR \$2.50 EA X 04	76848-JG00B	10.00	/ NEC /	
⑤	7 CLIP ARC \$2.50 EA X 04	76847-JG00A	10.00	/ NEC /	
⑥	8 CLIP ARC \$2.50 EA X 06	01553-10641	15.00	/ NEC /	
	9 FILLET-MLDG RH REAR ARC	78860-4CE0A	150.00	? x NAI	
	10 FILLET-MLDG LH REAR ARC	78861-4CE0A	150.00	? x NAI	
⑦	11 GROMMET BUMPER \$2.80 EA X 02	85099-1VA0A			5.60 / NEC /
	12 STAY-RR BUMPER RH	85210-4CC0A	174.80	? x NAI	
	13 STAY-RR BUMPER LH	85211-4CC0A	174.80	? x NAI	
	14 REINF-BUMPER RR	85032-4CC0A	533.80	? x NAI	
⑧	15 GROMMET BUMPER \$1.80 EA X 02	01281-00711			3.60 ? / NEC /
	16 BRACKET-BUMPER RH	85220-4CE0A	35.90	? x NAI	
	17 BRACKET-BUMPER LH	85221-4CE0A	35.80	? x NAI	
⑨	18 CLIP BUMPER \$1.20 EA X 04	01553-10501	4.80	/ NEC /	
	19 FINISHER BUMPER AIR VENT	85070-1KA0A	105.00	? x NAI	
⑩	20 FACE-RR BUMPER	85022-4CE0H	623.80	/ # 00 /	
	21 A FIN BACK DOOR NO PLATE	90810-4CE0A	138.60	x NAI	
	22 LOCK & REMOTE C	90500-1AA0B	557.90	? x NAI	
⑪	23 EMBLEM	84895-4CLOA	101.30	/ NEC /	
SUB TOTAL			2851.50	0.00	897.30
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			570.30	0.00	0.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SBOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH1972D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
	GRAND TOTAL		2281.20	0.00	897.30
	OVERALL TOTAL		3178.50		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH1972D

TOTAL LABOUR CHARGES	3078.00
TOTAL SPARE PARTS CHARGES	3178.50

GRAND TOTAL	6256.50 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

6/4.90

21-Mar-2019

INS/IC/LAW/0118/2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
Singapore 079909

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM
REGN. NO. : SLH1972D
POLICY NO. : -

(Supp)

Further to our claim INS/IC/LAW/0767/2008 we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>		
⑫ 1	GURAD-RR BMPR LOWER / BR	\$484.20 S/NETT /
2		
2		
3		

TOTAL \$ 484.20

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
TAN CHONG MOTOR SALES PTE LTD

LAWRENCE TEO
Insurance Claim Dept

Cc: Surveyor

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589523

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : IHS/IC/LAW/0118/2019
DATE : 28-FEB-2019

CHINA TAIFING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : ARUNUGAN SRIGANESHAKANTHA
ADDRESS : 54 SENGKANG SQUARE
#01-11 LA FIESTA
S(544832)
TELEPHONE NO : 90108547

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SME8480P
VEHICLE NO : 5LH1972D
MODEL CODE : JORNREH12EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MN20908015B
CHASSIS NO : JN1JANT3280002680
MILEAGE : 1 KM
DATE IN : 28/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/02/2019

STAVE
(LICK)

D/S

LOU

80/day x 03

= # 240/-

TAN CHONG MOTOR SALES PTE. LTD.
 SUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH1972D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVETOR'S RECOMMENDATION
①	1 RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 0J	360.00	120.00
②	2 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
③	3 REAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	100.00
④	4 22/001	REPAIR TAILGATE, END PANEL AND RENEW REAR BUMPER	1000.00	700.00
⑤	5 22/002	S/P/PAINT REAR BUMPER(4 TUNE), END PANEL AND TAILGATE	1000.00	850.00
⑥	6 22/003	CHECK LIGHTING	48.00	48.00
	7 22/004	CHECK REAR BOOTLID LOCKING SYSTEM AND RESET	120.00	.00
	8 22/005	RENEW ELECTRONIC PART BACKDOOR	240.00	.00
TOTAL LABOUR CHARGES			3078.00	1928.00

YAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL81972D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	GURAD-RR EMPR LOWER - SUPPLEMENTARY	H5901-4CE10			484.20	OK
2	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	OK
3	SUNDRIES	HPN			20.00	OK
4	SN-ASSY TRUNK OPENING	25380-4B1A			70.00	X
5	CONTROLLER ASSY POWER BACKDOOR	28460-4B1A			508.10	X
6	CLIP ARC \$3.00 EA X 10	76882-JG10A	30.00			OK
7	GROMMET ARC REAR \$2.50 EA X 04	76848-JG00B	10.00			OK
8	CLIP ARC \$2.50 EA X 04	76847-JG00A	10.00			OK
9	CLIP ARC \$2.50 EA X 06	01553-10641	15.00			OK
10	FILLET-MLDG RH REAR ARC	78860-4CE0A	150.00			X
11	FILLET-MLDG LH REAR ARC	78861-4CE0A	150.00			X
12	GROMMET BUMPER \$2.00 EA X 02	85099-1VA0A			5.60	OK
13	STAY-RR BUMPER RH	H5210-4C0A	174.80			X
14	STAY-RR BUMPER LH	H5211-4C0A	174.80			X
15	REINF-BUMPER RR	85032-4CC0A	533.80			X
16	GROMMET BUMPER \$1.00 EA X 02	01281-00711			3.60	OK
17	BRACKET-BUMPER RH	85220-4CE0A	35.90			X
18	BRACKET-BUMPER LH	85221-4CE0A	35.80			X
19	CLIP BUMPER \$1.20 EA X 04	01553-10501	4.80			OK
20	FINISHER BUMPER AIR VENT	85070-1XA0A	103.00			X
21	FACE-RR BUMPER	85022-4CE0B	523.80			OK
22	A FIN BACK DOOR NO PLATE	90810-4CE0A	128.60			X
23	LOCK & REMOIS C	90500-1AA0B	557.90			X
24	EMBLEM	84895-4CL0A	101.30			OK

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH1972D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		794.90	0.00	723.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		158.98	0.00	0.00
GRAND TOTAL		635.92	0.00	723.40
OVERALL TOTAL		1359.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLH1972D

NETT ITEM	794.90
LESS 20.00%	-158.98
NETT AMOUNT	635.92
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	723.40
LESS .00%	0.00
SPECIAL NETT AMOUNT	723.40
TOTAL LABOUR CHARGES	1928.00
TOTAL SPARE PARTS CHARGES	1359.32
TOTAL CHARGES	3287.32
ADD 7 % GST	230.11
GRAND TOTAL	3517.43

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2019		01 Mar 2019 15:08 Edit Adj Rpt	S\$3,287.32 Edit Estimates	S\$3,287.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ARUMUGAM SRIGANESHAKANTHA , ID: S7485662D								
Vehicle Reg. No.:	SLH1972D	Date of Loss:	23/02/2019 21:00 - :59 [27 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200977C02	Policy/Cover Note No.:	DMPCSN30612218000						
Vehicle Reg. No. (Insured):	SME8480P	Policy No. (Claimant):	GA134075/1						
		Excess:	S\$0.00						
Repairer:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road, 589622 Bukit Timah - Tel: 64601694								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 12/03/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH1972D (SNM19D200977C02)
[SME8480P]
TP
ARUMUGAM SRIGANESHAKANTHA
Feb 23 2019 9:00PM
[-]
Tan Chong Motor Sales

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)		Thumbnail	Print						
1	25/02/19 11:05	Video - Accident [Linked Accident Report Documents]		Load MP4							
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)		Thumbnail	Print						
1	25/02/19 11:15	Accident Statement		Load HTM							
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)		Thumbnail	Print						
1	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
2	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
3	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
4	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
5	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
6	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
7	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
8	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
9	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
10	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
11	25/02/19 11:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
2	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
3	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
4	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
5	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
6	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
7	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
8	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
9	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
10	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
11	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
12	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
13	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						
14	12/03/19 08:02	General View		Load JPG	<input checked="" type="checkbox"/>						

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
15	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
16	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
17	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
18	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
19	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
20	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
21	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
22	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
23	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
24	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
25	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
26	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
27	12/03/19 08:02	Odometer Reading		<input checked="" type="checkbox"/>
28	12/03/19 08:02	Chassis Number		<input checked="" type="checkbox"/>
29	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
30	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
31	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
32	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
33	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
34	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
35	12/03/19 08:02	General View		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/19 15:10	PRI CONTACT		<input type="checkbox"/>
2	01/03/19 15:10	REPAIR ESTIMATE		<input type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	25/02/19 11:08	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	25/02/19 11:08	Sketch Plan #2 [Linked Accident Report Documents]		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/19 17:10	Supplementary		<input type="checkbox"/>

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	25/02/19 11:05	Video - Accident		<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	25/02/19 11:15	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
2	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
3	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
4	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
5	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
6	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>
7	25/02/19 11:13	Accident Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
8	25/02/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	25/02/19 11:08	Sketch Plan	 Load TIF	
2	25/02/19 11:08	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004096/EQD3E2
Date: 10/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30612218000	
Claimant Vehicle No: SLH1972D	Insured Vehicle No: SME8480P	
Date of Loss: 23/02/2019	Nature of Claim: TP	Claim No: SNM19D200977C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH1972D		
Make & Model: NISSAN X-TRAIL, 2.0 (A)	Engine No: MR20908015B	
Reg. Date: 26/10/2016 (Man. Year: 2016)	Chassis No: JN1JANT3Z0002680	
Colour: Silver	Odometer: 45546 km	
Engine Capacity: 1997 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,662.70	1,359.32	2,303.38	62.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,078.00	1,928.00	1,150.00	37.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,740.70	3,287.32	3,453.38	51.23
+ GST 7.00/7.00% (S\$)	471.85	230.11	241.74	51.23
Nett Amount (S\$)	7,212.55	3,517.43	3,695.12	51.23

INSPECTION

Date of Assignment:	01/03/2019	
Date Inspected:	11/03/2019	Inspected At: Tan Chong Motor Sales (HQ) 911 BUKIT TIMAH ROAD SINGAPORE 589623
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts: M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH1972D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*CLIP ARC	Necessary	30.00 FN	*30.00 FN
2	4		*GROMMET ARC REAR	Necessary	10.00 FN	*10.00 FN
3	4		*CLIP ARC	Necessary	10.00 FN	*10.00 FN
4	6		*CLIP ARC	Necessary	15.00 FN	*15.00 FN
5	1		*FILLET - MLDG RH REAR ARC	Not Necessary	150.00 FN	*- FN
6	1		*FILLET - MLDG LH REAR ARC	Not Necessary	150.00 FN	*- FN
7	1		*STAY - RR BUMPER RH	Not Necessary	174.80 FN	*- FN
8	1		*STAY - RR BUMPER LH	Not Necessary	174.80 FN	*- FN
9	1		*REINF - BUMPER RR	Not Necessary	533.80 FN	*- FN
10	1		*BRACKET - BUMPER RH	Not Necessary	35.90 FN	*- FN
11	1		*BRACKET - BUMPER LH	Not Necessary	35.80 FN	*- FN
12	4		*CLIP BUMPER	Necessary	4.80 FN	*4.80 FN
13	1		*FINISHER BUMPER AIR VENT	Not Necessary	105.00 FN	*- FN
14	1		*FACE - RR BUMPER	Dented	623.80 FN	*623.80 FN
15	1		*A FIN BACK DOOR NO PLATE	Not Necessary	138.60 FN	*- FN
16	1		*LOCK & REMOTE C	Not Necessary	557.90 FN	*- FN
17	1		*EMBLEM	Necessary	101.30 FN	*101.30 FN
18	1		*REVERSE SENSOR	Broken	210.00 FS	*210.00 FS
19	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
20	1		*SW - ASSY TRUNK OPENING	Not Necessary	70.00 FS	*- FS
21	1		*CONTROLLER ASSY POWER BACKDOOR	Not Necessary	508.10 FS	*- FS
22	2		*GROMMET BUMPER	Necessary	5.60 FS	*5.60 FS
23	2		*GROMMET BUMPER	Necessary	3.60 FS	*3.60 FS
24	1		*GURAD - RR BMPR LOWER	Broken	484.20 FS	*484.20 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,233.00	1,518.30
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	570.30	158.98
Total Parts (\$\$)	3,662.70	1,359.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	New	380.00	120.00
2	SUPPLY & INSTALL REVERSE SENSOR.	New	110.00	110.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	New	200.00	100.00
4	REPAIR TAILGATE, END PANEL AND RENEW REAR BUMPER.	New	1,000.00	700.00
5	S/PAINT REAR BUMPER (2 TONE), END PANEL AND TAILGATE.	New	1,000.00	850.00
6	CHECK LIGHTING.	New	48.00	48.00
7	CHECK REAR BOOTLID LOCKING SYSTEM AND RESET.	New	120.00	0.00
8	RENEW ELECTRONIC PART BACKDOOR.	New	240.00	0.00
Gross Labour Cost (S\$)			3,078.00	1,928.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >