

ASS. REC. BY:

REF:

CS / SPF 19004098 / U9d3et

Special Instruction:

Survivor:

Marcus

ASSIGNMENT (Office)

From (Person):

Frankie

of

SPF

Date/Time:

6/3/19

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SSR 9162T

Insured:

at Workshop m/s

Automobile Hup

Tel:

97864483

of

1 Kaki Bukit Ave 6 #02-11

Policy No:

Claim No:

AFMD / 105/09 / 2019 / 008

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

6/3/19

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SSR 9162T / AX 410Y

NA / INCL 9003655 / 44 D.O.A. = 26/2/19

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*SPF/*

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 15/3/19 *4300*

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I. (\$) *4300*☐

: Preli. Report

☐

: Final Report

Days Of Repair: *4*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

) \$ + RS, SI

) Photos

) Others

TOTAL

*220**220*

RECEIVED 18 MAR 2019

*15/3/19 2/5 4300 summt (Red 67347.47, 63%)  
COR range 64300 - 64800*

## Denise Tay (LKKAuto)

---

**From:** Olivia Lau (LKKAuto)  
**Sent:** Wednesday, 6 March 2019 8:47 AM  
**To:** SUR; assignments  
**Subject:** FW: RE : Pre-Repair Inspection for vehicle SJR 9162T

6/3. 11.30 AM (in) est ✓

---

**From:** Frankie THAY (SPF)  
**Sent:** Wednesday, 6 March 2019 8:47:04 AM (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Veron Chen (LKKAuto); assignments  
**Cc:** Hafizul Farhan RAHMAT (SPF); Olivia Lau (LKKAuto)  
**Subject:** RE : Pre-Repair Inspection for vehicle SJR 9162T

Not in

Your reference : SJR 9162T  
Our reference: AEMD/105/09/2019/008

Veron,  
Please conduct a Pre-Repair Inspection for vehicle SJR 9162T at below workshop:

Automobile Hub Enterprise  
1 Kaki Bukit Avenue 6  
#02-11 Autobay@Kaki Bukit  
Singapore 417883  
Please contact Mr Ah Siong at 97864483 for appointment.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6198R
<b>Vehicle Details</b>	
Vehicle No.:	SJR9162T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	3ZZ4903598
Chassis No.:	MR053ZEE106147943
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,500.00
Original Registration Date:	22 Jul 2009
First Registration Date:	22 Jul 2009
Transfer Count:	3
Actual ARF Paid:	\$17,500.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2019
PARF Rebate Amount:	\$8,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$410.00
<b>Total Rebate Amount:</b>	<b>\$9,160.00</b>

The information contained herein is correct as at 06 Mar 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!

Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

SGCARMART

QUOTZ

Quoting Made Simple

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A

2.68%P.A Low Interest@GV Finance. 2 Years Warranty. \$2500 Down Monthly \$638 GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

SGCARMART

QUOTZ

Quoting Made Simple

Browse by Category

Back ( 1 2 3 4 5 6 7 8 ) Next

Sort by Date Posted

20 results/page

147 vehicles

Toyota altis

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota altis		Any	Any	2009	Any	Any	Any	Available
<div><div></div><div><div>starAd</div></div></div> <div><div>Toyota Corolla Altis 1.6A (New 5-yr COE)</div><div>\$28,800</div><div>\$5,750 /yr</div><div>24-Jun-2009</div><div>1,598 cc</div><div>-</div><div>Sedan</div><div>Available</div></div> <div><div>2.68% P.A Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.</div><div>2.68%P.A Low Interest@GV Finance. 2 Years Warranty. \$2000 Down Monthly From \$56 GV Credit Pte Ltd</div><div>Posted: 06-Mar-2019</div><div>Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div>									

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory


Products

Insurance

Articles

Forum

Resources



CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Toyota altis

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » 360 VR Cars » Toyota Corolla Altis 1.6A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Toyota Corolla Altis 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

360° VR Cars

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

Depreciation

Reg Date

Manufactured

Mileage

Transmission

Engine Cap

Road Tax

Power

Curb Weight

Features

Accessories

Description

COE

OMV

ARF

Dereg Value

No. of Owners

Type of Veh

Category

Availability

\$14,500

-

08-Jun-2009  
(3mths 1day COE left)

2009

141,000 km (14.5k /yr)

Auto

1,598 cc

\$742 /yr

80.0 kW (107 bhp)  
View specs of the Toyota Corolla Altis (2008-2013)

1,195 kg

Fuel Efficient And Powerful 1.6L DOHC VVTI Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon

Leather Seats, Sports Rims, Factory Fitted Touch Screen Audio System, Reverse Camera & Sensors, Retractable Side Mirrors, Fog Lamp & Etc.

Regularly Serviced And Well Maintained. Good For Renewal. Viewing By Appointment Only

\$9,889

\$17,500

\$17,500

\$9,002 as of today (change)

2

Mid-Sized Sedan

PARF Car

Available

360 VR Cars



\* dealer's pricelist

\* 79 vehs sold | 95 vehs available

Address

26 Sin Ming Lane #07-111

Search cars nearby this location

Location

Midview City

Office No

69310005

Contact Person(s)

Pauline

James Tan

96211963

90700005

Add to Shortlist

Add to Compare

Add a Note

Posted on: 05-Mar-2019 | Last Updated on: 05-Mar-2019

Tags: Toyota Corolla, toyota corolla, 2009 Toyota Corolla, 2009 toyota corolla, Toyota, Corolla, corolla, Used Toyota

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2019 09:14
Date Of Accident	26/02/2019 09:00
Exact Location Of Accident	CTE TWDS CITY AT PIE TWDS CTE SLIP RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR9162T
-----------------------------	----------

**Insured/Policyholder**

Name Of Registered Owner	SG VEHICLE RENTAL PRIVATE LIMITED
Co Reg No	201136198R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92729299

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099412393
Cover Note Number	-

### Driver

Name of Driver	CHNG YA LI KELVIN
NRIC No	S7919451D
Date Of Birth	07/07/1979
Occupation	OUTDOOR
Date Of Driving Pass	19/04/2001
Driving Experience	17 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83849981
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 625 AMK AVE 9 #04-100
Postcode	560625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NATASCHA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PAYA LEBAR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 114 HOUGANG AVENUE 1 #01-1270 , POSTCODE: 530114 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2899999 - FAX NO: 62815961
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

#### Details of Witness 1

Name	NATASCHA
Phone Number	81614468
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX410Y
Vehicle Make/Model/Colour	
Details Of Properties	



Vehicle Category

GOVERNMENT

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

GIANEC (S) 01/10/2019

RECEIVED 26/02/2019 12:21

# Accident Sketch Plan

## SKETCH PLAN


Please Refer to Sketch

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 

Policyholder's Signature  
Date & Time:





Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SHARON, Sharon@...\_V.R

RECEIVED 26/02/2019 12:21

# Accident Sketch Plan



A = 53R 91621  
B = QX 410Y.

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190226/2111

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2869599

Page 1 of 3  
Report No. T/20190226/2111

**REPORT OF TRAFFIC ACCIDENT**

Date/Time Report Made: 26/02/2019 15:32		Video Report No.		Station Diary No.: 24	
<b>Informant's Particulars</b>					
Name of Informant: G YA LI KELVIN		Address: APT BLK 625 ANG MO KIO AVENUE 9 #04-100 SINGAPORE 560625			
ID Type / ID No.: NRIC N-3 / S7919451D		Contact No. Home/Office:		Mobile: 83849981	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 39	Date of Birth: 07/07/1979	Type of Informant: Driver		
Race: Indian		Language:		Institution / School Name:	
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3		Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/02/2019 09:00	Type of Location: SLIP ROAD	
Location: Along Road 1 CENTRAL EXPRESSWAY				
Direction: TOWARD CITY				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Heavy		
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CX410Y	LAND ROVER					0
SIR9162T	Car					1


<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Paya Lebar NPP  
111 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2699899



T/20190226/2111

2 of 3

Report No. T/20190226/2111

CONTINUATION OF REPORT

Name	MANI GURUNG		ID No.	G6251027M
Related Vehicle	QX410Y (LAND ROVER)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
<b>Driver</b>				
Name	CHNG YA LI KELVIN		ID No.	S7919451D
Related Vehicle	SJR9162T (Car)		Contact No.	83649881
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

**Break Details.**

On 26/02/2019 at about 0900hrs, I was driving my car, vehicle number SJR9162T along CTE toward city. I was travelling straight and when I was approaching a slip road, I spotted a police land rover, vehicle number QX410Y trying to merge in to my lane from PIE from my left, as such I slowed down and came to a complete stop so to give way to the land rover.

However, the land rover while coming out from the merging lane, side swiped my car and in a result causing damages to left bumper, fender and rims of my vehicle. Upon the accident, we came out of our vehicle and that was when a LTA officer approached us and took photos. The LTA officer then called for police assistance. Both me and the other parties, a Gurkha officer was not injured. The LTA officer then instructed us to drive to an open car park and wait for traffic police arrival.

Traffic police then came and took my in car cctv ed card for investigation purposes. I was then instructed to lodge a police traffic accident report vide incident E/20190226/0050.

I wished to state that I had a witness in my vehicle during that accident. Her particular is as such, Natascha, contact number 81614488.

POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999



T/20190228/2111

3 of 3

Report No. T/20190228/2111

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /  
Sgt 2 KOH PEI QI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/02/2019 15:32

Officer In Charge Of Case:

YP / GIT /  
Staff Sgt SUFIYAN BIN KHAIRI  
Contact No: 65476300

SN 085

Classification Of Case:

Authentication Stamp

4P168

Signature

Singapore Police Force



# AUTOMOBILE HUB ENTERPRISE

51 Defu lane 9, Singapore 539291

H/P: 9786 4483 FAX:6758 3325

Email: autohub325@gmail.com

Vehicle No.: SJR 9162T

Model: TOYOTA ALTIS

not. Authorized  
L/KK  
6/3/19  
4300/2  
4/s  
4 day.  
Take photo after repair

## QTY List Price:

## Prices \$

1	Front bumper	DIS	548.20 ✓
1	Front bumper logo	nu	58.50 ✓
1	Front bumper fog lamp- LH	CNQ	281.90 ✓
1	Front bumper fog lamp cover	Torn	110.20 ✓
1	Front bumper top seal	11	68.60 X
2	Front bumper side retainers- R/L @ 42.20	MScre	84.40 (PC
10	Front bumper clips @ 4.50	nu	45.00 ✓
1	Front bonnet	nu	1076.50 X
1	Front fender- LH	Body m	617.30 ✓
1	Front fender emblem " VVT-I "	nu	42.20 ✓
1	Front fender inner shield	Torn	169.30 ✓
15	Front fender inner shield clips @ 4.50	nu	67.50 ✓
1	Front fender wheel housing	n	486.90 X
1	Front door- LH	n	1082.50 X
1	Front door protector	11	142.20 X
1	Front door side mirror <i>lamp only</i>	115-12	SCR 841.20 ✓
1	Front door side mirror cover	11	110.20 X
1	Front headlamps assy- LH	Scap/nu	680.60 ✓
1	Front support panel	n	991.20 X
1	Front shock absorber- LH	berf	482.90 ✓
1	Front shock absorber top mount	11	180.60 X
1	Front lower arm	3erf	602.10 ✓
1	Front lower arm ball joint	11	184.45 X
1	Front knuckle arm	berf	571.60 ✓
1	Front wheel hub	berf	244.65 ✓

Vehicle No.: SJR 9162T

1	Front wheel bearing	130.90 ✓
1	Front anti roll bar	343.20 X
1	Front anti roll bar link	195.60 X
1	Air cleaner intake duct	182.90 X
		<hr/>
		10623.30
Less 25%		(2655.83)
Subtotal		7967.47

**Special Nett items:**

1	Front sport wheel- LH	650.00 420
1	Front tyre- LH	350.00 X
		<hr/>
Subtotal		1000.00

**Labour Charges:**

To remove, refix F/undercarriage	300.00	120
To checking F/electrical wiring	50.00	30
To check wheel alignment	120.00	✓
To respray undercoating	80.00	30
To respray painting and etc	1080.00	650
Panel beating, cut, weld, remove and replacing above parts	1050.00	400
Subtotal	<u>2680.00</u>	

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 11647.47**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

**JusEquity Law Corporation****ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS**

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Fax : (65) 6536 5368 (Litigation &amp; Conveyancing)

Email : claims@juseq.com.sg

website : www.juseq.com.sg

Our Ref: JEQ/SJR9162T/AHE (zl)

Your Ref: QX410Y

27 February 2019

**SINGAPORE POLICE FORCE**  
**(POLICE LOGISTICS DEPARTMENT)**  
28 Irrawaddy Road  
New Phoenix Park  
Singapore 329560

**By Post & Fax : 6259 7643**

Dear Sir

**ACCIDENT INVOLVING SJR9162T & QX410Y ON 26.02.2019**

We act for the owner of vehicle no. SJR9162T.

We hereby notify you of a road traffic accident on **26 February 2019** at about **0900 hrs**, at PIE towards CTE slip road involving our client's vehicle and vehicle registration no. **QX410Y** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

*Morans H. H.*  
6/3/19

Encl.

**CONFIDENTIALITY CAUTION**

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19004098/Uqd3e2	
ACCIDENT CLAIM SECTION(SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333			Date : 19-03-2019 	
ATTN : FRANKIE THAY			Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 410Y	Veh. Inspected	SJR 9162T	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/09/2019/008	Excess (\$)	0.00	
Assign From	FRANKIE THAY	Assign Date	06/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106147943	Colour	WHITE	
Odometer	236039	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/02/2019	Inspection Date	06/03/2019	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 9162T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DISTORTED	548.20	548.20
1	FRONT BUMPER LOGO	NECESSARY	58.50	58.50
1	FRONT BUMPER FOG LAMP - LH	CRACKED	281.90	281.90
1	FRONT BUMPER FOG LAMP COVER	TORN	110.20	110.20
1	FRONT BUMPER TOP SEAL	NOT NECESSARY	68.60	-
2	FRONT BUMPER SIDE RETAINERS - R/L @\$42.20	N/S CRACKED	84.40	42.20
10	FRONT BUMPER CLIPS @\$4.50	NECESSARY	45.00	45.00
1	FRONT BONNET	NOT NECESSARY	1,076.50	-
1	FRONT FENDER - LH	BADLY DENTED	617.30	617.30
1	FRONT FENDER EMBLEM "VVT-I"	NECESSARY	42.20	42.20
1	FRONT FENDER INNER SHIELD	TORN	169.30	169.30
15	FRONT FENDER INNER SHIELD CLIPS @\$4.50	NECESSARY	67.50	67.50
1	FRONT FENDER WHEEL HOUSING	TO REPAIR SEE LABOUR	486.90	-
1	FRONT DOOR - LH	TO REPAIR SEE LABOUR	1,082.50	-
1	FRONT DOOR PROTECTOR	NOT NECESSARY	142.20	-
1	FRONT DOOR SIDE MIRROR	SCRATCHED-LAMP ONLY	841.20	115.10
1	FRONT DOOR SIDE MIRROR COVER	NOT NECESSARY	110.20	-
1	FRONT HEADLAMPS ASSY - LH	SCRATCHED / CRACKED	680.60	680.60
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	991.20	-
1	FRONT SHOCK ABSORBER - LH	BENT	482.90	482.90
1	FRONT SHOCK ABSORBER TOP MOUNT	NOT NECESSARY	180.60	-
1	FRONT LOWER ARM	BENT	602.10	602.10
1	FRONT LOWER ARM BALL JOINT	NOT NECESSARY	184.45	-
1	FRONT KNUCKLE ARM	BENT	571.60	571.60
1	FRONT WHEEL HUB	BENT	244.65	244.65
1	FRONT WHEEL BEARING	NECESSARY	130.90	130.90
1	FRONT ANTI ROLL BAR	NOT NECESSARY	343.20	-
1	FRONT ANTI ROLL BAR LINK	NOT NECESSARY	195.60	-
1	AIR CLEANER INTAKE DUCT	NOT NECESSARY	182.90	-

Report Ref No. CS/SPF19004098/Uqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,655.83	-1,202.54
			7,967.47	3,607.61
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT SPORT WHEEL - LH (SN)	CUT / BENT	650.00	420.00
1	FRONT TYRE - LH (SN)	SERVICEABLE	350.00	-
			1,000.00	420.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REFIX F/UNDERCARRIAGE.		300.00	120.00
	TO CHECKING F/ELECTRICAL WIRING.		50.00	30.00
	TO CHECK WHEEL ALIGNMENT.		120.00	120.00
	TO RESPRAY UNDERCOATING.		80.00	30.00
	TO RESPRAY PAINTING AND ETC.		1,080.00	650.00
	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER WHEEL HOUSING, FRONT DOOR - LH AND FRONT SUPPORT PANEL .		1,050.00	400.00
			2,680.00	1,350.00
	<b>GRAND TOTAL</b>		<b>11,647.47</b>	<b>5,377.61</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,300.00</b>

Report Ref No. CS/SPF19004098/Uqd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,300-\$4,800

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.