

SAI/Moyan

ASSIGNMENT (Office)From (Person): Chang Boon Sen of CTI Date/Time: 05/3/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 6683G Insured: SKC 6677Lat Workshop m/s: S-Tech Automotive Tel: 62722141 Sallyof B11C 1002 Bukit Merah Lane 3 #01-87Policy No: DMPCN30816219011 Claim No: SNM19D201057602

Sum Insured: Excess:

Make of Veh: D.O.A. 28/2/19
(Client's Record)CA / REV / REP. / REV 24 HRS 1WP H.O.D. Endorsement:Date/Time: 6/3 Person Contacted: Pony Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>SLC 6683G / SKC 6677L NBA/INC19003997/Y D.O.A: 28/2/19</u>
	<u>SKC6677L - CS/CT119004268/Ked3 D.O.A: 28/2/2019.</u>
	<u>Disassemble: 12/3/2019</u>
	<u>Before paint: 13/3/2019</u>

Taufik

REF

CTI

Form No. _____ Date _____

Insured's Name _____

Policy No. _____

Vehicle No. _____

Make of Vehicle _____

Model _____

Year _____

Engine No. _____

Chassis No. _____

Color _____

Sp. Reading _____

Engine _____

Chassis _____

Condition _____


Remarks: The veh had commenced its repair at the time of inspection.

Est. Repair _____ days

Est. Cost _____ %

GA / REV / REP / 24 HRS

Date _____ Person Contacted _____



Vehicle No. **SLC66836** Date **May 16**

Type ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make **Toyota Harrier** Year **1986**

Color **Black** A/C ☐ Insured / Std / Nil / NA

Sp. Reading **62273** L/Radio ☐ Insured / Std / Nil / NA

Engine No. **ZS4600075490**

Chassis No. **235/SSR/8**

Condition ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / STD / R/Rim or

Tyre Size **F: 235/SSR/8**

R: _____

☒ DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal **6 mm** Rear R/Bal **6 mm**

Front L/Bal **6 mm** Rear L/Bal **6 mm**

D.O.A. **6/5/19**

Survey held at **S-Tech Auto**

Des. of Damages: ☒ Frt / ☒ Rar / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or

The A/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction **No G/LH**

Repair range **\$5000 - \$6000** **7 days**

Date / Time / File Pass to: ☐ : Prel. Report

h) ☐ : Final Report

Days Of Repair: **7**

Resurvey No. of Trip: **2**

Survey Fee: **190**

Transportation: _____

Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Footprint (\$) ☐ Workload (\$)

Report Format **PRE**

Lump Sum / L.B.R. (\$) **190**

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Tuesday, 5 March 2019 1:59 PM
To: assignments
Subject: FW: Our ref: LCH.jp/STEC-90201.19 Your ref: SNM19D201057 - Accident involving SLC 6683 G / SKC 6677 L (China Taiping) on 28/2/19 along West Coast - Pre-repair survey ("PRS") of SLC 6683 G

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 5 March 2019 1:10 PM
To: Cheonghoh Law <mail@cheonghoh.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Our ref: LCH.jp/STEC-90201.19 Your ref: SNM19D201057 - Accident involving SLC 6683 G / SKC 6677 L (China Taiping) on 28/2/19 along West Coast - Pre-repair survey ("PRS") of SLC 6683 G

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Tuesday, 5 March, 2019 12:44 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Our ref: LCH.jp/STEC-90201.19 Your ref: SNM19D201057 - Accident involving SLC 6683 G / SKC 6677 L (China Taiping) on 28/2/19 along West Coast - Pre-repair survey ("PRS") of SLC 6683 G

Dear Mr Chong

We refer to the above matter and your email of even date below.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Liaw Leong San
- (2) Lee Kok Weng
- (3) Ang Guea Kiang
- (4) Lim Yong Tian, Sebastian
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to liaise with our client's repairer workshop for the pre-repair survey of our clients vehicle no. SLC 6683 G, the details are as follows:-

S-TECH Automotive Services
Blk 1002 Bukit Merah Lane 3 #01-87
Singapore 159719

Person In Charge : Ms Sally at 62722141.

91463293 Tony.

Kindly acknowledge.

Thank you.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 5 Mar 2019, at 11:54, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7169G
Vehicle Details	
Vehicle No.:	SLC6683G
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	3ZRB760385
Chassis No.:	ZSU600075490
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$31,175.00
Original Registration Date:	23 May 2016
First Registration Date:	23 May 2016
Transfer Count:	0
Actual ARF Paid:	\$30,645.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2026
PARF Rebate Amount:	\$22,983.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$34,958.00
Total Rebate Amount:	\$57,941.00

The information contained herein is correct as at 03 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/03/2019 18:39
Date Of Accident	28/02/2019 19:35
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLC6683G
Insured/Policyholder	
Name Of Registered Owner	YEO CHOON SIONG MELVYN
NRIC No	S7207169G
Email Address	MEL@LIFELINE.COM.SG
Mobile Phone No	(LOCAL) +65-90903408
Alternative Phone No	OTHERS-90903408
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARREIR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080541023-02
Cover Note Number	
Driver	
Name of Driver	YEO CHOON SIONG MELVYN
NRIC No	S7207169G
Date Of Birth	07/03/1972
Occupation	INDOOR
Date Of Driving Pass	14/11/1989
Driving Experience	29 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90903408
Fax Number	
Contact Number	OTHERS-90903408
EEmail Address	MEL@LIFELINE.COM.SG

Address	32 KEPPEL BAY DRIVE #08-55
Postcode	098651
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC6677L
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN HUAZAI
NRIC/Passport Number	
Contact Number	85517551
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


4 MARCH 2019
5:10 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was coming out of carpark and stopped
at stop line to let 2x pedestrians cross.
was hit from the back by Chen Huezai's
car coming out from the carpark.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: [Signature]
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's signature: *[Signature]*
Name: *[Signature]*
NRIC/FIN No.: *[Signature]*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2019		13 May 2019 10:15 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	YEO CHOON SIONG MELVYN , ID: S7207169G								
Vehicle Reg. No.:	SLC6683G	Date of Loss:	28/02/2019 19:00 - :59 [33 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201057C02	Policy/Cover Note No.:	DMPCSN30816219011						
Vehicle Reg. No. (Insured):	SKC6677L	Policy No. (Claimant):	5080541023-02						
		Excess:	S\$0.00						
Repairer:	Lkk Auto Consultants Pte Ltd (HQ) 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park, 408933 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC6683G (SNM19D201057C02)**
[SKC6677L]

TP

YEO CHOON SIONG MELVYN

Feb 28 2019 7:00PM










[-]

Lkk Auto Consultants Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	04/03/19 18:53	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 18:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
2	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
3	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
4	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
5	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
6	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
7	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
8	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
9	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
10	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
11	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
12	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
13	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
14	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
15	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
16	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
17	16/05/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>
18	16/05/19 17:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
19	16/05/19 17:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
20	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	16/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	16/05/19 17:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
32	16/05/19 17:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
33	16/05/19 17:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
34	16/05/19 17:39	Photo Before Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 10:15	pri contact	 Load PDF	
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/03/19 18:52	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 18:52	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/03/19 18:53	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 18:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/03/19 18:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 18:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119004099/T1CD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30816219011

Claimant Vehicle
No: SLC6683GInsured Vehicle
No: SKC6677L

Date of Loss: 28/02/2019

Nature of Claim: TP

Claim
No: SNM19D201057C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC6683G**

Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A) Engine No: 3ZRB760385

Reg. Date: 23/05/2016 (Man. Year: 2016) Chassis No: ZSU600075490

Colour: Black Odometer: 62273 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 11/03/2019 Inspected At:

S-TECH AUTOMOTIVE SERVICES
BLK 1002, BUKIT MERAH LANE 3 #01-87
SINGAPORE 159719

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 24 May 2019)
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC6683G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >